

1 YEAR  
WARRANTY



User's Guide



Shop online at

**omega.com**

OMEGA

[www.omega.com](http://www.omega.com)

e-mail: [info@omega.com](mailto:info@omega.com)

ISO 9001  
CERTIFIED  
CORPORATE QUALITY  
STAMFORD, CT

ISO 9002  
CERTIFIED  
CORPORATE QUALITY  
MANCHESTER, UK

**CL100MA**  
**4-20mA Loop Calibrator**



**Where Do I Find Everything I Need for  
Process Measurement and Control?  
OMEGA...Of Course!**  
*Shop online at [www.omega.com](http://www.omega.com)*

**TEMPERATURE**

- ☑ Thermocouple, RTD & Thermistor Probes, Connectors, Panels & Assemblies
- ☑ Wire: Thermocouple, RTD & Thermistor
- ☑ Calibrators & Ice Point References
- ☑ Recorders, Controllers & Process Monitors
- ☑ Infrared Pyrometers

**PRESSURE, STRAIN AND FORCE**

- ☑ Transducers & Strain Gages
- ☑ Load Cells & Pressure Gages
- ☑ Displacement Transducers
- ☑ Instrumentation & Accessories

**FLOW/LEVEL**

- ☑ Rotameters, Gas Mass Flowmeters & Flow Computers
- ☑ Air Velocity Indicators
- ☑ Turbine/Paddlewheel Systems
- ☑ Totalizers & Batch Controllers

**pH/CONDUCTIVITY**

- ☑ pH Electrodes, Testers & Accessories
- ☑ Benchtop/Laboratory Meters
- ☑ Controllers, Calibrators, Simulators & Pumps
- ☑ Industrial pH & Conductivity Equipment

**DATA ACQUISITION**

- ☑ Data Acquisition & Engineering Software
- ☑ Communications-Based Acquisition Systems
- ☑ Plug-in Cards for Apple, IBM & Compatibles
- ☑ Datalogging Systems
- ☑ Recorders, Printers & Plotters

**HEATERS**

- ☑ Heating Cable
- ☑ Cartridge & Strip Heaters
- ☑ Immersion & Band Heaters
- ☑ Flexible Heaters
- ☑ Laboratory Heaters

**ENVIRONMENTAL**

**MONITORING AND CONTROL**


- ☑ Metering & Control Instrumentation
- ☑ Refractometers
- ☑ Pumps & Tubing
- ☑ Air, Soil & Water Monitors
- ☑ Industrial Water & Wastewater Treatment
- ☑ pH, Conductivity & Dissolved Oxygen Instruments

M3689/0501

**Table of Contents**

|  |           |
|--|-----------|
| <b>I. PANEL DESCRIPTION .....</b>                      | <b>1</b>  |
| <b>II. OPERATING INSTRUCTION.....</b>                  | <b>7</b>  |
| 1. MA OUTPUT.....                                      | 7         |
| 1A. GENERAL OPERATION 4 - 20mA .....                   | 7         |
| 1B. SELECT 0 - 20mA OR 0 - 24mA.....                   | 8         |
| 1C. ENTER A VALUE LESS THAN 1 .....                    | 9         |
| 2. % (PERCENTAGE) INPUT.....                           | 9         |
| 3. EASY STEP UP AND DOWN .....                         | 11        |
| 4. AUTO STEP FUNCTION: .....                           | 13        |
| 5. AUTO RAMP FUNCTION.....                             | 15        |
| 6. 0 TO 24 V OUTPUT.....                               | 17        |
| <b>III. ELECTRICAL SPECIFICATION (23°C ± 5°C).....</b> | <b>18</b> |
| <b>IV. USE THE AC ADAPTER.....</b>                     | <b>19</b> |
| <b>V. USE EXTERNAL BATTERY PACK.....</b>               | <b>19</b> |
| <b>VI. BATTERY REPLACEMENT.....</b>                    | <b>20</b> |




## I. Panel Description




1. LCD DISPLAY  
2. ON/OFF BUTTON  
3. SHIFT BUTTON  
4. OUTPUT LEADS

5. NUMERICAL & FUNCTION KEYPAD  
6. STAND  
7. AC ADAPTOR INPUT SOCKET




- |   |                        |
|---|------------------------|
| 1. mA:  | Units                  |
| 2. 04-204mA :   | Range of mA            |
| 3. %:   | Percentage             |
| 4.  :  | Ramp                   |
| 5.  : | STEP                   |
| 6. OL:  | Overload, output open  |
| 7. SHIFT:   | Select SHIFT functions |
| 8.   | Battery low            |

1



1.




Press SHIFT button, and then press one of these three buttons to select desired mA range

2.



Press SHIFT button, then press this button to enter the START value for auto ramp function


3.



3


Press SHIFT button, then press this button to enter END value for auto ramp function

4.



Press SHIFT button, then press this button to enter duration in SECONDS for auto ramp function.


5.



Press SHIFT button, then press this button to perform auto-ramp function. To stop the auto-ramp function, press this button again




6.




Press SHIFT button, then press this button first to enter percentage (0 –100)

7.



While the calibrator is in the SHIFT mode, and the percentage is entered, press these buttons to increment or decrement %.

8.



Press this button to start auto STEP function. To temporarily stop STEP function, press this button again.

9.




Always press this button to complete the entry of numbers.

## II. Operating Instruction

### 1. mA Output

#### 1a. General Operation 4 - 20mA


- 1 Turn the power on, and wait until the STBY symbol disappears (about 1 min.)
- 2 Plug the test leads into the output connectors of calibrator accordingly (Black to black, red to red). Attach alligator clip if necessary.
- 3 Press the keypad (including the decimal point) to enter the value of mA directly.
- 4 Using the test leads or alligator clips, touch or clip on the terminals to be calibrated.




entry. If users enter 5 or more digits, calibrator will automatically end the entry and output specified value current.

### 1b. Select 0 - 20mA or 0 - 24mA

The default setting for mA function is 4 - 20mA. But users can select 0 - 20mA or 0 - 24 mA by pressing the SHIFT button to enter the SHIFT mode. Then press the NUMBER 2 or NUMBER 3 button to select desired DC current range. After desired range is selected, press the shift button to exit the SHIFT mode. Corresponding current range symbol will be displayed in the LCD.





### 1c. Enter a value less than 1

In the mA functions, the standard way to enter a value less than 1 is to press leading 0 before pressing the decimal point. Though the decimal point can be entered, the decimal point will not be shown in the LCD.


### 2. % (percentage) input


To enter percentage (%)

1. Users press the shift button first, then SHIFT symbol will be

displayed in the LCD.

- 2 Press % button first, then press the number (no decimal number, the % resolution is 1%).
- 3 After percentage is entered, the percentage will be displayed in the upper LCD, and the corresponding value will be displayed in the lower LCD.
4. The corresponding value is calculated based upon the range selected.  
4-20mA: 1% = 0.16mA (start at 4 mA)  
0-20mA: 1% = 0.2mA  
0-24mA: 1% = 0.24mA
5. To exit the percentage-input mode, press the SHIFT button again.
6. After the SHIFT button is pressed, the upper LCD will become blank, while the lower LCD retains its last value.





### 3. Easy Step Up and Down

While the percentage is entered and calibrator is still in the SHIFT mode, users can step up or down by the percentage entered. The maximum


percentage is 100% while the minimum percentage is 0%. If the next step up or down exceeds the maximum or minimum percentage, the percentage will stay in the previous step.

Example 1: Step Up and Down(25%):


25% -> 50% -> 75% -> 100% -> 75% -> 50% -> 25% -> 0% -> 25%

Example 2: Step Up and Down(30%):

30% -> 60% -> 90% -> 60% -> 30% -> 0% -> 30%







#### 4. Auto Step Function:

##### 4a. Start Auto Step Function

The default percentage is 25%, and the default duration for step is 4

seconds.

1. To start auto step function, press the SHIFT key to enter SHIFT mode.
  2. Press the NUMBER 9 key to start. Calibrator outputs 0% of the range for 4 seconds. Then increment the output to 25% and keep the output at that value for another 4 seconds, then 75%(4 seconds), 100%(4 seconds), 75%(4 seconds), 25%(4 seconds), 0%(4 seconds), 25%(4 seconds) ...
  3. To temporarily stop the step function, press the NUMBER 9 key again.
- 4b. Change the Step Size (%) and Duration

**Step Size (%)**

1. Press the SHIFT key to enter SHIFT mode.
2. Press the DOT key, enter the value of percentage (%), then press the ENTER key.

**Duration**

1. Press the SHIFT key to enter SHIFT mode.
2. Press the NUMBER 6 key, enter the value in seconds for the DURATION, then press the ENTER key.

## 5. Auto Ramp Function


### 5a. Start Ramp Function

The default setup for the auto ramp function is as follows:

| RANGE  | START | END  | DURATION |
|--------|-------|------|----------|
| 4-20mA | 4mA   | 20mA | 4seconds |
| 0-20mA | 0mA   | 20mA | 4seconds |
| 0-24mA | 0mA   | 24mA | 4seconds |

To start the ramp function:

1. Press the SHIFT button to enter the SHIFT mode.
2. Press the NUMBER 7 key to start
3. Calibrator outputs current (mA) from START value to END value in the DURATION specified by users then outputs from END value to START value in the DURATION repeatedly.
4. To temporarily stop the ramp function, press the NUMBER 7 key, and the output will stay at the value when the NUMBER 7 key is pressed. To restart again, press the NUMBER 7 button again.
5. To return to the regular output mode, press the SHIFT button again when ramp function is stopped.



5b. How to change the START, END and DURATION of the RAMP function

**START:**

1. Press the SHIFT button to enter the SHIFT mode.
2. Press the NUMBER 4 key, then LCD will display STA in the upper LCD.
3. Enter the desired start value, then press ENTER key.

**END:**

1. Press the SHIFT button to enter the SHIFT mode.
2. Press the NUMBER 5 key, then LCD will display END in the upper LCD.
3. Enter the desired end value, then press ENTER key.

**DURATION:**


1. Press the SHIFT button to enter the SHIFT mode.
2. Press the NUMBER 6 key, then LCD will display SEC in the upper LCD.
3. Enter the desired duration in seconds, then press ENTER key. The range for duration is from 1 to 2000 seconds

NOTE: Users should set an appropriate value for the duration of ramp function. For a full range ramp, users should enter at least 4 seconds for the duration.

## 6. 0 to 24 V Output

To set unit in voltage output mode, hold the “SHIFT” button, then press the ON/OFF button to turn the power on. When the unit is in Voltage output mode, the LCD will show symbol of V instead of mA. The mA and the dash symbols in the range indication will disappear. For example, “0 20” means 0 to 20V. “4 20” means 4 to 20V. “0 24” means 0 to 24V. The default range is 0 to 24V.

The rest of the operation is exactly the same as mA output.



### III. Electrical Specification (23°C ± 5°C)

mA DC Current (1K $\Omega$  Max. Load, 24V Loop Supply)

| Range     | Resolution | Accuracy                  |
|-----------|------------|---------------------------|
| 0 – 4mA   | 1 $\mu$ A  | $\pm 0.025\% \pm 10\mu$ A |
| 4 – 20mA  | 1 $\mu$ A  | $\pm 0.025\% \pm 5\mu$ A  |
| 20 – 24mA | 1 $\mu$ A  | $\pm 0.025\% \pm 5\mu$ A  |

Beeper warning when output is open and specified output > 1mA

V DC Voltage

| Range    | Resolution | Accuracy               |
|----------|------------|------------------------|
| 0 – 4V   | 1mV        | $\pm 0.05\% \pm 10$ mV |
| 4 – 20V  | 1mV        | $\pm 0.05\% \pm 5$ mV  |
| 20 – 24V | 1mV        | $\pm 0.05\% \pm 5$ mV  |


Beeper warning when output is short and specified output > 100mV

General Specification:

|                        |   |
|------------------------|---|
| Battery Type:          | 9V Alkaline Battery   |
| Power Consumption:     | 25 mA at 100 $\Omega$ load  |
| Display:               | 4+ 5 Digits   |
| Operating Temperature: | 0 to 50°C ( 32 to 122 °F)   |
| Operating Humidity:    | Less than 85% relative  |
| Storage Temperature:   | -20 to 60° C (-4 to 140 °F)   |
| Storage Humidity:      | Less than 85% relative  |
| Dimension:             | 88 x 168 x 26 mm<br>(3.46" x 6.61" x 1.03")   |
| Weight:                | 330 g / 11.63 oz  |
| Accessories:           | Carrying case x 1<br>Users Manual x 1<br>External Battery Pack<br>6 1.5V AA Batteries<br>Alligator clip x 1 |

#### IV. Use the AC adapter

If long term usage of the calibrator is required, AC adapter can be used. The 12V AC terminal is located in the back of the calibrator. The voltage should be regulated between 9 to 15V.




#### V. Use External Battery Pack



An external battery pack is included for a longer period usage. The external battery pack needs to be packed with 6 pieces of 1.5 volts AA batteries. To use the external battery pack, plug into the AC terminals located in the back

of the calibrator.

## BATTERY HOLDER



## BATTERIES 6x1.5V AA






## VI. Battery Replacement

When the low battery symbol is displayed on LCD, follow the following procedures to replace the battery.

- 1 Turn off the calibrator by pushing the On/Off button.
- 2 Remove the screw of the battery compartment cover and remove the battery compartment cover.
- 3 Replace the old 9V battery with a new alkaline 9V battery.
- 4 Replace the battery compartment cover and fasten the screw.







OMEGAnet® Online Service  
www.omega.com

Internet e-mail  
info@omega.com

#### Servicing North America:

**USA:**  
ISO 9001 Certified  
One Omega Drive, Box 4047  
Stamford CT 06907-0047  
Tel: (203) 359-1660  
e-mail: info@omega.com  
FAX: (203) 359-7700

**Canada:**  
976 Bergar  
Laval (Quebec) H7L 5A1  
Tel: (514) 856-6928  
e-mail: info@omega.ca  
FAX: (514) 856-6886

#### For immediate technical or application assistance:

**USA and Canada:** Sales Service: 1-800-826-6342 / 1-800-TC-OMEGA®  
Customer Service: 1-800-622-2378 / 1-800-622-BEST®  
Engineering Service: 1-800-872-9436 / 1-800-USA-WHEN®  
TELEX: 996404 EASYLINK: 62968934 CABLE: OMEGA

**Mexico:** En Español: (001) 203-359-7803  
FAX: (001) 203-359-7807  
e-mail: espanol@omega.com  
info@omega.com.mx

#### Servicing Europe:

**Benelux:** Postbus 8034, 1180 LA Amstelveen, The Netherlands  
Tel: +31 (0)20 3472121  
Toll Free in Benelux: 0800 0993344  
e-mail: nl@omega.com  
FAX: +31 (0)20 6434643

**Czech Republic:** Rudé armády 1868, 733 01 Karviná 8  
Tel: +420 (0)69 6311899  
Toll Free: 0800-1-66342  
FAX: +420 (0)69 6311114  
e-mail: czech@omega.com

**France:** 9, rue Denis Papin, 78190 Trappes  
Tel: +33 (0)130 621 400  
Toll Free in France: 0800-4-06342  
e-mail: france@omega.com  
FAX: +33 (0)130 699 120

**Germany/Austria:** Daimlerstrasse 26, D-75392 Deckenpfronn, Germany  
Tel: +49 (0)7056 9398-0  
Toll Free in Germany: 0800 639 7678  
e-mail: germany@omega.com  
FAX: +49 (0)7056 9398-29

**United Kingdom:** One Omega Drive, River Bend Technology Centre  
ISO 9002 Certified  
Northbank, Irlam, Manchester  
M44 5BD United Kingdom  
Tel: +44 (0)161 777 6611  
Toll Free in United Kingdom: 0800-488-488  
e-mail: sales@omega.co.uk  
FAX: +44 (0)161 777 6622

It is the policy of OMEGA to comply with all worldwide safety and EMC/EMI regulations that apply. OMEGA is constantly pursuing certification of its products to the European New Approach Directives. OMEGA will add the CE mark to every appropriate device upon certification.

The information contained in this document is believed to be correct, but OMEGA Engineering, Inc. accepts no liability for any errors it contains, and reserves the right to alter specifications without notice.  
**WARNING:** These products are not designed for use in, and should not be used for, patient connected applications.

## WARRANTY/DISCLAIMER

OMEGA ENGINEERING, INC. warrants this unit to be free of defects in materials and workmanship for a period of **13 months** from date of purchase. OMEGA's Warranty adds an additional one (1) month grace period to the normal **one (1) year product warranty** to cover handling and shipping time. This ensures that OMEGA's customers receive maximum coverage on each product.

If the unit malfunctions, it must be returned to the factory for evaluation. OMEGA's Customer Service Department will issue an Authorized Return (AR) number immediately upon phone or written request. Upon examination by OMEGA, if the unit is found to be defective, it will be repaired or replaced at no charge. OMEGA's WARRANTY does not apply to defects resulting from any action of the purchaser, including but not limited to mishandling, improper interfacing, operation outside of design limits, improper repair, or unauthorized modification. This WARRANTY is VOID if the unit shows evidence of having been tampered with or shows evidence of having been damaged as a result of excessive corrosion; or current, heat, moisture or vibration; improper specification; misapplication; misuse or other operating conditions outside of OMEGA's control. Components which wear are not warranted, including but not limited to contact points, fuses, and triacs.

**OMEGA is pleased to offer suggestions on the use of its various products. However, OMEGA neither assumes responsibility for any omissions or errors nor assumes liability for any damages that result from the use of its products in accordance with information provided by OMEGA, either verbal or written. OMEGA warrants only that the parts manufactured by it will be as specified and free of defects. OMEGA MAKES NO OTHER WARRANTIES OR REPRESENTATIONS OF ANY KIND WHATSOEVER, EXPRESS OR IMPLIED, EXCEPT THAT OF TITLE, AND ALL IMPLIED WARRANTIES INCLUDING ANY WARRANTY OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE ARE HEREBY DISCLAIMED. LIMITATION OF LIABILITY: The remedies of purchaser set forth herein are exclusive, and the total liability of OMEGA with respect to this order, whether based on contract, warranty, negligence, indemnification, strict liability or otherwise, shall not exceed the purchase price of the component upon which liability is based. In no event shall OMEGA be liable for consequential, incidental or special damages.**

CONDITIONS: Equipment sold by OMEGA is not intended to be used, nor shall it be used: (1) as a "Basic Component" under 10 CFR 21 (NRC), used in or with any nuclear installation or activity; or (2) in medical applications or used on humans. Should any Product(s) be used in or with any nuclear installation or activity, medical application, used on humans, or misused in any way, OMEGA assumes no responsibility as set forth in our basic WARRANTY/DISCLAIMER language, and, additionally, purchaser will indemnify OMEGA and hold OMEGA harmless from any liability or damage whatsoever arising out of the use of the Product(s) in such a manner.

## RETURN REQUESTS/INQUIRIES

Direct all warranty and repair requests/inquiries to the OMEGA Customer Service Department. BEFORE RETURNING ANY PRODUCT(S) TO OMEGA, PURCHASER MUST OBTAIN AN AUTHORIZED RETURN (AR) NUMBER FROM OMEGA'S CUSTOMER SERVICE DEPARTMENT (IN ORDER TO AVOID PROCESSING DELAYS). The assigned AR number should then be marked on the outside of the return package and on any correspondence.

The purchaser is responsible for shipping charges, freight, insurance and proper packaging to prevent breakage in transit.

FOR **WARRANTY** RETURNS, please have the following information available BEFORE contacting OMEGA:

1. Purchase Order number under which the product was PURCHASED,
2. Model and serial number of the product under warranty, and
3. Repair instructions and/or specific problems relative to the product.

FOR **NON-WARRANTY** REPAIRS, consult OMEGA for current repair charges. Have the following information available BEFORE contacting OMEGA:

1. Purchase Order number to cover the COST of the repair,
2. Model and serial number of the product, and
3. Repair instructions and/or specific problems relative to the product.

OMEGA's policy is to make running changes, not model changes, whenever an improvement is possible. This affords our customers the latest in technology and engineering.

OMEGA is a registered trademark of OMEGA ENGINEERING, INC.

© Copyright 2001 OMEGA ENGINEERING, INC. All rights reserved. This document may not be copied, photocopied, reproduced, translated, or reduced to any electronic medium or machine-readable form, in whole or in part, without the prior written consent of OMEGA ENGINEERING, INC.