

# Where Do I Find Everything I Need for Process Measurement and Control? OMEGA...Of Course!

## TEMPERATURE

- ☑ Thermocouple, RTD & Thermistor Probes, Connectors, Panels & Assemblies
- ☑ Wire: Thermocouple, RTD & Thermistor
- ☑ Calibrators & Ice Point References
- ☑ Recorders, Controllers & Process Monitors
- ☑ Infrared Pyrometers

## PRESSURE, STRAIN AND FORCE

- ☑ Transducers & Strain Gauges
- ☑ Load Cells & Pressure Gauges
- ☑ Displacement Transducers
- ☑ Instrumentation & Accessories

## FLOW/LEVEL

- ☑ Rotameters, Gas Mass Flowmeters & Flow Computers
- ☑ Air Velocity Indicators
- ☑ Turbine/Paddlewheel Systems
- ☑ Totalizers & Batch Controllers

## pH/CONDUCTIVITY

- ☑ pH Electrodes, Testers & Accessories
- ☑ Benchtop/Laboratory Meters
- ☑ Controllers, Calibrators, Simulators & Pumps
- ☑ Industrial pH & Conductivity Equipment

## DATA ACQUISITION

- ☑ Data Acquisition & Engineering Software
- ☑ Communications-Based Acquisition Systems
- ☑ Plug-in Cards for Apple, IBM & Compatibles
- ☑ Datalogging Systems
- ☑ Recorders, Printers & Plotters

## HEATERS

- ☑ Heating Cable
- ☑ Cartridge & Strip Heaters
- ☑ Immersion & Band Heaters
- ☑ Flexible Heaters
- ☑ Laboratory Heaters


## ENVIRONMENTAL MONITORING AND CONTROL

- ☑ Metering & Control Instrumentation
- ☑ Refractometers
- ☑ Pumps & Tubing
- ☑ Air, Soil & Water Monitors
- ☑ Industrial Water & Wastewater Treatment
- ☑ pH, Conductivity & Dissolved Oxygen Instruments

M2367/0896

# User's Guide

CE




**CE OMEGA**  
An OMEGA Technologies Company

<http://www.omega.com>  
e-mail: [info@omega.com](mailto:info@omega.com)

## HH-30A, HH-31A, HH-32A Handheld Anemometer



## Unpacking Instructions



<b>OMEGAnet™ On-Line Service</b> <a href="http://www.omega.com">http://www.omega.com</a>	<b>Internet e-mail</b> <a href="mailto:info@omega.com">info@omega.com</a>
---	--

### Servicing North America:

**USA:** One Omega Drive, Box 4047  
ISO 9001 Certified Stamford, CT 06907-0047  
 Tel: (203) 359-1660 FAX: (203) 359-7700  
 e-mail: [info@omega.com](mailto:info@omega.com)

**Canada:** 976 Bergar  
 Laval (Quebec) H7L 5A1  
 Tel: (514) 856-6928 FAX: (514) 856-6886  
 e-mail: [canada@omega.com](mailto:canada@omega.com)

### For immediate technical or application assistance:

**USA and Canada:** Sales Service: 1-800-826-6342 / 1-800-TC-OMEGA<sup>SM</sup>  
 Customer Service: 1-800-622-2378 / 1-800-622-BEST<sup>SM</sup>  
 Engineering Service: 1-800-872-9436 / 1-800-USA-WHEN<sup>SM</sup>  
 TELEX: 996404 EASYLINK: 62968934 CABLE: OMEGA

**Mexico and Latin America:** Tel: (95) 800-TC-OMEGA<sup>SM</sup> FAX: (95) 203-359-7807  
 En Español: (203) 359-1660 ext: 2203 e-mail: [espanol@omega.com](mailto:espanol@omega.com)

### Servicing Europe:

**Benelux:** Postbus 8034, 1180 LA Amstelveen, The Netherlands  
 Tel: (31) 20 6418405 FAX: (31) 20 6434643  
 Toll Free in Benelux: 06 0993344  
 e-mail: [nl@omega.com](mailto:nl@omega.com)

**Czech Republic:** Ostravska 767, 733 01 Karvina  
 Tel: 42 (69) 6311899 FAX: 42 (69) 6311114  
 e-mail: [czech@omega.com](mailto:czech@omega.com)

**France:** 9, rue Denis Papin, 78190 Trappes  
 Tel: 33 0130-621-400 FAX: 33 0130-699-120  
 Toll Free in France: 05-4-06342  
 e-mail: [france@omega.com](mailto:france@omega.com)

**Germany/Austria:** Daimlerstrasse 26, D-75392 Deckenpfronn, Germany  
 Tel: 49 (07056) 3017 FAX: 49 (07056) 8540  
 Toll Free in Germany: 0130 11 21 66  
 e-mail: [germany@omega.com](mailto:germany@omega.com)

**United Kingdom:** 25 Swannington Road, P.O. Box 7, Omega Drive,  
ISO 9002 Certified Broughton Astley, Leicestershire, Irlam, Manchester,  
 LE9 6TU, England M44 5EX, England  
 Tel: 44 (1455) 285520 Tel: 44 (161) 777-6611  
 FAX: 44 (1455) 283912 FAX: 44 (161) 777-6622  
 Toll Free in England: 0800-488-488  
 e-mail: [uk@omega.com](mailto:uk@omega.com)

Remove the Packing List and verify that you have received all equipment, including the following (quantities in parentheses):

- Vane type probe head (1)
- Extension rods (one piece with handle grip) (3)
- Flexible rod (1)
- 5 feet of connecting cable (1)  
(note: the cable is attached to the 1" dia probe)
- "AA" 1.5 Volt alkaline batteries (2)
- Carrying case (1)
- Operator's Manual (1)

If you have any questions about the shipment, please call the OMEGA Customer Service Department.

When you receive the shipment, inspect the container and equipment for signs of damage. Note any evidence of rough handling in transit. Immediately report any damage to the shipping agent.

### NOTE

The carrier will not honor damage claims unless all shipping material is saved for inspection. After examining and removing contents, save packing material and carton in the event reshipment is necessary.

From the Technical Library of \_\_\_\_\_

It is the policy of OMEGA to comply with all worldwide safety and EMC/EMI regulations that apply. OMEGA is constantly pursuing certification of its products to the European New Approach Directives. OMEGA will add the CE mark to every appropriate device upon certification.

The information contained in this document is believed to be correct but OMEGA Engineering, Inc. accepts no liability for any errors it contains, and reserves the right to alter specifications without notice.

**WARNING:** These products are not designed for use in, and should not be used for, patient connected applications.

	<b>Page</b>
<b>Chapter 1 Introduction .....</b>	<b>1</b>
<b>Chapter 2 Parts of Anemometer .....</b>	<b>2</b>
2.1 Pushbuttons .....	2
2.2 Parts of the Display .....	4
<b>Chapter 3 Installation .....</b>	<b>5</b>
3.1 Installing the Batteries .....	5
3.2 Installing the Probe .....	5
<b>Chapter 4 Operating the Anemometer .....</b>	<b>6</b>
<b>Chapter 5 Internal MAX/MIN Calculations .....</b>	<b>7</b>
<b>Chapter 6 Volume Airflow Calculations .....</b>	<b>8</b>
<b>Chapter 7 Specifications .....</b>	<b>9</b>

The HH-30A Series digital anemometer is a versatile instrument for measuring air velocity. Special features include switchable between Feet Per Minute (FPM) and Meters Per Second (MPS). This includes a hold/reset button so the display can be frozen to help when recording readings. Also it can indicate your average, minimum and maximum readings. This instrument is a must for anyone in the heating, ventilation and air conditioning industry. Specific applications include environmental, paint booths, air balancing and many others where air velocity measurements are essential.

## 2.1 Pushbuttons




Figure 2-1. Front View of the Meter

ON  
OFF

Pressing the "ON/OFF" key switches the unit ON.  
Pressing the "ON/OFF" key a second time turns the unit off.

FPM  
MPS

Pressing the "FPM/MPS" key displays air velocity in feet per minute with 1 FPM resolution.  
Pressing "FPM/MPS" key a second time display air velocity in meters per second with 0.01 MPS resolution.

MAX  
MIN

Pressing the "MAX/MIN" key will display the highest reading since turn on. The maximum hold will operate in both the "2 SEC." and "16 SEC." mode. The measuring mode is indicated by a flashing "H 2" and then the reading for the 2 second mode and a flashing "H 16" and then the reading for the 16 second mode.

MAX  
MIN

(Cont'd)

Pressing the "MAX/MIN" key a second time will display the lowest reading since turn on. The minimum hold will operate in both the "2 SEC." and "16 SEC." mode. The measuring mode is indicated by a flashing "L 2" and then the reading for the 2 second mode, and a flashing "L 16" and then the reading for the 16 second mode. This mode is cleared by pressing the "2 SEC." key. The maximum and minimum readings are cleared by turning the unit Off. More information on calculating the maximum and minimum is in Chapter 5.

2  
SEC.

Pressing the "2 SEC." key sets the measurement period to two seconds. The LCD will display "2 SEC.". The display will then update every two seconds with average for the last two seconds.

16  
SEC.

Pressing the "16 SEC." key sets the measurement period to sixteen seconds. The display will display "16 S" for the first 16 seconds, after which the display will update every two seconds with the average for the last sixteen seconds. Every time the "16 SEC." key is pressed, the averaging time will be restarted.

HOLD  
RESET

Pressing the "HOLD/RESET" key will freeze (HOLD) the reading on the display (the "HOLD" symbol is displayed on the LCD). The current reading is held until reset or turn off. Pressing the "HOLD/RESET" key a second time will unfreeze (RESET) the display (the "HOLD" symbol is not displayed on the LCD). The unit will go back into the measuring mode it was in before the "HOLD" function was initiated.

NOTE: continuing to press the "HOLD/RESET" key will cause the instrument to toggle back and forth between hold and reset.

## 2.2 Parts of the Display




Figure 2-2. LCD Display

## 3.1 Installing the Batteries

1. Remove battery compartment lid by pushing the battery lid tab to the right and lifting. The battery lid should swing out of the way and off.
2. Insert 2 "AA" alkaline batteries into the battery compartment as shown in Figure 3-1.
3. Replace battery compartment lid by placing the battery hinge points into the slots and swing it shut. Make sure the unit is OFF before replacing batteries.

## 3.2 Installing the Probe

1. Attach the probe's connector to the instrument and/or cable by lining up the key to the keyway and inserting the connector. Rotate the locking collar. The 1" diameter probe connects directly to the instrument. The 2 $\frac{3}{4}$ " diameter probe connects to an extension cable that in turn connects to the instrument. Refer to Figure 3-2.
2. Attach the handle to probe using extension and flex rods as needed. Make sure the unit is OFF before attaching the probe.




Figure 3-1. Battery Compartment




Figure 3-2. Connector Configuration

1. Press "ON/OFF" key, and the unit will turn on. The start up sequence displays information about the unit. The unit will display "8 8.8.8"; this is a display check. After display check the unit will display the battery condition ("bA85" means the battery is at 85%). After the battery condition, the unit will display which type of probe is connected (2.75 means the 2.75" diameter probe is connected, 1.00 means the 1" probe is connected). Now the startup sequence is complete and the unit starts displaying air velocity in FPM in the 2 sec average mode. When the low battery symbol appears on display, replace the batteries.
2. Now press the FPM/MPS key for desired function and place the probe head in the area where air velocity is to be measured. When using the 1" probe, line up the arrow with the direction of airflow. The 2¾" probe is bidirectional so just line up the blade's shaft to the airflow. To calculate CFM, refer to Chapter 6.
3. To get the maximum or minimum reading since turn on, press "MAX/MIN" key. Pressing the "MAX/MIN" key again causes the unit to toggle between maximum and minimum.

The flashing "H 2" is the 2 second maximum.

The flashing "L 2" is the 2 second minimum.

The flashing "H 16" is the 16 second maximum.

The flashing "L 16" is the 16 second minimum.

To clear MAX/MIN mode, press the 2 SEC key. More information on internal instrument maximum/minimum calculations is in Chapter 5.

4. To get an average air velocity over a large area, press the "16 SEC." key and move the probe head to cover the opening to be measured. After 16 seconds the unit will display the average air velocity for the last 16 sec. (updating every 2 seconds).
5. When in the 16 sec averaging mode, the maximum or minimum 16 sec reading can be displayed by pressing the "MAX/MIN" key.
6. Press ON/OFF key to turn the unit off when not in use.

The instrument stores readings every 2 seconds. Figure 5-1 shows how the instrument takes a reading and evaluates it against the next group of readings and determines whether it is the MAX reading or the MIN reading.




Figure 5-1. Max and Min Calculations

- A First maximum reading. Also first minimum reading until B occurs.
- B The new MIN will register after the air speed starts to increase.
- C The new higher MAX will register after the air speed starts to decrease.
- D This speed is between the earlier MAX and MIN and will not be reflected.
- E This speed is slower than the previous Min and will now be the new Min after the air speed starts to increase.
- F This speed will not be reflected in the Min reading because it goes directly to zero without increasing speed in the process. This protects against false Min readings when the probe is withdrawn from the air stream.

To calculate cubic feet per minute (ft<sup>3</sup>/min) CFM from a measured air velocity (ft/min) FPM, you need the cross sectional area of the flow stream.

volume flow (CFM)=airflow reading (FPM) x A {area (ft<sup>2</sup>)}

In rectangular duct work this cross sectional area is the width times the height.




Figure 6-1. Cross Sectional Area

$$W \times H = A \text{ (CROSS SECTIONAL AREA)}$$

In circular duct work this cross sectional area is the radius squared times  $\pi$  ( $\pi = 3.14$ ).




Figure 6-2. Cross Sectional Area

$$R \times R \times 3.14 = A \text{ (CROSS SECTIONAL AREA)}$$

$$(D/2) \times (D/2) \times 3.14 = A \text{ (CROSS SECTIONAL AREA)}$$

CONVERSION FACTORS:

To convert from square inches (in<sup>2</sup>) to square feet (ft<sup>2</sup>) divide by 144.

EXAMPLE

An air duct is rectangular and the width is 24" and the length is 12". The air velocity reading in the duct is 450 FPM.

$$W \times L = A \text{ (area)}$$

$$24" \times 12" = 288 \text{ square inches}$$

$$288 \text{ square inches} \div 144 = 2 \text{ square feet (ft}^2\text{)}$$

$$\text{volume flow (CFM)} = \text{airflow reading (FPM)} \times A \text{ (area (ft}^2\text{))}$$

$$900 \text{ CFM} = 450 \text{ FPM} \times 2 \text{ square feet (ft}^2\text{)}$$

## Ranges

HH-30A:	40 to 7800 FPM (0.2 to 40.00 MPS)
HH-31A:	60 to 6800 FPM (0.3 to 35.00 MPS)
HH-32A:	combines both probes for both ranges

## Accuracy

### Air Velocity:

2 3/4" Probe :	±0.25% FS, ± 0.75% of reading ± 1 digit
1" Probe:	±0.5% FS, ± 1.0% of reading ± 1 digit

### Resolution:

1 FPM or 0.01 MPS

### Display:

0.5" LCD, 4 digits

### Operating Temperature:

32°F to 125°F (instrument)  
-4°F to 210°F (probe heads)

### Power Supply:

2 AA alkaline batteries

### Battery Life:

Approximately 300 hours

### Battery Check:

Automatic low battery display, battery capacity readout at startup

### Dimensions:

Instrument:	7.1" x 3.0" x 0.8" (178 x 76 x 20 mm)
HH-30A Probe:	2 3/4" diameter
HH-31A Probe:	1" diameter

### Weight:

8 ounces (227g) with batteries



## WARRANTY/DISCLAIMER

OMEGA ENGINEERING, INC. warrants this unit to be free of defects in materials and workmanship for a period of **13 months** from date of purchase. OMEGA Warranty adds an additional one (1) month grace period to the normal **one (1) year product warranty** to cover handling and shipping time. This ensures that OMEGA's customers receive maximum coverage on each product.

If the unit should malfunction, it must be returned to the factory for evaluation. OMEGA's Customer Service Department will issue an Authorized Return (AR) number immediately upon phone or written request. Upon examination by OMEGA, if the unit is found to be defective it will be repaired or replaced at no charge. OMEGA's WARRANTY does not apply to defects resulting from any action of the purchaser, including but not limited to mishandling, improper interfacing, operation outside of design limits, improper repair, or unauthorized modification. This WARRANTY is VOID if the unit shows evidence of having been tampered with or shows evidence of being damaged as a result of excessive corrosion; or current, heat, moisture or vibration; improper specification; misapplication; misuse or other operating conditions outside of OMEGA's control. Components which wear are not warranted, including but not limited to contact points, fuses, and triacs.

**OMEGA is pleased to offer suggestions on the use of its various products. However, OMEGA neither assumes responsibility for any omissions or errors nor assumes liability for any damages that result from the use of its products in accordance with information provided by OMEGA, either verbal or written. OMEGA warrants only that the parts manufactured by it will be as specified and free of defects. OMEGA MAKES NO OTHER WARRANTIES OR REPRESENTATIONS OF ANY KIND WHATSOEVER, EXPRESSED OR IMPLIED, EXCEPT THAT OF TITLE, AND ALL IMPLIED WARRANTIES INCLUDING ANY WARRANTY OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE ARE HEREBY DISCLAIMED. LIMITATION OF LIABILITY: The remedies of purchaser set forth herein are exclusive and the total liability of OMEGA with respect to this order, whether based on contract, warranty, negligence, indemnification, strict liability or otherwise, shall not exceed the purchase price of the component upon which liability is based. In no event shall OMEGA be liable for consequential, incidental or special damages.**

CONDITIONS: Equipment sold by OMEGA is not intended to be used, nor shall it be used: (1) as a "Basic Component" under 10 CFR 21 (NRC), used in or with any nuclear installation or activity; or (2) in medical applications or used on humans. Should any Product(s) be used in or with any nuclear installation or activity, medical application, used on humans, or misused in any way, OMEGA assumes no responsibility as set forth in our basic WARRANTY/DISCLAIMER language, and additionally, purchaser will indemnify OMEGA and hold OMEGA harmless from any liability or damage whatsoever arising out of the use of the Product(s) in such a manner.

## RETURN REQUESTS / INQUIRIES

Direct all warranty and repair requests/inquiries to the OMEGA Customer Service Department. BEFORE RETURNING ANY PRODUCT(S) TO OMEGA, PURCHASER MUST OBTAIN AN AUTHORIZED RETURN (AR) NUMBER FROM OMEGA'S CUSTOMER SERVICE DEPARTMENT (IN ORDER TO AVOID PROCESSING DELAYS). The assigned AR number should then be marked on the outside of the return package and on any correspondence.

The purchaser is responsible for shipping charges, freight, insurance and proper packaging to prevent breakage in transit.

FOR **WARRANTY** RETURNS, please have the following information available BEFORE contacting OMEGA:

1. P.O. number under which the product was PURCHASED,
2. Model and serial number of the product under warranty, and
3. Repair instructions and/or specific problems relative to the product.

FOR **NON-WARRANTY** REPAIRS, consult OMEGA for current repair charges. Have the following information available BEFORE contacting OMEGA:

1. P.O. number to cover the COST of the repair,
2. Model and serial number of product, and
3. Repair instructions and/or specific problems relative to the product.

OMEGA's policy is to make running changes, not model changes, whenever an improvement is possible. This affords our customers the latest in technology and engineering.

OMEGA is a registered trademark of OMEGA ENGINEERING, INC.

© Copyright 1996 OMEGA ENGINEERING, INC. All rights reserved. This document may not be copied, photocopied, reproduced, translated, or reduced to any electronic medium or machine-readable form, in whole or in part, without prior written consent of OMEGA ENGINEERING, INC.

### Notes