

# User's Guide

**Shop online at**

**omega.com™**  
Ω OMEGA®

**www.omega.com**

**e-mail: info@omega.com**

ISO 9001  
CERTIFIED  
CORPORATE QUALITY

STAMFORD, CT

ISO 9002  
CERTIFIED  
CORPORATE QUALITY

MANCHESTER, UK

## CDCN-5800 Conductivity/Resistivity Controller



**OMEGAnet® Online Service**  
**www.omega.com**

**Internet e-mail**  
**info@omega.com**

### **Servicing North America:**

**USA:**  
ISO 9001 Certified

One Omega Drive, P.O. Box 4047  
Stamford CT 06907-0047  
TEL: (203) 359-1660 FAX: (203) 359-7700  
e-mail: info@omega.com

**Canada:**

976 Bergar  
Laval (Quebec) H7L 5A1  
TEL: (514) 856-6928 FAX: (514) 856-6886  
e-mail: info@omega.ca

### **For immediate technical or application assistance:**

**USA and Canada:** Sales Service: 1-800-826-6342 / 1-800-TC-OMEGA®  
Customer Service: 1-800-622-2378 / 1-800-622-BEST®  
Engineering Service: 1-800-872-9436 / 1-800-USA-WHEN®  
TELEX: 996404 EASYLINK: 62968934 CABLE: OMEGA

**Mexico:**

En Español: (001) 203-359-7803 e-mail: espanol@omega.com  
FAX: (001) 203-359-7807 info@omega.com.mx

### **Servicing Europe:**

**Benelux:**

Postbus 8034, 1180 LA Amstelveen, The Netherlands  
TEL: +31 (0)20 3472121 FAX: +31 (0)20 6434643  
Toll Free in Benelux: 0800 0993344  
e-mail: sales@omegaeng.nl

**Czech Republic:**

Rudé arm·dy 1868, 733 01 Karvin· 8  
TEL: +420 (0)59 6311899 FAX: +420 (0)59 6311114  
Toll Free: 0800-1-66342 e-mail: info@omegashop.cz

**France:**

11, rue Jacques Cartier, 78280 Guyancourt, France  
TEL: +33 (0)1 61 37 29 00 FAX: +33 (0)1 30 57 54 27  
Toll Free in France: 0800 466 342  
e-mail: sales@omega.fr

**Germany/Austria:**

Daimlerstrasse 26, D-75392 Deckenpfronn, Germany  
TEL: +49 (0)7056 9398-0 FAX: +49 (0)7056 9398-29  
Toll Free in Germany: 0800 639 7678  
e-mail: info@omega.de

**United Kingdom:**

ISO 9002 Certified

One Omega Drive, River Bend Technology Centre  
Northbank, Irlam, Manchester  
M44 5BD United Kingdom  
TEL: +44 (0)161 777 6611 FAX: +44 (0)161 777 6622  
Toll Free in United Kingdom: 0800-488-48  
e-mail: sales@omega.co.uk

It is the policy of OMEGA to comply with all worldwide safety and EMC/EMI regulations that apply. OMEGA is constantly pursuing certification of its products to the European New Approach Directives. OMEGA will add the CE mark to every appropriate device upon certification.

The information contained in this document is believed to be correct, but OMEGA Engineering, Inc. accepts no liability for any errors it contains, and reserves the right to alter specifications without notice.

**WARNING:** These products are not designed for use in, and should not be used for, patient-connected applications.

# OMEGA CDCN-5800 Conductivity/Resistivity Monitor Instructions

### CAUTION!




- Refer to instruction manual for more details.
- Remove power to unit before wiring input and output connections.
- Follow instructions carefully to avoid personal injury.

### Contents

1. Power Connections
2. Compatible Sensor Wiring
3. 4 - 20 mA Current Output Connections
4. Relay Connections
5. Relay Operation
6. Menu Functions
7. Parts Per Million (PPM) Factor
8. Temperature Coefficient
9. Parts and Accessories
10. Specifications
11. Quick Reference Menu Parameters
12. Troubleshooting
13. Maintenance

### Remove terminal blocks for easy wiring




### 1. Power Connections



#### CAUTION!

**Never connect 110 VAC or 220 VAC** to rear power terminals. High voltage AC will damage instrument and void warranty.


= Double Insulated  
 = DC or AC power



#### Technical Notes:

- To reduce the possibility of noise interference, isolate AC power lines from signal lines.
- Maximum 4-20 mA loop impedance (sec. 3) is affected by the supply voltage.


### 2. Compatible Sensor Wiring



#### Technical Notes:

- Resistivity measurements within the 10 MΩ to 18 MΩ range must be performed in solution temperatures from 20°C to 100°C.
- Use three conductor shielded cable for cable extensions up to 30 m (100 ft) max.
- Cable shield **MUST** be maintained through cable splice.

### 3. 4-20 mA Current Output Connections



To isolate output and prevent ground loop problems:

1. Use monitor device with isolated inputs, or
2. Use separate DC supply for 5800CR and monitor device, or
3. Power 5800CR with 12 - 24 VAC step down transformer

#### Technical Notes:


- \*\* 1/8A fuse recommended (customer supplied)
- \* 4-20 mA output is **internally powered** (non-isolated), maximum loop impedance 350 Ω with a 12 V instrument supply voltage, 950 Ω with a 24 V instrument supply voltage.

## 4. Relay Connections

Two internal relay contact sets (COM, NO, and NC) may be used for external device control. Front panel LED annunciators indicate the activation status of each relay. Each relay can control up to two devices simultaneously, as shown. Relay operation modes include Low alarm, High alarm, and Proportional Pulse (sec. 5).

Common device connections include:

- Pulse mode - metering pump control
- Pulse mode - solenoid valve control
- Low or High mode - warning lamps
- Low or High mode - bells or sirens
- Low or High mode - external heavy-duty relay



### Wiring Example Right

Device A IS powered when relay 2 is de-energized (front panel LED "off"). Power is discontinued when the relay 2 setpoint is reached (front panel LED "on"). Device B IS NOT powered when the relay 2 is de-energized. Power is applied after the relay 2 setpoint is reached.


### Technical Notes:

- Maximum relay contact ratings: 5A@30VDC, 5A@125VAC, or 3A@250VAC
- An external heavy-duty relay must be used for devices with surge currents or operating currents that exceed the above specifications.

## 5. Relay Operation


### A. LOW alarm mode

The relay is energized when the solution conductivity ( $\mu\text{S}$ ) drops below the setpoint, and is de-energized when the solution conductivity rises above the setpoint plus hysteresis (sec. 6.2F, 6.2G).



### B. HIGH alarm mode

The relay is energized when the solution conductivity ( $\mu\text{S}$ ) rises above the setpoint and is de-energized when the solution conductivity falls below the setpoint plus hysteresis (sec. 6.2F, 6.2G).




### C. Proportional PULSE mode

The proportional pulse relay configuration is primarily designed for metering pump control. The operator is prompted to enter a minimum and maximum conductivity setpoint and maximum pulse rate for the assigned relay (sec. 6.2H, 6.2I). Relay pulse width is fixed at 130 ms. Refer to the operation examples below.

- Metering pump chemical addition (dry contact activation type required)


#### Example 1 (right):

As the process conductivity ( $\mu\text{S}$ ) rises above the minimum pulse setpoint (10  $\mu\text{S}$ ) the relay begins pulsing; triggering the metering pump for deionized water addition. As the process conductivity continues to rise, pulsing accelerates proportionally until the maximum programmed pulse rate of 300 pulses/minute and setpoint (90  $\mu\text{S}$ ) are reached, forcing the process conductivity back down to intended levels (e.g.  $\leq 10 \mu\text{S}$ ).




#### Example 2 (right):

As the process conductivity falls below the minimum pulse setpoint (90  $\mu\text{S}$ ) the relay begins pulsing; triggering the metering pump for chemical addition. As the process conductivity continues to decrease, pulsing accelerates proportionally until the maximum programmed pulse rate of 300 pulses/minute and setpoint (10  $\mu\text{S}$ ) are reached, forcing the process conductivity back up to intended levels (e.g. 90  $\mu\text{S}$ ).




6. Menu Functions

To access either CALIBRATE or OPTIONS menus, press and hold the ENTER key as illustrated below:



Menus:

- VIEW menu (sec. 6.1):** The VIEW menu is displayed during standard operation. The operator can navigate freely through the menu by pressing either UP or DOWN arrow keys.
- CALIBRATE Menu (sec. 6.2):** The CALIBRATE menu contains all critical display setup and output parameters. A simple security code feature prevents unauthorized tampering. The operator is required to enter a simple access code for menu access. The same code also unlocks OPTIONS menus.
- OPTIONS Menu (sec. 6.4):** The OPTIONS menu contains setup and display features that are seldom accessed for minor display or output adjustments.
- Reversible Dials**  
The 5800CR includes a dial kit with 6 reversible dial faces and units decals (factory installed dial: 0 - 100). See dial kit for additional information.



6.1 VIEW Menu

1	2	3
Choose:	Change:	Save:
<div>↓F ▲</div> <div>A. 0.0 uS/cm</div> <div>▲ +25.0 °C ▼</div> <div>Cond./temp.</div> <div>B. Loop Output:</div> <div>20.00 mA</div> <div>▲ Loop output ▼</div> <div>C. Min+Max: uS/cm</div> <div>0.0000+100.000</div> <div>▲ Range ▼</div> <div>D. Relay 1: Low</div> <div>10.0000 uS/cm</div> <div>▲ Relay 1 ▼</div> <div>E. Relay 2: High</div> <div>90.0000 uS/cm</div> <div>▲ Relay 2 ▼</div> <div>F. Last CAL:</div> <div>01-01-98</div> <div>▲ Last calibration ▼</div>	<div>⊘</div> <div>▲</div> <div>▶</div> <div>▼</div>	

- Menu Displays A - F:**  
(Factory default displays shown in menu column 1)
- A. Active display of conductivity, resistivity, or PPM (TDS) and Temperature in degrees Celsius (°C) or Fahrenheit (°F).
  - B. Loop output display: shows the loop current output level.
  - C. Range display: shows the programmed min and max meter dial range (sec. 6.2D).
  - D. Relay 1 display: shows the programmed operation mode and setpoint for relay 1 (sec. 6.2F).
  - E. Relay 2 display: shows the programmed operation mode and setpoint for relay 2 (sec. 6.2F).
  - F. Last calibration: shows a user defined setup date for maintenance records. This feature is not an internal timer or calender.

## 6.2 CALIBRATE Menu

### Requirements

System calibration (Step E, WET CAL) is required for first-time system setup or periodic sensor verification. System calibration can be performed with a solution of known conductivity and an accurate thermometer, or with fixed resistors. Refer to the WET CAL procedure (sec. 6.3) for calibration details.

CALIBRATE: ---- Enter Key Code		Press keys in sequence     to continue, **** will appear during code entry.	
<b>1</b> Choose:	<b>2</b> Change:	<b>3</b> Save:	
A. Cell: Standard 1 >	Cell: Standard .01 .1 1 10 20 Cell type	Cell: Custom 01.0200 Cell value	 "SAVING" briefly displays
Sensor			
B. Units: uS >	Units: uS mS PPM kΩ MΩ Measured units	Units: uS mS PPM kΩ MΩ*	
Units			
Shown only with PPM units selected above			
C. PPM Factor: 2.00 >	PPM Factor: 2.00 Factory default: 2.00	PPM Factor: 1.95	
PPM Factor			
D. Min→Max: uS/cm 0.0000+100.000 >	Min→Max: uS/cm 00.0000+100.000 Meter Min→Max	Min→Max: uS/cm 00000.0+000400.0	
Range			
E. WET CAL: >	WET CAL: Press <ENTER> key to access WET CAL procedure (sec. 6.3); "Please Wait" briefly displays System calibration		
Wet Calibration			
Relay Low or High Mode Selected			
F. Relay 1: Low 10.0000 uS/cm >	Relay 1: Low 10.000 uS/cm Mode Setpoint	Relay 1: Low 100.000 uS/cm	 "SAVING" briefly displays
Relay			
G. Relay 1 Hys: 1.0000 uS/cm >	Relay 1 Hys: 01.0000 uS/cm Hysteresis	Relay 1 Hys: 00200.0 uS/cm	
Relay			
Relay Pulse Mode Selected, Step F			
H. Relay 1: Pulse 10.0000+90.0000 >	Relay 1: Pulse 10.0000+90.0000 Mode Range	Relay 1: Pulse 0070.0+00095.0	
Relay			
I. Relay 1 Rate: 120 Pulses/min >	Relay 1 Rate: 120 Pulses/min Pulse rate	Relay 1 Rate: 025 Pulses/min	
Relay			
J. Last CAL: 01-01-98 >	Last CAL: 01-01-98 Optional	Last CAL: 02-05-98	
Last calibration			
To return to VIEW:   quick press	To restore original value:   quick press		

### Menu Settings A - J:

(Factory default displays shown in menu column 1)

- A. Selects cell type and cell value:
  - Standard cells: 0.01, 0.1, 1.0, 10.0, or 20.0
  - Custom (certified) cells: 00.0000 - 999999.
 See section 2 for recommended cell constant and operation range
- B. Selects displayed conductivity units; Solution temperatures limited from 20°C to 100°C for measurements from 10 MΩ to 18 MΩ.
- C. Sets PPM factor when PPM display units are selected (step B), 0.01 - 9.99. Refer to section 7 for feature explanation.
- D. Sets Min → Max meter dial range (factory installed dial, 0 - 100). Contact factory for custom dial configurations. **Does not affect 4 to 20 mA output**
- E. Selects WET CAL procedure for first time system setup or periodic system recalibration (sec. 6.3).

### Menu items F - I repeat for relay 2 setup.

- F. Sets relay operation mode Low or High, and setpoint, 00.0000 - 999999. units (sec. 5).
- G. Sets relay hysteresis, 00.0000 - 999999. units (sec. 5). Set to zero to disable feature
- H. Sets relay minimum and maximum pulse setpoint, 00.0000 - 999999. units (sec 5).
- I. Sets relay pulse rate, 000 - 300 pulses/minute (sec. 5).
- J. Sets user defined setup date for maintenance records. This feature is not an internal timer or calendar

6.3 WET CAL Procedure

Requirements

Electronic calibration is performed to exacting standards by OMEGA. System calibration will reduce errors which may be caused by sensor wire lengths longer than the standard fifteen feet length. Wire lengths of 100 feet are acceptable; cable shield must be maintained through cable splice. Calibration may be done by known solution value (A), or by resistance simulation (B).

A) Calibration with NIST Traceable Solutions:

When using calibration standards traceable to the National Institute of Standards and Technology (NIST), care must be taken to ensure the sensor and test solution are at the solution temperature specified on the test solution label. Care must be taken to prevent contamination of the calibration solution. It is recommended to thoroughly rinse the sensor in a small amount of test solution (then discard) before placing in any test solution for calibration purposes. The two step WET CAL process first allows for verification or calibration of temperature, followed by verification or calibration of either conductivity, resistivity, or PPM (TDS) using a known process solution.

B) Optional Verification with Precision Resistors:


The use of precision resistors (±0.1%) connected to the rear "Temp In", "Signal IN", and "Iso Gnd" terminals in place of the OMEGA sensor, will yield quick and accurate electronic instrument calibration. The WET CAL procedure allows for verification or calibration of temperature, followed by conductivity, resistivity, or PPM (TDS) utilizing precision resistors. Calibration is completed as follows:

- 1) Select a standard cell constant based on desired range of operation (sec. 10, Fig. 1).
- 2) Place a 1096Ω TC resistor between "Temp IN" and "Iso. Gnd" terminals as shown. Note: Temperature simulation errors can adversely effect calibration: 3.85 ohms = 1°C error.
- 3) Calculate the required simulation resistor that represents a value within the selected cell range (sec. 10, Fig. 1). The formula for determining the required simulation resistance is:

Resistance =  $\frac{\text{Cell}}{\text{Desired conductivity (Siemens*)}}$  ; e.g.  $\frac{0.1}{0.000020 \text{ (Siemens*)}}$  = 5,000Ω or 5 kΩ

\*Conversion: 1 μS = 1 X 10<sup>-6</sup> Siemens or 0.000001 Siemens

Conductivity =  $\frac{\text{Sensor cell}}{\text{Simulation resistance (Ohms)}}$  ; e.g.  $\frac{0.1}{100,000}$  = 0.000001 Siemens\* or 1 μS/cm



- 4) Place the calculated simulation resistance between the "Signal IN" and "Iso Gnd" terminals as shown.
- 5) Perfor WET CAL Procedure below, setting temperature to 25.0 °C and conductivity to the calculated value, step 3.

WET CAL Procedure (Solution Calibration Illustrated below)

1	2	3
Display:	To Change:	To Accept:
Temperature: +25.7 °C >  A) Solution cal.: place sensor and thermometer into standard solution then press right arrow key.  B) Resistor verification: press right arrow key.	Temperature: +25.0 °C ▲▼▶ A) Solution cal.: allow approx. 3 minutes for stabilization, then enter solution temperature* B) Resistor verification: enter 25.0 C on display.	Press ENTER to accept temperature calibration.  Temperature: +25.0 °C
★ Conductivity: 10017.3 uS/cm >  Measured conductivity shown after temperature calibration	Conductivity: 10000.0 uS/cm ▲▼▶ Enter known solution conductivity or calculated conductivity.  Optional: enter zero to reset factory calibration (zero MUST be re-entered if currently displayed to reset factory calibration).	Conductivity: 1000.0 uS/cm  Press ENTER to accept conductivity calibration; display returns to CALIBRATE MENU in 3 seconds (sec. 6.2E)
To exit WET CAL at any time without saving changes:  ▲▼▶ quick press		

\*IMPORTANT:  
Always match test solution manufacturer's temperature recommendation.  
  
Conductivity units are displayed as selected in the CALIBRATE menu (sec. 6.2B).  
  
Resistivity units are displayed when kΩ or MΩ ranges are selected (sec. 6.2B).



6.4 OPTIONS Menu

OPTIONS: ----  
Enter Key Code

Press keys in sequence to continue,  
\*\*\*\* will appear during code entry.

1 Choose:	2 Change:	3 Save:
A. Contrast: 3 >	Contrast: 1 2 3 4 5 1 2 3 4 5 Low ----- High	
Contrast ▼		
B. Display Decimal: ***** >	Display Decimal: Display Decimal: *****	
Conductivity ▼	Display decimal 	
C. Display Average: Low >	Display Average: Display Average: Off Low High Off Low High 0s 4s 8s	
Averaging ▼		
D. Set 4 mA: 0.0000 uS/cm >	Set 4 mA: 00.0000 uS/cm	Set 4 mA: 02000.0 uS/cm
Loop output ▼	Set 4 mA 	
E. Set 20 mA: 100.000 uS/cm >	Set 20 mA: 100.000 uS/cm	Set 20 mA: 120.000 uS/cm
Loop output ▼	Set 20 mA 	
F. 4 mA Adjust: 4.00 mA >	4 mA Adjust: 4.00 mA	4 mA Adjust: 3.88 mA
Loop output ▼	4 mA adjust 	
G. 20 mA Adjust: 20.00 mA >	20 mA Adjust: 20.00 mA	20 mA Adjust: 19.98 mA
Loop output ▼	20 mA adjust 	
H. Temperature: °C >	Temperature: °C °F	Temperature: °C °F
Temp. display ▼	C or F 	
I. Temperature Comp %: 2.00 >	Temperature Comp %: 2.00	Temperature Comp %: 1.81
Temp. comp % ▼	Factory default: 2.00 	
To return to VIEW: quick press	To restore original value: quick press	

ENTER  
"SAVING"  
briefly  
displays

- Menu Settings A - I:**  
(Factory default displays shown in menu column 1)
- A. Selects LCD display contrast: 5 levels
  - B. Selects display decimal:  
\*\*\*\*\* to \*\*\*\*\*
  - C. Selects LCD display averaging:  
Off = 0 seconds, Low= 4 seconds, High= 8 seconds (also effects 4 - 20 mA output)
  - D. Sets 4 mA output setpoint. 4 mA and 20 mA setpoints are reversible.
  - E. Sets 20 mA output setpoint. 20 mA and 4 mA setpoints are reversible.
  - F. Sets 4 mA current output: 3.0 to 5.0 mA (overrides 4.00 mA factory calibration)
  - G. Sets 20 mA current output: 19 to 21 mA (overrides 20.00 mA factory calibration)
  - H. Selects temperature display: °C or °F  
Recalibration is not required when switching from Celsius to Fahrenheit.
  - I. Selects temperature compensation % (coefficient), see section 8 for feature explanation.

7. Parts Per Million (PPM) Factor

This feature is only applicable when PPM display units are selected (sec. 6.2B).

The 5800CR is capable of displaying total dissolved solids (TDS) in parts per million (PPM) units. This is done by dividing the actual solution conductivity in  $\mu\text{S}$  by the programmed parts per million factor (sec. 6.2C).

$$\text{TDS (PPM)} = \frac{\text{Solution conductivity } (\mu\text{S})}{\text{PPM Factor}}$$

Example:

- PPM Factor = 2.00 (factory default)
- Solution conductivity = 400  $\mu\text{S}$
- TDS (PPM) =  $\frac{400 \mu\text{S}}{2.00 \text{ PPM Factor}} = 200 \text{ PPM on the display}$



The programmable PPM Factor is adjustable from 0.01 to 9.99 (factory default = 2.00). You can determine the best PPM Factor for your process solution if you know the solution's conductivity ( $\mu\text{S}$ ) and the percent of total dissolved solids (PPM), see example below:

$$\text{PPM Factor} = \frac{\text{Solution conductivity } (\mu\text{S})}{\text{Total dissolved solids (PPM)}}$$

#### Example:

- Solution conductivity = 400  $\mu\text{S}$
- TDS = 200 PPM (mg/L)
- PPM Factor =  $\frac{400 \mu\text{S}}{200 \text{ PPM}} = 2.00$

## 8. Temperature Coefficient (Temp. Comp. %)

Conductivity measurement is highly dependent on temperature. Temperature dependence is usually expressed as the relative change per  $^{\circ}\text{C}$ , commonly known as percent/ $^{\circ}\text{C}$  change from 25  $^{\circ}\text{C}$ , or slope of the solution.

Slopes can vary significantly depending on process solution type. The factory default temperature compensation factor is 2.00%/ $^{\circ}\text{C}$ . This setting satisfies many general applications. Your process solution may require adjustment for maximum accuracy. The following procedure can be used to determine the optimum temperature compensation factor for your process. This procedure can be used when published references are not available.

#### NOTE:

Do not use this procedure for solutions from 0.055  $\mu\text{S}$  to 0.1  $\mu\text{S}$  (10 M $\Omega$  to 18 M $\Omega$ ). An internal pure water curve is used for these ranges. The factory default setting of 2.00%/ $^{\circ}\text{C}$  should be used.

#### Equipment Required

- CDCN-5800 monitor and CDCE-90-X series conductivity sensor
- Process solution samples (2)
- Temperature source

#### Procedure

1. Disable the temperature comp % factor by entering 0.00 (sec. 6.4I).
2. Heat the sample solution close to the maximum process temperature. Place sensor in the sample solution (allow several minutes for stabilization). Access the VIEW menu (sec. 6.1A) and record the displayed temperature and conductivity values in the spaces provided below:

#### Sample Solution (Step 2)

Displayed temperature:

T1= \_\_\_\_\_  $^{\circ}\text{C}$

Displayed conductivity:

C1= \_\_\_\_\_

3. Cool the sample solution close to the minimum process temperature. Place sensor in the sample solution (allow several minutes for stabilization). Record displayed temperature and conductivity values in the spaces provided below:

#### Sample Solution (Step 3)

Displayed temperature:

T2= \_\_\_\_\_  $^{\circ}\text{C}$

Displayed conductivity:

C2= \_\_\_\_\_

A 10% change in conductivity between steps 2 and 3 is required for optimum performance. If necessary, increase maximum (step 2) and reduce minimum (step 3) sample temperatures. This will result in a larger change in conductivity between steps.

4. Substitute recorded readings (steps 2 and 3) into the following formula:


$$\text{TC Slope} = \frac{100 \times (C1 - C2)}{(C2 \times (T1 - 25)) - (C1 \times (T2 - 25))}$$

#### Example:


A sample solution has a conductivity of 205  $\mu\text{S}$  @ 48 $^{\circ}\text{C}$ . After cooling the solution, the conductivity was measured at 150  $\mu\text{S}$  @ 23 $^{\circ}\text{C}$ . Therefore: C1 = 205, T1 = 48, C2 = 150, T2 = 23. The TC is calculated as follows:

$$\text{TC Slope} = \frac{100 \times (205 - 150)}{(150 \times (48 - 25)) - (205 \times (23 - 25))} = \frac{5500}{3860} = 1.42\%/^{\circ}\text{C}$$


## 9. Parts and Accessories



Splashproof rear cover  
FPM-5000-SBCK



5 x 5 inch adapter plate  
for OMEGA retrofit  
FPM-5000-RAK



Optional surface mount  
bracket FP-5000-MB

## 10. Specifications

### General

Compatible sensors: OMEGA CDCE-90-X Standard and Certified Series Sensors (Figure 1)

Accuracy:  $\pm 2\%$  of reading

Input range: 0.055 to 400,000  $\mu\text{S}$  (10 k $\Omega$  to 18 M $\Omega$ ), optically isolated

Resistivity measurements from **10 M $\Omega$  to 18 M $\Omega$**  (or conductivity range 0.055  $\mu\text{S}$  to 0.1  $\mu\text{S}$ ) must be performed in solution temperatures from 20°C to 100°C.

### Enclosure:

- NEMA 4X/IP65 front
- Dimensions: ¼ DIN, 96 x 96 x 88 mm (3.8 x 3.8 x 3.5 in.)
- Case materials: ABS plastic
- Keypad material: Sealed 4-key silicone rubber
- Weight: 500 g (18 oz.)

### Display:

- Type: Microprocessor controlled air-core meter movement and backlit alphanumeric 2 x 16 LCD
- Update rate: <2s
- Contrast: User selected
- Relay annunciators: 2 LEDs
- Displayed units:  $\mu\text{S}$ , mS, k $\Omega$ , M $\Omega$ , PPM

### Environmental

Operating temp.: -10 to 55°C (14 to 131°F), 50°C (122°F) max. with optional rear cover

Storage temp.: -15 to 80°C (5 to 176°F)

Relative humidity: 0 to 95%, non-condensing

Altitude: 4000 m max.

Pollution degree: 2

### Electrical

#### Power requirements:

- 12 to 24 VDC or 12 to 24 VAC, unregulated, 50-60 Hz, 10 W max.

#### Temperature input:

- PT1000, 0 to 100°C (32 to 212°F), optically isolated

#### Relay outputs (2 sets):

- Mechanical SPDT contacts
- Max. voltage rating: 5 A @ 30 VDC, 5 A @ 125 VAC, or 3 A @ 250 VAC, (power factor = 1.0)
- Hysteresis: User adjustable


#### Current output:

- 4 to 20 mA, non-isolated, internally powered, fully adjustable and reversible
- Update rate: <2s
- Max loop impedance: 350  $\Omega$  with a 12 V instrument supply voltage, 950  $\Omega$  with a 24 V instrument supply voltage
- Accuracy  $\pm 0.1\%$  of max range


### Agency Approvals

- CE
- Manufactured under ISO 9001 and ISO 14001


Figure 1




### Dimensions:



Front View



Dimensions:



11. Quick Reference Menu Parameters

11.1 VIEW Menu Setup Parameters (sec. 6.1)

Menu Parameters	Display Description	Range	Factory Default
A. 0.0 uS/cm +25.0 °C	• Process conductivity • Process temperature	• 0.055 - 400,000 mS (10 kΩ - 18 MΩ) • Process temperature	n/a n/a
B. LOOP Output: 20.00 mA	Current loop output	3 - 21 mA	n/a
C. Min→Max: uS/cm 0.0000→100.000	Min → Max meter dial range	0.055 - 400,000 mS (10 kΩ - 18 MΩ ★)	0.0000 - 100.000 μS/cm
D. Relay 1: Low 10.0000 uS/cm	• Relay 1 mode • Relay 1 setpoint	Low, High, or Pulse, 0.055 - 400,000 mS (10 kΩ - 18 MΩ)	Low 10.0000 μS/cm
E. Relay 2: High 90.0000 uS/cm	• Relay 2 mode • Relay 2 setpoint	Low, High, or Pulse, 0.055 - 400,000 mS (10 kΩ - 18 MΩ)	High 90.0000 μS/cm
F. Last CAL: 01-01-98	Last calibration date	00 - 00 - 00 - 39 - 39 - 99	01 - 01 - 98

Resistivity measurements from **10 MΩ to 18 MΩ** (or conductivity from 0.055 μS to 0.1 μS) must be performed in solution temperatures from 20°C to 100°C.

## 11.2 CALIBRATE Menu Setup Parameters (sec. 6.2)

Menu Parameters	Display Description	Range	Factory Default
A. Cell: Standard 1 >	Sensor type: and cell constant	<ul style="list-style-type: none"> <li>Standard sensor cells: 0.01, 0.1, 1.0, 10.0, 20.0</li> <li>Custom sensor cells: 00.0000 - 999999.</li> </ul>	<ul style="list-style-type: none"> <li>Standard sensor •Cell 1.0</li> </ul>
B. Units: uS >	Process units	mS, mS, PPM, kΩ, or MΩ	μS
C. PPM Factor: 2.00 >	Total dissolved solids (PPM) factor	0.01 - 9.99	2.00
D. Min+Max: uS/cm 0.0000+100.000 >	Min → max meter dial range	0.055 - 400,000 mS or 10 kΩ - 18 MΩ	0.0000 - 100.000 μS
E. WET CAL: >	System Calibration Procedure	Wet Solution or resistor calibration	n/a
F. Relay 1: Low 10.0000 uS/cm >	<ul style="list-style-type: none"> <li>Relay 1 mode</li> <li>Relay 1 setpoint</li> </ul>	<ul style="list-style-type: none"> <li>Low or High</li> <li>00.0000 - 999999.</li> </ul>	Low 10.0000 μS/cm
G. Relay 1 Hys: 1.0000 uS/cm >	Relay 1 hysteresis	<ul style="list-style-type: none"> <li>Low or High</li> <li>00.0000 - 999999.</li> </ul>	1.0000 μS/cm
H. Relay 1: Pulse 10.0000+90.0000 >	<ul style="list-style-type: none"> <li>Relay 1 mode</li> <li>Relay 1 range</li> </ul>	<ul style="list-style-type: none"> <li>Pulse</li> <li>00.0000 - 999999.</li> </ul>	10.0000 - 90.0000 μS/cm
I. Relay 1 Rate: 120 Pulses/min >	Relay 1 pulse rate	000 - 300 pulses/minute	120 pulses/minute
J. Last CAL: 01-01-98 >	Last calibration date	00 - 00 - 00 - 39 - 39 - 99	01 - 01 - 98

PPM Factor shown  
only with PPM units  
selected above  
(step B)

Relay mode and set-  
point displays repeat  
for relay 2 setup

## 11.3 OPTIONS Menu Setup Parameters (sec. 6.4)

Menu Parameters	Display Description	Range	Factory Default
A. Contrast: 3 >	Display contrast	0 - 5	3
B. Display Decimal: xxxx.x >	Display decimal	*.**** _ ****.	****.*
C. Display Average: Low >	Display averaging	Off= 0 sec., Low= 4 sec., High= 8 sec.	Low= 4 sec.
D. Set 4 mA: 0.0000 uS/cm >	4 mA setpoint	00.0000 - 999999.	00.0000 μS/cm
E. Set 20 mA: 100.000 uS/cm >	20 mA setpoint	00.0000 - 999999.	100.000 μS/cm
F. 4 mA Adjust: 4.00 mA >	4 mA adjust	3.0 - 5.0 mA	4.00 mA
G. 20 mA Adjust: 20.00 mA >	20 mA adjust	19 - 21 mA	20.00 mA
H. Temperature: °C >	Temperature display	Celsius or Fahrenheit	°C
I. Temperature Comp %: 2.00 >	Temperature comp. percentage	0.00 % - 9.99 %	2.00 %

## 12. Troubleshooting

Display	Problem	Solution
1. 0.0 $\mu\text{S}/\text{cm}$ ----- °C <b>or</b> ----- $\mu\text{S}/\text{cm}$ ----- °C <b>or</b> 0.0 $\text{M}\Omega\cdot\text{cm}$ ----- °C <b>or</b> ----- $\text{M}\Omega\cdot\text{cm}$ ----- °C	Temperature wiring shorted or temperature element in sensor bad	A) Verify sensor wiring (sec. 2) B) Verify instrument temperature input: • Remove Black and White sensor wires from rear Temp. IN and Iso. Gnd terminals, then place a 1100 $\Omega$ resistor across terminals. • Power instrument and verify approximately 26.0 °C (79 °F) on display. If instrument reads correctly, replace sensor. If error condition persists, instrument requires factory service.
2. 0.0 $\mu\text{S}/\text{cm}$ 25.0 °C <b>or</b> ----- $\text{M}\Omega\cdot\text{cm}$ 25.0 °C	A) Sensor not connected or improperly connected B) Pipe empty or sensor not in solution C) Wrong scale selected D) Wrong range selected (cell constant too small) E) TC% set incorrectly for process temperature F) Sensor wiring open G) Water too cold for high-purity water measurement	A) Verify sensor wiring (sec. 2) B) Fill pipe or place sensor in process solution. C) Choose $\mu\text{S}$ or $\text{M}\Omega$ scale instead of $\text{mS}$ or $\text{k}\Omega$ scale (sec. 6.2B) D) Choose a sensor with cell constant adequate for your process solution (sec. 10, Figure 1) E) Set TC% to zero (sec. 6.4I) and check reading. If reading is ok, calculate proper TC% for your process solution (sec. 8), then re-enter correct value (sec. 6.4I). F) Replace sensor G) See specifications section 10 for recommended high-purity range and temperature requirements.
3. ----- $\mu\text{S}/\text{cm}$ 25.0 °C <b>or</b> 0.0 $\text{M}\Omega\cdot\text{cm}$ 25.0 °C	A) Sensor shorted or improperly connected B) Wrong scale selected C) Wrong range selected (cell constant too large) D) TC% set incorrectly for process temperature	A) Verify sensor wiring including cable splice (sec. 2); cable shield must continue through splice. B) Choose $\text{mS}$ or $\text{k}\Omega$ scale instead of $\mu\text{S}$ or $\text{M}\Omega$ scale (sec. 6.2B) C) Choose a sensor with cell constant adequate for your process solution, see section 10, Figure 1. D) Set TC% to zero (sec. 6.4I) and check reading. If reading is ok, calculate proper TC% for your process solution (sec. 8), then re-enter correct value (sec. 6.4I).
4. Too Much Error Check Sensor	Temperature input out of tolerance during WET CAL Procedure (sec. 6.3)	Exit WET CAL Procedure by pressing UP and DOWN arrow keys simultaneously, then refer to solution steps 1B above to verify sensor temperature input.
5. Reset To Factory Calibration	Zero entered as solution conductance or resistance during WET CAL step 2	Measured conductivity, Resistivity, PPM, or resistivity entered as zero during WET CAL step 2. Operator can enter zero to quickly recall factory defaults.
6. SETUP READ ERROR Press any Key	Power fault occurred while saving setup menu entry	Press any key to reload factory defaults then reprogram conductivity system setup parameters.

## 13. Maintenance

Clean the instrument case and front panel with a soft cloth and a mild liquid soap solution.





## WARRANTY/DISCLAIMER

OMEGA ENGINEERING, INC. warrants this unit to be free of defects in materials and workmanship for a period of **13 months** from date of purchase. OMEGA's WARRANTY adds an additional one (1) month grace period to the normal **one (1) year product warranty** to cover handling and shipping time. This ensures that OMEGA's customers receive maximum coverage on each product.

If the unit malfunctions, it must be returned to the factory for evaluation. OMEGA's Customer Service Department will issue an Authorized Return (AR) number immediately upon phone or written request. Upon examination by OMEGA, if the unit is found to be defective, it will be repaired or replaced at no charge. OMEGA's WARRANTY does not apply to defects resulting from any action of the purchaser, including but not limited to mishandling, improper interfacing, operation outside of design limits, improper repair, or unauthorized modification. This WARRANTY is VOID if the unit shows evidence of having been tampered with or shows evidence of having been damaged as a result of excessive corrosion; or current, heat, moisture or vibration; improper specification; misapplication; misuse or other operating conditions outside of OMEGA's control. Components which wear are not warranted, including but not limited to contact points, fuses, and triacs.

**OMEGA is pleased to offer suggestions on the use of its various products. However, OMEGA neither assumes responsibility for any omissions or errors nor assumes liability for any damages that result from the use of its products in accordance with information provided by OMEGA, either verbal or written. OMEGA warrants only that the parts manufactured by it will be as specified and free of defects. OMEGA MAKES NO OTHER WARRANTIES OR REPRESENTATIONS OF ANY KIND WHATSOEVER, EXPRESS OR IMPLIED, EXCEPT THAT OF TITLE, AND ALL IMPLIED WARRANTIES INCLUDING ANY WARRANTY OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE ARE HEREBY DISCLAIMED. LIMITATION OF LIABILITY: The remedies of purchaser set forth herein are exclusive, and the total liability of OMEGA with respect to this order, whether based on contract, warranty, negligence, indemnification, strict liability or otherwise, shall not exceed the purchase price of the component upon which liability is based. In no event shall OMEGA be liable for consequential, incidental or special damages.**

CONDITIONS: Equipment sold by OMEGA is not intended to be used, nor shall it be used: (1) as a "Basic Component" under 10 CFR 21 (NRC), used in or with any nuclear installation or activity; or (2) in medical applications or used on humans. Should any Product(s) be used in or with any nuclear installation or activity, medical application, used on humans, or misused in any way, OMEGA assumes no responsibility as set forth in our basic WARRANTY / DISCLAIMER language, and, additionally, purchaser will indemnify OMEGA and hold OMEGA harmless from any liability or damage whatsoever arising out of the use of the Product(s) in such a manner.

## RETURN REQUESTS/INQUIRIES

Direct all warranty and repair requests/inquiries to the OMEGA Customer Service Department. BEFORE RETURNING ANY PRODUCT(S) TO OMEGA, PURCHASER MUST OBTAIN AN AUTHORIZED RETURN (AR) NUMBER FROM OMEGA'S CUSTOMER SERVICE DEPARTMENT (IN ORDER TO AVOID PROCESSING DELAYS). The assigned AR number should then be marked on the outside of the return package and on any correspondence.

The purchaser is responsible for shipping charges, freight, insurance and proper packaging to prevent breakage in transit.

FOR **WARRANTY** RETURNS, please have the following information available BEFORE contacting OMEGA:

1. Purchase Order number under which the product was PURCHASED,
2. Model and serial number of the product under warranty, and
3. Repair instructions and/or specific problems relative to the product.

FOR **NON-WARRANTY** REPAIRS, consult OMEGA for current repair charges. Have the following information available BEFORE contacting OMEGA:

1. Purchase Order number to cover the COST of the repair,
2. Model and serial number of the product, and
3. Repair instructions and/or specific problems relative to the product.

OMEGA's policy is to make running changes, not model changes, whenever an improvement is possible. This affords our customers the latest in technology and engineering.

OMEGA is a registered trademark of OMEGA ENGINEERING, INC.

© Copyright 2000 OMEGA ENGINEERING, INC. All rights reserved. This document may not be copied, photocopied, reproduced, translated, or reduced to any electronic medium or machine-readable form, in whole or in part, without the prior written consent of OMEGA ENGINEERING, INC.



# Where Do I Find Everything I Need for Process Measurement and Control? **OMEGA...Of Course!**

Shop online at [www.omega.com](http://www.omega.com)

## **TEMPERATURE**

- ☒ Thermocouple, RTD & Thermistor Probes, Connectors, Panels & Assemblies
- ☒ Wire: Thermocouple, RTD & Thermistor
- ☒ Calibrators & Ice Point References
- ☒ Recorders, Controllers & Process Monitors
- ☒ Infrared Pyrometers

## **PRESSURE, STRAIN AND FORCE**

- ☒ Transducers & Strain Gages
- ☒ Load Cells & Pressure Gages
- ☒ Displacement Transducers
- ☒ Instrumentation & Accessories

## **FLOW/LEVEL**

- ☒ Rotameters, Gas Mass Flowmeters & Flow Computers
- ☒ Air Velocity Indicators
- ☒ Turbine/Paddlewheel Systems
- ☒ Totalizers & Batch Controllers

## **pH/CONDUCTIVITY**

- ☒ pH Electrodes, Testers & Accessories
- ☒ Benchtop/Laboratory Meters
- ☒ Controllers, Calibrators, Simulators & Pumps
- ☒ Industrial pH & Conductivity Equipment

## **DATA ACQUISITION**

- ☒ Data Acquisition & Engineering Software
- ☒ Communications-Based Acquisition Systems
- ☒ Plug-in Cards for Apple, IBM & Compatibles
- ☒ Datalogging Systems
- ☒ Recorders, Printers & Plotters

## **HEATERS**

- ☒ Heating Cable
- ☒ Cartridge & Strip Heaters
- ☒ Immersion & Band Heaters
- ☒ Flexible Heaters
- ☒ Laboratory Heaters

## **ENVIRONMENTAL MONITORING AND CONTROL**

- ☒ Metering & Control Instrumentation
- ☒ Refractometers
- ☒ Pumps & Tubing
- ☒ Air, Soil & Water Monitors
- ☒ Industrial Water & Wastewater Treatment
- ☒ pH, Conductivity & Dissolved Oxygen Instruments