

# Where Do I Find Everything I Need for Process Measurement and Control? OMEGA ... Of Course!

M-3478/0899

99-MAN 100180 v1 09/99

## TEMPERATURE

- ☐ Thermocouple, RTD & Thermistor Probes, Connectors, Panels & Assemblies
- ☐ Wire: Thermocouple, RTD & Thermistor
- ☐ Calibrators & Ice Point References
- ☐ Recorders, Controllers & Process Monitors
- ☐ Infrared Pyrometers

## PRESSURE / STRAIN FORCE

- ☐ Transducers & Strain Gauges
- ☐ Load Cells & Pressure Gauges
- ☐ Displacement Transducers
- ☐ Instrumentation & Accessories

## FLOW / LEVEL

- ☐ Rotameters, Gas Mass Flowmeters & Flow Computers
- ☐ Air Velocity Indicators
- ☐ Turbine / Paddlewheel Systems
- ☐ Totalizers & Batch Controllers

## pH/CONDUCTIVITY

- ☐ pH Electrodes, Testers & Accessories
- ☐ Benchtop / Laboratory Meters
- ☐ Controllers, Calibrators, Simulators & Pumps
- ☐ Industrial pH & Conductivity Equipment

## DATA ACQUISITION

- ☐ Data Acquisition & Engineering Software
- ☐ Communications-Based Acquisition Systems
- ☐ Plug-in Cards for Apple, IBM & Compatibles
- ☐ Datalogging Systems
- ☐ Recorders, Printers & Plotters

## HEATERS

- ☐ Heating Cable
- ☐ Cartridge & Strip Heaters
- ☐ Immersion & Band Heaters
- ☐ Flexible Heaters
- ☐ Laboratory Heaters


## ENVIRONMENTAL MONITORING AND CONTROL

- ☐ Metering & Control Instrumentation
- ☐ Refractometers
- ☐ Pumps & Tubing
- ☐ Air, Soil & Water Monitors
- ☐ Industrial Water & Wastewater Treatment
- ☐ pH, Conductivity & Dissolved Oxygen Instruments

**omega.com**

 **OMEGA**

CE



<http://www.omega.com>

*e-mail:*

*info@omega.com*

Model HHM72

Model HHM75

AC/DC Current Probes

## WARRANTY/DISCLAIMER

OMEGA ENGINEERING, INC. warrants this unit to be free of defects in materials and workmanship for a period of **13 months** from date of purchase. OMEGA Warranty adds an additional one (1) month grace period to the normal **one (1) year product warranty** to cover handling and shipping time. This ensures that OMEGA's customers receive maximum coverage on each product.

If the unit should malfunction, it must be returned to the factory for evaluation. OMEGA's Customer Service Department will issue an Authorized Return (AR) number immediately upon phone or written request. Upon examination by OMEGA, if the unit is found to be defective it will be repaired or replaced at no charge. OMEGA's WARRANTY does not apply to defects resulting from any action of the purchaser, including but not limited to mishandling, improper interfacing, operation outside of design limits, improper repair, or unauthorized modification. This WARRANTY is VOID if the unit shows evidence of having been tampered with or shows evidence of being damaged as a result of excessive corrosion; or current, heat, moisture or vibration; improper specification; misapplication; misuse or other operating conditions outside of OMEGA's control. Components which wear are not warranted, including but not limited to contact points, fuses, and triacs.

**OMEGA is pleased to offer suggestions on the use of its various products. However, OMEGA neither assumes responsibility for any omissions or errors nor assumes liability for any damages that result from the use of its products in accordance with information provided by OMEGA, either verbal or written. OMEGA warrants only that the parts manufactured by it will be as specified and free of defects. OMEGA MAKES NO OTHER WARRANTIES OR REPRESENTATIONS OF ANY KIND WHATSOEVER, EXPRESSED OR IMPLIED, EXCEPT THAT OF TITLE, AND ALL IMPLIED WARRANTIES INCLUDING ANY WARRANTY OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE ARE HEREBY DISCLAIMED. LIMITATION OF LIABILITY: The remedies of purchaser set forth herein are exclusive and the total liability of OMEGA with respect to this order, whether based on contract, warranty, negligence, indemnification, strict liability or otherwise, shall not exceed the purchase price of the component upon which liability is based. In no event shall OMEGA be liable for consequential, incidental or special damages.**

CONDITIONS: Equipment sold by OMEGA is not intended to be used, nor shall it be used: (1) as a "Basic Component" under 10 CFR 21 (NRC), used in or with any nuclear installation or activity; or (2) in medical applications or used on humans. Should any Product(s) be used in or with any nuclear installation or activity, medical application, used on humans, or misused in any way, OMEGA assumes no responsibility as set forth in our basic WARRANTY/ DISCLAIMER language, and additionally, purchaser will indemnify OMEGA and hold OMEGA harmless from any liability or damage whatsoever arising out of the use of the Product(s) in such a manner.

## RETURN REQUESTS/ INQUIRIES

Direct all warranty and repair requests/inquiries to the OMEGA Customer Service Department. BEFORE RETURNING ANY PRODUCT(S) TO OMEGA, PURCHASER MUST OBTAIN AN AUTHORIZED RETURN (AR) NUMBER FROM OMEGA'S CUSTOMER SERVICE DEPARTMENT (IN ORDER TO AVOID PROCESSING DELAYS). The assigned AR number should then be marked on the outside of the return package and on any correspondence.

The purchaser is responsible for shipping charges, freight, insurance and proper packaging to prevent breakage in transit.

FOR **WARRANTY** RETURNS, please have the following information available BEFORE contacting OMEGA:

1. P.O. number under which the product was PURCHASED,
2. Model and serial number of the product under warranty, and
3. Repair instructions and/or specific problems relative to the product.

FOR **NON-WARRANTY REPAIRS**, consult OMEGA for current repair charges. Have the following information available BEFORE contacting OMEGA:

1. P.O. number to cover the COST of the repair,
2. Model and serial number of product, and
3. Repair instructions and/or specific problems relative to the product.

OMEGA's policy is to make running changes, not model changes, whenever an improvement is possible. This affords our customers the latest in technology and engineering.

OMEGA is a registered trademark of OMEGA ENGINEERING, INC.

© Copyright 1996 OMEGA ENGINEERING, INC. All rights reserved. This document may not be copied, photocopied, reproduced, translated, or reduced to any electronic medium or machine-readable form, in whole or in part, without prior written consent of OMEGA ENGINEERING, INC.

**omega.com**

CE OMEGA

OMEGAnet<sup>SM</sup> On-Line Service:

<http://www.omega.com>

Internet e-mail: [info@omega.com](mailto:info@omega.com)

**Servicing North America:**

**USA:** One Omega Drive, Box 4047  
Stamford, CT 06907-0047  
Tel: (203) 359-1660 FAX: (203) 359-7700  
e-mail: [info@omega.com](mailto:info@omega.com)

**Canada:** 976 Bergar  
Laval (Quebec) H7L 5A1  
Tel: (514) 856-6928 FAX: (514) 856-6886  
e-mail: [canada@omega.com](mailto:canada@omega.com)

**For Immediate Technical or Application Assistance:**

**USA and Canada:** Sales Service: 1-800-826-6342 1-800-TC-OMEGA<sup>SM</sup>  
Customer Service: 1-800-622-2378 / 1-800-622-BEST<sup>SM</sup>  
Engineering Service: 1-800-872-9436 / 1-800-USA-WHEN<sup>SM</sup>  
TELEX: 996404 EASYLINK 62968934 CABLE: OMEGA

**Mexico and Latin America:** Tel: (95) 800-TC-OMEGA<sup>SM</sup> FAX: (95) 203-359-7807  
En Espanol: (203) 359-1660 ext: 2203  
e-mail: [espanol@omega.com](mailto:espanol@omega.com)

**Servicing Europe:**

**Benelux:** Postbus 8034, 1180 LA Amstelveen, The Netherlands  
Tel: (31) 20 6418405 FAX: (31) 20 6434643  
Toll Free in Benelux: 06 0993344 e-mail: [nl@omega.com](mailto:nl@omega.com)

**Czech Republic:** Ostravska 767, 733 01 Karvina  
Tel: 420 (69) 6311627 FAX: 420 (69) 6311114  
e-mail: [czech@omega.com](mailto:czech@omega.com)

**France:** 9, rue Denis Papin, 78190 Trappes  
Tel: (33) 130-621-400 FAX: (33) 130-699-120  
Toll Free/France: 0800-4-06342 e-mail: [france@omega.com](mailto:france@omega.com)

**Germany/Austria:** Daimlerstrasse 26, D-75392 Deckenfronn, Germany  
Tel: 49 (07056) 3017 FAX: 49 (07056) 8540  
Toll Free in Germany: 0130 11 21 66  
e-mail: [germany@omega.com](mailto:germany@omega.com)

**United Kingdom:** 25 Swannington Road, P.O. Box 7, Omega Drive,  
Broughton Astley, Leicestershire, Irlam, Manchester,  
LE9 6TU, England M44 5EX, England  
Tel: 44 (1455) 285520 Tel: 44 (161) 777-6611  
FAX: 44 (1455) 283912 FAX: 44 (161) 777-6622

Toll Free in England: 0800-488-488  
e-mail: [uk@omega.com](mailto:uk@omega.com)

It is the policy of OMEGA to comply with all worldwide safety and EMC/EMI regulations that apply. OMEGA is constantly pursuing certification of its products to the European New Approach Directives. OMEGA will add the CE mark to every appropriate device upon certification.

The information contained in this document is believed to be correct but OMEGA Engineering, Inc. accepts no liability for any errors it contains, and reserves the right to alter specifications without notice.

**WARNING:** These products are not designed for use in, and should not be used for, patient connector applications.

## Maintenance



### Warning

- For maintenance use only specified replacement parts.
- Avoid electrical shock: do not attempt to perform any servicing unless you are qualified to do so.
- Avoid electrical shock and/or damage to the instrument: do not get water or other foreign agents into the case. Turn the current probe OFF and disconnect the unit from all circuits before opening the case.
- Also see warning on page 2.

### Battery Replacement

- When the probe is turned on, the green LED should light up. If it does not, replace the 9 V battery. Completely disconnect the probe from the circuit under test and from the oscilloscope or measuring instrument. Turn the probe “Off”, unscrew the battery compartment screw and remove cover. Replace the battery and put the cover back on.
- Do not replace the battery while the probe is in use.

### Cleaning

- Clean the body of the clamp with a cloth lightly moistened with soapy water. Wipe clean with a cloth moistened with clean water and dry. Do not use solvent.

## Table of Contents


Warning.....	2
International Electrical Symbols.....	2
Receiving Your Shipment.....	2
Packaging .....	3
Description .....	3
Specifications.....	4
DMM/Display Compatibility .....	11
Operating Procedure .....	12
Making Measurements with the Models HHM72 and HHM75.....	12
DC Measurement.....	12
AC Measurement.....	13
Indicator Lights.....	13
Auto-Off.....	13
Operation Examples .....	14
Tips for Getting the Best Accuracy .....	17
Typical Response Curves .....	18
Maintenance .....	20
Warning.....	20
Battery Replacement.....	20
Cleaning .....	20


## Warning

These safety warnings are provided to ensure the safety of personnel and proper operation of the instrument.

- Read the instruction manual completely and follow all the safety information before attempting to use or service this instrument.
- Use caution on any circuit: Potentially high voltages and currents may be present and may pose a shock hazard.
- Read the Safety Specifications section prior to using the current probe. Never exceed the maximum voltage ratings given.
- Safety is the responsibility of the operator.
- NEVER open the back of the instrument while connected to any circuit or input.
- ALWAYS connect the current probe to the display device before clamping the probe onto the sample being tested.
- ALWAYS inspect the instrument, probe, probe cable, and output terminals prior to use. Replace any defective parts immediately.
- NEVER use the current probe on electrical conductors rated above 600 V in overvoltage category III (CAT III). Use extreme caution when clamping around bare conductors or bus bars.

## International Electrical Symbols

 This symbol signifies that the probes are protected by double or reinforced insulation. Use only specified replacement parts when servicing the instrument.


 This symbol signifies CAUTION! and requests that the user refer to the user manual before using the instrument.

## Receiving Your Shipment


Upon receiving your shipment, make sure that the contents are consistent with the packing list. Notify Omega of any missing items. If the equipment appears to be damaged, file a claim immediately with the carrier and notify Omega at once, giving a detailed description of any damage.

## Typical Response Curves

### Model HHM75




Typical accuracy at 50 Hz: Range 150 A (10 mV/A)




Typical accuracy at 50 Hz: Range 1500 A (1 mV/A)

## Typical Response Curves

### Model HHM72



Typical accuracy at 50 Hz: Range 60 A (10 mV/A)



Typical accuracy at 50 Hz: Range 600 A (1 mV/A)

## Packaging

The AC/DC Current Probes Model HHM72 and Model HHM75 include a 9 V battery and user manual.

## Description

The Models HHM72 and HHM75 are the newest line of professional AC/DC current probes. They are designed to the latest safety and performance standards. Two different hook-shaped jaws are offered, both permitting the user to “pry” into or “hook” onto cables (will accept 2 x 500 MCM) or even smaller bus bars.

Differing from traditional AC transformers, AC/DC current sensing is often achieved by measuring the strength of a magnetic field created by a current-carrying conductor in a semiconductor chip using the Hall effect principle. When a thin semiconductor is placed at right angles to a magnetic field, and a current is applied to it, a voltage is developed across the semiconductor. This voltage is known as the Hall voltage, named after the US scientist Edwin Hall who first reported the phenomenon. Since the Hall voltage is not dependent on a reversing magnetic field, but only on its strength, the device can be used for DC measurement. Second, when the magnetic field strength varies due to varying current flow in the conductor, response to change is instantaneous. Thus, complex AC wave forms may be detected and measured with high accuracy and low phase shift. The basic construction of a probe jaw assembly is shown Figure 1. (Note: one or two Hall generators are used depending on the type of current probe).




Figure 1

The electronics and batteries are self-contained in the handles. The output of the AC/DC probes is 1 mV/A and 10 mV/A. An auto zero push button ensures rapid and stable zeroing. There is no output filtering - True RMS with DC components is possible. Phase shift is excellent, making this series well suited for power and power quality applications.

The Model HHM72 is a portable 400 A AC (600 A peak), 600 A DC current probe. The unit has proportional mV output for direct readings on multimeters, recorders, loggers and other instruments accepting banana plugs. The Model HHM75 is a portable 1000 A AC (1500 A peak), 1500 A DC current probe that accurately measures AC or DC current waveforms using Hall effect technology.

Both probes have proportional mV output for direct readings on multimeters, recorders, loggers and other instruments accepting banana plugs.

## HHM72 Specifications

### ELECTRICAL

#### **Current Range:**

60 A range:  
0.2 to 40 A AC (60 A Peak)  
0.4 to 60 A DC

600 A range:  
0.5 to 400 A AC (600 A Peak)  
0.5 to 600 A DC

#### **Output Signal:**

10 mV/A on 60 A range  
1 mV/A on 600 A range

#### **Accuracy and Phase Shift\*:**

60 A Range:  
0.5 to 40 A: 1.5% reading  $\pm$  0.5 A  
40 to 60 A DC only: 1.5% reading

#### *Phase Shift:*

45 to 65 Hz 10 to 20 A:  $\leq$  3°  
20 to 40 A:  $\leq$  2°

600 A Range:  
0.5 to 100 A: 1.5% reading  $\pm$  1 A  
100 to 400 A: 2.0% reading  
400 to 600 DC only: 2.5% reading

#### *Phase Shift:*

45 to 65 Hz 10 to 100 A:  $\leq$  2°  
100 to 400 A:  $\leq$  1.5°

#### **Overload:**

2000 A DC and 1000 A AC  
continuous up to 1 kHz

## HHM75 Specifications

### ELECTRICAL

#### **Current Range:**

150 A Range:  
0.2 to 100 A AC (150 A Peak)  
0.4 to 150 A DC

1500 A Range:  
0.5 to 1000 A AC (1400 A Peak)  
0.5 to 1500 A DC

#### **Output Signal:**

10 mV/A on 150 A range  
1 mV/A on 1500 A range

#### **Accuracy and Phase Shift\*:**

150 A Range:  
0.5 to 20 A: 1.5% reading  $\pm$  0.5 A  
20 to 100 A: 1.5% reading  
100 to 150 A DC only: 2.5% reading

#### *Phase Shift:*

45 to 65 Hz 10 to 20 A:  $\leq$  3°  
20 to 100 A:  $\leq$  2°

1500 A Range:  
0.5 to 100 A: 1.5% reading  $\pm$  1 A  
100 to 800 A: 2.5% reading  
800 to 1000 A: 4% reading  
1000 to 1400 DC only: 4% reading.

#### *Phase Shift:*

45 to 65 Hz 10 to 200 A:  $\leq$  2°  
200 to 1000 A:  $\leq$  1.5°

## Tips for Getting the Best Accuracy

The Models HHM72 and HHM75 are capable of measuring DC and low frequency currents over a wide range. Here are some key considerations for getting the most accuracy from your display instrument:


- When using the Models HHM72 and HHM75 with a DMM or other meter, it is important to select the range that provides the best resolution.
- Make sure that probe jaw mating surfaces are free of dust and contamination.
- Beware of short-circuit currents. Large in-rush DC currents (which can occur when power is first applied in a circuit) and large high-current transients may cause varying degrees of residual readings. If in doubt of a particular reading, remove the probe from the conductor under test and check to see that the display device returns to zero. If not, it will be necessary to rezero the probe.

\*Reference conditions: 18° to 28°C, 20 to 75% RH, external magnetic field <40 A/m, no DC component, no external current carrying conductor, test sample centered, 1 M $\Omega$   $\leq$  100 pF load, zero adjustment prior to measurement [DC only] DC to 65 Hz. Battery voltage 9 V  $\pm$  0.1 V.

## Operation Examples

### Measuring the AC Component of an (AC+DC) Waveform for the Model HHM75

- Conductor carrying 2.5 A DC + 900 A AC
- Voltmeter placed in AC volts mode
- Voltmeter displays 900.0 mV with probe in the 1500 A (10 mV/A) range



## HHM72 Specs Cont.

### Noise:

60 A Range:  
 DC to 1 kHz  $\leq$  8 mV  
 DC to 5 kHz:  $\leq$  12 mV  
 0.1 Hz to 5 kHz:  $\leq$  2 mV

600 A Range:  
 DC to 1 kHz  $\leq$  1 mV  
 DC to 5 kHz:  $\leq$  1.5 mV  
 0.1 Hz to 5 kHz:  $\leq$  500 $\mu$ V

### Rise and Fall Time:

60 A Range:  
 $\leq$  100 $\mu$ s from 10 to 90% Vout

600 A Range:  
 $\leq$  70 $\mu$ s from 10 to 90% Vout

## MECHANICAL

### Humidity Influence:

10 to 90% RH @ reference temperature  $\leq$  0.5%

### Jaw Opening:

1.2" (31 mm)

### Maximum Cable Diameter:

One 1.18" (30 mm) or two 0.95" (24 mm) or two bus bars 1.2 x 0.4" (31.5 x 10 mm)

### Dimensions:

8.8 x 3.82 x 1.73" (224 x 97 x 44 mm)

### Weight:

15 oz (440 g)

## HHM75 Specs Cont.

**Overload:** 3000 A DC and 2000 A AC continuous up to 1 kHz

### Noise:

150 A Range:  
 DC to 1 kHz:  $\leq$  8 mV  
 DC to 5 kHz:  $\leq$  12 mV  
 0.1 Hz to 5 kHz:  $\leq$  2 mV

1500 A Range:  
 DC to 1 kHz:  $\leq$  1 mV  
 DC to 5 kHz:  $\leq$  1.5 mV  
 0.1 Hz to 5 kHz:  $\leq$  500 $\mu$ V

### Rise and Fall Time:

150 A Range:  
 $\leq$  100 $\mu$ s from 10 to 90% Vout

1500 A Range:

$\leq$  70 $\mu$ s from 10 to 90% Vout

## MECHANICAL

### Humidity Influence:

10 to 90% RH @ reference temperature  $\leq$  0.1%

**Jaw Opening:** 1.55" (40 mm)

### Maximum Cable Diameter:

One 1.5" (39 mm) or one bus bar 1.96 x 0.49 (50 x 12.5 mm) or Two 0.98" (25 mm) or two bus bars 1.96 x 0.19" (50 x 5 mm)

**Dimensions:** 9.31 x 3.82 x 1.73" (236.5 x 97 x 44mm)

**Weight:** 16 oz (480 g)



## Common Specifications (HHM72 & HHM75)

### ELECTRICAL

**Frequency Range:** DC to 10 kHz at -3 dB

**Load Impedance:** >100 k $\Omega$ /100 pF

**Insertion Impedance:** 0.39 m $\Omega$  @ 50 Hz, 58 m $\Omega$  @1000 Hz

**Working Voltage:** 600 Vrms

**Common Mode Voltage:** 600 Vrms

**Influence of Adjacent Conductor:**  
< 10 mA/A at 50 Hz at 23 mm from the probe

**Influence of Conductor in Jaw Opening:**  
0.5% reading (DC to 440 Hz)

**Battery:** 9 V alkaline (NEDA 1604A, IEC 6LR61) recommended, 6LF22

**Low Battery:** Green LED when battery voltage  $\geq$  6.5 V

**Battery Life:** Approx. 50 hours with alkaline battery

**Overload Indication:**  
Red LED indicates input greater than the selected range

**Auto-Off:**  
10 minutes (may be disabled at power-up by pressing Zero button while turning on; green LED blinks three times to indicate that auto-off is disabled)

### MECHANICAL

**Operating Temperature Range:**  
14° to 131°F (-10° to 55°C)

**Storage Temperature Range:**  
-40° to 176°F (-40° to 80°C)


**Temperature Influence:**  
 $\leq$  300 ppm/°K or 0.3%/10°K

**Operating Relative Humidity:**  
10-35°C: 90%  $\pm$ 5% RH (without condensation)  
40-55°C: 70%  $\pm$ 5% RH (without condensation)

## Operation Examples

### Measuring the DC Component of an (AC+DC) Waveform for the Model HHM72


- Conductor carrying 300 A DC + 25.0 A AC
- DMM placed in DC volts mode
- DMM displays 300.0 mV with the probe in the 600 A (10 mV/A) range



## Operation Examples

### DC Current Measurement Example for the Model HHM72

- Conductor carrying 25 A DC in the direction of the arrow
- DMM placed in DC volts mode
- DMM displays 250.0 mV with the probe in the 60 A (10 mV/A) range



## Common Specifications Continued

### RH Influence:

10-35°C: 90% RH at reference  
Temperature:  $\leq 0.5\%$  (HHM72)  
 $\leq 0.1\%$  (HHM75)

### Altitude:

Operating: 0 to 2000 m  
Non-operating: 0 to 12,000 m

### Zero Adjustment:

Automatic zero ( $\pm 10$  A) by simple push button increment of 25 to 40 mA.  
Red LED goes on at push of button and turns off when zero is reached;  
no need to hold button down.

**Case protection:** IP30 per IEC529

### Drop Test:

1.0 m on 38 mm of oak on concrete; test according to IEC 1010

### Mechanical Shock:

100 G, test per IEC 68-2-27

**Vibration:** Test Per IEC 68-2-6,

### Frequency Range:

5 to 15 Hz, amplitude: 1.5 mm  
15 to 25 Hz, amplitude 1 mm  
25 to 55 Hz, amplitude: 0.25 mm

**Handle:** UL94 V0

**Jaws:** UL94 V0

### Color:

Dark gray with red jaws

### Output:

Double/reinforced insulated 5 ft. (1.5m) with safety 4 mm banana plug

## Common Specifications Continued

### SAFETY



Double insulation or reinforced insulation between primary, secondary and outer case of handle per IEC 1010-2-032.

- 600 V Category III, Pollution: 2

#### **Electromagnetic Compatibility:**

- Susceptibility in accordance with EN 50082-2 and EN 50082-1
- Electrostatic discharge IEC 1000-4-2  
Test voltages: 4 kV level 2 in contact, aptitude criteria B  
8 kV level 3 in the air, aptitude criteria B
- Radiated Field IEC 1000-4-3 (1995)  
With max. interference of 5% of the measurement range:  
3 V/m level 3, aptitude criteria A
- Fast transients IEC 1000-4-4 (1995):  
Test voltage: 1 kV level 2, aptitude criteria B
- Magnetic fields at the frequency of the network to IEC 1000-4-8 (1995):  
With a max. distortion of 0.5 A: 30 A/m 50 Hz level 4, aptitude criteria A
- Emissions in accordance with EN 50081-1
- Radiated emission through the case to EN 55022 (1994): class B
- Conducted emission to EN 55022 (1994): class B

### **AC Measurement**

- Select the appropriate AC mV or V range on the DMM or measuring instrument.
- The DC zero adjustment is not required when measuring AC current with a voltmeter that is AC coupled. The DC zero adjustment is required if you are using a voltmeter that is DC coupled.
- Select the appropriate mV AC or V AC range on the DMM or measuring instrument.
- Clamp the probe around the conductor (1) to be tested. The display device should now display the measured conductor current. Apply the conversion ratio (1mV/A or 10 mV/A) to get the value of the current.

### **Indicator Lights: Green LED and Red LED**

- The green LED (6) indicates that the probe is on and that the battery is good. The green LED will not light under low battery conditions. Replace the 9 V battery if the green LED is not lit.
- The red LED (5) indicates a momentary or continuous overload of the instrument. Readings taken while the red LED is on or flashing should be considered inaccurate. Momentary or continuous currents exceeding 60 A peak on the 60 A range or 600 A peak on the 600 A range for the Model HHM72, and 150 A peak on the 150 A range or 1500 A on the 1500 A range for the Model HHM75 will trigger the red LED.

### **Auto-Off**

- The Models HHM72 and HHM75 have an Auto-off feature which turns off the instrument after 10 minutes if no control has been used.
- When the probe is switched off by this automatic function, the switch (7) must first be set to the off position before the probe may be powered up again.
- Auto-off may be disabled at power-up by the user. Simply press the auto zero button (4) at the same time as moving the switch (7) from the OFF position to one of the ranges. The green LED (6) blinks three times to indicate that the auto-off is disabled.

## Operating Procedure


### Making Measurements with the Models HHM72 and HHM75

- Plug the probe into the display device (e.g., DMM, logger). Note the polarity of the probe output banana plugs (red = positive [+], black = negative [-]).
- Select the appropriate range on the display device. Note that the probe's outputs are 1 mV/A and 10 mV/A AC or DC. Note the maximum current capability on 10 mV/A range.
- Turn display device power on. Turn on (7) the probe: the green LED (6) should be on, and the red LED (5) off. If the green indicator does not come on or goes off before the probe has operated for 10 minutes, it is necessary to replace the battery (see "Battery Replacement," pg. 20).
- After approximately 10 minutes of operation, if none of the control buttons has been manipulated power will automatically shut off (see "Auto-Off" on pg. 13).

### DC Measurement


- Select the appropriate DC mV or V range on the DMM or measuring instrument.
- "Zero" the probe. With the probe disconnected from test samples (no conductor in probe jaw window), press the auto zero button (4). The red LED (%) comes on for approximately three seconds to indicate that the probe is zeroing. If the red LED remains lit, this indicates that zero has not been attained - repeat the zeroing operation.
- For best accuracy, especially on low-level measurement, it is recommended that you zero the probe before each measurement.
- Clamp the probe around the conductor (1) to be tested. The DMM or display device should now display the measured conductor current. A positive reading indicates current flowing in the direction of the arrow located on the side of the jaw (2). A negative reading indicates current flow in the opposite direction of the arrow. Apply the conversion ratio (1mV/A or 10 mV/A) to get the value of the current.

## HHM72



1. Conductor
2. Jaws
3. Protective non-slip guard
4. Automatic zero DC button
5. Red light (overrange and incorrect zero adjustment)
6. Green light (on when battery voltage  $\geq 6.5$  V)
7. Three-position range selection switch:
  - On/Off
  - 600 A (1 mV/A)
  - 60 A (10 mV/A)
8. Lead, 5 ft (1.5 m)
9. Safety banana plug  $\varnothing$  4 mm

# HHM75



1. Conductor
2. Jaws
3. Protective non-slip guard
4. Automatic zero DC button
5. Red light (overrange and incorrect zero adjustment)
6. Green light (on when battery voltage  $\geq 6.5$  V)
7. Three-position range selection switch:
  - On/Off
  - 1500 A (1 mV/A)
  - 150 A (10 mV/A)
8. Lead, 5 ft (1.5 m)
9. Safety banana plug  $\varnothing$  4 mm

## DMM/Display Compatibility

The Models HHM72 and HHM75 current probes are compatible with any multimeter, voltmeter or other voltage measuring instrument which has the following features:

- Input jack that accepts 4 mm safety banana plug
- Range and resolution capable of displaying 1 mV of output per amp of measured current
- Voltmeter accuracy of 0.3% or better to take full advantage of the probe accuracy
- Input impedance of 1 M $\Omega$ /100 pF or greater

When the probe is making a measurement, the current-carrying conductor is not broken and remains electrically isolated from the probe output. As a result, the probe output common may be either floated (isolated) or grounded.

### Warning: User Safety:

Always use a DMM, voltmeter or other display, appropriately rated for safety. Also see warning on page 2.