


.1 YEAR
WARRANTY

MADE IN
USA



User's Guide



Shop online at

omega.com®

Ω OMEGA®

www.omega.com

e-mail: info@omega.com

ISO 9001
CERTIFIED
CORPORATE QUALITY

STAMFORD, CT

ISO 9002
CERTIFIED
CORPORATE QUALITY

MANCHESTER, UK

CDCN684 Conductivity Analyzer



OMEGAnet® Online Service
www.omega.com

Internet e-mail
info@omega.com

Servicing North America:

USA:
ISO 9001 Certified

One Omega Drive, P.O. Box 4047
Stamford CT 06907-0047
TEL: (203) 359-1660 FAX: (203) 359-7700
e-mail: info@omega.com

Canada:

976 Bergar
Laval (Quebec) H7L 5A1, Canada
TEL: (514) 856-6928 FAX: (514) 856-6886
e-mail: info@omega.ca

For immediate technical or application assistance:

USA and Canada: Sales Service: 1-800-826-6342 / 1-800-TC-OMEGA®
Customer Service: 1-800-622-2378 / 1-800-622-BEST®
Engineering Service: 1-800-872-9436 / 1-800-USA-WHEN®
TELEX: 996404 EASYLINK: 62968934 CABLE: OMEGA

Mexico:

En Español: (001) 203-359-7803 e-mail: espanol@omega.com
FAX: (001) 203-359-7807 info@omega.com.mx

Servicing Europe:

Benelux:

Postbus 8034, 1180 LA Amstelveen, The Netherlands
TEL: +31 (0)20 3472121 FAX: +31 (0)20 6434643
Toll Free in Benelux: 0800 0993344
e-mail: sales@omegaeng.nl

Czech Republic:

Frystatska 184/46, 733 01 Karviná, Czech Republic
TEL: +420 (0)59 6311899 FAX: +420 (0)59 6311114
Toll Free: 0800-1-66342 e-mail: info@omegashop.cz

France:

11, rue Jacques Cartier, 78280 Guyancourt, France
TEL: +33 (0)1 61 37 29 00 FAX: +33 (0)1 30 57 54 27
Toll Free in France: 0800 466 342
e-mail: sales@omega.fr

Germany/Austria:

Daimlerstrasse 26, D-75392 Deckenpfronn, Germany
TEL: +49 (0)7056 9398-0 FAX: +49 (0)7056 9398-29
Toll Free in Germany: 0800 639 7678
e-mail: info@omega.de

United Kingdom:

ISO 9002 Certified

One Omega Drive, River Bend Technology Centre
Northbank, Irlam, Manchester
M44 5BD United Kingdom
TEL: +44 (0)161 777 6611 FAX: +44 (0)161 777 6622
Toll Free in United Kingdom: 0800-488-488
e-mail: sales@omega.co.uk

It is the policy of OMEGA to comply with all worldwide safety and EMC/EMI regulations that apply. OMEGA is constantly pursuing certification of its products to the European New Approach Directives. OMEGA will add the CE mark to every appropriate device upon certification.

The information contained in this document is believed to be correct, but OMEGA Engineering, Inc. accepts no liability for any errors it contains, and reserves the right to alter specifications without notice.

WARNING: These products are not designed for use in, and should not be used for, human applications.

IMPORTANT SAFETY INFORMATION

This analyzer is compliant with safety standards as outlined in:

FMRC Class Numbers 3600, 3611, and 3810 (U.S.A.)
CSA C22.2 No. 142 and C22.2 No. 213 (Canada)
EN 61010-1 (European Community)

Please read and observe the following:

- Line voltage may be present at terminals on TB1 at the back of the analyzer enclosure. This may be hazardous. Always remove line power before going near this area of the analyzer. The front bezel assembly of the analyzer, however, contains only low voltage and is completely safe to handle.
- Wiring or repairs should only be performed by qualified personnel and only to an unpowered analyzer.
- Whenever it appears that analyzer safety is questionable, disable the analyzer to ensure against any unintended operation. For example, an unsafe condition is likely when:
 - 1) The analyzer appears visibly damaged.
 - 2) The analyzer fails to operate properly or provide the intended measurements.
 - 3) The analyzer has been stored for long periods at temperatures above 158°F (70°C).
- This analyzer must be installed by specially trained personnel in accordance with relevant local codes and instructions contained in this operating instruction manual. Observe the analyzer's technical specifications and input ratings. If one line of the line power mains is not neutral, use a double-pole mains switch to disconnect the analyzer.

HELPFUL IDENTIFIERS

In addition to information on installation and operation, this instruction manual may contain **WARNINGS** pertaining to user safety, **CAUTIONS** regarding possible instrument malfunction, and **NOTES** on important, useful operating guidelines.

WARNING:

A WARNING LOOKS LIKE THIS. ITS PURPOSE IS TO WARN YOU OF THE POTENTIAL FOR PERSONAL INJURY.

CAUTION:

A CAUTION LOOKS LIKE THIS. ITS PURPOSE IS TO ALERT YOU TO POSSIBLE INSTRUMENT MALFUNCTION OR DAMAGE.

 **NOTE:** *A note looks like this. Its purpose is to alert you to important, useful operating information.*

Definition of Equipment Symbols



This symbol **means CAUTION** and alerts you to possible danger or instrument malfunction. Refer to this manual before proceeding.



This symbol, which appears on the analyzer POWER terminal block (shown in Figure 2-2), **means that this is a protective ground terminal** and alerts you to connect an earth ground to it.



This symbol **means that there is alternating current present** and alerts you to be careful.

CONDENSED OPERATING INSTRUCTIONS

This manual contains details for all operating aspects of the instrument. The following condensed instructions are provided to assist you in getting the instrument started up and operating as quickly as possible. **These condensed instructions only pertain to basic conductivity measurement operation.** To measure resistivity, TDS, or a calculated Sensor A and B measurement, or to use specific features of the instrument, refer to the appropriate sections in this manual for instructions.

A. CONNECTING SENSOR(S)/CONFIGURING TEMPERATURE ELEMENT(S)

1. After the analyzer is properly mounted (Part Two, Section 2), connect the Omega's CDE680 Series contacting conductivity sensor(s), matching wire colors to terminals as indicated:

Sensor A Wire Colors	Connect To	Sensor B Wire Colors	Connect To
Red	Terminal #1 on TB3	Red	Terminal #6 on TB3
Black	Terminal #2 on TB3	Black	Terminal #7 on TB3
Clear (inner shield wire)	Terminal #3 on TB3	Clear (inner shield wire)	Terminal #8 on TB3
White	Terminal #4 on TB3	White	Terminal #9 on TB3
Blue	Terminal #5 on TB3	Blue	Terminal #10 on TB3
Clear w/black (outer shield)	Terminal #1 on TB2	Clear w/black (outer shield)	Terminal #2 on TB2

NOTE: For best immunity to electromagnetic interference, connect the sensor cable's outer shield wire (clear with black band -- not its clear only inner shield wire) to a "SENSOR SHIELD (OUTER)" terminal on TB2.

2. The analyzer is supplied factory-set for automatic temperature compensation using the Pt 1000 ohm temperature element built into Omega's CDE680 Series contacting conductivity sensors. When using a sensor with a different temperature element, or if you want fixed MANUAL temperature compensation, you must change the temperature element type (see Part Three, Section 3.2, subheading "Selecting Temperature Element Type").

NOTE: When using only one sensor, select "MANUAL" for the unused sensor input element type to prevent a "WARNING: CHECK STATUS" message due to analyzer detecting no element.

B. CONNECTING LINE POWER

Important: Follow the instructions in Part Two, Section 3.4 to connect line power to the analyzer.

C. CALIBRATING THE ANALYZER

The analyzer must be calibrated so that measured values will correspond to actual process values. It can be traditionally "wet" calibrated. However, since measured conductivity is greatly affected by small changes in temperature, OMEGA strongly recommends using its DRY method for highest measuring accuracy of conductivity and temperature. Besides, the DRY method is actually a normal part of configuring the sensor characteristics during initial startup, and **eliminates the need for conductivity reference solutions**. This method also automatically sets the analyzer measuring range to match the inherent range of the sensor's cell constant. For more details about the benefits of DRY, refer to the "Calibration Tip!" in Part Three, Section 4.1.

NOTE: DRY method eliminates the need for periodic re-calibration! The only requirement, depending on the application, may be to periodically clean the sensor. Only when the sensor is replaced is it necessary to perform a new DRY calibration.

Calibration Tip! Each contacting conductivity sensor has a unique zero point and offset. Consequently, when calibrating a sensor for the first time, always zero it according to step 1. Zeroing provides the best possible measuring accuracy, and eliminates any discrepancy between Sensor A and B measurement channels.

(continued on next page)

CONDENSED OPERATING INSTRUCTIONS

C. CALIBRATING THE ANALYZER -- (continued)

DRY calibration, routinely attained while configuring the analyzer for sensor characteristics, requires entry of the sensor's OMEGA-certified "K" value and temperature "T factor" which are unique to each sensor. When using two sensors, enter each unique set of values using the respective sensor menu screens.

1. Zero the sensor if it is being calibrated for the first time. If not, disregard this step and perform steps 2 through 17.

Zeroing Tip! If at any time during zeroing, the "ZERO: CONFIRM FAILURE?" screen appears, press **ENTER** key to confirm. Then, use the **↑** or **↓** key to select between "CAL REPEAT?" or "CAL EXIT?" and do one of the following:

- With the "ZERO: CAL REPEAT?" screen selected, press **ENTER** key to repeat zeroing.
- With the "ZERO: CAL: EXIT?" screen selected, press **ENTER** key. After the "ZERO: CONFIRM ACTIVE?" screen appears, press **ENTER** key to return the analog outputs and relays to their active states (MEASURE screen appears).

- A. Make sure that the sensor is dry before zeroing.

- B. Press **MENU** key to display

MAIN MENU
▶CALIBRATE

 ↓ .

- C. Press **ENTER** key to display

CALIBRATE
▶SENSOR A

 ↓ .

- D. Press **ENTER** key again to display

SENSOR A
▶1 POINT SAMPLE

 ↓ .

- E. Press **↓** key once to display

SENSOR A
▶ZERO

 ↓ .

- F. Press **ENTER** key to display

ZERO?
(HOLD OUTPUTS)

 .

- G. Press **ENTER** key again to "hold" the analog outputs and relays at their present states during zeroing. (Outputs can also be transferred to preset values or allowed to remain active.)

- H. With the "ZERO: IN DRY AIR?" screen displayed and the dry sensor held in air, press **ENTER** key to start the automatic zeroing.

- I. After the "ZERO: CONFIRM ZERO OK?" screen appears, press **ENTER** key to end zeroing.

- J. After the "ZERO: CONFIRM ACTIVE?" screen appears, press **ENTER** key to return the analog outputs and relays to their active states (MEASURE screen appears).

2. Press **MENU** key to display

MAIN MENU
▶CALIBRATE

 ↓ .

3. Press **↓** key once to display

MAIN MENU
▶CONFIGURE

 ⇅ .

4. Press **ENTER** key to display

CONFIGURE
▶SET OUTPUT 1

 ↓ .

5. Press **↓** key until you display















CONFIGURE
▶SENSOR A

 ⇅ .

(continued on next page)

CONDENSED OPERATING INSTRUCTIONS

C. CALIBRATING THE ANALYZER – (continued)

6. Press **ENTER** key to display .
7. Press **↓** key until you display .
8. Press **ENTER** key to display .
9. Press **ENTER** key again to display a cell category selection screen like . Use **↑** and **↓** keys to select the nominal cell category that corresponds to the sensor's OMEGA-certified "K" value shown on a label attached to the sensor cable or to the inside cover of its optional junction box. Then press **ENTER** key to enter the selection.
10. After the  screen re-appears, press **↓** key once to display .
11. Press **ENTER** key to display a cell "K" value screen like . Use **⇒** and **⇐** keys to coarse adjust, and **↑** and **↓** keys to fine adjust the displayed value to exactly match the sensor's OMEGA-certified "K" value. Then press **ENTER** key to enter the value.
12. After the  screen re-appears, press **ESC** key once to display .
13. Press **↓** key until you display .
14. Press **ENTER** key to display .
15. Press **↓** key once to display .
16. Press **ENTER** key to display a "T" factor value screen like . Use **⇒** and **⇐** keys to coarse adjust, and **↑** and **↓** keys to fine adjust the displayed value to exactly match the sensor's OMEGA-certified "T" factor. Then press **ENTER** key to enter the value.
17. After the  screen re-appears, press **MENU** key once and then **ESC** key once to display the MEASURE screen.

This completes OMEGA's DRY calibration. The analyzer is now ready to measure conductivity.

To change the display format of the MEASURE screen, for example, from 0-2000 $\mu\text{S}/\text{cm}$ to 0.000-2.000 mS/cm , see Part Three, Section 3.2 under the subheading "Selecting Measurement Display Format."

NOTE: If the values you intend to measure are above the analyzer's set measuring range (not its selected display format), use a different sensor that has the appropriate nominal cell constant. For a listing of sensor cell constants and their inherent measuring ranges, see Table A in Part Three, Section 3.2 under the subheading "Selecting Measurement Display Format."

D. COMPLETING ANALYZER CONFIGURATION

To further configure the analyzer to your application requirements, use the appropriate CONFIGURE screens to make selections and "key in" values. Refer to Part Three, Section 3 for complete configuration details.

TABLE OF CONTENTS

PART ONE - INTRODUCTION

SECTION 1	GENERAL INFORMATION	
	1.1 Capability Highlights.....	10-12
	1.2 Modular Construction.....	12
	1.3 Retained Configuration Values	12
	1.4 Analyzer Serial Number	12
	1.5 EMI/RFI Immunity	13
SECTION 2	SPECIFICATIONS	14-15

PART TWO - INSTALLATION

SECTION 1	UNPACKING.....	16
SECTION 2	MECHANICAL REQUIREMENTS	
	2.1 Location	16
	2.2 Mounting	16-17
SECTION 3	ELECTRICAL CONNECTIONS	
	3.1 Omega's CDE680 Series Contacting Conductivity Sensor(s).....	19
	3.2 Analog Outputs	20
	3.3 Relay Outputs	21
	3.4 Line Power	22

PART THREE - OPERATION

SECTION 1	USER INTERFACE	
	1.1 Display	23
	1.2 Relay A and B Indicators.....	23
	1.3 Keypad.....	23-24
	1.4 MEASURE Screen (normal display mode).....	25
SECTION 2	MENU STRUCTURE	
	2.1 Displaying Main Branch Selection Screens.....	26
	2.2 Displaying Top-level Menu Screens.....	27
	2.3 Displaying Submenu Screens	28
	2.4 Adjusting Edit/Selection Screen Values	28
	2.5 Entering (Storing) Edit/Selection Screen Values/Choices.....	28

TABLE OF CONTENTS (continued)

SECTION 3	CONFIGURING THE ANALYZER	
3.1	Selecting Language to Operate Analyzer.....	29
3.2	Configuring Sensor (A and B) Characteristics:	
	Selecting Measurement (CONDUCTIVITY, RESISTIVITY, or TDS).....	29-30
	Selecting Measurement Display Format.....	30-31
	Selecting Temperature Compensation	31-32
	Configuring TDS Measurement (not needed for other measurements).....	32-33
	Configuring LINEAR Temperature Compensation (not needed for other compensation methods)	33-34
	Entering Sensor's OMEGA-certified "K" Value	35
	Setting Sensor Signal Filter Time	36
	Selecting Pulse Suppression (on/off).....	36
	Changing Top Line Notation on MEASURE Screen	37
	Selecting Temperature Element Type	37-38
	Entering Sensor's OMEGA-certified "T" Factor.....	38-39
3.3	Configuring Calculated Sensor A and B Measurement:	
	Selecting Calculated Measurement (none, % rejection, % passage, ratio A/B, ratio B/A, difference A-B, or difference B-A).....	40
	Selecting Calculated RATIO A/B or RATIO B/A Measurement Display Format (not needed for other calculated measurements).....	40-41
3.4	Selecting Temperature Display Format (°C or °F).....	41
3.5	Configuring Outputs (1 and 2):	
	Assigning Representative Parameter	42
	Setting Parameter Values for 0/4 and 20 mA	42-43
	Setting Transfer Value (mA)	43
	Setting Output Filter Time.....	43-44
	Setting Output Scale Low Endpoint (0/4 mA)	44
3.6	Configuring Relays (A and B):	
	Assigning Representative Parameter	44-45
	Selecting Function Mode (alarm, control, or status) ...	45-46
	Selecting Transfer Mode (relay on or off)	46
	Setting Activation (Configuration) Values	46-48
3.7	Enabling/Disabling Passcode.....	48
3.8	Summary of Configuration Settings (Ranges/Choices and Defaults)	48-51
SECTION 4	CALIBRATING THE ANALYZER	
4.1	Things to Know About Calibration.....	52
4.2	Zeroing Sensor for First-time Calibration	53-54
4.3	DRY Method (highly recommended):	
	Entering "K" Value	54-55
	Entering Temperature "T" Factor	55-56

TABLE OF CONTENTS (continued)

	4.4 1 POINT SAMPLE Method (wet calibration)	57-58
	4.5 Analog Outputs (1 and 2) Calibration	59-60
SECTION 5	TEST/MAINTENANCE	
	5.1 Checking Analyzer, Sensor, and Relay Status	61-62
	5.2 Holding Outputs	63
	5.3 Resetting Overfeed Timers	63
	5.4 Providing Output (1 and 2) Test Signals	64
	5.5 Testing Relay (A and B) Operation	64
	5.6 Testing Alarm LEDs	65
	5.7 Checking EPROM Version	65
	5.8 Selecting Type of Simulated Value	65-66
	5.9 Setting Simulation Value	66
	5.10 Resetting Configuration Values to Factory Defaults	67
SECTION 6	RELAY OVERFEED TIMER FEATURE	
	6.1 Why Use an Overfeed Timer	68
	6.2 Configuring Relay Overfeed Timers	68
	6.3 Overfeed Timer "Timeout" Operation	68
	6.4 Resetting Overfeed Timers	68
	6.5 Interactions with Other Analyzer Functions	68-69

PART FOUR - SERVICE AND MAINTENANCE

SECTION 1	GENERAL INFORMATION	
	1.1 Inspecting Sensor Cable(s)	70
	1.2 Replacing Fuse(s)	70
	1.3 Replacing Relays	70
SECTION 2	PRESERVING MEASUREMENT ACCURACY	
	2.1 Keeping Sensor(s) Clean	71
	2.2 Keeping Analyzer Calibrated	71
	2.3 Avoiding Electrical Interference	71
SECTION 3	TROUBLESHOOTING	
	3.1 Ground Loops:	
	Determining if Ground Loop Exists	72
	Finding Source of Ground Loop	73
	3.2 Isolating Measuring System Problem:	
	Checking Electrical Connections	73
	Verifying Sensor Operation	73
	Verifying Analyzer Operation	73-74
	Verifying Interconnect Cable Integrity	74-75

ILLUSTRATIONS

Figure 1-1	EMI/RFI Immunity Diagram.....	13
Figure 2-1	Analyzer Enclosure Dimensions and Panel Mounting Details.....	17
Figure 2-2	Analyzer Terminal Block Designations	18
Figure 2-3	Connecting Omega's CDE680 Series Contacting Conduct. Sensor(s).....	19
Figure 2-4	Connecting Control/Alarm Device(s) to Electromechanical Relay(s)	21
Figure 2-5	Connecting 115 Volt Single Phase Line Power (90-130 VAC).....	22
Figure 2-6	Connecting 230 Volt Single Phase Line Power (190-260 VAC).....	22
Figure 2-7	Connecting 230 Volt Split Phase Line Power (190-260 VAC).....	22
Figure 3-1	Analyzer Keypad.....	24

TABLES

Table A	Sensor Cell Constants and Measuring Ranges.....	31
Table B	Relay Configuration Settings.....	46-47
Table C	Analyzer Configuration Settings (Ranges/Choices and Defaults).....	49-51
Table D	Conductivity Reference Solutions	657
Table E	Relay Overfeed Timer Interactions with Other Analyzer Functions	69
Table F	Full-scale Equivalent Test Resistor Values	74

PART ONE - INTRODUCTION

SECTION 1

GENERAL INFORMATION

1.1 Capability Highlights

Sensor Input	The analyzer has two independent sensor inputs for monitoring two measurement points. Each input accepts OMEGA CDE680 series enhanced performance contacting conductivity sensors.
MEASURE Screen	<p>The MEASURE screen (normal display mode) can provide seven different readouts of measured data. With the MEASURE screen displayed, press \leftarrow or \rightarrow key to show:</p> <ol style="list-style-type: none">1. Measured Sensor A conductivity (or resistivity or TDS).2. Measured Sensor A temperature (°C or °F).3. Measured Sensor B conductivity (or resistivity or TDS).4. Measured Sensor B temperature (°C or °F).5. Analog Output # 1 and #2 values (mA).6. Measured Sensor A and B values <u>and</u> temperatures.7. *Calculated Sensor A and B measurement (% reject, % pass, ratio A/B, ratio B/A, diff. A-B, or diff. B-A). <div><p>*The calculated measurement can only be displayed when two sensors are used <u>and</u> the analyzer has been correctly configured for CALCULATION.</p></div>
Passcode-protected Access	For security, you can enable a passcode feature to restrict access to configuration and calibration settings to authorized personnel only. See Part Three, Section 3.7 for details.
Calibration Methods	It is highly recommended to calibrate the analyzer using the DRY method. However, the analyzer can be traditionally "wet" calibrated. For calibration details, refer to Part Three, Sections 4.2 or 4.3 respectively. The mA values for each analog output can also be calibrated (Section 4.4).

Analog Outputs

The analyzer provides two isolated analog outputs (#1 and #2). Each output can be set to be 0-20 mA or 4-20 mA, and assigned to represent one of the following:

- Measured Sensor A conductivity, resistivity, or TDS.
- Measured Sensor A temperature.
- Measured Sensor B conductivity, resistivity, or TDS.
- Measured Sensor B temperature.
- *Calculated Sensor A and B measurement (% reject, % pass, ratio A/B, ratio B/A, diff. A-B, or diff. B-A).

*An analog output can only represent the calculated measurement when two sensors are used and the analyzer has been correctly configured for CALCULATION.

Parameter values (or calculated measurement values) can be entered to define the endpoints at which the minimum and maximum analog output values are desired.

During calibration, both analog outputs can be selected to:

- Hold their present values (HOLD OUTPUTS).
- Transfer to preset values to operate control elements by an amount corresponding to those values (XFER OUTPUTS).
- Remain active to respond to the measured value (ACTIVE OUTPUTS).

For analog output transfer setup details, refer to Part Three, Section 3.5 under the subheading "Setting Transfer Value."

Relays

The analyzer has two electromechanical relays with SPDT contacts. Each relay can be set to function as a control relay, a dual-alarm relay, or a status relay. A control or alarm relay can be assigned to be driven by one of the following:

- Measured Sensor A conductivity, resistivity, or TDS.
- Measured Sensor A temperature.
- Measured Sensor B conductivity, resistivity, or TDS.
- Measured Sensor B temperature.
- *Calculated Sensor A and B measurement (% reject, % pass, ratio A/B, ratio B/A, diff. A-B, or diff. B-A).

*A relay can only be driven by the calculated measurement when two sensors are used and the analyzer has been correctly configured for CALCULATION.

Refer to Part Three, Section 3.6 for relay setup details.



NOTE: When a relay is set to function as a status relay, it is no longer configurable. Instead, it becomes a dedicated system diagnostic-only alarm relay that automatically energizes when the "WARNING CHECK STATUS" message flashes on the MEASURE screen. This occurs when the analyzer detects a diagnostic condition. See Part Three, Section 5.1 for more details.

Except for status relays, during calibration the relay on/off states are affected in the same way as the analog outputs by the "(HOLD/XFER/ACTIVE) OUTPUTS" screen selection. These relays are also held at their present on/off states, transferred to desired preset on/off states, or remain active to respond to measured values. For relay transfer setup details, see Part Three, Section 3.6, under the sub-heading "Selecting Transfer Mode."

1.2 Modular Construction

The modular construction of the analyzer provides electrical safety. The front panel keypad assembly uses voltages no greater than 24 VDC, and is completely safe to handle.

Line power must be connected to specifically designated terminals on TB1.

WARNING:

REMOVE LINE POWER BEFORE NEARING THIS AREA
TO PREVENT ELECTRICAL SHOCK.

1.3 Retained Configuration Values

All user-entered configuration values are retained indefinitely, even if power is lost or turned off. The non-volatile analyzer memory does not require battery backup.

1.4 Analyzer Serial Number

A label with the analyzer model number, serial number, build date, and other items is located on top of the enclosure.

1.5 EM/RFI Immunity

The analyzer is designed to provide protection from most normally encountered electromagnetic interference. This protection exceeds U.S. standards and meets European IEC 801-series testing for electromagnetic and radio frequency emissions and susceptibility. Refer to Figure 1-1 and the specifications in Section 2.1 for more information.




FIGURE 1-1 EMI/RFI Immunity Diagram

SECTION 2

SPECIFICATIONS

2.1 Operational

Display Two-line by 16 character backlit LCD

NOTE: *Sensor A or B's measured values or temperatures can be shown separately, or all four measurements can be displayed together. A calculated Sensor A and B measurement can also be displayed.*

<u>Measurement</u>	<u>Selectable Ranges</u>
Conductivity	μS/cm: 0-2.000, 0-20.00, 0-200.0, or 0-2000 mS/cm: 0-2.000, 0-20.00, 0-200.0, or 0-2000
Resistivity	0-19.99 MΩ • cm or 0-999.9 KΩ • cm
TDS	0-9999 ppm or 0-9999 ppb
Calculated Sensor A and B Measurement:	
% Rejection.....	0-100%
% Passage.....	0-100%
Ratio A/B or B/A.....	0-9.999, 0-99.99, 0-999.9, or 9999
Difference A-B or B-A	Same ranges as those listed above for conductivity, resistivity, and TDS
Temperature	-4.0 to +392.0°F or -20.0 to +200.0°C
mA Outputs (#1 and #2)	0.00-20.00 mA or 4.00-20.00 mA

Ambient Conditions:

Operation.....	-4 to +140°F (-20 to +60°C); 0-95% relative humidity, non-condensing
Storage.....	-22 to +158°F (-30 to +70°C); 0-95% relative humidity, non-condensing

Relays: Types/Outputs Two electromechanical relays; SPDT (Form C)
contacts; U.L. rated 5A 115/230 VAC, 5A @
30 VDC resistive

Operational Mode..... Each relay (A and B) can be assigned to be
driven by the:

- Sensor A or B measurement (con-
ductivity, resistivity, TDS)
- Sensor A or B temperature
- Calculated Sensor A and B measure-
ment
(% rejection, % passage, ratio A/B, ratio B/A,
difference A-B, or difference B-A)

Function Modes:

Control	Settings for high/low phasing, setpoint, dead- band, overfeed timer, off delay, and on delay
Alarm.....	Settings for low alarm point, low alarm point deadband, high alarm point, high alarm point deadband, off delay, and on delay
Status	Not configurable; relay only activates when a sensor or analyzer diagnostic WARNING condi- tion exists

Indicators Relay A and B LEDs indicate respective relay status

Temperature Compensation Automatic or manual, -4.0 to +392.0°F (-20.0 to
+200.0°C), with selection for temperature ele-
ment (Pt 1000 ohm RTD or Pt 100 ohm RTD) or
a manually entered value

NOTE: *Depending on Sensor A or B's selected measurement (conductivity,
resistivity, or TDS) not all of the following temperature compensation
methods are available:*

*Linear % per °C slope, built-in ammonia temp. properties table,
built-in natural water temp. properties table, or no compensation*

Sensor-to-Analyzer Distance	300 ft. (91 m) maximum
Power Requirements	90-130 VAC, 50/60 Hz. (10 VA max.) or 190-260 VAC, 50/60 Hz. (10 VA max.)
Calibration Methods:	
DRY	Enter OMEGA-certified cell constant "K" value and temperature "T" factor of the sensor.
1-POINT SAMPLE	Enter one reference solution value or one sample value (determined by laboratory analysis or a comparison reading).
ZERO	With the dry sensor in air, press keys to initiate automatic system zeroing.
Analog Outputs	Two Isolated 0/4-20 mA outputs; each with 0.004 mA (12-bit) resolution and capability to drive up to 600 ohm loads
<p>NOTE: Each output can be assigned to represent Sensor A or B's selected measurement (conductivity, resistivity, or TDS), Sensor A or B's temperature, or a calculated Sensor A and B measurement (% rejection, % passage, ratio A/B, ratio B/A, difference A-B, or difference B-A). Parameter values (or calculated measurement values) can be entered to define the endpoints at which the minimum and maximum mA output values are desired. During calibration, both outputs can be selected to hold their present values, transfer to preset values to operate control elements by an amount corresponding to those values, or remain active to respond to the measured value.</p>	
Communication: RS-232	For factory configuration only
Memory Backup (non-volatile)	All user settings are retained indefinitely in memory (EEPROM)
EMI/RFI Conformance	Exceeds US and meets European standards for conducted and radiated emissions and immunity; certified CE compliant for applica- tions as specified by EN 50081-2 for emissions and EN 50082-2 for immunity
Electrical Certifications:	
General Purpose (pending)	UL, C-UL, FM, and CENELEC
Division 2 (pending)	UL, C-UL, and FM: Groups A, B, C, D, F, and G
Zone 2 (pending)	CENELEC: Group IIC
Accuracy	0.1% of span
Stability	0.05% of span per 24 hours, non-cumulative
Repeatability	0.1% of span or better
Temperature Drift	Zero and Span: less than 0.03% of span/°C
Enclosure	Polycarbonate with NEMA 4X front panel; general purpose; two zinc-plated steel brackets for panel mounting
Mounting Configuration	Panel mounting
Net Weight	1.7 lbs. (0.8 kg) approximately

2.2 Analyzer Performance (Electrical, Analog Outputs)

2.3 Mechanical

PART TWO - INSTALLATION

SECTION 1

UNPACKING

After unpacking, it is recommended to save the shipping carton and packing materials in case the instrument must be stored or re-shipped. Inspect the equipment and packing materials for signs of shipping damage. If there is any evidence of damage, notify the transit carrier immediately.

SECTION 2

MECHANICAL REQUIREMENTS

2.1 Location

1. It is recommended to locate the analyzer as close as possible to the installed sensor. The maximum allowable distance between an installed sensor and the analyzer is 300 ft. (91 m).
2. Mount the analyzer in a location that is:
 - ◆ Clean and dry where there is little or no vibration.
 - ◆ Protected from corrosive fluids.
 - ◆ Within ambient temperature limits (-4 to +140°F or -20 to +60°C).

CAUTION:

EXPOSING THE ANALYZER TO DIRECT SUNLIGHT MAY INCREASE THE OPERATING TEMPERATURE ABOVE ITS SPECIFIED LIMIT.

2.2 Mounting

Figure 2-1 illustrates the analyzer enclosure dimensions and panel mounting details. Use the two supplied brackets to panel mount the analyzer. The brackets may be attached to the top and bottom of the analyzer case, or to each of its sides.




FIGURE 2-1 Analyzer Enclosure Dimensions and Panel Mounting Details

SECTION 3

ELECTRICAL CONNECTIONS

Figure 2-2 shows the terminal block arrangement and terminal designations on the back of the analyzer case.



NOTE: For easier wiring, terminal blocks can be unplugged from their mating connectors. All terminals are suitable for single wires up to 14 AWG (2.5 mm²).



Wiring Tip! To comply with European Community (CE) electromagnetic compatibility requirements, follow these general wiring guidelines:

1. Keep all cable shields as short as possible and connect them to earth ground.
2. Use Steward ferrite 28 B0590-000 or equivalent on:
 - ◆ Mains (line power) cable -- no turns required.
 - ◆ Sensor cable -- one turn required.
 - ◆ mA analog output cables -- two turns required.
 - ◆ Relay cables -- no turns required.
3. In harsh conducted RF conditions, connect the earth ground of the analyzer (Terminal 4 on TB1) to a local, known earth ground source.




FIGURE 2-2 Analyzer Terminal Block Designations

3.1 Omega's CDE680 Series Contacting Conductivity Sensor(s)

All OMEGA Model CDE680 series contacting conductivity sensors have a built-in Pt 1000 ohm RTD temperature element for automatic temperature compensation and for measuring process temperature.



Wiring Tip! Route the sensor cable in 1/2-inch, grounded metal conduit to protect it from moisture, electrical noise, and mechanical damage.

For installations where the distance between sensor and analyzer exceeds the sensor cable length, indirectly connect the sensor to the analyzer using a junction box and interconnect cable.



NOTE: Do not route the sensor cable in any conduit containing AC power wiring ("electrical noise" may interfere with the sensor signal).

The analyzer can be used with one or two conductivity sensors. Refer to Figure 2-3 and connect Sensor A's cable (or interconnect) wires to SENSOR Terminals 1 through 5 on TB3, matching colors as indicated. If using a second sensor, connect Sensor B's cable to Terminals 6 through 10.



NOTE: For best immunity to electromagnetic interference, connect the sensor cable's outer shield wire (clear with black band -- not its clear-only inner shield wire) to a "SENSOR SHIELD (OUTER)" terminal on TB2.




FIGURE 2-3 Connecting Omega's CDE680 Series Contacting Conductivity Sensor(s)

3.2 Analog Outputs

Two analog outputs (#1 and #2) are provided. Each output can be set to be 0/4-20 mA. These outputs are isolated from the inputs and earth ground, but not from each other. Each output can be assigned to represent one of the following:

- Measured Sensor A conductivity, resistivity, or TDS.
- Measured Sensor A temperature.
- Measured Sensor B conductivity, resistivity, or TDS.
- Measured Sensor B temperature.
- *Calculated Sensor A and B measurement (% reject, % pass, ratio A/B, ratio B/A, diff. A-B, or diff. B-A).

*An analog output can only represent the calculated measurement when two sensors are used and the analyzer has been correctly configured for CALCULATION.

For details on configuring the outputs, refer to Part Three, Section 3.5.



Wiring Tip! Use high quality, shielded instrumentation cable for connecting the analog outputs.

Each 0/4-20 mA output can drive a load of up to 600 ohms.

- **Output #1:** Connect the load to Terminals 4 and 5 on TB4, matching polarity as indicated.
- **Output #2:** Connect the load to Terminals 6 and 7 on TB4, matching polarity as indicated.

3.3 Relay Outputs

The analyzer is equipped with two electromechanical relays. For relay setup details, see Part Three, Section 3.6.

CAUTION:

DO NOT EXCEED THE CONTACT RATING FOR EACH RELAY (5A 115/230 VAC). WHEN SWITCHING LARGER CURRENTS, USE AN AUXILIARY RELAY SWITCHED BY THE ANALYZER RELAY TO EXTEND ANALYZER RELAY LIFE. WHEN USING RELAY OUTPUTS, MAKE SURE THAT LINE POWER WIRING CAN ADEQUATELY CONDUCT THE CURRENT DRAW OF THE SWITCHED LOAD(S).

Two sets of SPDT relay outputs (Relays A and B) are provided at Terminals 8 through 13 on TB4. **The relay outputs are not powered.** The line power used to power the analyzer may also be used to power control/alarm devices with these relay contacts. Refer to Figure 2-4 for a general wiring arrangement. Always check control wiring to insure that line power will not be shorted by the relay switching action, and that wiring conforms to local codes.

WARNING:

MAKE SURE LINE POWER IS NOT PRESENT WHILE CONNECTING WIRES TO TB5 RELAY TERMINALS.




FIGURE 2-4 Connecting Control/Alarm Device(s) to Electromechanical Relay(s)

3.4 Line Power

Refer to Figure 2-5, 2-6 or 2-7 and connect line power to appropriate terminals on TB1 using the standard three-wire connection arrangement. **Use wiring practices which conform to local codes** (example: National Electric Code Handbook in the U.S.A.).

WARNING:

REMOVE LINE POWER WHILE CONNECTING LINE POWER WIRES TO THE TB1 TERMINALS. ALSO, USE ONLY THE STANDARD THREE-WIRE CONNECTION ARRANGEMENT FOR SINGLE-PHASE LINE POWER TO PREVENT AN UNSAFE CONDITION, AND TO ENSURE PROPER ANALYZER OPERATION.



NOTE: *In all cases, connect the line power cable ground wire (usually green) to the "ground symbol" terminal on TB1.*

The "115" and "230" voltage circuits are protected with internal, board-mounted slow-blow fuses.



NOTE: *For 230 volt split phase line power, be sure to conform to local codes with regard to fusing the 115 volt line connected to the "N" terminal.*




FIGURE 2-5
Connecting 115 Volt
Single Phase Line Power
(90-130 VAC)




FIGURE 2-6
Connecting 230 Volt
Single Phase Line Power
(190-260 VAC)




FIGURE 2-7
Connecting 230 Volt
Split Phase Line Power
(190-260 VAC)

PART THREE - OPERATION

SECTION 1

USER INTERFACE

The user interface consists of a two-line LCD display and a keypad with **MENU**, **ENTER**, **ESC**, \leftarrow , \rightarrow , \uparrow , and \downarrow keys.

1.1 Display

The backlit, high resolution display is factory-set for optimum viewing contrast under all lighting conditions. By using the keypad, you can display three types of screens:

- **MEASURE screen** to sequentially show, by pressing the \leftarrow or \rightarrow key, the measured Sensor A value, Sensor A temperature, Sensor B value, Sensor B temperature, analog Output #1 and #2 mA values, Sensor A and B values with their measured temperatures, and a calculated Sensor A and B measurement (% reject, % pass, ratio A/B or B/A, or difference A-B or B-A).
- **MENU screens** to move within the three main branches of the analyzer menu tree, enabling access to edit/selection screens. (EXIT screens indicate the end of a menu branch and enable you, by pressing the **ENTER** key, to move up one level in the menu tree. This is functionally the same as pressing the **ESC** key.)
- **Edit/Selection screens** to enter values/choices to calibrate, configure, and test the analyzer.

1.2 Relay A and B Indicators

Relay A and B red LED indicators light when their respective relay energizes. (When a relay overfeed timer has “timed out,” the respective indicator blinks continuously until the overfeed condition is resolved.)

1.3 Keypad

The keypad enables you to move throughout the analyzer menu tree. The keys and their related functions are:

1. **MENU key:** Pressing this key always displays the top of the menu tree (“MAIN MENU ► CALIBRATE” screen). To display the CONFIGURE and TEST/MAINT main branches of the menu tree, press the \downarrow key. The **MENU** key can also be used to “abort” the procedure to change values or selections.

2. **ENTER key:** Pressing this key displays an available submenu or edit/selection screen, or enters (saves) values/selections.
3. **ESC key:** Pressing this key always takes the display up one level in the menu tree. (Example: With the "MAIN MENU" screen displayed, pressing the **ESC key** once takes the display up one level to the MEASURE screen.) This key can also "abort" the procedure to change a value or selection.
4. **⇐ and ⇒ keys:** Depending on the type of displayed screen, these keys do the following:
 - **MEASURE Screen:** Changes the readout (in continuous loop sequence) to show different measurements.
 - **Menu Screens:** These keys are non-functional.
 - **Edit/Selection Screens:** "Coarse" adjusts the displayed numerical value.
5. **↑ and ↓ keys:** Depending on the type of displayed screen, these keys do the following:
 - **MEASURE Screen:** These keys are non-functional.
 - **Menu Screens:** Moves up or down respectively between other same-level menu screens.
 - **Edit/Selection Screens:** "Fine" adjusts the displayed numerical value (holding key down changes value faster), or moves up or down between choices.





FIGURE 3-1 Analyzer Keypad

1.4 MEASURE Screen (normal display mode)

The MEASURE screen is normally displayed. Pressing the **MENU** key temporarily replaces the MEASURE screen with various screens to calibrate, configure, or test the analyzer. If the keypad is not used within 30 minutes, except during calibration and while using specific analyzer test/maintenance functions, the display automatically returns to the MEASURE screen. To display the MEASURE screen at any time, press the **MENU** key once and then the **ESC** key once.

The MEASURE screen can be viewed in one of seven different readout versions. To select between them, in continuous loop sequence, press the \Leftarrow or \Rightarrow key:



NOTE: When the analyzer returns to its normal MEASURE screen mode, the appearing MEASURE screen readout is always the version last selected. Note that the first four MEASURE screen readout examples show “SENSOR A” and “SENSOR B” notations on their top lines, illustrating the analyzer notation feature. To create your own notation, refer to Part Three, Section 3.2, under the subheading “Changing Top Line Notation on MEASURE Screen.”

Also, the “CALC: % REJECT” readout is an example of a calculated Sensor A and B measurement. The analyzer can also calculate and display other measurements. Refer to Part Three, Section 3.3 for details.

When the measured value is beyond the analyzer measuring range, a series of “+” or “-” screen symbols appear, respectively indicating that the value is above or below range.

SECTION 2

MENU STRUCTURE

The analyzer menu tree is divided into three main branches: CALIBRATE, CONFIGURE, and TEST/MAINT. Each main branch is structured similarly in layers with top-level screens, related lower level submenu screens and, in many cases, sub-submenu screens.


Each layer contains an EXIT screen to return the display up one level to the previous layer of screens.



Menu Structure Tip! For operating convenience, the layers within each main branch are organized with the most frequently used function screens at their beginning, rather than the function screens used for initial startup.

2.1 Displaying Main Branch Selection Screens

1. Press **MENU key** to always display the start of the analyzer menu tree (CALIBRATE branch selection screen).
2. Press **↓** and **↑** keys to select between the three main branch selection screens or the EXIT screen:




3. With the desired branch selection screen displayed, press **ENTER key** to display the first top-level menu screen within that branch.

2.2 Displaying Top-level Menu Screens

With the first top-level menu screen within the desired main branch displayed, use the \downarrow and \uparrow keys to scroll through other top-level screens to access a desired screen.

The top-level menu screens for each main branch are:



Menu Structure Tip! A menu screen with a horizontal bar symbol (≡) at the start of its first line indicates there is a related submenu or edit/selection screen.

A menu screen with a "▶" symbol at the start and a "↓" symbol at the end of its second line indicates that you can select other screens within the same layer by pressing the \downarrow key. A "↑" symbol at the end of the second line indicates that you can move up or down between screens by respectively pressing the \uparrow or \downarrow key. When a "↑" symbol appears, it indicates you have reached the end of the screens in that layer. You can select previous screens using the \uparrow key.

2.3 Displaying Submenu Screens

After selecting a top-level menu screen, press the **ENTER** key to display a related submenu or edit/selection screen:

- **Submenu Screens** always have a first line starting with a horizontal bar symbol. Pressing the \downarrow key displays one or more related menu screens within this same level.

Example: With this submenu screen displayed:

```
≡SET OUTPUT 1
▶SET PARAMETER ↓
```

pressing the \downarrow key displays this related, same-level submenu screen:

```
≡SET OUTPUT 1
▶SET 4mA VALUE ⇅
```

- **Edit/Selection Screens** always have a first line ending with a "?". Pressing the \downarrow or \uparrow key changes the value/choice enclosed by parenthesis (second line on screen).

Example: With this submenu screen displayed:

```
SET °C OR °F?
( °C )
```

pressing the \downarrow key displays this related choice:

```
SET °C OR °F?
( °F )
```

2.4 Adjusting Edit/Selection Screen Values

Edit/selection screens always contain a second line enclosed by parenthesis -- see examples shown above and below. The enclosed value/choice can be edited/changed by using the \uparrow and \downarrow keys. Pressing the **ENTER** key saves the change.

```
SET PARAMETER?
(SENSOR A )
```

```
SET 4mA VALUE?
(10.22 uS/cm )
```

Use the \Leftarrow and \Rightarrow keys to "coarse" adjust numerical values. The \uparrow and \downarrow keys "fine" adjust numerical values up or down respectively. The longer the key is pressed, the faster the number changes.

2.5 Entering (Storing) Edit/Selection Screen Values/Choices



After the desired value/choice is displayed, press the **ENTER** key to enter (store) it into the non-volatile analyzer memory. The previous screen will then re-appear.

NOTE: You can always press the **ESC** key to abort saving a new setting. The original setting will be retained.

SECTION 3






CONFIGURING THE ANALYZER



NOTE: When the passcode feature is enabled (Section 3.7), you must successfully enter the passcode before attempting to enter a configuration setting.

3.1 Selecting Language to Operate Analyzer

The analyzer can display screens in various languages including English, French (Français), German (Deutsche), Spanish (Español), and others. The analyzer is factory-set for English. To change languages:

1. Press **MENU** key to display .
2. Press **↓** key once to display .
3. Press **ENTER** key to display .
4. Press **↓** key six times to display .
5. Press **ENTER** key to display . Use **↓** and **↑** keys to view the language choices.
6. With the desired language displayed, press **ENTER** key to enter this selection.



NOTE: After a language is selected and entered, all screens are displayed in that language.

3.2 Configuring Sensor (A and B) Characteristics




The analyzer can be used with one or two sensors, providing up to two separate measurement channels. Each sensor can be independently selected to measure a different parameter. Also, each sensor can have a different nominal cell constant.

The analyzer must be configured to define the characteristics of each sensor including its "K" value, temperature element type, "T" factor, and other related items such as temperature compensation, input signal filtering, pulse suppression, etc. **When using two sensors, configure them in the same way using their respective menu screens.**






Selecting Measurement (CONDUCTIVITY, RESISTIVITY, or TDS)

NOTE: For calculated Sensor A and B measurements (% reject, % pass, ratio A/B, ratio B/A, diff. A-B, or diff. B-A), both sensors must be configured for the same measurement (conductivity, resistivity, or TDS). However, each sensor may be set for a different display format and a different cell constant.

1. With the  screen displayed, press  **key once** to display .

2. Press **ENTER** key to display .

3. Press **ENTER** key again to display . Use  and  keys to view the three choices:

- **CONDUCTIVITY:** Selects system to measure conductivity.
- **RESISTIVITY:** Selects system to measure resistivity.
- **TDS:** Selects system to measure total dissolved solids.

WARNING:

CHANGING THE SENSOR MEASUREMENT AUTOMATICALLY REPLACES ALL USER-ENTERED VALUES WITH FACTORY-DEFAULT VALUES.

4. With the desired choice displayed, press **ENTER** key to enter this selection.

Selecting Measurement Display Format

After choosing the measurement, select the desired MEASURE screen display format. The selected units and resolution will also appear on all applicable edit/selection menu screens.




The nominal cell constant of a sensor determines the sensor's inherent measuring range. Table A lists cell constants and their respective measuring ranges. When configuring the measuring units and display resolution for your application, make sure they are within the sensor's inherent listed range. If not, choose a sensor with the appropriate constant.




Table A – SENSOR CELL CONSTANTS and MEASURING RANGES

Sensor Cell Constant	Inherent Measuring Range		
	Conductivity (in $\mu\text{S}/\text{cm}$)	Resistivity (in $\text{M}\Omega \cdot \text{cm}$)	TDS (in ppm)
0.05	0-100	0.002-20	See Note below
0.5	0-1000	0.001-20	See Note below
1	0-2000	not applicable	See Note below
5	0-10,000	not applicable	See Note below
10	0-200,000	not applicable	See Note below



NOTE: To determine which cell constant to use, convert the full-scale TDS value to its equivalent conductivity value at 25°C. Do this by multiplying the TDS value by "2." Then find the range in the Conductivity column corresponding to the calculated value. The cell constant to use is in that row.

1. With the  **SELECT MEASURE** screen displayed, press  **key once** to display  **DISPLAY FORMAT**.




2. Press **ENTER** key to display . Use  **and**  **keys** to view all choices. Depending on the sensor's selected measurement, the choices are:

For CONDUCTIVITY		For RESISTIVITY
2.000 $\mu\text{S}/\text{cm}$	2.000 mS/cm	XX.XX $\text{M}\Omega \cdot \text{cm}$
20.00 $\mu\text{S}/\text{cm}$	20.00 mS/cm	XXX.X $\text{K}\Omega \cdot \text{cm}$
200.0 $\mu\text{S}/\text{cm}$	200.0 mS/cm	
2000 $\mu\text{S}/\text{cm}$	2000 mS/cm	
		For TDS
		XXXX ppm
		XXXX ppb

3. With the desired choice displayed, press **ENTER** key to enter this selection.

Selecting Temperature Compensation

Configure the required type of temperature compensation for the selected measurement.

1. With the  **DISPLAY FORMAT** screen displayed, press  **key once** to display  **T-COMPENSATION**.

2. Press **ENTER** key to display T-COMPENSATION?
(LINEAR). Use
↓ and ↑ keys to view all choices:

- **LINEAR** (recommended for most aqueous solutions)
- **AMMONIA** (not shown for TDS measurement; only use this built-in temperature properties table for specific applications -- consult factory)
- **NATURAL WATER** (not shown for TDS measurement; only use this built-in temperature properties table for specific applications -- consult factory)
- **OPTIONAL TABLE*** (user-specified temperature table)
- **NONE** (measurement values are not compensated)

* Only select OPTIONAL TABLE choice when the analyzer is equipped with a customer-specified, factory-configured temperature compensation table.

NOTE: The factory default for temperature compensation is **LINEAR** with a 2.00% per °C slope and 25.0°C reference temperature. This provides the best results for most aqueous solutions. To enter different slope and reference temperature values for an uncommon solution, refer to subheading "Configuring Selected Temp. Compensation" for details.

3. With the desired choice displayed, press **ENTER** key to enter this selection.

Configuring TDS
Measurement
(not needed for
other measurements)

Only when TDS is selected must the measurement be further configured by defining a conductivity-to-TDS conversion factor. If CONDUCTIVITY or RESISTIVITY was selected, disregard this subsection -- no measurement configuration is needed.

1. With the ≡SENSOR A
▶T-COMPENSATION↕ screen displayed, press
↓ key once to display ≡SENSOR A
▶CONFIG TDS ↕.
2. Press **ENTER** key to display ≡CONFIG TDS
▶SELECT FACTOR ↓.

3. Press **ENTER** key again to display SELECT FACTOR?
(NaCl).
Use **↓** and **↑** keys to view both choices:
- **NaCl:** Configures analyzer to use the built-in NaCl conductivity-to-TDS conversion factor.
 - **USER DEFINED:** Configures analyzer to use a user-entered conductivity-to-TDS conversion factor.
4. With the desired choice displayed, press **ENTER** key to enter this selection. If the "NaCl" conversion factor was selected, TDS measurement configuration is complete. If you selected "USER DEFINED," you must enter a conductivity-to-TDS conversion factor:

A. With the ≡CONFIG TDS
▶SELECT FACTOR ↓ screen displayed, press **↓** key once to display ≡CONFIG TDS
▶SET FACTOR ⇅.

B. Press **ENTER** key to display SET FACTOR?
(0.492 ppm/uS).

C. Adjust the displayed value to the desired conductivity-to-TDS conversion factor, and press **ENTER** key to enter the value. (Use **⇒** and **⇐** keys for coarse adjust; **↑** and **↓** keys for fine adjust.)

D. After the ≡CONFIG TDS
▶SET FACTOR ⇅ screen re-appears, press **ESC** key once to return to the ≡SENSOR A
▶CONFIG TDS ⇅ screen.

Configuring LINEAR
Temperature Compensation
(not needed for other
compensation methods)



Only when LINEAR is the selected temperature compensation, determine if it should be further configured by entering a slope, in % per °C, and a reference temperature. If the built-in AMMONIA or NATURAL WATER properties table or NONE was selected, disregard this subsection -- no compensation configuration is needed.

NOTE: If "OPTIONAL TABLE" compensation was selected, the analyzer must be equipped with a customer-specified, factory-configured temperature compensation table.

LINEAR compensation factory defaults are 2.00%/°C slope and 25.0° reference temperature. These values are appropriate for most aqueous solutions. Use chemical handbook tables to find values for uncommon solutions. To enter different values, do the following:

1. With the

≡	SENSOR A
▶	T-COMPENSATION

 screen displayed, press \downarrow **key twice**.

(If the

≡	SENSOR A
▶	CONFIG TDS

 screen is displayed, press \downarrow **key just once**.)

In either case, the

≡	SENSOR A
▶	CONFIG LINEAR

 screen appears.

2. Press **ENTER key** to display

≡	CONFIG LINEAR
▶	SET SLOPE

 \downarrow .

3. Press **ENTER key** again to display

SET SLOPE?
(2.00 %/°C)

.

4. Adjust the displayed value to the desired % per °C slope, and press **ENTER key** to enter the value. (Use \Rightarrow and \Leftarrow **keys** for coarse adjust; \uparrow and \downarrow **keys** for fine adjust.)

5. After the

≡	CONFIG LINEAR
▶	SET SLOPE

 \downarrow screen re-appears, press \downarrow **key once** to display

≡	CONFIG LINEAR
▶	SET REF TEMP

.

6. Press **ENTER key** to display

SET REF TEMP?
(25.0 °C)

.

7. Adjust the displayed value to the desired reference temperature, and press **ENTER key** to enter it. (Use \Rightarrow and \Leftarrow **keys** for coarse adjust; \uparrow and \downarrow **keys** for fine adjust.)

8. After the

≡	CONFIG LINEAR
▶	SET REF TEMP


 \downarrow screen re-appears, press **ESC key once** to return to the


≡	SENSOR A
▶	CONFIG LINEAR


 screen.



Entering Sensor's OMEGA-certified "K" Value



Each OMEGA sensor has a unique, certified "K" value shown on a label attached to the sensor cable or to the inside cover of its optional junction box head. By entering this "K" value, calibration (including zeroing) is only necessary when this sensor is replaced. This also sets the analyzer measuring range to match the inherent range of the sensor's cell constant.


1. With the  screen displayed, press **↓** key three times.



(If the  screen is displayed, press **↓** key once.)

In either case, the  screen appears.

2. Press **ENTER** key to display .
3. Press **ENTER** key again to display .
4. Use **↓** and **↑** keys to select the nominal cell category that corresponds to the sensor's OMEGA-certified "K" value, and press **ENTER** key to enter this selection.









5. After the  screen re-appears, press **↓** key once to display .

6. Press **ENTER** key to display .
7. Adjust the displayed value to exactly match the sensor's OMEGA-certified "K" value, and press **ENTER** key to enter the value. (Use **⇒** and **⇐** keys for coarse adjust; **↑** and **↓** keys for fine adjust.)

8. After the  screen re-appears, press **ESC** key once to return to the  screen.







Setting Sensor Signal Filter Time

A time constant (in seconds) can be set to filter or “smooth out” the sensor signal. A minimum value of “0 seconds” has no smoothing effect. A maximum value of “60 seconds” provides maximum smoothing. Deciding what sensor signal filter time to use is a compromise. The higher the filter time, the longer the sensor signal response time will be to a change in the actual process value.

1. With the  screen displayed, press  **key** once to display  .
2. Press **ENTER** key to display  .
3. Adjust the displayed value to the desired filter time, and press **ENTER** key to enter this value. (Use  and  keys for coarse adjust;  and  keys for fine adjust.)




Selecting Pulse Suppression (on/off)


Sometimes an external interference may occasionally cause the measurement system to provide unstable readings. Common causes include entrained gas bubbles in the process, and electromagnetic interference (EMI or “electrical noise” pulses). The analyzer has a pulse suppression feature to counteract this condition and stabilize readings. Example: Suppose the analyzer reading is steadily showing 1880 $\mu\text{S}/\text{cm}$, then suddenly jumps to 1950 $\mu\text{S}/\text{cm}$ for a few seconds, and returns to 1880 $\mu\text{S}/\text{cm}$. By turning on this feature, the analyzer will perceive this as a temporary upset, “suppressing” most of this pulse change and providing a smoother measurement reading.






1. With the  screen displayed, press  **key** once to display  .
2. Press **ENTER** key to display  . Use  and  keys to view both choices (OFF or ON).
3. With the desired choice displayed, press **ENTER** key to enter this selection.

Changing Top Line Notation on MEASURE Screen (only COND A and B readouts)

The top line of the four MEASURE screen readouts that separately show measurement and temperature values are factory set to read "COND A" and "COND B." These notations can be changed, for example, to "BASIN 1" and "BASIN 2" to tailor the analyzer MEASURE screen to the application. The respective top lines would then be "MEASURE BASIN 1" and "MEASURE BASIN 2." Each notation is limited to eight characters which can be a combination of capital letters A through Z, numbers 0 through 9, and spaces.

1. With the  screen displayed, press  **key** once to display .

2. Press **ENTER** key to display . Create the desired notation within the second line's parenthesis:

- A. Starting with the extreme left character position, use  **and**  **keys** to select the desired first character.
- B. Press  **key** to access the second character position. Use  **and**  **keys** to select the desired second character.
- C. Repeat procedure until desired notation is displayed.



3. Press **ENTER** key to enter the displayed notation.

Configure the analyzer to define the temperature element being used for temperature compensation.


It is recommended that the CDCN684 is used with the CDE680 series sensors only which have PT 1000 temperature compensation.

Selecting Temperature Element Type

NOTE: When not using a temperature element, select "MANUAL" for the element type and enter a temperature for fixed temperature compensation. Also, when using only one sensor, select "MANUAL" for the unused sensor input element type. In either case, this prevents (or clears) a "WARNING: CHECK STATUS" message due to the analyzer detecting no temperature element.



1. With the  screen displayed, press \downarrow **key once** to display .

2. Press **ENTER key** to display .

3. Press **ENTER key** again to display . Use \downarrow and \uparrow **keys** to view the three choices:

- **PT1000:** Configures analyzer for use with a Pt 1000 RTD temperature element (used in all OMEGA Model 3400-series contacting conductivity sensors).
- **PT100:** Configures analyzer for use with a Pt 100 RTD temperature element.
- **MANUAL:** Configures analyzer for fixed manual temp. compensation when not using a temperature element.

4. With the desired choice displayed, press **ENTER key** to enter this selection. If "MANUAL" was selected, set a desired fixed manual temperature compensation value:

- A. With the  screen displayed, press \downarrow **key once** to display .

- B. Press **ENTER key** to display .



- C. Adjust displayed value to the desired fixed temperature, and press **ENTER key** to enter it. (Use \Rightarrow and \Leftarrow **keys** for coarse adjust; \uparrow and \downarrow **keys** for fine adjust.)

Entering Sensor's OMEGA-certified "T" Factor

OMEGA tests each sensor to provide a unique, certified temperature "T" factor because:

- Temperature greatly affects conductivity measurement accuracy.
- The inherent ohm value of the Pt 1000 RTD temperature element varies slightly from sensor to sensor, affecting temperature measurement accuracy.

By entering the sensor's unique "T" factor, you enable the analyzer to provide the highest possible measuring accuracy for both temperature and conductivity.

With the  screen displayed, press  key once to display

2. Press **ENTER** key to display .

3. Use **↑** and **↓** keys to adjust the displayed value to exactly match the sensor's OMEGA-certified "T" factor, and press **ENTER** key to enter the value.



SPECIAL CASE – ALTERED SENSOR CABLE LENGTH
(only for sensors with PT 1000 temperature elements*)

Changing the standard 20 ft. (6 m) sensor cable length, by shortening it or adding an interconnect cable, will affect temperature measuring accuracy. The OMEGA-certified "T" factor is based on standard cable length. To compensate for altered cable length measuring error, change the certified "T" factor entry:

- Shortened Sensor Cable: To increase the analyzer temperature reading to match the known solution temperature, decrease the "T" factor by 3.85 ohms for each °C difference.
- Added Interconnect Cable: To decrease the analyzer temperature reading to match the known solution temperature, increase the "T" factor by 3.85 ohms for each °C difference.

Example: Suppose the known solution temperature is 50°C and the analyzer reads 53°C due to interconnect cable resistance. Multiply the 3°C difference by 3.85 ohms to get 11.55. Then increase the sensor "T" factor by adding 11.55 to it and entering that value. If, due to a shortened sensor cable, the analyzer was reading 3°C less than the known solution temperature you would decrease the sensor "T" factor by subtracting 11.55 from it.

*Sensors with PT100 temperature elements provide inherently less accurate temperature readings and are not recommended.

4. After the  screen re-appears, press **ESC** key twice to return to the  screen:

3.3 Configuring Calculated Sensor A and B Measurement










Selecting Calculated Measurement (none, % reject, % pass, ratio A/B, ratio B/A, diff. A-B, or diff. B-A)

Selecting Calculated RATIO A/B or RATIO B/A Measurement Display Format (not needed for other calculated measurements)




The analyzer can provide a calculated measurement by using the measured Sensor A and Sensor B values. The calculated measurement can be displayed, and an analog output and/or relay can be assigned to represent it.

NOTE: For a calculated measurement, both sensors must be:




- Connected and used.
- Configured for the same measurement (conductivity, resistivity, or TDS).
- Set for the same measurement units. However, each sensor can have a different cell constant providing an inherently different measuring range.

1. With the  screen displayed, press  **key twice** to display .
2. Press **ENTER key** to display .
3. Press **ENTER key** again to display . Use  and  **keys** to view the choices (NONE, % REJECT, % PASS, RATIO A/B, RATIO B/A, DIFF A-B, or DIFF B-A).
4. With the desired choice displayed, press **ENTER key** to enter this selection.


Only when RATIO A/B or RATIO B/A is the selected calculated measurement must its display format be further configured. If % REJECT or % PASS was selected, disregard this subsection -- no display format configuration is needed. If DIFF A-B or DIFF B-A was selected, the display format is automatically set by the Sensor A and B display format selections -- no format configuration is needed.


1. With the  screen displayed, press  **key once** to display .


3.4 Selecting Temperature Display Format (°C or °F)


2. Press **ENTER** key to display . Use **↓** and **↑** keys to view the four choices (XXXX, XXX.X, XX.XX or X.XXX).
3. With the desired choice displayed, press **ENTER** key to enter this selection.
4. After the  screen re-appears, press **ESC** key once to return to  screen:

The MEASURE screen can be set to display temperature values in °C or °F. In either case, the display resolution for measured temperature is always "XX.X."

1. With the  screen displayed, press **↑** key -- not **↓** key -- twice.

(If the  screen is displayed, press **↑** key -- not **↓** key -- four times.)

In either case, the  screen appears.

2. Press **ENTER** key to display . Use **↓** and **↑** keys to view both choices (°C or °F).
3. With the desired choice displayed, press **ENTER** key to enter this selection.

3.5 Configuring Outputs (1 and 2)









The analyzer provides two isolated analog outputs (#1 and #2). **Configure both outputs in the same way using their respective menu screens.**

Assigning Representative Parameter

Depending on the system setup, each output can be assigned to represent one of the following:









- Measured Sensor A conductivity, resistivity, or TDS.
- Measured Sensor A temperature.
- Measured Sensor B conductivity, resistivity, or TDS.
- Measured Sensor B temperature.
- *Calculated Sensor A and B measurement (% reject, % pass, ratio A/B, ratio B/A, diff. A-B, or diff. B-A).




*An analog output can only represent the calculated measurement when two sensors are used and the analyzer has been correctly configured for CALCULATION.

1. With the  screen displayed, press  **key** -- not  **key** -- five times to display .
2. Press **ENTER** key to display .
3. Press **ENTER** key again to display . Use  and  **keys** to view the choices.
4. With the desired choice displayed, press **ENTER** key to enter this selection.

Setting Parameter Values for 0/4 mA and 20 mA

You can set the parameter (or calculated measurement) values to define the endpoints at which the minimum and maximum output values are desired.

1. With the  screen displayed, press  **key** once to display .
2. Press **ENTER** key to display a screen like .
3. Set the displayed value at which 0/4 mA is desired, and press **ENTER** key to enter the value. (Use  and  **keys** for coarse adjust;  and  **keys** for fine adjust.)

4. After the  screen re-appears, press  **key** once to display .

5. Press **ENTER** key to display .

6. Set the displayed value at which 20 mA is desired, and press **ENTER** key to enter the value.






NOTE: If the same values are set for 0/4 mA and 20 mA, the output automatically goes to, and remains at, 20 mA.





Setting Transfer Value (mA)

Normally, each analog output is active, responding to the measured value of its assigned parameter. During calibration, however, you can transfer (XFER) each output to a preset value to operate a control element by an amount corresponding to that value.

To set a milliamp transfer value for an analog output to suit your application:

1. With the  screen displayed, press  **key** once to display .









2. Press **ENTER** key to display .

3. Set the displayed value to the desired transfer value, and press **ENTER** key to enter it. (Use  and  keys for coarse adjust;  and  keys for fine adjust.)







Setting Output Filter Time

A time constant (in seconds) can be set to filter or "smooth out" the output signal. A minimum value of "0 seconds" has no smoothing effect. A maximum value of "60 seconds" provides maximum smoothing. Deciding what output filter time to use is a compromise. The higher the filter time, the longer the output signal response time will be to a change in the measured value.

Setting Output Scale Low Endpoint (0/4 mA)

1. With the  screen displayed, press  **key once** to display  .
2. Press **ENTER** key to display  .
3. Adjust the displayed value to the desired filter time, and press **ENTER** key to enter it. (Use  and  keys for coarse adjust;  and  keys for fine adjust.)

Each output can be set to be 0-20 mA or 4-20 mA.

1. With the  screen displayed, press  **key once** to display  .
2. Press **ENTER** key to display  . Use  and  keys to view both choices (0mA or 4mA).
3. With the desired choice displayed, press **ENTER** key to enter this selection.

3.6 Configuring Relays (A and B)

The analyzer is equipped with two electromechanical relays (A and B). Each relay can be set to function as a control, alarm, or status relay. Only a control or alarm relay operates in response to the measured value. For details on each relay function, see subsection "Selecting Function Mode."

Configure both relays in the same way using their respective menu screens.



During calibration, control and alarm relays can be held, transferred to preset on/off states, or remain active. During normal measurement operation, these relays can be held in their present on/off states for up to 30 minutes by using the "HOLD OUTPUTS" function in the TEST/MAINT menu.

Assigning
Representative Parameter

Depending on the system setup, each control or alarm relay can be assigned to use one of the following for its operation:


- Measured Sensor A conductivity, resistivity, or TDS.
- Measured Sensor A temperature.
- Measured Sensor B conductivity, resistivity, or TDS.
- Measured Sensor B temperature.
- *Calculated Sensor A and B measurement (% reject, % pass, ratio A/B, ratio B/A, diff. A-B, or diff. B-A).

*A relay can only use the calculated measurement for its operation when two sensors are used and the analyzer has been correctly configured for CALCULATION.

1. With the  screen displayed, press **ESC** key once to display .

2. Press **↓** key twice to display .

3. Press **ENTER** key to display .



4. Press **ENTER** key again to display . Use **↓** and **↑** keys to view the choices.

5. With the desired choice displayed, press **ENTER** key to enter this selection.

Selecting Function Mode
(alarm, control, or status)

Each relay can be selected to function as a:

- **Dual-alarm relay** (with separate high and low alarm points and deadbands) that operates in response to the selected measured value.
- **Control relay** (with phasing, setpoint, deadband, and overfeed timer) that operates in response to the selected measured value.
- **Status relay** that is not configurable. It is a dedicated system diagnostic-only alarm relay that automatically energizes when the "WARNING CHECK STATUS" message flashes on the MEASURE screen. This occurs when the analyzer detects a sensor or analyzer "FAIL" diagnostic condition (see Part Three, Section 5.1 for details).

1. With the  screen displayed, press **↓** key once to display .

Selecting Transfer Mode (relay on or off)

2. Press **ENTER** key to display SET FUNCTION?
(ALARM). Use \downarrow and \uparrow keys to view the choices (ALARM, CONTROL, or STATUS).
3. With the desired choice displayed, press **ENTER** key to enter this selection.

Normally, each control or alarm relay is active, responding to the measured value of its assigned parameter. During calibration, however, you can transfer each relay to a preset on/off state.

To set a relay on/off transfer state for a control or alarm relay to suit your application:

1. With the SET RELAY A
▶SET FUNCTION ◀ screen displayed, press \downarrow key once to display SET RELAY A
▶SET TRANSFER ◀.
2. Press **ENTER** key to display SET TRANSFER?
(DE-ENERGIZED). Use \downarrow and \uparrow keys to view both choices (DE-ENERGIZED or ENERGIZED).
3. With the desired choice displayed, press **ENTER** key to enter this selection.

Setting Activation (Configuration) Values

The group of configuration settings available to a relay is dependent on its selected function mode (alarm or control). **Relays set for status function mode are not configurable.** Table B describes all relay configuration settings, categorized by relay function mode:

Table B -- RELAY CONFIGURATION SETTINGS	
Setting	Description
For Alarm Relay	
Low Alarm	Sets the value at which the relay will turn on in response to <u>decreasing</u> measured value.
High Alarm	Sets the value at which the relay will turn on in response to <u>increasing</u> measured value.
Low Deadband	Sets the range in which the relay remains on after the measured value <u>increases above the low alarm value</u> .

Table B -- RELAY CONFIGURATION SETTINGS (continued)	
Setting	Description
For Alarm Relay (continued)	
High Deadband	Sets the range in which the relay remains on after the measured value <u>decreases below</u> the <u>high alarm value</u> .
Off Delay	Sets a time (0-300 seconds) to delay the relay from normally turning <u>off</u> .
On Delay	Sets a time (0-300 seconds) to delay the relay from normally turning <u>on</u> .
For Control Relay	
Phase	A "high" phase assigns the relay setpoint to respond to increasing measured value; conversely, a "low" phase assigns the relay setpoint to respond to decreasing measured value.
Setpoint	Sets the value at which the relay will turn on.
Deadband	Sets the range in which the relay remains on after the measured value decreases below the setpoint value (high phase relay) or increases above the setpoint value (low phase relay).
Overfeed Timer	Sets the time (0-999.9 min.) to limit how long the relay can remain "on." For more details on overfeed timer operation, see Part Three, Section 6.
Off Delay	Sets a time (0-300 seconds) to delay the relay from normally turning <u>off</u> .
On Delay	Sets a time (0-300 seconds) to delay the relay from normally turning <u>on</u> .



NOTE: When a relay is set to function as a status relay, the ▷ symbol at the start of the "ACTIVATION" line denotes that this menu item is not relevant and, therefore, not available.

Also, it is possible to enter values which always keep a relay active or inactive. To avoid this, be sure that "low" values are lower than "high" values.

The "off delay" and "on delay" settings, available to control or alarm function relays, may be beneficial in eliminating process "overshoot" when there are long process pipe runs or delays in mixing.

To set Relay A configuration values:

- With the

≡SET RELAY A
▷SET TRANSFER ⇅

 screen displayed, press
 ↓ key once to display

≡SET RELAY A
▷ACTIVATION ⇅

.

3.7 Enabling/Disabling Passcode







2. Press **ENTER** key to display the first respective relay function "ACTIVATION" screen setting.
3. Use the same basic keypad operations described in previous setup procedures to enter the desired value for the displayed relay activation setting.
4. Repeat this procedure for each relay activation setting.

The analyzer has a passcode feature to restrict access to configuration and calibration settings to only authorized personnel.

- **DISABLED:** With the passcode feature disabled, all configuration settings can be displayed and changed, and the analyzer can be calibrated.
- **ENABLED:** With the passcode feature enabled, all configuration settings can be displayed -- but they cannot be changed -- and the analyzer cannot be calibrated. When you attempt to change a setting by pressing the **ENTER** key, a displayed notification requests passcode entry. A valid passcode entry saves the changed setting and returns the display to the "MAIN MENU" branch selection screen. An incorrect passcode entry causes the display to momentarily show an error notification and return to the "MAIN MENU" branch selection screen. There is no limit on attempts to enter a valid passcode.

The passcode is factory set to "3 4 5 6." It cannot be changed.

To enable or disable the passcode feature:

1. With the  screen displayed, press  **key four times** to display .
2. Press **ENTER** key to display . Use  **and**  **keys** to view both choices (DISABLED or ENABLED).
3. With the desired choice displayed, press **ENTER** key to enter this selection.

3.8 Summary of Configuration Settings

Table C lists all configuration settings and their entry ranges/choices and factory defaults, categorized by basic functions.

Table C – ANALYZER CONFIGURATION SETTINGS (RANGES/CHOICES and DEFAULTS)			
Displayed Screen Title	Entry Range or Choices (where applicable)	Factory Default	Your Setting
LANGUAGE Configuration Setting			
LANGUAGE?	ENOMEGASH, FRENCH, GERMAN, SPANISH, etc.	ENOMEGASH	
SENSOR A and B Configuration Settings			
SELECT MEASURE?	CONDUCTIVITY, RESISTIVITY, or TDS	CONDUCTIVITY	
DISPLAY FORMAT? (full scale value)	CONDUCTIVITY: μS/cm: 2.000, 20.00, 200.0, or 2000 mS/cm: 2.000, 20.00, 200.0, or 2000 RESISTIVITY: XX.XX MΩ • cm or XXX.X KΩ • cm TDS: XXXX ppm or XXXX ppb	CONDUCTIVITY: For 0.05 cell: 20.00 μS/cm For 0.5 cell: 200.0 μS/cm For 1.0 cell: 2000 μS/cm For 5.0 cell: 20.00 mS/cm For 10 cell: 200.0 mS/cm RESISTIVITY: XX.XX MΩ • cm TDS: XXXX ppm	
T-COMPENSATION?	LINEAR, AMMONIA, NATURAL WATER, OPTIONAL TABLE, or NONE	Sensor A: LINEAR at 2.00% per °C with 25.0°C reference temp. Sensor B: MANUAL	
TDS: SELECT FACTOR?	NaCl or USER DEFINED	NaCl	
TDS: SET FACTOR?	0.01-99.99 ppm/μS	0.492 ppm/μS	
LINEAR: SET SLOPE?	0-4.00% per °C	2.00% per °C	
LINEAR: SET REF TEMP?	0-200.0°C or 32-392°F	25.0°C or 77°F	
SELECT CELL K?	0.05, 0.5, 1.0, 5.0, or 10	1.0	
SET CELL K?	0.0500-10.0000	1.0000	
SET FILTER?	0-60 seconds	0 seconds	
PULSE SUPPRESS?	OFF or ON	OFF	
ENTER NOTE?	Enter up to eight characters to replace COND A or COND B	COND A and COND B	
TEMP ELE: SELECT TYPE?	PT1000, PT100, or MANUAL	PT1000	
TEMP ELEMENT: SET T FACTOR?	950-1050 ohms or 95-105 ohms	1000 OHMS	
TEMP ELE: SET MANUAL?	0.0-200.0°C	25.0°C	
CALCULATION Configuration Settings (Sensor A and B)			
SELECT MEASURE?	NONE, % REJECT, % PASS, RATIO (A/B), RATIO (B/A), DIFF (A-B), or DIFF (B-A)	NONE	
DISPLAY FORMAT?	% REJECT: non-selectable % PASS: non-selectable RATIO: XXXX, XXX.X, XX.XX, or X.XXX DIFF: Same ranges as those listed in "SENSOR A and B Configuration Settings" category above	% REJECT: 0-100% % PASS: 0-100% RATIO A/B or B/A: XXXX DIFF: Same defaults as those listed in "SENSOR A and B Configuration Settings" category above	Not applicable Not applicable

(Table C continued on next page.)

Table C -- ANALYZER CONFIGURATION SETTINGS (RANGES/CHOICES and DEFAULTS -- continued)			
Displayed Screen Title	Entry Range or Choices (where applicable)	Factory Default	Your Setting
TEMPERATURE Display Configuration Setting			
CONFIGURE: °C OR °F?	°C or °F	°C	
OUTPUT Configuration Settings			
SET PARAMETER?	SENSOR A, SENSOR B, TEMPERATURE A, TEMPERATURE B, or CALCULATED	Output 1: SENSOR A Output 2: SENSOR B	
SET 4mA VALUE?	CONDUCTIVITY: μS/cm: 0-2,000, 0-20.00, 0-200.0, or 0-2000 mS/cm: 0-2,000, 0-20.00, 0-200.0, or 0-2000 RESIST: 0-19.99 MΩ • cm or 0-999.9 KΩ • cm TDS: 0-9999 ppm or 0-9999 ppb TEMP: -20.0 to +200.0°C or -4.0 to 392.0°F	CONDUCTIVITY: 0 μS/cm or 0 mS/cm RESIST: 0 MΩ or 0 KΩ • cm TDS: 0 ppm or 0 ppb TEMP: 0.0°C or 32.0°F	
SET 20mA VALUE?	CONDUCTIVITY: μS/cm: 0-2,000, 0-20.00, 0-200.0, or 0-2000 mS/cm: 0-2,000, 0-20.00, 0-200.0, or 0-2000 RESIST: 0-19.99 MΩ • cm or 0-999.9 KΩ • cm TDS: 0-9999 ppm or 0-9999 ppb TEMP: -20.0 to +200.0°C or -4.0 to 392.0°F	CONDUCTIVITY: μS/cm: 2,000, 20.00, 200.0, or 2000 mS/cm: 2,000, 20.00, 200.0, or 2000 RESIST: 19.99 MΩ or 999.9 KΩ • cm TDS: 9999 ppm or 9999 ppb TEMP: 200.0°C or 392.0°F	
SET TRANSFER?	0-20 mA or 4-20 mA	All Outputs: 12 mA	
SET FILTER?	0-60 seconds	All Outputs: 0 seconds	
SCALE 0mA/4mA?	0mA or 4mA	All Outputs: 4 mA	
RELAY Configuration Settings			
Settings Common To Alarm and Control Relays:			
SET PARAMETER?	SENSOR A, SENSOR B, TEMPERATURE A, TEMPERATURE B, or CALCULATED	Relay A: SENSOR A Relay B: SENSOR B	
SET FUNCTION?	ALARM, CONTROL, or STATUS	All Relays: ALARM	
SET TRANSFER?	DE-ENERGIZED or ENERGIZED	All Relays: DE-ENERGIZED	
OFF DELAY?	0-300 seconds	0 seconds	
ON DELAY?	0-300 seconds	0 seconds	
Settings For Alarm Relays Only:			
LOW ALARM?	CONDUCTIVITY: μS/cm: 0-2,000, 0-20.00, 0-200.0, or 0-2000 mS/cm: 0-2,000, 0-20.00, 0-200.0, or 0-2000 RESIST: 0-19.99 MΩ • cm or 0-999.9 KΩ • cm TDS: 0-9999 ppm or 0-9999 ppb TEMP: -20.0 to +200.0°C or -4.0 to 392.0°F	CONDUCTIVITY: 0 μS/cm or 0 mS/cm RESIST: 0 MΩ or 0 KΩ • cm TDS: 0 ppm or 0 ppb TEMP: 0.0°C or 32.0°F	

(Table C continued on next page.)

Table C -- ANALYZER CONFIGURATION SETTINGS (RANGES/CHOICES and DEFAULTS -- continued)			
Displayed Screen Title	Entry Range or Choices (where applicable)	Factory Default	Your Setting
RELAY Configuration Settings (continued)			
Settings For Alarm Relays Only (continued):			
HIGH ALARM?	CONDUCTIVITY: $\mu\text{S/cm}$: 0-2.000, 0-20.00, 0-200.0, or 0-2000 mS/cm : 0-2.000, 0-20.00, 0-200.0, or 0-2000 RESIST: 0-19.99 $\text{M}\Omega \cdot \text{cm}$ or 0-999.9 $\text{K}\Omega \cdot \text{cm}$ TDS: 0-9999 ppm or 0-9999 ppb TEMP: -20.0 to +200.0°C or -4.0 to 392.0°F	CONDUCTIVITY: $\mu\text{S/cm}$: 2.000, 20.00, 200.0, or 2000 mS/cm : 2.000, 20.00, 200.0, or 2000 RESIST: 19.99 $\text{M}\Omega$ or 999.9 $\text{K}\Omega \cdot \text{cm}$ TDS: 9999 ppm or 9999 ppb TEMP: 200.0°C or 392.0°F	
LOW DEADBAND?	CONDUCTIVITY: 0-10% of range RESISTIVITY: 0-10% of range TDS: 0-10% of range TEMPERATURE: 0-10% of range	COND: 0 $\mu\text{S/cm}$ or 0 mS/cm RESIST: 0 $\text{M}\Omega$ or 0 $\text{K}\Omega \cdot \text{cm}$ TDS: 0 ppm or 0 ppb TEMP: 0.0°C or 0.0°F	
HIGH DEADBAND?	CONDUCTIVITY: 0-10% of range RESISTIVITY: 0-10% of range TDS: 0-10% of range TEMPERATURE: 0-10% of range	COND: 0 $\mu\text{S/cm}$ or 0 mS/cm RESIST: 0 $\text{M}\Omega$ or 0 $\text{K}\Omega \cdot \text{cm}$ TDS: 0 ppm or 0 ppb TEMP: 0.0°C or 0.0°F	
Settings For Control Relays Only:			
PHASE?	HIGH or LOW	For Relays A and B: HIGH	
SET SETPOINT?	CONDUCTIVITY: $\mu\text{S/cm}$: 0-2.000, 0-20.00, 0-200.0, or 0-2000 mS/cm : 0-2.000, 0-20.00, 0-200.0, or 0-2000 RESIST: 0-19.99 $\text{M}\Omega \cdot \text{cm}$ or 0-999.9 $\text{K}\Omega \cdot \text{cm}$ TDS: 0-9999 ppm or 0-9999 ppb TEMP: -20.0 to +200.0°C or -4.0 to 392.0°F	CONDUCTIVITY: $\mu\text{S/cm}$: 2.000, 20.00, 200.0, or 2000 mS/cm : 2.000, 20.00, 200.0, or 2000 RESIST: 19.99 $\text{M}\Omega$ or 999.9 $\text{K}\Omega \cdot \text{cm}$ TDS: 9999 ppm or 9999 ppb TEMP: 200.0°C or 392.0°F	
DEADBAND?	CONDUCTIVITY: 0-10% of range RESISTIVITY: 0-10% of range TDS: 0-10% of range TEMPERATURE: 0-10% of range	COND: 0 $\mu\text{S/cm}$ or 0 mS/cm RESIST: 0 $\text{M}\Omega$ or 0 $\text{K}\Omega \cdot \text{cm}$ TDS: 0 ppm or 0 ppb TEMP: 0.0°C or 0.0°F	
OVERFEED TIMER?	0-999.9 minutes	0 minutes	
PASSCODE CONFIGURATION Setting			
SET PASSCODE?	DISABLED or ENABLED	DISABLED	
TEST/MAINTENANCE Simulation Function Settings			
SELECT SIM?	SENSOR A, SENSOR B, TEMPERATURE A, TEMPERATURE B, or CALCULATED	SENSOR A	
SIM SENSOR?	Same ranges as those listed in the "OUTPUT Configuration Settings" category under "SET 4 mA VALUE."	Present measured value of Sensor A's selected parameter.	

SECTION 4

CALIBRATING THE ANALYZER

4.1 Things to Know About Calibration

Each contacting conductivity sensor has a unique zero point and offset. Consequently, **always zero the sensor when calibrating it the first time** (Section 4.2). Zeroing provides the best possible measuring accuracy, and eliminates any discrepancies between Sensor A and B measurement channels. Then calibrate for sensor offset using the DRY method (Section 4.3) or the 1-POINT SAMPLE method (Section 4.4).



Calibration Tip! Conductivity measurement is greatly affected by small changes in temperature. To measure temperature and, therefore, conductivity more accurately, OMEGA highly recommends using the DRY method to calibrate for sensor offset. This is actually a normal part of configuring the sensor characteristics during initial startup. **DRY eliminates the need for conductivity reference solutions.** It also automatically sets the analyzer measuring range to match the inherent range of the sensor's cell constant. Furthermore, DRY eliminates the need to periodically re-calibrate! The only requirement, depending on the application, may be periodic cleaning of the sensor. Only when the sensor is replaced is a new DRY calibration necessary.

In addition to zeroing and calibrating each sensor for offset, you can also calibrate the mA values for each analog output. Refer to Section 4.5 for details.



NOTE: When the passcode feature is enabled (Section 3.7), you must successfully enter the passcode before attempting to calibrate the analyzer.

Also, an in-progress calibration can always be aborted by pressing the ESC key. After the "ABORT: YES?" screen appears, do one of the following:

- Press **ENTER** key to abort. After the "CONFIRM ACTIVE?" screen appears, press **ENTER** key to return the analog outputs and relays to their active states (MEASURE screen appears).
- Press **↑** or **↓** key to choose "ABORT: NO?" screen and press **ENTER** key to continue calibration.



Zeroing/Calibration Tip! If a "CONFIRM FAILURE?" screen appears during zeroing/calibration, press **ENTER** key to confirm. Then, use \uparrow or \downarrow key to select between "CAL REPEAT?" or "CAL EXIT?" and:

- With "CAL REPEAT?" screen selected, press **ENTER** key to repeat zeroing/calibration.
- With "CAL EXIT?" screen selected, press **ENTER** key. After the "CONFIRM ACTIVE?" screen appears, press **ENTER** key to return the analog outputs and relays to their active states (MEASURE screen appears).


4.2 Zeroing Sensor for First-time Calibration

Zero the sensor if it is being calibrated the first time. If not, disregard this section and proceed with sensor offset calibration using the DRY method (Section 4.3) or the 1 POINT SAMPLE CAL method (Section 4.4).


1. Make sure that the sensor is dry before zeroing.

2. Press **MENU** key to display .

3. Press **ENTER** key to display .

4. Press **ENTER** key again to display .

5. Press \downarrow key once to display .

6. Press **ENTER** key to display . Use \uparrow and \downarrow keys to view the three states that the analog outputs (and relays) can be in during zeroing:

- **HOLD OUTPUTS:** Holds their present values.
- **XFER OUTPUTS:** Transfers to preset values.
- **ACTIVE OUTPUTS:** Responds to measured values.

7. With the desired screen displayed, press **ENTER** key to enter this selection.

8. With the "ZERO: IN DRY AIR?" screen displayed and the dry sensor held in air, press **ENTER** key to confirm and to start automatic zeroing.

Entering "K" Value

9. After the "ZERO: CONFIRM ZERO OK?" screen appears, press **ENTER key** to end zeroing.
10. After the "ZERO: CONFIRM ACTIVE?" screen appears, press **ENTER key** to return the analog outputs and relays to their active states (MEASURE screen appears).

This completes zeroing the sensor (first-time calibration only). Now calibrate for sensor offset using the DRY method (Section 4.2) or the 1 POINT SAMPLE method (Section 4.3).





4.3 DRY Calibration Method (highly recommended)








Each Omega's CDE680 Series conductivity sensor has two unique, OMEGA-certified values that must be entered to complete a DRY calibration:

- **Sensor cell "K" value** shown on a label attached to its cable or to the inside cover of its optional junction box.
- **Temperature "T" factor** shown on the same label. (Since the inherent ohm value of the Pt 1000 RTD temperature element built into each sensor varies slightly, OMEGA tests each sensor to provide its specific "T" factor.)

If these two certified values were previously entered during initial setup (Section 3.2 under respective subheadings), DRY calibration is complete. If the certified values have not been entered, follow the steps in the "Entering K Value" and "Entering Temperature T Factor" subsections.






When using both sensors, enter each set of unique values using the respective sensor menu screens.

1. Press **MENU key** to display  .
2. Press **↓ key** once to display  .
3. Press **ENTER key** to display  .
4. Press **↓ key** until you display  .

5. Press **ENTER** key to display  .
6. Press **↓** key until you display  .
7. Press **ENTER** key to display  .
8. Press **ENTER** key again to display a cell category selection screen like  . Use **↑** and **↓** keys to select the nominal cell category that corresponds to the sensor's OMEGA-certified "K" value (shown on label attached to sensor cable or to inside cover of its junction box). Then press **ENTER** key to enter this selection.
9. After the  screen re-appears, press **↓** key once to display  .
10. Press **ENTER** key to display a cell "K" value screen like  . Use **⇒** and **⇐** keys to coarse adjust, and **↑** and **↓** keys to fine adjust the displayed value to exactly match the sensor's OMEGA-certified "K" value. Then press **ENTER** key to enter the value.

After entering the "K" value, complete DRY calibration by entering the OMEGA-certified "T" factor:

Entering Temperature "T" Factor

1. After the  screen re-appears, press **ESC** key once to display  .
2. Press **↓** key until you display  .
3. Press **ENTER** key to display  .
4. Press **↓** key once to display  .

5. Press **ENTER** key to display a "T" factor value screen like SET T FACTOR?
(1000.0 OHMS). Use \Rightarrow and \Leftarrow keys to coarse adjust, and \uparrow and \downarrow keys to fine adjust the displayed value to exactly match the sensor's OMEGA-certified "T" factor. Then press **ENTER** key to enter the value.

SPECIAL CASE -- ALTERED SENSOR CABLE LENGTH
(only for sensors with PT 1000 temperature elements*)

Changing the standard 20 ft. (6 m) sensor cable length, by shortening it or adding an interconnect cable, will affect temperature measuring accuracy. The OMEGA-certified "T" factor is based on standard cable length. To compensate for altered cable length measuring error, change the certified "T" factor entry:

- Shortened Sensor Cable: To increase the analyzer temperature reading to match the known solution temperature, decrease the "T" factor by 3.85 ohms for each °C difference.
- Added Interconnect Cable: To decrease the analyzer temperature reading to match the known solution temperature, increase the "T" factor by 3.85 ohms for each °C difference.

Example: Suppose the known solution temperature is 50°C and the analyzer reads 53°C due to interconnect cable resistance. Multiply the 3°C difference by 3.85 ohms to get 11.55. Then increase the sensor "T" factor by adding 11.55 to it and entering that value. If, due to a shortened sensor cable, the analyzer was reading 3°C less than the known solution temperature you would decrease the sensor "T" factor by subtracting 11.55 from it.

*Sensors with PT100 temperature elements provide inherently less accurate temperature readings and are not recommended.

6. After the TEMP ELEMENT
▶SET T FACTOR ◀ screen reappears, press **MENU** key once and then **ESC** key once to display the MEASURE screen.

This completes OMEGA's DRY calibration.

4.4 1 POINT SAMPLE Method (wet calibration)

This "wet" calibration method requires removing the sensor from the process, immersing it into a properly prepared conductivity reference solution or process sample, and entering the solution's known value. **If using both sensors, calibrate each one in the same way using its respective sensor menu screens.**

1. When using a conductivity reference solution, its value should be near the typical measured process value for best accuracy. Prepare the solution by adding the listed grams of pure, dried NaCl shown in Table D on the next page to one liter of high purity, de-ionized, CO₂-free water at 25°C to obtain the listed conductivity. Solution conductivity can be decreased by dilution with de-ionized water.

Table D -- CONDUCTIVITY REFERENCE SOLUTIONS			
Desired Solution Value			Grams NaCl To Be Added
µS/cm	mS/cm	ppm (NaCl)*	
100	0.10	50	0.05
200	0.20	100	0.10
500	0.50	250	0.25
1000	1.00	500	0.50
2000	2.00	1010	1.01
3000	3.00	1530	1.53
4000	4.00	2060	2.06
5000	5.00	2610	2.61
8000	8.00	4340	4.34
10,000	10.00	5560	5.56
20,000	20.00	11,590	11.59

*When using ppm measuring scale for compounds other than NaCl, refer to appropriate chemistry handbook for reference solution formulation.

2. Thoroughly rinse the clean sensor in de-ionized water. Then immerse the sensor in the prepared reference solution (or process sample). **Important:** Allow the sensor and solution temperatures to equalize. Depending on their temperature differences, this may take a few minutes.

3. Press **MENU** key to display

≡MAIN MENU
▶CALIBRATE ↓

.

4. Press **ENTER** key to display

≡CALIBRATE
▶SENSOR A ↓

.

5. Press **ENTER** key again to display

≡SENSOR A
▶1 POINT SAMPLE↓

.

6. Press **ENTER** key again to display 1 POINT SAMPLE?
(HOLD OUTPUTS). Use \uparrow or \downarrow key to view the three states that the analog outputs (and relays) can be in during calibration:
 - **HOLD OUTPUTS:** Holds their present values.
 - **XFER OUTPUTS:** Transfers to preset values.
 - **ACTIVE OUTPUTS:** Responds to measured values.
7. With the desired choice displayed, press **ENTER** key to enter this selection.
8. If a process sample is used, determine its value using laboratory analysis or a calibrated portable meter.
9. With the sensor in solution and the 1 POINT SAMPLE:
SAMPLE READY? screen displayed, press **ENTER** key to confirm. This XXXX uS/cm
READING STABLE? active screen appears showing the measurement reading.
10. Wait for the reading to stabilize which may take a few minutes. Then press **ENTER** key. The "PLEASE WAIT" screen may appear if the reading is still too unstable. After the reading has stabilized, this static 1 POINT SAMPLE?
(XXXX uS/cm) screen appears showing the "last measured" value.
11. Use \uparrow and \downarrow keys to adjust the displayed value to exactly match the known value of the reference solution (or process sample).
12. Press **ENTER** key to enter the value and complete calibration ("CONFIRM CAL OK?" screen appears).
13. Re-install the sensor into the process.
14. Press **ENTER** key to display the active measurement reading on the "1 POINT SAMPLE: CONFIRM ACTIVE?" output status screen. When the reading corresponds to the actual typical process value, press **ENTER** key again to return the analog outputs and relays to their active states (MEASURE screen appears).

This completes "1 POINT SAMPLE" calibration.







4.5 Analog Outputs (1 and 2) Calibration











The analyzer analog outputs are factory-calibrated. However, they can be re-calibrated at any time if desired. **Calibrate each output in the same way using its respective menu screens.**

NOTE: When the passcode feature is enabled (Section 3.7), you must successfully enter the passcode before attempting to calibrate the analog outputs.

When an output is configured to be 0-20 mA, the analyzer will calibrate the 4 mA and 20 mA values (not the 0 mA value). Also, the analyzer adjustment range for output values during calibration is ± 2 mA.

1. Press **MENU** key to display  .
2. Press **ENTER** key to display  .
3. Press **↓** key twice to display  .
4. Press **ENTER** key to display  .
5. Press **ENTER** key again to display  .
6. Press **ENTER** key again to display  .
7. The displayed value is "counts" -- not mA -- that dynamically change when the output is adjusted. Use a calibrated digital multimeter to measure Output 1's actual minimum value provided at Terminals 4 and 5 on TB4.
8. Use **⇐** and **⇒** keys (coarse adjust) and **↑** and **↓** keys (fine adjust) to adjust Output 1's minimum value to read exactly "4.00 mA" on the digital multimeter -- not the analyzer display.
9. Press **ENTER** key to complete calibration of the minimum endpoint value.

10. With the  screen displayed, press  **key** once to display .
11. Press **ENTER** key to display .
12. Once again, the displayed value is "counts" -- not mA -- that dynamically change when the output is adjusted. Use a calibrated digital multimeter to measure Output 1's actual maximum value.
13. Use  **and**  **keys** (coarse adjust) and  **and**  **keys** (fine adjust) to adjust Output 1's maximum value to read exactly "20.00 mA" on the digital multimeter -- not the analyzer display.
14. Press **ENTER** key to complete calibration of the maximum endpoint value.

This completes Output 1 calibration.

SECTION 5




TEST/MAINTENANCE

The analyzer has TEST/MAINT menu screens to:

- Check system status for the analyzer, sensor and temperature inputs, and relays.
- Hold the analog outputs.
- Manually reset all relay overfeed timers.
- Provide analog output test signals to confirm operation of connected devices.
- Test relay operation (energize or de-energize) and check status of front panel alarm LEDs (on or off).
- Identify analyzer EPROM version.
- Simulate a measurement or temperature signal to exercise the measurement loop.
- Reset all configuration and calibration values to factory-set defaults.

5.1 Checking Analyzer, Sensor, and Relay Status

With the analyzer's system diagnostic capabilities, you can check the operating status of the analyzer, sensors (measurement and temperature inputs), and relays. The MEASURE screen will flash the "WARNING CHECK STATUS" message when a sensor or analyzer "FAIL" diagnostic condition has been detected. To determine the condition causing the warning, display the "STATUS" screens.

1. Press **MENU** key to display  .
2. Press **↓** key twice to display  .
3. Press **ENTER** key to display  .
4. Press **ENTER** key again to display the "STATUS: ANALYZER OK" screen. This screen confirms that the analyzer is operating properly. If "FAIL" appears, it may mean:
 - EPROM failure (data is not valid).
 - Scaling card not present or not recognized.
 - Analog-to-digital converter not responding.
 - RAM failure.
 - Internal serial communications failure.




5. Press **ENTER key** once to view the "STATUS: SENSOR OK" screen. Then press the **ENTER key** again to view the "STATUS: TEMP OK" screen. If "FAIL" appears on either input status screen, it may indicate:
 - Sensor is disconnected or incorrectly wired.
 - Signal is very noisy or exceeds measuring range.
6. With the "STATUS: TEMP OK" screen displayed, press **ENTER key** once to view the "STATUS: RLY A" screen. Press the **ENTER key** again to view the "STATUS: RLY B" screen. Status indications can be:

Status Indication	Meaning
ACTIVE (Relay energized; LED is on.)	Control Relay: Measured value exceeds setpoint. Alarm Relay: Measured value exceeds low or high alarm point. Status Relay: Existing system diagnostic condition has been detected.
INACTIVE (Relay not energized; LED is off.)	Control Relay: Measured value does not exceed setpoint. Alarm Relay: Measured value does not exceed low or high alarm point. Status Relay: Analyzer has not detected system diagnostic condition.
TIMEOUT (Relay not energized; LED is blinking.)	Control Relay: Overfeed timer has timed out; manually reset it. NOTE: TIMEOUT only applies to control relays.
COUNTING (Relay energized; LED is on.)	Control Relay: Overfeed timer is counting, but has not timed out. NOTE: COUNTING only applies to control relays.

7. To end relay status checking, press **ESC** or **ENTER key**.

5.2 Holding Outputs

The analyzer has a convenient feature to hold the analog outputs, suspending operation of any connected devices.

1. With the  screen displayed, press  **key once** to display .

2. Press **ENTER** key to immediately hold the analog outputs ("HOLD OUTPUTS: ENTER TO RELEASE" screen appears, acknowledging hold is operating).






NOTE: If the keypad is not used within 30 minutes, the analog outputs will automatically change back to their active states and the display will return to the MEASURE screen.

3. To release the hold and return analog outputs back to their "active" states, press **ENTER** key.

5.3 Resetting Overfeed Timers




When a relay overfeed timer "times out," as indicated by its blinking LED, the timer must be manually reset using TEST/MAINT menu screens. The LED stops blinking after reset.

1. With the  screen displayed, press  **key twice** to display .

2. Press **ENTER** key to reset all overfeed timers ("OVERFEED RESET: DONE" screen appears, acknowledging reset has occurred).
3. Press **ESC** or **ENTER** key to return to the previous level of the TEST/MAINT menu branch.

5.4 Providing Output (1 and 2) Test Signals

The analyzer can provide analog output test signals of a desired milliamp value to confirm operation of connected devices. **Test signals can be provided for both outputs in the same way using their respective menu screens.**

1. With the  screen displayed, press  key until you display .

2. Press **ENTER** key to display .



NOTE: The mA test signal for Output #1 is now active. Its value is shown on this screen.




3. Adjust the displayed value to obtain the desired mA test signal. (Use \Rightarrow and \Leftarrow keys for coarse adjust; \Uparrow and \Downarrow keys for fine adjust.)
4. To end the output test signal and return to the previous level of the TEST/MAINT menu branch, press **ESC** or **ENTER** key.


5.5 Testing Relay (A and B) Operation


Relays A and B can be tested to confirm their operation. **Test each relay in the same way using its respective menu screens.**



NOTE: The front panel alarm LEDs will not operate during this test.

1. With the  screen displayed, press  key until you display .





2. Press **ENTER** key to display . Relay A should be energized. Confirm this by checking NO and NC relay output terminals with a continuity meter.

3. Press \Uparrow or \Downarrow key once to display . Relay A should now be de-energized. Confirm this by checking NO and NC relay output terminals with a continuity meter.

4. To end this test and return to the previous level of the TEST/MAINT menu branch, press **ESC** or **ENTER** key.




5.6 Testing Alarm LEDs

Both front panel alarm LEDs can be simultaneously tested.

1. With the  screen displayed, press  key until you display  .
2. Press **ENTER** key to display  . Both front panel LEDs should continuously blink on and off.
3. To end this test and return to the previous level of the TEST/MAINT menu branch, press **ESC** or **ENTER** key.







5.7 Checking EPROM Version

You can check the EPROM version used in your analyzer.

1. With the  screen displayed, press  key until you display  .
2. Press **ENTER** key to view the EPROM version.
3. To return to the previous level of the TEST/MAINT menu branch, press **ESC** or **ENTER** key.

5.8 Selecting Type of Simulated Value

You can simulate a measured value to make the relays and analog outputs respond accordingly. First, select the type of simulated value using this subsection. Then, set the desired simulation value following the steps in subsection 5.9.

1. With the  screen displayed, press  key until you display  .
2. Press **ENTER** key to display  . Use  and  keys to view all choices:





5.9 Setting Simulation Value

- **SENSOR A:** Depending on the sensor's configured measurement, selects the simulated value to be a Sensor A conductivity, resistivity, or TDS value.
- **SENSOR B:** Depending on the sensor's configured measurement, selects the simulated value to be a Sensor B conductivity, resistivity, or TDS value.
- **TEMPERATURE A:** Selects the simulated value to be a Sensor A temperature value.
- **TEMPERATURE B:** Selects the simulated value to be a Sensor B temperature value.
- ***CALCULATION:** Selects the simulated value to be a calculated Sensor A and B measurement value (% reject, % pass, ratio A/B, ratio B/A, diff. A-B, or diff. B-A).

*A simulated value can only represent the calculated measurement when two sensors are used and the analyzer has been correctly configured for CALCULATION.





3. With the desired choice displayed, press **ENTER** key to enter this selection.

After selecting the type of simulated measurement (subsection 5.8), set the desired simulation value.

1. With the  screen displayed, press  key until you display  .
2. Press **ENTER** key to display  .






NOTE: The value shown on this screen is now active, providing a corresponding mA value for both analog output signals. (Both relays, depending on their configured settings, may also respond to this simulation value.)

3. Adjust the displayed simulation value to the desired value. (Use  and  keys for coarse adjust;  and  keys for fine adjust.)
4. To end simulation and return to the previous level of the TEST/MAINT menu branch, press **ESC** or **ENTER** key.

5.10 Resetting Configuration Values to Factory Defaults

You can conveniently reset all stored configuration settings, including calibration settings, simultaneously to factory-set defaults.

1. With the  screen displayed, press  **↓** key until you display .
2. Press **ENTER** key to display the "RESET DEFAULTS: ARE YOU SURE?" screen, asking if you really intend to perform this extreme action. (If you want to abort this action, press **ESC** key now.)
3. Press **ENTER** key to reset all stored configuration settings to factory defaults ("RESET DEFAULTS: DONE" screen appears, acknowledging reset has occurred).
4. To return to the previous level of the TEST/MAINT menu branch, press **ESC** or **ENTER** key.

SECTION 6

RELAY OVERFEED TIMER FEATURE

The useful relay overfeed timer feature, **only available to a relay set for the “control” function**, is described in more detail in this section.

6.1 Why Use an Overfeed Timer

Suppose that you configure a control relay with a high phase to operate in response to increasing measured value. The control relay will then turn on whenever the measured value exceeds its preset setpoint. When the measured value decreases below the setpoint by an amount you preset (the deadband setting), the relay will turn off. But what if a damaged sensor or a process upset condition keeps the measured value above the setpoint or deadband setting? The control element (valve, pump, etc.) switched by that relay would then continue to operate. Depending on the application control scheme, this may excessively disperse costly chemical additives or overly drain or divert the process. Also, the control element itself could be damaged due to excessive continuous or unusual operation such as a pump that is running dry. The useful overfeed timer prevents undesirable conditions like these from happening. It restricts how long the relay and its connected control element will remain on regardless of conditions.

6.2 Configuring Relay Overfeed Timers

To set a relay overfeed timer, use its respective configuration menu screen. The time you set to restrict how long the relay stays on (0-999.9 minutes) should be just enough to provide acceptable results. An excessive setting may waste chemicals or the process itself. Initially, set this time as an estimate. Then, by experimenting and observing the response, periodically “fine tune” to optimize the setting.

6.3 Overfeed Timer “Timeout” Operation

When a control relay is on and its overfeed timer “times out,” its LED indicator will blink. This indicates that the relay is now off and will remain off until you manually reset the overfeed timer. After reset, the relay LED stops blinking. (Both overfeed timers are reset simultaneously.)

6.4 Resetting Overfeed Timers

To manually reset both relay overfeed timers, please refer to Part Three, Section 5.3.

6.5 Interactions With Other Analyzer Functions

A relay overfeed timer can, and often will, interact with other analyzer functions while those functions are in use. Table E on the next page explains common overfeed timer interactions.

**Table E – RELAY OVERFEED TIMER INTERACTIONS
WITH OTHER ANALYZER FUNCTIONS**

Function Conditions		Resulting Action of Overfeed Timer
Manually Holding Relay Operation (When Outputs are Held at Start of Calibration)		
Off relay held in "off"	Overfeed timer was off	Overfeed timer remains off. After you change back to ACTIVE from the HOLD mode, the overfeed timer will remain off until the measured value (or a value you simulate) causes the relay to turn on.
On relay held in "on"	Overfeed timer was counting	Overfeed timer continues its "count down" until it turns the relay off. If you release HOLD <u>before</u> the timer "times out," the timer continues its "count down" until it turns the relay off or the timer automatically resets when the measured value (or a value you simulate) causes the relay to turn off. If you release HOLD <u>after</u> the timer has "timed out," it must be manually reset (Part Three, Section 5.3).
On relay held in "on"	Overfeed timer was timed out	Overfeed timer remains off which keeps the relay turned off. You must manually reset the timer (Part Three, Section 5.3).
Manually Transferring Relay Operation (When Outputs are Transferred at Start of Calibration)		
Off relay is transferred to "on"	Overfeed timer was off	Overfeed timer starts its "count down" until it turns the relay off. After you change the "on" relay back to "off," the overfeed timer automatically resets.
On relay is transferred to "off"	Overfeed timer was counting	Overfeed timer automatically resets. After you change the "off" relay back to "on," the overfeed timer starts its "count down" until it turns the relay off, or the timer automatically resets again when the measured value (or a value you simulate) causes the relay to turn off.
On relay is transferred to "off"	Overfeed timer was timed out	
Manually Testing Relay Operation (By Using TEST/MAINT Menu Screens)		
Off relay is changed to "on"	Overfeed timer was off	Overfeed timer starts its "count down" until it turns the relay off. After you change the "on" relay back to "off," the overfeed timer automatically resets.
On relay is changed to "off"	Overfeed timer was counting	Overfeed timer automatically resets. After you change the "off" relay back to "on," the overfeed timer starts its "count down" until it turns the relay off, or the timer automatically resets again when the measured value (or a value you simulate) causes the relay to turn off.
On relay is changed to "off"	Overfeed timer was timed out	
Operating a Relay By Simulating a Value (Using TEST/MAINT Menu Screens)		
Off relay is turned "on" by simulated value	Overfeed timer was off	Overfeed timer starts its "count down" until it turns the relay off. After you change the "on" relay back to "off," the overfeed timer automatically resets.
On relay is turned "off" by simulated value	Overfeed timer was counting	Overfeed timer automatically resets. After you change the "off" relay back to "on," the overfeed timer starts its "count down" until it turns the relay off, or the timer automatically resets again when the measured value (or a value you simulate) causes the relay to turn off.
On relay is turned "off" by simulation value	Overfeed timer was timed out	

PART FOUR - SERVICE AND MAINTENANCE

SECTION 1

GENERAL INFORMATION

1.1 Inspecting Sensor Cables

If a measurement problem exists and you suspect the sensor cables, inspect them for physical damage. If an interconnect cable is used, disconnect the cable at both ends (sensor and analyzer) and, using an ohmmeter, check its wires for continuity and internal shorts.

1.2 Replacing Fuse(s)

The analyzer is equipped with two internal, board-mounted fuses (80 mA and 100 mA type T slow-blow; 5 mm x 20 mm size). The fuses protect the 115 and 230 volt line power circuits.

WARNING:

DISCONNECT LINE POWER TO PREVENT POSSIBLE ELECTRICAL SHOCK.

1. After disconnecting line power, unplug all terminal strip connectors to enable removal of the back panel.
2. Remove the four screws fastening the back panel and remove the panel. The board-mounted fuses are located on the left circuit board.
3. Remove the blown fuse and replace it with a OMEGA fuse or an equivalent. (OMEGA fuse kit part number is 1000G3315-101.)
4. Reinstall the back panel and attach all terminal connectors.

1.3 Replacing Relays

The analyzer relays are soldered into a complex, multi-layered circuit board. To avoid the possibility of damaging this board while attempting to replace a relay, simply return the complete analyzer to the OMEGA Customer Service Dept. for relay replacement.

SECTION 2**PRESERVING MEASUREMENT ACCURACY****2.1 Keeping Sensor(s)
Clean**

To maintain measurement accuracy, periodically clean the sensor(s). Operating experience will help you determine when to clean the sensor (typically, monthly intervals). Use the recommended cleaning procedure described in the OMEGA contacting conductivity sensor instruction manual.

**2.2 Keeping Analyzer
Calibrated**

If the DRY method (Part Three, Section 4.2) was used to calibrate the analyzer, re-calibration is only required when replacing the OMEGA conductivity sensor. **If the analyzer was calibrated using the 1 POINT SAMPLE method, periodic re-calibration is required.** In all cases, always calibrate the analyzer when a sensor is replaced.



NOTE: *If your measuring application requires utmost accuracy, OMEGA offers a re-certification service to verify a used sensor's "K" value and temperature "T" factor. For details, call your local OMEGA representative or the OMEGA Customer Service Department.*

**2.3 Avoiding Electrical
Interference**

Recommendation: Do not run sensor cables (and inter-connect cables, if used) in the same conduit with line power.

Maintenance Tip! Excess cable should not be coiled near motors or other equipment that may generate electrical or magnetic fields. Cut cables to proper length during installation to avoid unnecessary inductive pickup ("electrical noise" may interfere with sensor signal).

SECTION 3**TROUBLESHOOTING****3.1 Ground Loops**

The analyzer may be affected by a "ground loop" problem (two or more electrically grounded points at different potentials).

Symptoms Indicating a Possible Ground Loop

- Analyzer reading is offset from the actual value by a consistent amount, or
- Analyzer reading is frozen on one value, or
- Analyzer reading is "off scale" (upscale or downscale).

Although the source of a ground loop is difficult to determine, there are several common causes.

Common Causes of a Ground Loop

- Components, such as recorders or computers, are connected to non-isolated analog outputs.
- Not using shielded cabling or failure to properly connect all cable shields.
- Moisture or corrosion in a junction box.

**Determining if
Ground Loop Exists**

The following simple test can help to determine if there is a ground loop:

1. With the conductivity MEASURE screen displayed, put the sensor in a non-conductive container (plastic or glass) filled with a known value conductivity reference solution. Note the analyzer reading for this solution.
2. Connect one end of a wire to a known earth ground, such as the analyzer ground terminal on TB1 or a metal water pipe. Place the other end of this wire into the reference solution next to the sensor.
3. Note the analyzer reading now and compare it with the reading taken in step 1. If the reading changed, a ground loop exists.

Finding Source of Ground Loop



Sometimes the source of a ground loop is easy to find, but it usually takes an organized approach to isolate the problem.

Troubleshooting Tip! Use a systematic troubleshooting method. If possible, start by grounding all shields and electrical grounds at one stable point. One at a time, turn off all pumps, motors and switches that are in contact with the process. Each time you do this, check if the ground loop still exists. Since the process media being measured is electrically conductive, the source of the ground loop may not be readily apparent.

3.2 Isolating Measuring System Problem

Checking Electrical Connections

When experiencing problems, try to determine the primary measurement system component causing the problem (sensor, analyzer, or interconnect cable, if used).

1. Verify that line power exists at the appropriate analyzer TB1 terminals.
2. Check all analyzer cable connections to ensure they are properly connected.

Verifying Sensor Operation

To verify sensor operation, refer to the procedure in the troubleshooting section of the sensor instruction manual.

Verifying Analyzer Operation

Verify the operation of the Sensor A measuring channel. If the Sensor B channel is used, verify it in the same way. The following procedure applies to the Sensor A channel.

WARNING:

DISCONNECT LINE POWER TO PREVENT POSSIBLE ELECTRICAL SHOCK.

1. After disconnecting line power and the sensor(s) from the analyzer, connect a 1% tolerance, 1097 ohm resistor between Terminals 4 (white) and 5 (blue) on TB3. (When configured for a PT100 temperature element, use a 1% tolerance, 110 ohm resistor.)

- Depending on the configured sensor cell constant, measuring units, and range, use the listed resistance in Table F (1% tolerance resistor or decade box) and connect it between Terminals 1 (red) and 2 (black) on TB3.

Table F – FULL-SCALE EQUIVALENT TEST RESISTANCE VALUES					
Configured Display Format	Configured "Nominal" Cell Constant				
	0.05 (see Note 1)	0.5	1	5	10
For Conductivity Measurement					
0-2.000 $\mu\text{S}/\text{cm}$	25 K Ω	not applicable	not applicable	not applicable	not applicable
0-20.00 $\mu\text{S}/\text{cm}$	2.5 K Ω	25 K Ω	not applicable	not applicable	not applicable
0-200.0 $\mu\text{S}/\text{cm}$	not applicable	2.5 K Ω	5 K Ω	not applicable	not applicable
0-2000 $\mu\text{S}/\text{cm}$	not applicable	not applicable	500 K Ω	2.5 K Ω	5 K Ω
0-2.000 mS/cm	not applicable	not applicable	not applicable	2.5 K Ω	5 K Ω
0-20.00 mS/cm	not applicable	not applicable	not applicable	not applicable	500 Ω
0-200.0 mS/cm	not applicable	not applicable	not applicable	not applicable	50 Ω
For Resistivity Measurement					
0-19.99 M $\Omega \cdot \text{cm}$	1 M Ω	not applicable	not applicable	not applicable	not applicable
0-999.9 K $\Omega \cdot \text{cm}$	50 K Ω	not applicable	not applicable	not applicable	not applicable
For TDS Measurement					
0-9999 ppm	3.2 Ω	32 Ω	64 Ω	320 Ω	640 Ω
0-9999 ppb	3.2 K Ω	32 K Ω	64 K Ω	320 K Ω	640 K Ω

NOTE 1: When measuring ultrapure water as conductivity (less than 1.00 microSiemens/cm), an 877 K Ω resistance will display 0.057 $\mu\text{S}/\text{cm}$. When measuring ultrapure water as resistivity, a 910 K Ω resistance will display 18.2 M $\Omega \cdot \text{cm}$.

- Reconnect line power to the analyzer.

WARNING:

WHEN LINE POWER IS PRESENT, BE CAREFUL TO PREVENT ELECTRICAL SHOCK.

- Verify that the analyzer conductivity reading is full-scale for the applicable range. Also, verify that the analyzer temperature reading is 0°C.

If these readings are achieved, the analyzer is operating properly, but the interconnect cable (if used) may be faulty.

Verifying Interconnect Cable Integrity

WARNING:

DISCONNECT LINE POWER TO PREVENT POSSIBLE ELECTRICAL SHOCK.

1. After disconnecting line power, reconnect the sensor(s) directly to the analyzer (purposely bypassing the interconnect cable and junction box, if used).
2. Place the sensor(s) in a container of known value conductivity reference solution that is at room temperature.
3. Reconnect line power to the analyzer.

WARNING:

WHEN LINE POWER IS PRESENT, BE CAREFUL TO PREVENT ELECTRICAL SHOCK.

4. Verify that the analyzer reading is the same as the known reference solution value. If the reading is achieved, the interconnect cable and/or junction box connections are probably faulty. Use a digital multimeter to check the interconnect cable for shorted or open wires.



WARRANTY/DISCLAIMER

OMEGA ENGINEERING, INC. warrants this unit to be free of defects in materials and workmanship for a period of **13 months** from date of purchase. OMEGA's WARRANTY adds an additional one (1) month grace period to the normal **one (1) year product warranty** to cover handling and shipping time. This ensures that OMEGA's customers receive maximum coverage on each product.

If the unit malfunctions, it must be returned to the factory for evaluation. OMEGA's Customer Service Department will issue an Authorized Return (AR) number immediately upon phone or written request. Upon examination by OMEGA, if the unit is found to be defective, it will be repaired or replaced at no charge. OMEGA's WARRANTY does not apply to defects resulting from any action of the purchaser, including but not limited to mishandling, improper interfacing, operation outside of design limits, improper repair, or unauthorized modification. This WARRANTY is VOID if the unit shows evidence of having been tampered with or shows evidence of having been damaged as a result of excessive corrosion; or current, heat, moisture or vibration; improper specification; misapplication; misuse or other operating conditions outside of OMEGA's control. Components which wear are not warranted, including but not limited to contact points, fuses, and triacs.

OMEGA is pleased to offer suggestions on the use of its various products. However, OMEGA neither assumes responsibility for any omissions or errors nor assumes liability for any damages that result from the use of its products in accordance with information provided by OMEGA, either verbal or written. OMEGA warrants only that the parts manufactured by it will be as specified and free of defects. OMEGA MAKES NO OTHER WARRANTIES OR REPRESENTATIONS OF ANY KIND WHATSOEVER, EXPRESS OR IMPLIED, EXCEPT THAT OF TITLE, AND ALL IMPLIED WARRANTIES INCLUDING ANY WARRANTY OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE ARE HEREBY DISCLAIMED. LIMITATION OF LIABILITY: The remedies of purchaser set forth herein are exclusive, and the total liability of OMEGA with respect to this order, whether based on contract, warranty, negligence, indemnification, strict liability or otherwise, shall not exceed the purchase price of the component upon which liability is based. In no event shall OMEGA be liable for consequential, incidental or special damages.

CONDITIONS: Equipment sold by OMEGA is not intended to be used, nor shall it be used: (1) as a "Basic Component" under 10 CFR 21 (NRC), used in or with any nuclear installation or activity; or (2) in medical applications or used on humans. Should any Product(s) be used in or with any nuclear installation or activity, medical application, used on humans, or misused in any way, OMEGA assumes no responsibility as set forth in our basic WARRANTY/DISCLAIMER language, and, additionally, purchaser will indemnify OMEGA and hold OMEGA harmless from any liability or damage whatsoever arising out of the use of the Product(s) in such a manner.

RETURN REQUESTS/INQUIRIES

Direct all warranty and repair requests/inquiries to the OMEGA Customer Service Department. **BEFORE RETURNING ANY PRODUCT(S) TO OMEGA, PURCHASER MUST OBTAIN AN AUTHORIZED RETURN (AR) NUMBER FROM OMEGA'S CUSTOMER SERVICE DEPARTMENT (IN ORDER TO AVOID PROCESSING DELAYS).** The assigned AR number should then be marked on the outside of the return package and on any correspondence.

The purchaser is responsible for shipping charges, freight, insurance and proper packaging to prevent breakage in transit.

FOR **WARRANTY** RETURNS, please have the following information available **BEFORE** contacting OMEGA:

1. Purchase Order number under which the product was **PURCHASED**,
2. Model and serial number of the product under warranty, and
3. Repair instructions and/or specific problems relative to the product.

FOR **NON-WARRANTY** REPAIRS, consult OMEGA for current repair charges. Have the following information available **BEFORE** contacting OMEGA:

1. Purchase Order number to cover the **COST** of the repair,
2. Model and serial number of the product, and
3. Repair instructions and/or specific problems relative to the product.

OMEGA's policy is to make running changes, not model changes, whenever an improvement is possible. This affords our customers the latest in technology and engineering.

OMEGA is a registered trademark of OMEGA ENGINEERING, INC.

© Copyright 2003 OMEGA ENGINEERING, INC. All rights reserved. This document may not be copied, photocopied, reproduced, translated, or reduced to any electronic medium or machine-readable form, in whole or in part, without the prior written consent of OMEGA ENGINEERING, INC.

Where Do I Find Everything I Need for Process Measurement and Control? OMEGA...Of Course!

Shop online at www.omega.com

TEMPERATURE

- ☒ Thermocouple, RTD & Thermistor Probes, Connectors, Panels & Assemblies
- ☒ Wire: Thermocouple, RTD & Thermistor
- ☒ Calibrators & Ice Point References
- ☒ Recorders, Controllers & Process Monitors
- ☒ Infrared Pyrometers

PRESSURE, STRAIN AND FORCE

- ☒ Transducers & Strain Gages
- ☒ Load Cells & Pressure Gages
- ☒ Displacement Transducers
- ☒ Instrumentation & Accessories

FLOW/LEVEL

- ☒ Rotameters, Gas Mass Flowmeters & Flow Computers
- ☒ Air Velocity Indicators
- ☒ Turbine/Paddlewheel Systems
- ☒ Totalizers & Batch Controllers

pH/CONDUCTIVITY

- ☒ pH Electrodes, Testers & Accessories
- ☒ Benchtop/Laboratory Meters
- ☒ Controllers, Calibrators, Simulators & Pumps
- ☒ Industrial pH & Conductivity Equipment

DATA ACQUISITION

- ☒ Data Acquisition & Engineering Software
- ☒ Communications-Based Acquisition Systems
- ☒ Plug-in Cards for Apple, IBM & Compatibles
- ☒ Datalogging Systems
- ☒ Recorders, Printers & Plotters

HEATERS

- ☒ Heating Cable
- ☒ Cartridge & Strip Heaters
- ☒ Immersion & Band Heaters
- ☒ Flexible Heaters
- ☒ Laboratory Heaters

ENVIRONMENTAL MONITORING AND CONTROL

- ☒ Metering & Control Instrumentation
- ☒ Refractometers
- ☒ Pumps & Tubing
- ☒ Air, Soil & Water Monitors
- ☒ Industrial Water & Wastewater Treatment
- ☒ pH, Conductivity & Dissolved Oxygen Instruments