

User's Guide

Shop online at

omega.com

THE OMEGA

www.omega.com

e-mail: info@omega.com



OMEGAETTE™ OS545 Infrared/Type K Thermometer

M3659/0401

INTRODUCTION

The Infrared Thermometer is digital and accepts as a second input a type K thermocouple. The Infrared Thermometer is a Non-contact thermometer with built-in laser circle sighting. It can be used to measure the temperature of objects' surface that is improper to be measured by traditional (contact) thermometer (such as moving object, the surface with electricity current or the objects which are impractical to be touched.)

I. SAFETY INFORMATION

- 1.** Read the following safety information carefully before attempting to operate or service the meter.
- 2.** Use the meter only as specified in this manual; otherwise, the protection provided by the meter may be impaired.

CAUTION

You may receive harmful laser radiation exposure if you do not adhere to the warnings listed below.

- **USE OF CONTROLS OR ADJUSTMENTS OR PERFORMANCE OF PROCEDURES OTHER THAN THOSE SPECIFIED HERE MAY RESULT IN HAZARDOUS RADIATION EXPOSURE.**
- **DO NOT LOOK AT THE LASER BEAM COMING OUT OF THE LENS OR VIEW DIRECTLY WITH OPTICAL INSTRUMENTS -EYE DAMAGE CAN RESULT.**
- **USE EXTREME CAUTION WHEN OPERATING THE LASER SIGHTING**
- **NEVER POINT THE LASER BEAM AT A PERSON.**
- **KEEP OUT OF REACH OF CHILDREN**

3. Precautions:

- a). Do not operate the thermometer near the large electrical or magnetic field.
- b). Keep the thermometer away from direct sunlight or strong source of light, hot objects (70°C/158°F), high temperatures, high humidity, or dust during using and storing.
- c). If the thermometer was at the environment where's temperature changes drastically, it would be fine to start measuring until the thermometer return to the stable status.
- d). Condensation may form on the focal lens if the thermometer was moved quickly from a cold to a hot environment. Before taking measurements, please wait for the condensation to evaporate.

4. Environment Conditions:

- a). Altitude up to 2000 meters.
- b). Relatively humidity 80% max.
- c). Operating Ambient 0 ~ 40°C

5. Maintenance & Cleaning

- a). Repairs or servicing aren't covered in this manual should only be performed by qualified personnel.
- b). Periodically wipe the case with a dry cloth. Don't use abrasives or solvents on this instrument.
- c). When servicing, use only specified replacement parts.
- d). Keep Lens Clean: use detergent and lint free cloth.

6. Safety Symbols:



Complies with EMC

II. FEATURES

- °C / °F Selectable
- Back-light LCD display
- Laser targeting
- Emissivity adjustable
- Audible and visible alarm

III. SPECIFICATIONS

3-1 General Information

Display:	Backlight LCD Display.
Auto power off:	Approx. 15sec (Infrared)
Over range indication:	"OL" or "-OL"
Low battery indication:	The BT will be displayed in LCD when the battery voltage drops below the operating voltage.
Power supply:	Single 9V battery006P 9V or IEC6F22, or NEDA 1604
Battery life:	Approx. 50hours (laser pointer and backlight turn off)
Operating temperature: and humidity	0°C to 40°C (32°F to 104°F), below 80%RH.

Storage temperature: and humidity	-10°C to 60°C (14°F to 140°F). below 70%RH
Dimensions:	170(L)x52(W)x38mm(H) 6.7(L) x 2.1(W) x 1.5(H) inches.
Weight:	Approx. 180g with battery.
Accessories:	Instruction manual, carry case, battery.

3-2 ELECTRICAL SPECIFICATIONS

<input type="checkbox"/> Infrared	
Measuring range:	-20°C to 500°C (-4°F to 932°F).
Resolution:	1°C, 1°F.
Accuracy:	± 3% reading or ± 3°C or 6°F.
Temperature coefficient:	0.1 times the applicable accuracy specification per °C to 18°C and 28°C to 40°C. (32°F to 64°F and 82°F to 104°F).
Responding time:	once per second.
Spectral Response:	6 ~ 14µm.
Field of view:	8:1 optics ratio with a 1" min target.
Emissivity:	0.1 ~ 1.0.
Sighting	Circle 1mW (class 2).
Sensor:	Thermopile.
Laser Wavelength:	670nm (Red).
Max. Laser Power Output:	1mW (class 2).

□ Type K

Measuring range: -50°C to 1333°C (-58°F to 1999°F)
 Resolution: 0.1°C, 1°C, 0.1°F, 1°F.
 Response time: 1 second.
 Basic accuracy: (@ 23±5°C calibration) accuracy area ± (...% of reading = degree) at 18°C to 28°C with relative humidity up 80%.

Function	Resolution	Range	Accuracy
°C	0.1°C	-50°C ~ 0°C	± (0.2%rdg + 1.0°C)
		0°C ~ 200°C	± (0.1%rdg + 0.8°C)
	1°C	200°C ~ 1333°C	± (0.2%rdg + 2°C)
°F	0.1°F	-58°F ~ 32°F	± (0.2%rdg + 2°F)
		32°F ~ 200°F	± (0.1%rdg + 1.6°F)
	1°F	200°F ~ 1999°F	± (0.2%rdg + 3°F)


TEMPERATURE COEFFICIENT:

0.1 times the applicable accuracy specification per °C from 0°C to 18°C and 28°C to 40°C (32°F to 64°F and 82°F to 104°F).

NOTE:

The basic accuracy specification does not include the error of the probe. Please refer to the probe accuracy specification for additional details.


IV. FRONT PANEL DESCRIPTION



1. Display.
2. ▼ * : Backlight button.
3. **MEAS** : Button for powering on.
Press **MEAS** button to turn on the thermometer,
the Infrared Thermometer is selected.
4. ▲ ▲ : Laser pointer button.

5. **MODE** : Measuring mode and mode settings selection.
 - a). Press **MODE** button to select measuring mode. (Infrared thermometer ↔ Type K thermometer)
 - b). Press **MODE** button for 3 seconds entering into the mode settings.
6. Type K input connector
7. Laser aperture
8. Focal lens

V. LCD DISPLAY DESCRIPTION



1. Low battery mark.	6. Laser indicator
2. Maximum	7. Hold function
3. Negative polarity	8. Hi Alarm
4. Measure value	9. Lo Alarm
5. Unit " °C " , " °F "	10. SET symbols

VI. EMISSIVITY

1. Emissivity Principles:

Emissivity is a value between 0 and 1 that indicates an object's ability to emit infrared energy. Emissivity is determined primarily by the object's composition and surface finish. The thermometer's sensitivity to emissivity " ϵ " was set at 0.95 before shipment because the objects of 90% that emissivity are around 0.95.

2. Emissivity Procedure

- a). Apply black tape, black mat paint, or black magic marker to the object if it is safe.
- b). " ϵ " is set at 0.95 to measure the dark surface.
- c). To aim the laser at dark surface, press **MEAS** button to get measurement as T1.
- d). Remove the black tape or black mat paint and aim laser at the same area again then press **MEAS** button to get the measurement as (T).
- e). Change & reset a value for emissivity " ϵ " to get measurement (T) until T equal to T1.

Emissivity VALUES (cont.)

Typical Emissivity Values-Metals (cont.)	
SURFACE	EMISSIVITY
Zinc (oxidized)	0.1*
Galvanized iron	0.3
Tin-plated steel	0.1*
Gold (polished)	0.1*
Silver (polished)	0.1*
Chromium (polished)	0.1*
Emissivity Values-Non-Metals	0.75 to 0.9
Refractory & Building Materials	
Red brick (rough)	

Fire clay	0.75
Asbestos	0.95
Concrete	0.7
Marble	0.9
Carborundum	0.85
Plaster	0.9
Alumina (fine grain)	0.25
Alumina (coarse grain)	0.45
Silica (fine grain)	0.4
Silica (coarse grain)	0.55
Zirconium silicate up to 500°C	0.85
Zirconium silicate at 850°C	0.6
Quartz (rough)	0.9
Carbon (graphite)	0.75
Carbon (soot)	0.95
Timber (various)	0.8 to 0.9
Miscellaneous	
Enamel (any color)	0.9
Oil paint (any color)	0.95
Lacquer	0.9
Matte black paint	0.95 to 0.98
Aluminum lacquer	0.5
Water	0.98
Rubber (smooth)	0.9
Rubber (rough)	0.98
Plastics (various, solid)	0.8 to 0.95
Plastic films (05 mm thick)	0.5 to 0.95
Polythene film (03 mm thick)	0.2 to 0.3
Paper and cardboard	0.9
Silicone polish (03 mm thick)	0.7
* Emissivity varies with purity	

EMISSION VALUES	
Typical Emissivity Values-Metals	
SURFACE	EMISSION
Iron and Steel	
Cast iron (polished)	0.2

Cast iron (turned at 100°C)	0.45
Cast iron (turned at 1000°C)	0.6 to 0.7
Steel (ground sheet)	0.6
Mild steel	0.3 to 0.5
Steel plate (oxidized)	0.9
Iron plate (rusted)	0.7 to 0.85
Cast iron (rough) rusted	0.95
Rough ingot iron	0.9
Molten cast iron	0.3
Molten mild steel	0.3 to 0.4
Stainless steel (polished)	0.1
Stainless steel (various)	0.2 to 0.6
Aluminum	
Polished aluminum	0.1*
Aluminum (heavily oxidized)	0.25
Aluminum oxide at 260°C	0.8
Aluminum oxide at 800°C	0.3
Aluminum Alloys various	0.1 to 0.25
Brass	
Brass (polished)	0.1*
Brass (roughened surface)	0.2
Brass (oxidized)	0.6
Copper	
Copper (polished)	0.05*
Copper plate (oxidized)	0.8
Molten copper	0.15
Lead	
Lead (pure)	0.1*
Lead (oxidized at 25°C)	0.3
Lead (oxidized, treated to 200°C)	0.6
Nickel and its alloys	
Nickel (pure)	0.1*
Nickel plate (oxidized)	0.4 to 0.5
Nichrome	0.7
Nichrome (oxidized)	0.95

VII. TEMPERATURE MEASUREMENT

1. Infrared measuring :

- a). Infrared measuring : Press **MEAS** button to power on the meter and start measuring. Release **MEAS** button to stop measuring and auto hold the reading, the meter will be off automatically after 15 secs.
- b). Under the Infrared measuring mode, press & hold **MEAS** button and press **MODE** button to select MAX measurement & General measuring mode.

2. Continuous infrared measuring

Start with power-off status, press **MODE** and **MEAS** buttons to power on the meter, the Infrared Thermometer can start the continuous measurement. In the meanwhile, **H** symbol won't appear in LCD, the Hold function is unavailable.

- a). Under continuous measurement, press **MEAS** button to stop continuous measurement and lock the reading, the meter will be off automatically after 15 secs.
- b). Under continuous measurement, press & hold **MEAS** button and press **MODE** button to select MAX measurement & General measurement.

Note:

- Laser offset: The laser beam is offset 16mm(0.63in) from the focal lens. Choose a sampling spot that is large enough to include the laser offset.
- Surface Temperatures: The thermometer will measure the first surface it detects, even a glass cover, dust, or fog. Make sure the object is not obstructed.

3. Type - K measuring :

- a). Under the Infrared measuring mode, press **MODE** button entering into Type - K measuring.
- b). Under Type - K measuring mode, press **MEAS** button for 3 secs to power off the meter.

4. Selecting C/F unit

While powering on the meter, the temperature unit that appears in LCD would be the last unit you measured. If user wants to change the temperature unit, first of all, user has to power-off the meter, then press & hold **▲** (°C) or **▼** (°F) and press **MEAS** button to power on the meter and get the proper unit.

VIII. MODE SETTING

Press **MEAS** button to power on the meter, then press & hold **MODE** button for 3 seconds entering into the setting mode for option. While flashed "SET" symbol appears in LCD, user should press **▼** **▲** to choose the setting mode for **Infrared** or **Type K** measurement.

It is under the parameter settings of infrared measurement if "K" doesn't appear in LCD.

1. Parameter settings for Infrared measuring:

Under the infrared parameter setting mode, LCD will show
SET
---, press **MODE** button to select in turn for setting " ϵ ",
"ALM \uparrow ", " \downarrow ALM", press **MODE** button again to escape the
setting mode and return to the general measurement.

Note: In the setting mode, if users don't push any button in
15 seconds, then it will escape from setting mode and
enter into Infrared temperature measuring mode.

2. Parameter settings for Type-K measuring:

Under the Type-K parameter setting mode, LCD will show ,
SET
K
--- press **MODE** button to select in turn for setting
"ALM \uparrow " , " \downarrow ALM", press **MODE** button again to escape the
setting mode and return to the general measurement.



Note: In the set mode, if users don't push any button in 15
seconds , then it will escape from setting mode and
enter into Type K temperature measuring mode.

ϵ : Emissivity, users can press **▲** or **▼** button to
adjust parameter.

ALM \uparrow : Hi Alarm Function. Press **▲** or **▼** to set up a
value as an alarm value, while the measurement
exceed it, the beeper will beep and "ALM \uparrow " symbol
will appear in LCD.

\downarrow ALM: Lo Alarm Function. Press **▲** or **▼** to set up a
value as an alarm value, while the measurement low
it, the beeper will beep and " \downarrow ALM" symbol will
appear in LCD.

MAX: Display the Maximum reading.

-  : Button for increasing the value of Parameters, increasing the parameter rapidly.
-  : Button for decreasing the value of Parameters, decrease the parameter rapidly.

Note:

- After finishing the setting procedure, the parameter will be memorized until next setting.
- Under mode settings, Backlight and Laser light function will be disabled.

IX. BATTERY REPLACEMENT

1. As battery power is not sufficient, LCD will display **BT** replacement with one new battery type 9V is required.
2. Open battery cover, then take out the battery from instrument and replace with a new 9-Volt battery and place the battery cover back.

LASER SIGHT COVERED BY ONE OR MORE OF THE FOLLOWING PATENTS :

Patent Notice: U.S.PAT. B1 5,368,392; 5,524,984; 5,727,880; 5,823,678; 5,823,679; 6,123,453/Germany G 94 22 197.9. G 94 22 203.7/ EPO 0 644 408/ France 2 767 921/ Holland 1007752/ Other Patents Pending.



OMEGAnet® On-Line Service www.omega.com	Internet e-mail info@omega.com
--	-----------------------------------

Servicing North America:

USA: One Omega Drive, Box 4047
Stamford CT 06907-0047
ISO 9001 Tel: (203) 359-1660 FAX: (203) 359-7700
Certified e-mail: info@omega.com

Canada: 976 Bergar
Laval (Quebec) H7L 5A1
Tel: (514) 856-6928 FAX: (514) 856-6886
e-mail: info@omega.ca

WARRANTY/DISCLAIMER

OMEGA ENGINEERING, INC. warrants this unit to be free of defects in materials and workmanship for a period of 13 months from date of purchase. OMEGA's WARRANTY adds an additional one (1) month grace period to the normal one (1) year product warranty to cover handling and shipping time. This ensures that OMEGA's customers receive maximum coverage on each product. If the unit malfunctions, it must be returned to the factory for evaluation. OMEGA's Customer Service Department will issue an Authorized Return (AR) number immediately upon phone or written request. Upon examination by OMEGA, if the unit is found to be defective, it will be repaired or replaced at no charge. OMEGA's WARRANTY does not apply to defects resulting from any action of the purchaser, including but not limited to mishandling, improper interfacing, operation outside of design limits, improper repair, or unauthorized modification. This WARRANTY is VOID if the unit shows evidence of having been tampered with or shows evidence of having been damaged as a result of excessive corrosion; or current, heat, moisture or vibration; improper specification; misapplication; misuse or other operating conditions outside of OMEGA's control. Components which wear are not warranted, including but not limited to contact points, fuses, and triacs.

OMEGA is pleased to offer suggestions on the use of its various products. However, OMEGA neither assumes responsibility for any omissions or errors nor assumes liability for any damages that result from the use of its products in accordance with information provided by OMEGA, either verbal or written. OMEGA warrants only that the parts manufactured by it will be as specified and free of defects. OMEGA MAKES NO OTHER WARRANTIES OR REPRESENTATIONS OF ANY KIND WHATSOEVER, EXPRESS OR IMPLIED, EXCEPT THAT OF TITLE, AND ALL IMPLIED WARRANTIES INCLUDING ANY WARRANTY OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE ARE HEREBY DISCLAIMED. LIMITATION OF LIABILITY: The remedies of purchaser set forth herein are exclusive, and the total liability of OMEGA with respect to this order, whether based on contract, warranty, negligence, indemnification, strict liability or otherwise, shall not exceed the purchase price of the component upon which liability is based. In no event shall OMEGA be liable for consequential, incidental or special damages.

CONDITIONS: Equipment sold by OMEGA is not intended to be used, nor shall it be used: (1) as a "Basic Component" under 10 CFR 21 (NRC), used in or with any nuclear installation or activity; or (2) in medical applications or used on humans. Should any Product(s) be used in or with any nuclear installation or activity, medical application, used on humans, or misused in any way, OMEGA assumes no responsibility as set forth in our basic WARRANTY/DISCLAIMER language, and, additionally, purchaser will indemnify OMEGA and hold OMEGA harmless from any liability or damage whatsoever arising out of the use of the Product(s) in such a manner.

RETURN REQUESTS / INQUIRIES

Direct all warranty and repair requests/inquiries to the OMEGA Customer Service Department. BEFORE RETURNING ANY PRODUCT: TO OMEGA, PURCHASER MUST OBTAIN AN AUTHORIZED RETURN (AR) NUMBER FROM OMEGA'S CUSTOMER SERVICE DEPARTMENT (IN ORDER TO AVOID PROCESSING DELAYS). The assigned AR number should then be marked on the outside of its return package and on any correspondence. The purchaser is responsible for shipping charges, freight, insurance and proper packaging to prevent breakage in transit.

FOR WARRANTY RETURNS, please have the following information available BEFORE contacting OMEGA:

1. Purchase Order number under which the product was PURCHASED.
2. Model and serial number of the product under warranty, and
3. Repair instructions and/or specific problems relative to the product.

FOR NON-WARRANTY REPAIRS, consult OMEGA for current repair charges. Have the following information available BEFORE contacting OMEGA:

1. Purchase Order number to cover the COST of the repair.
2. Model and serial number of the product, and
3. Repair instructions and/or specific problems relative to the product.

OMEGA's policy is to make running changes, not model changes, whenever an improvement is possible. This affords our customers the latest in technology and engineering.

OMEGA is a registered trademark of OMEGA ENGINEERING, INC.

© Copyright 2001 OMEGA ENGINEERING, INC. All rights reserved. This document may not be copied, photocopied, reproduced, translated, or reduced to any electronic medium or machine-readable form, in whole or in part, without the prior written consent of OMEGA ENGINEERING, INC.