

# Where Do I Find Everything I Need for Process Measurement and Control? OMEGA...Of Course!



# User's Guide

## TEMPERATURE

- Thermocouple, RTD & Thermistor Probes, Connectors, Panels & Assemblies
- Wire: Thermocouple, RTD & Thermistor
- Calibrators & Ice Point References
- Recorders, Controllers & Process Monitors
- Infrared Pyrometers

## PRESSURE, STRAIN AND FORCE

- Transducers & Strain Gauges
- Load Cells & Pressure Gauges
- Displacement Transducers
- Instrumentation & Accessories

## FLOW/LEVEL

- Rotameters, Gas Mass Flowmeters & Flow Computers
- Air Velocity Indicators
- Turbine / Paddlesheel Systems
- Totalizers & Batch Controllers

## pH/CONDUCTIVITY

- pH Electrodes, Testers & Accessories
- Benchtop/Laboratory Meters
- Controllers, Calibrators, Simulators & Pumps
- Industrial pH & Conductivity Equipment

## DATA ACQUISITION

- Data Acquisition & Engineering Software
- Communications-Based Acquisition Systems
- Plug-in Cards for Apple, IBM & Compatibles
- Datalogging Systems
- Recorders, Printers & Plotters

## HEATERS

- Heating Cable
- Cartridge & Strip Heaters
- Immersion & Band Heaters
- Flexible Heaters
- Laboratory Heaters

## ENVIRONMENTAL MONITORING AND CONTROL

- Metering & Control Instrumentation
- Refractometers
- Pumps & Tubing
- Air, Soil & Water Monitors
- Industrial Water & Wastewater Treatment
- pH, Conductivity & Dissolved Oxygen Instruments



<http://www.omega.com>  
e-mail: [info@omega.com](mailto:info@omega.com)

# TX802P SERIES PROGRAMMABLE ISOLATING POTENTIOMETER TRANSMITTER

OMEGAnet <sup>SM</sup> On-Line Service http://www.omega.com	Internet e-mail info@omega.com
--	-----------------------------------

**Servicing North America:**

**USA:** One Omega Drive, Box 4047  
ISO 9001 Certified Stamford, CT 06907-0047  
 Tel: (203) 359-1660 FAX: (203) 359-7700  
 e-mail: info@omega.com

**Canada:** 976 Bergar  
 Laval (Quebec) H7L 5A1  
 Tel: (514) 856-6928 FAX: (514) 856-6886  
 e-mail: canada@omega.com

**For immediate technical or application assistance:**

**USA and Canada:** Sales Service: 1-800-826-6342 / 1-800-TC-OMEGA<sup>SM</sup>  
 Customer Service: 1-800-622-2378 / 1-800-622-BEST<sup>SM</sup>  
 Engineering Service: 1-800-872-9436 / 1-800-USA-WHEN<sup>SM</sup>  
 TELEX: 996404 EASYLINK: 62968934 CABLE: OMEGA

**Mexico and Latin America:** Tel: (95) 800-TC-OMEGA<sup>SM</sup> FAX: (95) 203-359-7807  
 En Espanol: (203) 359-7803 e-mail: espanol@omega.com

**Servicing Europe:**

**Benelux:** Postbus 8034, 1180 LA Amstelveen, The Netherlands  
 Tel: (31) 20 6418405 FAX: (31) 20 6434643  
 Toll Free in Benelux: 06 0993344  
 e-mail: nl@omega.com

**Czech Republic:** ul. Rude armady 1868, 733 01 Karvina-Hranice, Czech Republic  
 Tel: 420 (69) 6311627 FAX: 420 (69) 6311114  
 e-mail: czech@omega.com

**France:** 9, rue Denis Papin, 78190 Trappes  
 Tel: (33) 130-621-400 FAX: (33) 130-699-120  
 Toll Free in France: 0800-4-06342  
 e-mail: france@omega.com

**Germany/Austria:** Daimlerstrasse 26, D-75392 Deckenpfronn, Germany  
 Tel: 49 (07056) 3017 FAX: 49 (07056) 8540  
 Toll Free in Germany: 0130 11 21 66  
 e-mail: germany@omega.com

**United Kingdom:** 25 Swannington Road, P.O. Box 7, Omega Drive,  
ISO 9001 Certified Broughton Astley, Leicestershire, Irlam, Manchester,  
 LE9 6TU, England M44 5EX, England  
 Tel: 44 (1455) 285520 Tel: 44 (161) 777-6611  
 FAX: 44 (1455) 283912 FAX: 44 (161) 777-6622  
 Toll Free in England: 0800-488-488  
 e-mail: uk@omega.com

It is the policy of OMEGA to comply with all worldwide safety and EMC/EMI regulations that apply. OMEGA is constantly pursuing certification of its products to the European New Approach Directives. OMEGA will add the CE mark to every appropriate device upon certification.

The information contained in this document is believed to be correct but OMEGA Engineering, Inc. accepts no liability for any errors it contains, and reserves the right to alter specifications without notice.  
 WARNING: These products are not designed for use in, and should not be used for, patient connected applications.

OMEGA ENGINEERING, INC. warrants this unit to be free of defects in materials and workmanship for a period of **13 months** from date of purchase. OMEGA Warranty adds an additional one (1) month grace period to the normal **one (1) year product warranty** to cover handling and shipping time. This ensures that OMEGA's customers receive maximum coverage on each product.

If the unit should malfunction, it must be returned to the factory for evaluation. OMEGA's Customer Service Department will issue an Authorized Return (AR) number immediately upon phone or written request. Upon examination by OMEGA, if the unit is found to be defective it will be repaired or replaced at no charge. OMEGA's WARRANTY does not apply to defects resulting from any action of the purchaser, including but not limited to mishandling, improper interfacing, operation outside of design limits, improper repair, or unauthorized modification. This WARRANTY is VOID if the unit shows evidence of having been tampered with or shows evidence of being damaged as a result of excessive corrosion; or current, heat, moisture or vibration; improper specification; misapplication; misuse or other operating conditions outside of OMEGA's control. Components which wear are not warranted, including but not limited to contact points, fuses, and triacs.

**OMEGA is pleased to offer suggestions on the use of its various products. However, OMEGA neither assumes responsibility for any omissions or errors nor assumes liability for any damages that result from the use of its products in accordance with information provided by OMEGA, either verbal or written. OMEGA warrants only that the parts manufactured by it will be as specified and free of defects. OMEGA MAKES NO OTHER WARRANTIES OR REPRESENTATIONS OF ANY KIND WHATSOEVER, EXPRESSED OR IMPLIED, EXCEPT THAT OF TITLE, AND ALL IMPLIED WARRANTIES INCLUDING ANY WARRANTY OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE ARE HEREBY DISCLAIMED. LIMITATION OF LIABILITY: The remedies of purchaser set forth herein are exclusive and the total liability of OMEGA with respect to this order, whether based on contract, warranty, negligence, indemnification, strict liability or otherwise, shall not exceed the purchase price of the component upon which liability is based. In no event shall OMEGA be liable for consequential, incidental or special damages.**

CONDITIONS: Equipment sold by OMEGA is not intended to be used, nor shall it be used: (1) as a "Basic Component" under 10 CFR 21 (NRC), used in or with any nuclear installation or activity; or (2) in medical applications or used on humans, or misused in any way, OMEGA assumes no responsibility as set forth in our basic WARRANTY/DISCLAIMER language, and additionally, purchaser will indemnify OMEGA and hold OMEGA harmless from any liability or damage whatsoever arising out of the use of the Product(s) in such a manner.

**RETURN REQUESTS/INQUIRIES**

Direct all warranty and repair requests/inquiries to the OMEGA Customer Service Department. BEFORE RETURNING ANY PRODUCT(S) TO OMEGA, PURCHASER MUST OBTAIN AN AUTHORIZED RETURN (AR) NUMBER FROM OMEGA'S CUSTOMER SERVICE DEPARTMENT (IN ORDER TO AVOID PROCESSING DELAYS). The assigned AR number should then be marked on the outside of the return package and on any correspondence.

The purchaser is responsible for shipping charges, freight, insurance and proper packaging to prevent breakage in transit.

FOR **WARRANTY** RETURNS, please have the following information available BEFORE contacting OMEGA:

1. P.O. number under which the product was PURCHASED,
2. Model and serial number of the product under warranty, and
3. Repair instructions and/or specific problems relative to the product.

FOR **NON-WARRANTY** REPAIRS, consult OMEGA for current repair charges. Have the following information available BEFORE contacting OMEGA:

1. P.O. number to cover the COST of the repair,
2. Model and serial number of product, and
3. Repair instructions and/or specific problems relative to the product.

OMEGA's policy is to make running changes, not model changes, whenever an improvement is possible. This affords our customers the latest in technology and engineering. OMEGA is a registered trademark of OMEGA ENGINEERING, INC.

© Copyright 1996 OMEGA ENGINEERING, INC. All rights reserved. This document may not be copied, photocopied, reproduced, translated, or reduced to any electronic medium or machine-readable form, in whole or in part, without prior written consent of OMEGA ENGINEERING, INC.

INPUT RANGE (% of POTENTIOMETER.)			
%POT	IR	%POT	IR
0~10%	1	20~40%	16
0~15%	2	40~60%	17
0~20%	3	60~80%	18
0~25%	4	80~100%	19
0~30%	5	25~50%	20
0~33%	6	50~75%	21
0~40%	7	75~100%	22
0~50%	8	33~67%	23
0~60%	9	67~100%	24
0~67%	10	50~100%	25
0~70%	11	10~90%	26
0~75%	12	20~80%	27
0~80%	13	25~75%	28
0~90%	14	30~70%	29
0~100%	15	40~80%	30
Special Input Calibration Range			Z

# TX802P Potentiometer Transmitter.

Isolating 3 Wire Potentiometer  
Input to 4~20mA Output  
Loop Powered Transmitter.

### Features.

- Field Programmable Input Ranges.
- Isolated Input to Output 2.0kV.
- High Accuracy.
- 40~200mV Output Test Signal.
- LED Indication of Loop Current.
- Low Cost.
- Easy to Install.
- Compact DIN Rail Mount Enclosure.
- Available Standard or Special Calibration.
- Reverse Polarity Protection.
- Corrosion Proofed Circuit Board & Components by Isonel 642. (Except Terminals & DIP Switches.)



### The Proper Installation & Maintenance of TX802P.

#### MOUNTING.

- (1) Mount in a clean environment in an electrical cabinet on DIN or EN mounting rail.
- (2) Do not subject to vibration or excess temperature or humidity variations.
- (3) Avoid mounting in cabinets with power control equipment.
- (4) To maintain compliance with the EMC Directives the TX802P is to be mounted in a fully enclosed steel cabinet. The cabinet must be properly earthed, with appropriate input / output entry points, filtering and cabling.

#### WIRING.

- (1) All cables should be good quality overall screened INSTRUMENTATION CABLE with the screen earthed at one end only.
- (2) Signal cables should be laid a minimum distance of 300mm from any power cables.
- (3) For 2 wire current loops and 2 wire voltage signals or 2 wire current signals, Austral Standard Cables B5102ES is recommended. For 3 wire transmitters, RTDs, resistance probes, and potentiometers Austral Standard Cables B5103ES is recommended.
- (4) It is recommended that you do not ground current loops and use power supplies with ungrounded outputs.
- (5) Lightning arrestors should be used when there is a danger from this source.
- (6) Refer to diagrams for connection information.


#### COMMISSIONING.

- (1) Once all the above conditions have been carried out and the wiring checked apply power to the TX802P loop and allow five minutes for it to stabilize.
- (2) Due to cable resistance and errors within the potentiometer itself a small error may occur (usually less than 1%). To remove this error adjust the Zero and Span trim pots in the top of the TX802P enclosure with a small screwdriver. (Clockwise to increase the output reading & Anticlockwise to decrease the output reading)
- (3) Take a low (approx 10%) and high (approx 90%) reading of the variable being measured by the transducer supplying the signal to the LPI-P, and ensure that this agrees with the level being indicated by the PLC or indicator, etc, that the TX802P is connected into. Adjust for any difference using the Zero and Span trim pots in the top of the TX802P enclosure.


#### MAINTENANCE.

- (1) Repeat (3) of Commissioning.
- (2) Do it regularly - at least once every 12 months.

Graph Of Maximum Load Versus Power Supply.



Enclosure Dimensions.



### Quality Assurance Programme.


The modern technology and strict procedures of the ISO9001 Quality Assurance Programme applied during design, development, production and final inspection grant the long term reliability of the instrument.

### TX802P Specifications.

Potentiometer Input	3 Wire Potentiometer.
	Excitation = 0.25V.
	Minimum Potentiometer Resistance = 1kΩ.
	Maximum Potentiometer Resistance = 1MΩ.
	Field Programmable Zero From 0 to 100%.
	Field Programmable Span From 0 to 100%.
Output	- mA
	2 Wire 4~20mA. (Loop Powered.)
	- mV
	40~200mV ∞ 4~20mA. (Indicative Test Signal Only.)
	Other Output Voltages Available. eg 1~5V.
Power Supply	8~40Vdc.
Supply Voltage Sensitivity	<±0.005%/V FSO.
Output Load Resistance	800Ω @ 24Vdc. (50Ω/V Above 8Vdc.)
Maximum Output Current	Limited to <28mA.
Accurate to	<±0.1% FSO Typical.
Linearity & Repeatability	<±0.1% FSO Typical.
Ambient Drift	<±0.02%/C FSO Typical.
Noise Immunity	125dB CMRR Average. (2.0kVac RMS Limit.)
R.F. Immunity	<1% Effect FSO Typical.
Isolation Voltage	2.0kVac/dc Input to Output for 60sec.
Response Time	200msec Typical. (10 to 90% 50msec Typical.)
Operating Temperature	0~70C.
Storage Temperature	-20~80C.
Operating Humidity	90%RH Max. Non-Condensing.
Construction	6.6 Polyamide Thermoplastic Rail Mount Enclosure.

Note 1. Specifications based on Standard Calibration Unit, unless otherwise specified.  
 Note 2. Due to ongoing research and development, designs, specifications, and documentation are subject to change without notification. No liability will be accepted for errors, omissions or amendments to this specification.


### Examples of Input Connection.



### Terminations.

Input	1	HIGH
	2	COM
	3	WIPER
Output	4	+mA
	5	-mA
	6	mV TEST

### Plan View of TX802P Adjustments.



### TX802P Input Programming.

If the input range is not listed in the programming table, use the following formulae to work out the Zero and Span DIP switch settings for gain.

$$\text{Span Gain} = \frac{600}{\text{POT\% High} - \text{POT\% Low}}$$

$$\text{Zero Gain} = \frac{\text{POT\% Low}}{2}$$

Enter the Zero or Span gain value into the appropriate Zero or Span DIP switch.

Gain Value	1	2	4	8	16	32
DIP Switch No.	1	2	3	4	5	6

So if a gain value of 28 is required, put DIP switch No's 3, 4, 5 OFF (ie, gains of 4 + 8 + 16 = 28) and all the other DIP switches ON. Dip switches are accessed by seperating the two halves of the TX801P / TX802P enclosure

### TX802P Input Range Programming Table.

Notes: 1/ Switch status 1 = ON, 0 = OFF, X = DON'T CARE.  
 2/ Input ranges with '\*' beside them require more adjustment by the Zero & Span trimpots.

INPUT RANGE % of POT.	S1-ZERO						S2-SPAN					
	1	2	3	4	5	6	1	2	3	4	5	6
0~10%	1	1	1	1	1	1	1	1	0	0	0	0
0~15%	1	1	1	1	1	1	1	1	1	0	1	0
0~20%	1	1	1	1	1	1	1	0	0	0	0	1
0~25%	1	1	1	1	1	1	1	1	1	0	0	1
0~30%	1	1	1	1	1	1	1	1	0	1	0	1
0~33%	1	1	1	1	1	1	1	0	1	1	0	1
0~40%	1	1	1	1	1	1	0	0	0	0	1	1
0~50%	1	1	1	1	1	1	1	1	0	0	1	1
0~60%	1	1	1	1	1	1	1	0	1	0	1	1
0~67%	1	1	1	1	1	1	0	1	1	0	1	1
0~70%*	1	1	1	1	1	1	0	1	1	0	1	1
0~75%	1	1	1	1	1	1	1	1	1	0	1	1
0~80%*	1	1	1	1	1	1	1	1	1	0	1	1
0~90%*	1	1	1	1	1	1	0	0	0	1	1	1
0~100%	1	1	1	1	1	1	1	0	0	1	1	1
20~40%	1	0	1	0	1	1	1	0	0	0	0	1
40~60%	1	1	0	1	0	1	1	0	0	0	0	1
60~80%	1	0	0	0	0	1	1	0	0	0	0	1
80~100%	1	1	1	0	1	0	1	0	0	0	0	1
25~50%*	0	1	0	0	1	1	1	1	1	0	0	1
50~75%	0	1	1	0	0	1	1	1	1	0	0	1
75~100%	1	0	0	1	1	0	1	1	1	0	0	1
33~67%*	0	1	1	1	0	1	1	0	1	1	0	1
67~100%	1	0	1	1	1	0	1	0	1	1	0	1
50~100%	0	1	1	0	0	1	1	1	0	0	1	1
10~90%*	0	1	0	1	1	1	1	1	1	0	1	1
20~80%	1	0	1	0	1	1	1	0	1	0	1	1
25~75%*	0	1	0	0	1	1	1	1	0	0	1	1
30~70%	0	0	0	0	1	1	0	0	0	0	1	1
40~80%	1	1	0	1	0	1	0	0	0	0	1	1