





User's Guide



Shop online at

omega.com®

OMEGA®

www.omega.com

e-mail: info@omega.com



HX51, HX52 RH, RH/Temperature Transmitters



OMEGAnet® Online Service
www.omega.com

Internet e-mail
info@omega.com

Servicing North America:

USA: One Omega Drive, Box 4047
ISO 9001 Certified Stamford CT 06907-0047
Tel: (203) 359-1660 FAX: (203) 359-7700
e-mail: info@omega.com

Canada: 976 Bergar
Laval (Quebec) H7L 5A1
Tel: (514) 856-6928 FAX: (514) 856-6886
e-mail: info@omega.ca

For immediate technical or application assistance:

USA and Canada: Sales Service: 1-800-826-6342 / 1-800-TC-OMEGA®
Customer Service: 1-800-622-2378 / 1-800-622-BEST®
Engineering Service: 1-800-872-9436 / 1-800-USA-WHEN®
TELEX: 996404 EASYLINK: 62968934 CABLE: OMEGA

Mexico: En Español: (001) 203-359-7803 e-mail: espanol@omega.com
FAX: (001) 203-359-7807 info@omega.com.mx

Servicing Europe:

Benelux: Postbus 8034, 1180 LA Amstelveen, The Netherlands
Tel: +31 (0)20 3472121 FAX: +31 (0)20 6434643
Toll Free in Benelux: 0800 0993344
e-mail: sales@omegaeng.nl

Czech Republic: Rudé armády 1868, 733 01 Karviná 8
Tel: +420 (0)59 6311899 FAX: +420 (0)59 6311114
Toll Free: 0800-1-66342 e-mail: info@omegashop.cz

France: 11, rue Jacques Cartier, 78280 Guyancourt, France
Tel: +33 (0)1 61 37 29 00 FAX: +33 (0)1 30 57 54 27
Toll Free in France: 0800 466 342
e-mail: sales@omega.fr

Germany/Austria: Daimlerstrasse 26, D-75392 Deckenpfronn, Germany
Tel: +49 (0)7056 9398-0 FAX: +49 (0)7056 9398-29
Toll Free in Germany: 0800 639 7678
e-mail: info@omega.de

United Kingdom: One Omega Drive, River Bend Technology Centre
ISO 9002 Certified Northbank, Irlam, Manchester
M44 5BD United Kingdom
Tel: +44 (0)161 777 6611 FAX: +44 (0)161 777 6622
Toll Free in United Kingdom: 0800-488-488
e-mail: sales@omega.co.uk

It is the policy of OMEGA to comply with all worldwide safety and EMC/EMI regulations that apply. OMEGA is constantly pursuing certification of its products to the European New Approach Directives. OMEGA will add the CE mark to every appropriate device upon certification.

The information contained in this document is believed to be correct, but OMEGA Engineering, Inc. accepts no liability for any errors it contains, and reserves the right to alter specifications without notice.

WARNING: These products are not designed for use in, and should not be used for, patient-connected applications.

INTRODUCTION

The HX51 humidity and HX52 humidity-temperature transmitters supply accurate humidity and temperature (HX52) data from a room or process air source on a continuous basis to a computer, chart recorder, printer, meter or control circuit.

Every instrument has terminals for both DC and AC power, and 0-1V, 0-5V and 4-20 mA outputs.

The humidity or humidity-temperature probe can be mounted on the instrument enclosure or at a remote location; that choice must be made at the time of purchase. The probe can be fitted with a sintered-metal filter for dusty or harsh environments.

Optional is a RS-232C serial digital (ASCII) output.

Also optional is a front-cover-mounted display to help in setting up and monitoring; this can be very helpful when the output is used at a location distant from the instrument and probe.

Transmitters with RS-232C ports and/or displays will have a board-mounted DIP switch for choosing English or metric units.

SPECIFICATIONS

Sensors:

Humidity sensor: Capacitive (Thin Film)
Temperature (HX52): PT100 RTD

Range:

Relative Humidity: 5% to 95% RH
Temperature (HX52): -4° to 176°F (-20° to 80°C)

Accuracy:

Relative Humidity: ±2% RH
Temperature (HX52): ±0.5°C

Resolution (optional display):

Relative Humidity: .0.1%RH
Temperature (HX52): 0.1°F or °C

SPECIFICATIONS (continued)

Response Time:

Relative Humidity: 90% of final value in 15 sec.

Temperature (HX52): Approximately 60 seconds

Analog Outputs (separate and concurrent):

Relative Humidity:

0-1V, 0-5V and 4-20mA represent 0-100%RH

Temperature (HX52):

0-1V, 0-5V and 4-20mA represent -4 to 176°F (-20 to 80°C)

Operating Range: -4° to 176°F (-20° to 80°C)

Power Supply: 120 or 220VAC, 50-60Hz, also
10-30 VDC

Input Current (with all options):

10-30VDC: HX51: 25mA, HX52: 38mA

110VAC: HX51: 15mA, HX52: 18mA

220VAC: HX51: 8mA, HX52: 9mA

Output Impedance (0-1V and 0-5V outputs):

1KΩ

Enclosure: ABS plastic, NEMA Class 4

Note: Enclosures with displays or case-mounted probes are not watertight.

Dimensions:

Housing: 4.8" x 4.8" x 2.2"

Probe: 4.5" x 1" diameter

Weight: 18 ounces

Options:

Display: 0.5" LCD, 4 digits


RS-232C port: 4 wire: TXD, CTS, RTS, GND

RS-232 serial port cable: 9 pin D-Sub connector

Custom cable lengths: For probe and RS-232 cables^{1,2}

Sintered-metal filter: Harsh environments

TERMINAL CONNECTIONS



- | | | | |
|---|--------|--|--------------------------|
| <ul style="list-style-type: none"> 1. 4-20 mA Temp 2. 0-5 Volt Temp 3. 0-1 Volt Temp 4. 4-20 mA %RH 5. 0-5 Volt %RH 6. 0-1 Volt %RH 7. Ground 8. V+ (10-30 VDC) | } HX52 | <ul style="list-style-type: none"> 9. 220 VAC 10. 110 VAC 11. 220/110 VAC 12. No Connection 13. RTS 14. CTS 15. TXD | } RS-232C
port option |
|---|--------|--|--------------------------|

INSTALLATION AND SETUP FOR HX51, HX52

Note: Make all connections with Power Off. Remove cover to attach transmitter to mounting area and to attach power and signal cables. Attach in location free of physical dangers such as excessive heat or continuous condensing moisture.³

POWER HOOKUP*

- 1a) If using 110VAC power, hook white (neutral) wire into slot 10. Then hook black (hot) wire into slot 11.
- 1b) If using 220VAC power, hook either hot wire into slot 11. Then hook the other hot wire into slot 9.
- 1c) If using 10-30VDC, first hook ground wire into slot 7. Then hook V+ wire into slot 8.

%RH OUTPUT*

- 2a) If you want 0-1V FS, hook output ground reference to slot 7. Then hook %RH output wire to slot 6.
- 2b) If you want 0-5V FS, hook output ground reference to slot 7. Then hook %RH output wire to slot 5.
- 2c) If you want 4-20mA FS, hook output ground reference to slot 7. Then hook %RH wire to slot 4.

TEMPERATURE OUTPUT (HX52)*

- 3a) If you want 0-1V FS, hook output ground reference to slot 7. Then hook temperature output wire to slot 3.
- 3b) If you want 0-5V FS, hook output ground reference to slot 7. Then hook temperature output wire to slot 2.
- 3c) If you want 4-20mA FS, hook output ground reference to slot 7. Then hook temperature output wire to slot 1.

RS-232C PORT HOOKUP (optional feature, see Appendix A)*

- 4a) Hook RS-232 ground reference to slot 7.
- 4b) Hook RTS (Ready to Send) output wire to slot 13.
- 4c) Hook CTS (Clear to Send) input wire to slot 14.
- 4d) Hook TXD (Transmit Data) output wire to slot 15.

MOUNTING THE PROBE (remote probe)

Mount at location where measurements are to be made. Do not change the length of the cable supplied at purchase as doing so will change the calibration. Protect the probe with a sintered-metal filter (optional) if dust or spray is present.

METRIC OR ENGLISH UNITS (with RS232 and/or display)

To change units, set DIP switch #2 (see Diagram 1) to CLOSED for metric or OPEN for english units.


REPLACING COVER

Use care not to damage the seal; if the cover has a display, use proper polarity when reinstalling connectors (see Diagram 1).

DISPLAY SWITCH (HX52 with display)

Set the switch to "%RH" to display humidity and to "TEMP." to display temperature.

*NOTE: Be sure to tighten screws above slots when finished.



Connector Polarity:

- 1 Red wire down (display option)
- 2 Grey wire up
- 3 Red wire up
- 4 Black wire up
- 5 Black wire down (HX52 with display option)

Diagram 1: Location and Polarity of Connectors and Switches.

APPENDIX A – Communication by means of (optional)

RS-232C serial data port

The transmitter provides data output to the RS-232 terminals (see TERMINAL CONNECTIONS Pg 3). The voltage levels are plus and minus 9 volts. A voltage of +9 volts represents a space (logical “0”). A voltage of -9 volts represents a mark (logical “1”). The protocol is: 1 start bit, 7 data bits, 1 odd parity bit, 1 stop bit, ASCII data format, 1200 baud.

Sample data formats:

073.6 deg F 031.7 %RH

023.1 deg C 032.9 %RH

RS-232 Data output connection:

<u>Signal</u>	<u>Signal Direction</u>	<u>XMTR Terminal</u>	<u>9-pin D-S Pin No.</u>	<u>Wire Color</u>
Ground		7	5	BLK
TXD	to PC	15	2	GRN
CTS	from PC	14	7	GRY
RTS	to PC	13	8	WHT

When the transmitter is powered up, an RTS signal (logical “1”) becomes available on terminal 13. The PC program or printer must respond with a CTS signal (logical “0”). Once handshaking is established, ASCII data will be transferred at 1200 baud. Each line (record) of data is terminated with a CR (carriage return) and an LF (line feed). Transmission will continue until the CTS signal returns to a logical “1”.

APPENDIX B – Collecting data by means of resident “HyperTerminal” program on Win 95, 98, NT4, and Win 2000 PC’s

A. Set up Communication Port.

- 1) Find and open “HyperTerminal” under “Accessories” and “Communications”
- 2) Type a name like “Humidity Transmitter” and select an icon, then click “OK”
- 3) In the “Connect using:” box, select a COM port - probably “COM 1”. Click “OK”

- B. Set up "COM 1 Properties"
 - 1) Set "Bits per second:" to "1200"
 - 2) Set "Data bits:" to "8"
 - 3) Set "Parity:" to "None"
 - 4) Set "Stop bits:" to "1"
 - 5) Set "Flow control:" to "None"
 - 6) Click "OK", then select "Save"
- C. Connect cable and transfer data
 - 1) Connect the RS-232 cable to "COM 1" port
 - 2) Power up transmitter
 - 3) Select "Call" from "Call" menu. Data will fill window.
 - 4) To stop, select "Disconnect" from "Call" menu
 - 5) To save data, select "Save As..." and give file a name
- D. To transfer to Excel
 - 1) Select data file from C5 above and open with "Notepad"
 - 2) Select data to be transferred and "Copy"
 - 3) Open a new blank Excel worksheet, select "Paste"
 - 4) Select entire Column "A". Under "Data" menu, select "Text to columns..." and click "Next"
 - 5) Follow directions to separate data, then click "Finish"

APPENDIX C – Explanation of error codes

- E-06 Relative Humidity below range: $<3.0\%RH$
- E-07 Relative Humidity above range: $>97.0\%RH$
- E-08 Temperature below range: $<-4^{\circ}F$ or $<-20^{\circ}C$
- E-09 Temperature above range: $>175^{\circ}F$ or $>80^{\circ}C$

¹In order to insure the proper calibration, all custom-length cables for the HX52 must be ordered at the time the transmitter is purchased; or the unit must be returned for calibration.

²The maximum length for probe cables is 150 ft.; please consult manufacturer if longer cable is required.

³Cable grips will seal on round cables from 2.5 to 6.5mm diameter. For wire bundles, if you wish to insure water tightness, use RTV silicon or other sealant safe for electronics at end of cable grip.

NOTES:



WARRANTY/DISCLAIMER

OMEGA ENGINEERING, INC. warrants this unit to be free of defects in materials and workmanship for a period of **13 months** from date of purchase. OMEGA's Warranty adds an additional one (1) month grace period to the normal **one (1) year product warranty** to cover handling and shipping time. This ensures that OMEGA's customers receive maximum coverage on each product.

If the unit malfunctions, it must be returned to the factory for evaluation. OMEGA's Customer Service Department will issue an Authorized Return (AR) number immediately upon phone or written request. Upon examination by OMEGA, if the unit is found to be defective, it will be repaired or replaced at no charge. OMEGA's WARRANTY does not apply to defects resulting from any action of the purchaser, including but not limited to mishandling, improper interfacing, operation outside of design limits, improper repair, or unauthorized modification. This WARRANTY is VOID if the unit shows evidence of having been tampered with or shows evidence of having been damaged as a result of excessive corrosion; or current, heat, moisture or vibration; improper specification; misapplication; misuse or other operating conditions outside of OMEGA's control. Components which wear are not warranted, including but not limited to contact points, fuses, and triacs.

OMEGA is pleased to offer suggestions on the use of its various products. However, OMEGA neither assumes responsibility for any omissions or errors nor assumes liability for any damages that result from the use of its products in accordance with information provided by OMEGA, either verbal or written. OMEGA warrants only that the parts manufactured by it will be as specified and free of defects. OMEGA MAKES NO OTHER WARRANTIES OR REPRESENTATIONS OF ANY KIND WHATSOEVER, EXPRESS OR IMPLIED, EXCEPT THAT OF TITLE, AND ALL IMPLIED WARRANTIES INCLUDING ANY WARRANTY OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE ARE HEREBY DISCLAIMED. LIMITATION OF LIABILITY: The remedies of purchaser set forth herein are exclusive, and the total liability of OMEGA with respect to this order, whether based on contract, warranty, negligence, indemnification, strict liability or otherwise, shall not exceed the purchase price of the component upon which liability is based. In no event shall OMEGA be liable for consequential, incidental or special damages.

CONDITIONS: Equipment sold by OMEGA is not intended to be used, nor shall it be used: (1) as a "Basic Component" under 10 CFR 21 (NRC), used in or with any nuclear installation or activity; or (2) in medical applications or used on humans. Should any Product(s) be used in or with any nuclear installation or activity, medical application, used on humans, or misused in any way, OMEGA assumes no responsibility as set forth in our basic WARRANTY/DISCLAIMER language, and, additionally, purchaser will indemnify OMEGA and hold OMEGA harmless from any liability or damage whatsoever arising out of the use of the Product(s) in such a manner.

RETURN REQUESTS/INQUIRIES

Direct all warranty and repair requests/inquiries to the OMEGA Customer Service Department. BEFORE RETURNING ANY PRODUCT(S) TO OMEGA, PURCHASER MUST OBTAIN AN AUTHORIZED RETURN (AR) NUMBER FROM OMEGA'S CUSTOMER SERVICE DEPARTMENT (IN ORDER TO AVOID PROCESSING DELAYS). The assigned AR number should then be marked on the outside of the return package and on any correspondence.

The purchaser is responsible for shipping charges, freight, insurance and proper packaging to prevent breakage in transit.

FOR **WARRANTY** RETURNS, please have the following information available BEFORE contacting OMEGA:

1. Purchase Order number under which the product was PURCHASED,
2. Model and serial number of the product under warranty, and
3. Repair instructions and/or specific problems relative to the product.

FOR **NON-WARRANTY** REPAIRS, consult OMEGA for current repair charges. Have the following information available BEFORE contacting OMEGA:

1. Purchase Order number to cover the COST of the repair,
2. Model and serial number of the product, and
3. Repair instructions and/or specific problems relative to the product.

OMEGA's policy is to make running changes, not model changes, whenever an improvement is possible. This affords our customers the latest in technology and engineering.

OMEGA is a registered trademark of OMEGA ENGINEERING, INC.

© Copyright 2002 OMEGA ENGINEERING, INC. All rights reserved. This document may not be copied, photocopied, reproduced, translated, or reduced to any electronic medium or machine-readable form, in whole or in part, without the prior written consent of OMEGA ENGINEERING, INC.

Where Do I Find Everything I Need for Process Measurement and Control? **OMEGA...Of Course!**

Shop online at www.omega.com

TEMPERATURE

- MJ Thermocouple, RTD & Thermistor Probes, Connectors, Panels & Assemblies
- MJ Wire: Thermocouple, RTD & Thermistor
- MJ Calibrators & Ice Point References
- MJ Recorders, Controllers & Process Monitors
- MJ Infrared Pyrometers

PRESSURE, STRAIN AND FORCE

- MJ Transducers & Strain Gages
- MJ Load Cells & Pressure Gages
- MJ Displacement Transducers
- MJ Instrumentation & Accessories

FLOW/LEVEL

- MJ Rotameters, Gas Mass Flowmeters & Flow Computers
- MJ Air Velocity Indicators
- MJ Turbine/Paddlewheel Systems
- MJ Totalizers & Batch Controllers

pH/CONDUCTIVITY

- MJ pH Electrodes, Testers & Accessories
- MJ Benchtop/Laboratory Meters
- MJ Controllers, Calibrators, Simulators & Pumps
- MJ Industrial pH & Conductivity Equipment

DATA ACQUISITION

- MJ Data Acquisition & Engineering Software
- MJ Communications-Based Acquisition Systems
- MJ Plug-in Cards for Apple, IBM & Compatibles
- MJ Datalogging Systems
- MJ Recorders, Printers & Plotters

HEATERS

- MJ Heating Cable
- MJ Cartridge & Strip Heaters
- MJ Immersion & Band Heaters
- MJ Flexible Heaters
- MJ Laboratory Heaters

ENVIRONMENTAL MONITORING AND CONTROL

- MJ Metering & Control Instrumentation
- MJ Refractometers
- MJ Pumps & Tubing
- MJ Air, Soil & Water Monitors
- MJ Industrial Water & Wastewater Treatment
- MJ pH, Conductivity & Dissolved Oxygen Instruments

M3880/1002