




Where Do I Find Everything I Need for Process Measurement and Control? OMEGA...Of Course! Shop online at www.omega.com

- TEMPERATURE: Thermocouple, RTD & Thermistor Probes, Connectors, Panels & Assemblies; Wire: Thermocouple, RTD & Thermistor; Calibrators & Ice Point References; Recorders, Controllers & Process Monitors; Infrared Pyrometers; PRESSURE/STRAIN AND FORCE: Transducers & Strain Gauges; Load Cells & Pressure Gauges; Displacement Transducers; Instrumentation & Accessories; FLOW/LEVEL: Rotameters, Gas Mass Flowmeters & Flow Computers; Air Velocity Indicators; Turbine/Paddlewheel Systems; Totalizers & Batch Controllers; pH/CONDUCTIVITY: pH Electrodes, Testers & Accessories; Benchtop/Laboratory Meters; Controllers, Calibrators, Simulators & Pumps; Industrial pH & Conductivity Equipment; DATA ACQUISITION: Data Acquisition & Engineering Software; Communications-Based Acquisition Systems; Plug-in Cards for Apple, IBM & Compatibles; Dialogging Systems; Recorders, Printers & Plotters; HEATERS: Heating Cable; Cartridge & Strip Heaters; Immersion & Band Heaters; Flexible Heaters; Laboratory Heaters; ENVIRONMENTAL MONITORING AND CONTROL: Metering & Control Instrumentation; Refractometers; Pumps & Tubing; Air, Soil & Water Monitors; Industrial Water & Wastewater Treatment; pH, Conductivity & Dissolved Oxygen Instruments

M39160803

HHLM3 Digital Lightmeter



WARRANTY / DISCLAIMER: OMEGA ENGINEERING, INC. disclaims the unit to be free of defects in materials and workmanship for a period of 13 months from date of purchase. OMEGA WARRANTY adds an additional one (1) month grace period to the normal one (1) year product warranty to cover handling and shipping time. This assumes that OMEGA's customers receive the unit undamaged. It must be returned to the factory for evaluation. OMEGA's Customer Service Department will issue an Authorized Return (AR) number immediately upon phone or written request. Upon return to the factory, the unit is covered by OMEGA'S WARRANTY. OMEGA'S WARRANTY does not cover damage to the unit caused by misuse, abuse, or neglect. It is not limited to manufacturing, improper installation, operation outside of design limits, improper repair, or unauthorized modification. This WARRANTY VOID if the unit shows evidence of having been tampered with, or if the unit is used for any application not intended by OMEGA. OMEGA does not warrant, represent, or make any claim of accuracy, precision, or reliability for any application outside of OMEGA's control. Components which wear are not warranted, including but not limited to contact points, tubes, and valves. OMEGA does not warrant, represent, or make any claim of accuracy, precision, or reliability for any application outside of OMEGA's control. OMEGA neither assumes responsibility for any conditions or errors nor assumes liability for any damage that may result from the use of its products in accordance with information provided by OMEGA, either verbal or written. OMEGA warrants that the unit is free of defects in materials and workmanship at the time of shipment. OMEGA MAKES NO OTHER WARRANTIES OR REPRESENTATIONS OF ANY KIND WHATSOEVER, EXPRESS OR IMPLIED, EXCEPT THAT TITLE AND ALL IMPLIED WARRANTIES INCLUDING ANY WARRANTY OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE ARE HEREBY DISCLAIMED. OMEGA'S LIABILITY IS LIMITED TO THE EXTENT OF THE PURCHASE PRICE. OMEGA is not liable for consequential, incidental or special damages. CONDITIONS: Equipment sold by OMEGA is not intended to be used, nor shall it be used: (1) as a "trace component" under 10 CFR (400), (2) in any application where the unit is used in conjunction with any application or used on humans, should any Product(s) be used in or with any nuclear installation or facility, medical application, used on humans, or misused in any way; OMEGA assumes no responsibility as set forth in our basic WARRANTY / DISCLAIMER language, and is not liable for any damage or loss of data, information, or equipment, or any other liability or damage whatsoever arising out of the use of the Product(s) in such a manner.

RETURN REQUESTS / INQUIRIES: Direct all warranty and repair requests/inquiries to the OMEGA Customer Service Department. BEFORE RETURNING ANY PRODUCT(S) TO OMEGA, PURCHASER MUST OBTAIN AN AUTHORIZED RETURN (AR) NUMBER FROM OMEGA. OMEGA'S WARRANTY DOES NOT COVER SHIPPING CHARGES, CUSTOMER PROCESSING DELAYS, THE ASSIGNED AR NUMBER SHOULD THEN BE MARKED ON THE OUTSIDE OF THE PACKAGE AND ON ANY CORRESPONDENCE. The purchaser is responsible for shipping charges, freight, insurance and proper packaging to prevent damage in transit.

FOR WARRANTY RETURNS, REPAIRS, CONSULT OMEGA for current repair charges. Have the following information available BEFORE CONTACTING OMEGA: 1. Purchase Order number under which the product was purchased. 2. Model and serial number of the product under warranty, and any accessories. 3. Specific problems relative to the product.

OMEGA'S policy is to make tuning changes, not model changes, whenever an improvement is possible. This allows our customers the maximum flexibility in using OMEGA's registered trademark. © Copyright 2003 OMEGA ENGINEERING, INC. All rights reserved. The document may not be copied, photocopied, reproduced, translated, or reduced to any electronic medium or machine-readable form, in whole or in part, without the prior written consent of OMEGA ENGINEERING, INC.

OMEGA.com CANADA: One-Line Service: 1-800-431-0447; Internet e-mail: info@omega.com

Servicing North America: One Omega Drive, Box 4047; Stamford, CT 06907-0047; Tel: (203) 359-1660; FAX: (203) 359-7700; e-mail: info@omega.com

Canada: Laval (Quebec) HTL3A1, Canada; Tel: (514) 856-6928; FAX: (514) 856-6846; e-mail: info@omega.ca

For immediate technical or application assistance: USA: Sales Service: 1-800-426-6343 / 1-800-7C-OMEGA; Customer Service: 1-800-622-2378 / 1-800-622-BEST; Fax: 1-800-431-0447 / 1-800-USA-WHEN; Canada: TELE: 964-064; EASTLINK: 626-8974; CABLE: OMEGA

Mexico: 9716 Berqze; e-mail: csp@omega.com; Tel: (201) 339-7803; Fax: (201) 339-7807; info@omega.com.mx

Servicing Europe: Poshuis 8034, 1180 LA Amstelveen, The Netherlands; Tel: +31 (0)20 6418405; FAX: +31 (0)20 6434643; Toll Free In Benelux: 0800 099334; e-mail: sales@omega.nl

Czech Republic: Fryskova 164, 733 01 Kanižov, Czech Republic; Tel: +420 (0)59 6311899; FAX: +420 (0)59 6311114; Toll Free: 0800-1-66342; e-mail: info@omegacp.cz

France: 11, rue Jacques Cartier, 78280 Coyssoncourt, France; Tel: +33 (0)1 67 37 2900; FAX: +33 (0)1 30 37 5427; Toll Free France: 0800 466 464; e-mail: sales@omega.fr

Germany/Austria: Daimlerstrasse 26, D-75392 Deckenpfrond, Germany; Tel: +49 (0)7056 9398-0; FAX: +49 (0)7056 9398-29; Toll Free in Germany: 0800 639 7678; e-mail: info@omegag.de

United Kingdom: One Omega Drive River Road Technology Centre; M44 5BD, Uttoxeter, Staffordshire; ISO 9002; Tel: +44 (0)161 771 6611; FAX: +44 (0)161 771 6622; e-mail: sales@omega.co.uk

It is the policy of OMEGA to comply with all worldwide safety and EMC/CEA regulations. OMEGA is constantly pursuing certification of its products to the European New Approach Directives. OMEGA will add the CE mark to every appropriate device upon certification.

The information contained in this document is believed to be correct but OMEGA Engineering, Inc. accepts no liability for any errors it contains, and reserves the right to alter specifications without notice. WARNING: These products are not designed for use in, and should not be used for, human applications.

Table with 2 columns: ENVIRONMENT, UNIT(LUX). Rows include design room, general office, lobby, etc., with unit ranges from 2000-1500 to 15-30.

Table with 2 columns: ENVIRONMENT, UNIT(LUX). Rows include precision working, design, research & development department, etc., with unit ranges from 3000-1500 to 75-30.

Table with 2 columns: ENVIRONMENT, UNIT(LUX). Rows include vision examination, operating room, clinic room, etc., with unit ranges from 10000-5000 to 75-30.

Table with 2 columns: ENVIRONMENT, UNIT(LUX). Rows include computer room, classroom, laboratory, etc., with unit ranges from 1500-300 to 75-30.

Table with 2 columns: ENVIRONMENT, UNIT(LUX). Rows include sewing, writing, study desk, etc., with unit ranges from 2000-150 to 75-30.

Table with 2 columns: ENVIRONMENT, UNIT(LUX). Rows include check-out desk, lobby, office, etc., with unit ranges from 1500-750 to 75-30.

INTRODUCTION

This HHLM3 is a portable easy use 3 1/2 digit, compact-sized digital lightmeter designed for simple one hand operation. It provides measure ments in lux and fc units.

The HHLM3 features PEAK-HOLD (60ms pulse light) and DATA-HOLD function. There is a pocket hook and magnetic holder on the back of the unit.

SAFETY INFORMATION

It is recommended that you read the safety and operation instructions before using the lightmeter.

WARNING

- To avoid electric shock, do not operate this product in wet or damp conditions.
- To avoid injury or fire hazard, do not operate this product in an explosive atmosphere.
- To avoid eye injury, wear eye protection if there is a possibility of exposure to high-intensity rays.
- Do not immerse in liquids, clean the sensor head using only a damp cloth.
- Cover sensor head when not in use to extend silicon photodiode sensor life.

SPECIFICATIONS

GENERAL

Display: 3 1/2 digit liquid crystal display (LCD) with maximum reading of 1999.

Overrange:

(OL) is displayed.

Low battery indication:

The "E3" is displayed when the battery voltage drops below the operating level.

Measurement rate:

2.5 times per second, normal.

Operating Environment:

0°C to 50°C at < 75% R.H.

Storage Temperature:

-20°C to 60°C, 0 to 80% R.H. with battery removed from meter.

Accuracy:

Stated accuracy at 23°C ± 5°C, < 75% R.H.

Auto power off:

15 seconds.

Battery:

3 pcs 1.5V (AAA size) included.

Battery Life:

90 hours (continuous) typical.

Dimensions:

152mm(H) x 48mm(W) x 26mm(D).

Weight:

Approx. 2.9 oz. (81.2g) including battery.

ELECTRICAL

Photometric Formulas:

10,764 footcandles=lux (lumens/meter²)

0.0929 lux=footcandles(lumens/foot²)

Range:

20 lux, 200 lux, 2000 lux, 20000 lux

20 fc, 200fc, 2000fc, 20000fc

Resolution:

0.01lux, 0.01fc

Spectral response:

CIE photopic

The CIE photopic curve is an international standard for the color response of the average human eye

Acceptance angle:

f_1 < 2% cosine corrected (150°)

Total accuracy for CIE standard Illuminant A

±(3%/rdg + 10dgt)

CIE standard illuminant A can be realized by means of CIE standard source A, which is defined as: A gas-filled tungsten-filament lamp operating at a correlated colour temperature of 2856K

Temperature Coefficient:

0.1% (specified accuracy)/°C (<18°C or >28°C)

OPERATING INSTRUCTIONS

Push buttons

MEAS (MEASURE) Button

Press "MEAS" button to turn on the meter for measuring illumination. Press "MEAS" button again to turn off the meter.

Range Select Button

Press "RNG" button to select the desired lux range. Each time you press "RNG" button, the range (and the input range annunciator) increments, and a new value is displayed.

DATA HOLD Mode

Press the "HLD" key to enter the Data Hold mode, the "H" annunciator is displayed. When DATA HOLD mode is selected, the lightmeter holds the present readings and stops all further measurements.

Press the "HLD" key again cancels DATA HOLD mode, causing lightmeter to resume taking measurements.

PEAK HOLD Mode


Press "PK" button to toggle in and out of PEAK Hold mode. In the PEAK Hold mode, the "PH" annunciator is displayed.

OPERATION

- Set the power switch to the desired range (use range button) select 20lux(fc), 200lux(fc), 2000lux(fc), 20000lux(fc) range.
- Remove the cover of sensor head.
- Hold the sensor head steady and make certain that the light source completely fills the cosine correction dome.
- Move away from the sensor head to avoid shadowing it.
- Read the illuminance value from the display. If magnitude of lux (or fc) is not known, press "RNG" button to the highest range and reduce the range until a satisfactory reading is obtained.
- Cover the sensor head to extend the sensor life.

APO (Auto power off) Function

Remove rubber cover on front case and slide the switch to right to enable "APO" function, the "A" annunciator is displayed. It will turn off automatically after approximately 15 minutes to lengthen battery life. Slide the switch to left to disable "APO" function.



SPECIAL CONSIDERATIONS

- Keep the plastic domed cosine corrector clean and free of scratches. It may be cleaned with a soft cloth and isopropyl alcohol.
- When light is received from many directions simultaneously, take special care to avoid reflections or shadowing the sensor with your body.
- For best accuracy, repeat the measurement several times to ensure that the light source has remained stable.

The Inverse-square Law

The law states that the illuminance E at a point on a surface varies directly with the intensity I of a point source, and inversely as the square of the distance d between the source and the point. If the surface at the point is normal to the direction of the incident light, the law is expressed by $E=I/d^2$.

Cosine Law

The law that the illuminance on any surface varies as the cosine of the angle of incidence. The angle of incidence θ is the angle between the normal to the surface and the direction of the incident light. The inverse-square law and the cosine law can be combined as $E=I(\cos \theta)/d^2$.

PROCEDURE OF CALIBRATION

Note:

The following calibration procedure should perform only by a qualified technician who have access to the items as following.

Equipment:

A gas-filled tungsten-filament lamp operating at a correlated color temperature of 2856K.

Zero Calibration

Set the function/range to the 2000lux, then cover sensor head adjust VR21 until display reading 00.0±2dgt.

Basic Calibration

Set the function/range to the 2000lux, then apply 1800lux adjust VR10 until the reading 1800.±1dgt.

fc Calibration

Set the function/range to the 200fc, then apply 180fc adjust VR22 until display reading 180.0±2dgt.

MAINTENANCE

Battery Replacement

- Power is supplied by three 1.5V (AAA size) batteries.
- The "E3" appears on the LCD display when replacement is needed. To replace the batteries, remove the screw from the back of the meter and lift off the battery cover.
- Remove the batteries from battery contacts and replace.
- When not in use for long period of time, remove the batteries.
- Don't store in a location with high Temp. or high humidity.

Cleaning

Periodically wipe the case with a damp cloth and detergent, do not use abrasives or solvents.

Wavelength (nm)	V _A CIE Photopic Luminous Efficiency Coefficient	Photopic Lumen/Watt Conversion Factor
380	0.0000	0.05
390	0.0004	0.27
400	0.0011	0.82
410	0.0040	2.73
420	0.0116	7.81
430	0.0230	15.7
440	0.0390	25.9
450	0.0600	40.9
460	0.1000	64.8
470	0.1390	84.8
480	0.2080	142.0
500	0.3230	220.0
510	0.5030	343.0
520	0.7100	484.0
530	0.8620	586.0
540	0.9540	650.0
550	1.0000	683.0
560	0.9650	678.0
570	0.8520	649.0
580	0.6700	583.0
590	0.4570	516.0
600	0.2610	430.0
610	0.1330	343.0
620	0.0690	265.0
630	0.0350	181.0
640	0.01750	119.0
650	0.00810	41.4
660	0.00320	21.8
670	0.00170	11.6
680	0.00092	5.99
690	0.00041	2.78
700	0.00010	0.716
710	0.00005	0.355
720	0.00003	0.170
730	0.00001	0.082
740	0.00001	0.041
750	0.00001	0.041
760	0.00001	0.041