omega.com

OMEGAnet* On-Line Service www.omega.com

Servicing North America:

One Omega Drive, Box 4047
Stamford, CT 06907-0047
Tel: (203) 359-1660
e-mail: infu@omega.com

FAX: (203)359-7700

976 Bergar Laval (Quebec) H7L5A1, Canada UAX Tel: (514) 856-6928 e-mail: info@vmega.ca FAX: (314) 856-6886

for immediate technical or application assistance:

Sales Service: 1-900-826-6342 / 1-800-TC-OMBGA* Customer Service: 1-800-622-2378 / 1-800-622-8BST* Engineering Service: 1-900-672-826 / 1-90012A-WHEN* TELEX: 996404 EASYLINK: 6296994 CABLE: OMBGA

En Español: (001) 203 359-7803 e-mail: espanol@omega.com

e-mail: espanoi@omega.com Fax: (001) 203 359-7807 info@omega.com.mx

Servicing Europe:

Postbus 8034, 1180 LA Amstelveen, The Netherlands
Tel: +31 (0)20 6418405 FAX: +31 (0)20 6434643
Toll Free in Benelux: 0800 0993344 e-mail: sales@omegaeng.nl

Frystaska 184, 733 01 Karviná, Czech Repubic Tel: +420 (0)59 6311899 FAX: +420 (0)59 6311114 Toll Free: 0800-1-66342 e-mail: info@omegasbop.cz

11, ne Jacques Carrier, 78280 Guyancourt, France Tel: +33 (0)1 61 37 2900 FAX: +33 (0)1 30 57 5427 Toll Free Feature; 1980 466 342 e-mail: sales@omegaeng.fr

Daimlerstrasse 26, D-73392 Deckerpfronn, Germany Tel: +49 (0)7026 9398-0 FAX: +49 (0)7026 9398-29 Toll Free in Germany: 0800 639 7678 e-mail: info@nunega.de

One Omega Drive River Bend Technology Centre Northback, Irlam, Maxbester, M44 SBD United Kingdom Tel: +44 (0)161 777 6612 FAX: +44 (0)161 777 6622 e-mail: sales@omega.co.uk

It is the policy of OMEGA to comply with all worktwide safety and EMC/EMI regulations that apply OMEGA is constantly pursuing certification of its products to the European New Approach Direc-tives. OMEGA will add the CE mark to every appropriate devices upon certification.

The information contained in this document is believed to be cor-rect, but OMEGA Engineering, Inc. accepts no liability for any errors it contains, and reserves the right to alter apecifications without notice.

WARNING: These products are not designed for use in, and should not be used for, human applications.

WARRANTY / DISCLAIMER WAS

OMEGA ENGINEETHMO, INC. warrants the unit to be five of defects in materials and workmaneith to repeat the office of the operation of the oper

maximized coverage on the section of the factory by exclusion. If the unit malarization, it must be returned to the factory by exclusion. If the unit malarization factor is the unit malarization factor (AE) number immediately youn phone or written request. Upon examination by CMEGA, if the unit is found to be describe, It will be repaired or replaced at no charge. OMEGA w WARRANTY does not easily to describe sealing from any action of the purchases, including but not limited to malarization, improper instriction, colored charging limits, improper repair, or unauthorized modification. This WARRANTY is VOOD if the unit shows evidence of having been immpreed with or shows archeors of lawing been damaged as a result of excessive commands or comment, heat moletise or vibration; improper apportization, misupolization, misupo

additionally, purchaser will indemnity OMEGA and note OMEGA namive from any liability or damage whateoever arising out of the use of Product(s) in such a manner.

I RETURN REQUESTS / INQUIRIES IIII

Direct all warranty and repair requesta/frquiries to the OMEGA Customer Sanche Operatment BEFORE RETURNING ANY PRODUCTIS) TO OMEGA, PURCHASER MUST GORTAIN AN UTH-ORIZED RETURN (AR) NUMBER FROM OMEGA'S CUSTOMER SERVICE DEPARTMENT (IN ORDER TO AVOID PROCESSING DELIVES) The salgned AR number should then be marked on the outside of the return sociage and on any correspondence. The purchaser is respondable for shipping charges, freight, insurance and proper packaging to prevent breakage in transit.

FOR NON-WARRANTY
REPAIRS, consult OMEGA to

- FOR WARRANTY RETURNS.
 please have the lobowing
 information wantable BEFORE
 contacting OMEGA:
 1. Purchase Order number under
 which the product was
 PURCHASED.
- Model and serial number of the product under warranty.
- Repair Instructions and/or specific problems relative to
- the product, and
 3. Repair instructions and/or specific problems relative to the product. Purchase Order number to cover the COST of the repair
 Model and serial number of current repair charges. Have the following information available BEFORE contacting

OMEGA's policy is to make running changes, not model changes, whenever an improvement is possible. This afforces our customers the latest in technology and engineering OMEGA is registered indensity of OMEGA is registered indensity of OMEGA POLICY (INC. All rights reserved to Copyright 2003 OMEGANE, NAC.

O Copyright 2003 OMEGANE, CHOING, INC. All rights reserved to Copyright 2003 OMEGANE, Protocopied, reproduced, frantisted, or reduced to any detection residence or machine-seadable from, in whose or in part, without the prior written consent of OMEGA ENGINEERING, up.

Where Do I Find Everything I Need for Process Measurement OMEGA...Of Course! and Control?

Shop online at www.omega.com

TEMPERATURE

- Thermocruple, RTD & Thermistor Probes, Connectors, Punels & Assemblies
- Wire: Thermocouple, RTD & Thermistor
- Calibrators & Ice Point References
- Recorders, Controllers & Process Monitors
- 2 Infrared Pyrometers

PRESSURE/STRAIN AND FORCE

- Transducers & Strain Gauges
 Load Cells & Pressure Gauges
 Displacement Transducers
- Instrumentation & Accessories

FLOW/LEVEL

- 2 Rotameters, Gas Mass Flowmeters & Flow

- Air Velocity Indicators
 Turhine/Paddlewheel Systems
 Totalizers & Batch Controllers

PH/CONDUCTIVITY

- 12 pH Electrodes, Testers & Accessories
- 2 Benchtop/Laboratory Meters
- Controllers, Calibrators, Simulators & Pumps
- [2] Industrial pH & Conductivity Equipment

DATA ACQUISITION

- Communications-Based Acquisition Systems Data Acquisition & Engineering Software
- Plug-in Cards for Apple, IBM & Compatibles
- 27 Recorders, Printers & Plotters

HEATERS

- El Heating Cable
- ☑ Cartridge & Strip Heaters
- 🗹 Immersion & Band Heaters
- Flexible Heaters
- 2 Laboratory Heaters

ENVIRONMENTAL MONITORING AND CONTROL

- Metering & Control Instrumentation
- 2 Pumps & Tuhing Refractometers
- D Air, Soil & Water Monitors
- 27 Industrial Water & Wastewater Treatment
 27 pH, Conductivity & Dissolved Oxygen
- Instruments

M3917/0803

三

Shop online at

e-mail: info@omega.com L'ADMEGA"

omega.com





hermometer **Digital UVA HHUVA 1**

INTRODUCTION

simple one hand operation. The meter provides holder on the back of the unit. ties. There is a pocket hook and a magnetic cm² units, MAX-HOLD and DATA-HOLD facilimeasurements in 199.9µW/cm² and 19.99mW/ digit, compact-sized digital UVA designed for This HHUVA1 is a portable easy use 31/3

SAFETY INFORMATION

and operation instructions before using the UVA It is recommended that you read the safety

WARNING

- To avoid injury or fire hazard, do not use this product in an explosive atmosphere.
- To avoid eye injury, wear eye protection if there is a possibility of exposure to highintensity rays.
- Do not immerse in liquids, clean the sensor head using only a damp cloth.
- Cover sensor head when not in use to extend silicon photodiode sensor life.

SPECIFICATIONS

GENERA!

Display:

maximum reading of 1999. 3½ digit and stat display (LCD) with

Overrange:

(OL) is displayed

Low battery Indication:
The " 臼 " is displayed when the battery voltage drops below the operating level.

Measurement rate:

Operating Environment: 2.5 times per second, nominal

0°C to 50°C at < 75% R.H.

Storage Temperature: -20°C to 60°C, 0 to 80% R.H. with battery removed from meter

Battery:

3 pcs 1.5V (AAA size) included

Battery Life:

200 hours (continuous) typical

155mm(H) x 48mm(W) x 24mm(D)

Dimensions:

Approx. 2.9 oz. (81.2g) including battery

ELECTRICAL

Range: 199.9µW/cm² 19.99mW/cm² 1.999mW/cm²

Resolution:

\dashv	1.999mW/cm² 0.001mW/cm²	199.9µW/cm² 0.1µW/cm²	Range Resolution
----------	-------------------------	-----------------------	------------------

Accuracy:

Stated accuracy at 23°C ± 5°C, <75% R.H. ±(4% FS ± 2 dgts) (FS: full scale)

UV sensor spectrum: Band pass 320nm~400nm

Wavelength Peak:

OPERATING INSTRUCTIONS

MEAS (MEASURE) Button Push buttons

Press "MEAS" button to turn on the meter for measuring UVA. Press "MEAS" button again to turn off the meter.

Range Select Button

Press "RNG" button to select the desired range. Each time you press "RNG" button, the range (and the input range annunciator) incremants, and a new value is displayed

DATA HOLD Button

annunciator is displayed. Press "HLD" button to enter the Data Hold mode. In the DATA HOLD mode, the "H"

taking measurements. HOLD mode, causing UVA meter to resume Press the "HLD" button again cancels DATA

MAX HOLD Button

MAX HOLD mode. Press "MAX" button to toggle in and out of

ciator is displayed. In the MAX HOLD mode, the "MAX" annun-

OPERATION

- 1. Press "MEAS" button to turn meter on, and button select 199.9µW/cm², 1.999mW/cm² then set to the desired range (using range 19.99mW/cm² range).
- Remove the cover of sensor head.
- Hold the sensor head steady.
- 4. Read the UVA value from the display. If and reduce the range until a satisfactory button to the highest range 19.99mW/cm² magnitude of UV is not known, press "RNG" reading is obtained.
- 5. Cover sensor head to extend sensor life after
- Press "MEAS" button measure and down the button measure continuously ᇟ

APO (Auto power off) Function

Remove rubber cover on front case and slide the switch to right to enable "APO" function, the "P" annunciator is displayed. It will turn off lengthen battery life. Slide the switch to left to disable "APO" function. automaticaly after approximately 15 minutes to

SPECIAL CONSIDERATIONS

- When UVA is received from many directions simultaneously, take special care to avoid reflection or shadowing the sensor with any-
- several times to ensure that the UV source For best accuracy, repeat the measurement has remained stable.

PROCEDURE OF CALIBRATION

perform only by a qualified for technician who have access to the items as following. The following calibration procedure should

Equipment:

A UVA lamp the wavelength at 365nm

Zero Calibration

then cover sensor head adjust VR3 until display reading 00.0±5dgts Set the function/range to the 19.99mW/cm²,

Basic Calibration

Set the function/range to the 199.9µW/cm², then apply 130.0µW/cm² adjust VR10 until reading 130.0µA/cm² ±(4%FS.±2dgts)

MAINTENANCE

Battery Replacement

- 1. Power is supplied by three 1.5V (AAA size)
- 2. The "合面" appears on the LCD display when teries, remove the screw from the back of the replacement is needed. To replace the batmeter and lift off the battery cover.
- Remove the batteries from battery contacts and replace.
- 4. When not in use for long period of time remove the batteries.
- 5. Don't store in a location with high Temp. or high humidity

Cleaning

and detergent, do not use abrasives or sol-Periodically wipe the case with a damp cloth