



Ω OMEGA™ User's Guide



***Shop online at
omega.com***

***e-mail: info@omega.com
For latest product manuals:
www.omegamanual.info***



CN4000 SERIES Temperature Controllers



omega.com info@omega.com

Servicing North America:

**U.S.A.
Headquarters:**

Omega Engineering, Inc.

Toll-Free: 1-800-826-6342 (USA & Canada only)

Customer Service: 1-800-622-2378 (USA & Canada only)

Engineering Service: 1-800-872-9436 (USA & Canada only)

Tel: (203) 359-1660

Fax: (203) 359-7700

e-mail: info@omega.com

For Other Locations Visit omega.com/worldwide

SPECIFICATIONS

Input Type	Thermocouple						RTD
	K	S	R	E	J	N	PT100
Range °C/ °F	0 to1300 °C 32 to 2372 °F	0 to1700°C 32 to 3092 °F	0 to1600°C 32 to 2412 °F	0 to1000°C 32 to 1832 °F	0 to1200°C 32 to 2192 °F	0 to 1300°C 32 to 2372 °F	-200 to 800°C -328 to 1472 °F

Accuracy: CN 4116/CN414/CN418	0.3%FS ± 1°C/1.8°F
CN4216/CN424/CN428	0.3%FS ± 0.1°C/0.18°F

Temperature Display Resolution CN 4116/CN414/CN418	1°C/1°F
CN4216/CN424/CN428	0.1°C/0.1°F

Control Method	ON / OFF Control
	AI PID Control with Auto Tuning (AT)

Output Type	Relay Output (1A/250VAC)
	Voltage Output for SSR(12V/30mA)

Alarm (Modularization)	Limit High / Low
	High deviation/Low deviation

Supply Voltage	100~240VAC (-15%, +10%), or 24VDC
	50 to 60Hz

Power Consumption	≦ 3W
--------------------------	------

Operating Environments	Temperature: -10 to +60°C / 14 to 140°F
	Humidity: 0~90RH%

Electromagnetic compatibility (EMC)	IEC61000-4-4: ± 4KV/5KHz IEC61000-4-5: 4KV
--	---

PARAMETER AND SETTING

Field parameter table (Primary parameters)

Code	Description	Remarks	Setting Range	Default																														
HIAL	High limit alarm	Alarm on when PV>HIAL alarm off when PV<HIAL- AHYS	-999~+3000	3000																														
LoAL	Low limit alarm	Alarm on when PV<LoAL; alarm off when PV>LoAL + AHYS	-999~+3000	-999																														
HdAL	Deviation high alarm	Alarm on when PV-SV>HdAL; alarm off when PV-SV<HdAL - AHYS	-999~+3000	3000																														
LdAL	Deviation low alarm	Alarm on when PV-SV<LdAL; alarm off when PV-SV>LdAL + AHYS	-999~+3000	-999																														
Loc	Parameter Lock	<table border="1"> <thead> <tr> <th>Loc</th> <th>Auto Tuning</th> <th>SV</th> <th>Primary Parameter</th> <th>Secondary Parameter</th> </tr> </thead> <tbody> <tr> <td>0</td> <td></td> <td></td> <td></td> <td>X</td> </tr> <tr> <td>1</td> <td>X</td> <td></td> <td></td> <td>X</td> </tr> <tr> <td>2</td> <td>X</td> <td>X</td> <td></td> <td>X</td> </tr> <tr> <td>3</td> <td>X</td> <td>X</td> <td>X</td> <td>X</td> </tr> <tr> <td>808</td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Loc	Auto Tuning	SV	Primary Parameter	Secondary Parameter	0				X	1	X			X	2	X	X		X	3	X	X	X	X	808					0~255	0
		Loc	Auto Tuning	SV	Primary Parameter	Secondary Parameter																												
		0				X																												
		1	X			X																												
		2	X	X		X																												
		3	X	X	X	X																												
808																																		
: allow to modify data or execute AT																																		
X : not allow to modify data or execute AT																																		

System parameter table (Secondary parameters)

Set the parameter 'Loc'=808 to enter:

AHYS	Alarm Hysteresis	Avoid frequent alarm on-off action because of the fluctuation of PV	0~200	2																								
AOP	Alarm output assignment	<table border="1"> <tr> <td>Alarm Output to</td> <td>LdAL (x 1000)</td> <td>HdAL (x100)</td> <td>LoAL (x10)</td> <td>HIAL (x1)</td> </tr> <tr> <td>None</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> </tr> <tr> <td>AL1</td> <td>1</td> <td>1</td> <td>1</td> <td>1</td> </tr> </table> <p>eg: AOP=1101 means LdAL, HdAL and HIAL alarm action output from AL1;LoAL, no alarm action.</p>	Alarm Output to	LdAL (x 1000)	HdAL (x100)	LoAL (x10)	HIAL (x1)	None	0	0	0	0	AL1	1	1	1	1	0~1111	1111 or according to fixed module									
Alarm Output to	LdAL (x 1000)	HdAL (x100)	LoAL (x10)	HIAL (x1)																								
None	0	0	0	0																								
AL1	1	1	1	1																								
Ctrl	Control mode	onof : On-off control APId : AI PID control, high precision and no-overshot	onof, APId	APId																								
Act	NA	No any function on this model.	rE/dr/ rEbA/drba	rE																								
P	Proportion band	Proportion band in PID with unit °C or °F	1~999	30																								
I	Time of Integral	No integral effect when I=0	0~9999 Sec	100 s																								
d	Time of derivative	No derivative effect when d=0	0~999.9 Sec	50.0s																								
Ctl	Control period	Small value can improve control accuracy. For SSR output, generally 0.5 to 3 seconds. Large value can increase using life of relay. For Relay output, generally 15 to 40 seconds.	0.5~120 Sec	2 s Or 20 s																								
CHYS	Control hysteresis	CHYS is used for ON-OFF Control. PV > SV, Output turns OFF; PV<SV-CHYS, Output turns ON.	0~200	2																								
InP	Input specification	<table border="1"> <thead> <tr> <th>InP</th> <th>Input spec.</th> <th>InP</th> <th>Input spec.</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>K</td> <td>1</td> <td>S</td> </tr> <tr> <td>2</td> <td>R</td> <td>3</td> <td>Spare</td> </tr> <tr> <td>4</td> <td>E</td> <td>5</td> <td>J</td> </tr> <tr> <td>6</td> <td>Spare</td> <td>7</td> <td>N</td> </tr> <tr> <td>8-20</td> <td>Spare</td> <td>21</td> <td>Pt100</td> </tr> </tbody> </table>	InP	Input spec.	InP	Input spec.	0	K	1	S	2	R	3	Spare	4	E	5	J	6	Spare	7	N	8-20	Spare	21	Pt100	1~21	0
InP	Input spec.	InP	Input spec.																									
0	K	1	S																									
2	R	3	Spare																									
4	E	5	J																									
6	Spare	7	N																									
8-20	Spare	21	Pt100																									
dPt	Resolution (only for CN42 series)	0 : 1 °C/°F 0.0 : 0.1 °C/°F		0.0																								

Scb	Input Shift	Parameter Scb is used to make input shift to compensate the error produced by sensor or input signal itself. PV-after-compensation= PV-before-compensation + Scb.	-199~ +400	0
FILt	PV input filter	The value of FILt will determine the ability of filtering noise. When a large value is set, the measurement input is stabilized but the response speed is slow. Generally, if great interference exists, then you can increase parameter "FILt" gradually to make momentary fluctuation of measured value less than 2 to 5. When the meter of the instrument is being examined at laboratory, "FILt" should be set to 0 or 1 to short the response time.	0~40	1
Fru	Selection of power frequency and temperature scale	50C: 50Hz, °C 50F: 50Hz, °F 60C: 60Hz, °C 60F: 60Hz, °F	50C, 50F, 60C, 60F	50C
SPL	Low limit of SV		-999~ 3000	0
SPH	Upper limit of SV		-999~ 3000	400


SYMBOL DESCRIPTIONS

Symbol	Description
orAL	Input specification setting is incorrect Or Input wiring is disconnected/ thermocouple problem Or Short circuited
HIAL	High limit alarm
LoAL	Low limit alarm
HdAL	Deviation high alarm
LdAL	Deviation low alarm
EErr	IC Software error
8888	IC Software error


INSTRUMENT INSTALLATION AND WIRING

Wiring graph for instruments with dimension 1/4 DIN; 1/8 DIN Vertical and Horizontal

Note: The compensation wires for different kinds of thermocouple are different, and should be directly connect to the terminals. Connecting the common wire between the compensation wire and the terminals will cause measurement error.




Wiring graph for 1/16 DIN dimension instruments:



DISPLAY AND OPERATIONS

- ① Upper display window, displays PV, parameter code, etc.
- ② Lower display window, displays SV, parameter value, or alarm
- ③ Setup key, for accessing parameter table and conforming parameter modification.
- ④ Data shift key, and auto tuning.
- ⑤ Data decrease key
- ⑥ Data increase key
- ⑦ LED indicator. MAN, PRG, MIO, COM, OP2, AL2, AU1 and AU2 Com indicators is non-applicable.



OP1 and AL1 will indicate I/O operation of the corresponding module.

Basic display status:

When power on, the upper display window of the instrument shows the process value (PV), and the lower window shows the set-point (SV). This status is called basic display status.

When the input signal is out of the measurable range (for example, the thermocouple or RTD circuit is break, or input specification sets wrong), the upper display window will alternately display “orAL” and the high limit or the low limit of PV, and the instrument will automatically stop output. If the lower display window alternately display “HIAL”, “LoAL”, “HdAL” or “LdAL”, it means high limit alarm, low limit alarm, deviation high alarm, and deviation low alarm happening.

OPERATION DESCRIPTION

- **Set Value Setting:**

In basal display status, if the parameter lock "Loc" isn't locked, we can set setpoint (SV) by pressing \leftarrow , \downarrow or \uparrow . Press \downarrow key to decrease the value, \uparrow key to increase the value, and \leftarrow key to move to the digit expected to modify. Keep pressing \downarrow or \uparrow , the speed of decreasing or inscreasing value get quick. The range of setpoint is between the parameter SPL and SPH. The default range is 0~400.

- **Parameter Setting:**

In basal display status, press ⌂ and hold for about 2 seconds can access Field Parameter Table. Pressing ⌂ can go to the next parameter; pressing \leftarrow , \downarrow or \uparrow can modify a parameter. Press and hold \leftarrow can return to the preceding parameter. Press \leftarrow (don't release) and then press ⌂ key simultaneously can escape from the parameter table. The instrument will escape automatically from the parameter table if no key is pressed within 30 seconds. Setting Loc=808 and then press ⌂ can access System Parameter Table.

- **AI artificial intelligence control and auto tuning**

When AI artificial intelligence control method is chosen (Ctrl=APId), the PID parameters can be obtained by running auto-tuning. In basal display status, press \leftarrow for 2 seconds, the "At" parameter will appear. Press \uparrow to change the value of At from "oFF" to "on", then press ⌂ to active the auto-tuning process. During auto tuning, the instrument executes on-off control. After 2-3 times of on-off action, the instrument will obtain the optimal control parameter value. If you want to escape from auto tuning status, press and hold the \leftarrow key for about 2 seconds until the "At" parameter appear again. Change "At" from "on" to "oFF", press ⌂ to confirm, then the auto tuning process will be cancelled.

Note 1: If the setpoint is different, the parameters obtained from auto-tuning are possible different. So you'd better set setpoint to an often-used value or middle value first, and then start auto-tuning. For the ovens with good heat preservation, the setpoint can be set at the highest applicable temperature. Depending on the system, the auto-tuning time can be from several seconds to several hours.

Note 2: Parameter Ctl (on-off differential, control hysteresis) has influence on the accuracy of auto-tuning. Generally, the smaller the value of Ctl, the higher the precision of auto tuning. But Ctl parameter value should be large enough to prevent the instrument from error action around setpoint due to the oscillation of input. Ctl is recommended to be 2.0.

Note 3: The instrument has the function of self-learning. It is able to learn the process while working. The control effect at the first run after auto tuning is probably not perfect, but excellent control result will be obtained after a period of time because of self-learning.

WARRANTY/DISCLAIMER

OMEGA ENGINEERING, INC. warrants this unit to be free of defects in materials and workmanship for a period of **25 months** from date of purchase. OMEGA's WARRANTY adds an additional one (1) month grace period to the normal **two (2) year product warranty** to cover handling and shipping time. This ensures that OMEGA's customers receive maximum coverage on each product.

If the unit malfunctions, it must be returned to the factory for evaluation. OMEGA's Customer Service Department will issue an Authorized Return (AR) number immediately upon phone or written request. Upon examination by OMEGA, if the unit is found to be defective, it will be repaired or replaced at no charge. OMEGA's WARRANTY does not apply to defects resulting from any action of the purchaser, including but not limited to mishandling, improper interfacing, operation outside of design limits, improper repair, or unauthorized modification. This WARRANTY is VOID if the unit shows evidence of having been tampered with or shows evidence of having been damaged as a result of excessive corrosion; or current, heat, moisture or vibration; improper specification; misapplication; misuse or other operating conditions outside of OMEGA's control. Components in which wear is not warranted, include but are not limited to contact points, fuses, and triacs.

OMEGA is pleased to offer suggestions on the use of its various products. However, OMEGA neither assumes responsibility for any omissions or errors nor assumes liability for any damages that result from the use of its products in accordance with information provided by OMEGA, either verbal or written. OMEGA warrants only that the parts manufactured by the company will be as specified and free of defects. OMEGA MAKES NO OTHER WARRANTIES OR REPRESENTATIONS OF ANY KIND WHATSOEVER, EXPRESSED OR IMPLIED, EXCEPT THAT OF TITLE, AND ALL IMPLIED WARRANTIES INCLUDING ANY WARRANTY OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE ARE HEREBY DISCLAIMED. LIMITATION OF LIABILITY: The remedies of purchaser set forth herein are exclusive, and the total liability of OMEGA with respect to this order, whether based on contract, warranty, negligence, indemnification, strict liability or otherwise, shall not exceed the purchase price of the component upon which liability is based. In no event shall OMEGA be liable for consequential, incidental or special damages.

CONDITIONS: Equipment sold by OMEGA is not intended to be used, nor shall it be used: (1) as a "Basic Component" under 10 CFR 21 (NRC), used in or with any nuclear installation or activity; or (2) in medical applications or used on humans. Should any Product(s) be used in or with any nuclear installation or activity, medical application, used on humans, or misused in any way, OMEGA assumes no responsibility as set forth in our basic WARRANTY/DISCLAIMER language, and, additionally, purchaser will indemnify OMEGA and hold OMEGA harmless from any liability or damage whatsoever arising out of the use of the Product(s) in such a manner.

RETURN REQUESTS/INQUIRIES

Direct all warranty and repair requests/inquiries to the OMEGA Customer Service Department. BEFORE RETURNING ANY PRODUCT(S) TO OMEGA, PURCHASER MUST OBTAIN AN AUTHORIZED RETURN (AR) NUMBER FROM OMEGA'S CUSTOMER SERVICE DEPARTMENT (IN ORDER TO AVOID PROCESSING DELAYS). The assigned AR number should then be marked on the outside of the return package and on any correspondence.

The purchaser is responsible for shipping charges, freight, insurance and proper packaging to prevent breakage in transit.

FOR **WARRANTY** RETURNS, please have the following information available BEFORE contacting OMEGA:

1. Purchase Order number under which the product was PURCHASED,
2. Model and serial number of the product under warranty, and
3. Repair instructions and/or specific problems relative to the product.

FOR **NON-WARRANTY** REPAIRS, consult OMEGA for current repair charges. Have the following information available BEFORE contacting OMEGA:

1. Purchase Order number to cover the COST of the repair,
2. Model and serial number of the product, and
3. Repair instructions and/or specific problems relative to the product.

OMEGA's policy is to make running changes, not model changes, whenever an improvement is possible. This affords our customers the latest in technology and engineering.

OMEGA is a trademark of OMEGA ENGINEERING, INC.

© Copyright 2018 OMEGA ENGINEERING, INC. All rights reserved. This document may not be copied, photocopied, reproduced, translated, or reduced to any electronic medium or machine-readable form, in whole or in part, without the prior written consent of OMEGA ENGINEERING, INC.

Where Do I Find Everything I Need for Process Measurement and Control? **OMEGA...Of Course!** *Shop online at omega.com*

TEMPERATURE

- ☑ Thermocouple, RTD & Thermistor Probes, Connectors, Panels & Assemblies
- ☑ Wire: Thermocouple, RTD & Thermistor
- ☑ Calibrators & Ice Point References
- ☑ Recorders, Controllers & Process Monitors
- ☑ Infrared Pyrometers

PRESSURE, STRAIN AND FORCE

- ☑ Transducers & Strain Gages
- ☑ Load Cells & Pressure Gages
- ☑ Displacement Transducers
- ☑ Instrumentation & Accessories

FLOW/LEVEL

- ☑ Rotameters, Gas Mass Flowmeters & Flow Computers
- ☑ Air Velocity Indicators
- ☑ Turbine/Paddlewheel Systems
- ☑ Totalizers & Batch Controllers

pH/CONDUCTIVITY

- ☑ pH Electrodes, Testers & Accessories
- ☑ Benchtop/Laboratory Meters
- ☑ Controllers, Calibrators, Simulators & Pumps
- ☑ Industrial pH & Conductivity Equipment

DATA ACQUISITION

- ☑ Communications-Based Acquisition Systems
- ☑ Data Logging Systems
- ☑ Wireless Sensors, Transmitters, & Receivers
- ☑ Signal Conditioners
- ☑ Data Acquisition Software

HEATERS

- ☑ Heating Cable
- ☑ Cartridge & Strip Heaters
- ☑ Immersion & Band Heaters
- ☑ Flexible Heaters
- ☑ Laboratory Heaters

ENVIRONMENTAL MONITORING AND CONTROL

- ☑ Metering & Control Instrumentation
- ☑ Refractometers
- ☑ Pumps & Tubing
- ☑ Air, Soil & Water Monitors
- ☑ Industrial Water & Wastewater Treatment
- ☑ pH, Conductivity & Dissolved Oxygen Instruments