





User's Guide



Shop online at

omega.com® CEOMEGA*.

omega.com

e-mail: info@omega.com For latest product manuals: omegamanual.info



MADE IN TAIWAN

HHM250 AC Clamp Meter



OMEGAnet® Online Service omega.com

Internet e-mail info@omega.com

Servicing North America:

U.S.A.: Omega Engineering, Inc. One Omega Drive, P. O. Box 4047

ISO 9001 Certified Stamford CT 06907-0047 USA

Toll-Free: 1-800-826-6342 Tel: (203) 359-1660 FAX: (203) 359-7700 e-mail: info@omega.com

Canada: 976 Bergar

Laval (Quebec), Canada H7L 5A1

Toll-Free: 1-800-826-6342 TEL: (514) 856-6928 FAX: (514) 856-6886 e-mail: info@omega.ca

For immediate technical or application assistance:

U.S.A. and Canada: Sales Service: 1-800-826-6342/1-800-TC-OMEGA®

Customer Service: 1-800-622-2378/1-800-622-BEST®

Engineering Service: 1-800-872-9436/1-800-USA-WHEN®

Mexico: En Español: 001 (203) 359-7803 FAX: (001) 203-359-7

 Mexico:
 En Espan~ol: 001 (203) 359-7803
 FAX: (001) 203-359-7807

 info@omega.com.mx
 e-mail: espanol@omega.com

Servicing Europe:

Benelux: Managed by the United Kingdom Office

Toll-Free: 0800 099 3344 TEL: +31 20 347 21 21 FAX: +31 20 643 46 43 e-mail: sales@omega.nl

Czech Republic: Frystatska 184

733 01 Karviná, Czech Republic

Toll-Free: 0800-1-66342 TEL: +420-59-6311899 FAX: +420-59-6311114 e-mail: info@omegashop.cz

France: Managed by the United Kingdom Office

Toll-Free: 0800 466 342 TEL: +33 (0) 161 37 29 00 FAX: +33 (0) 130 57 54 27 e-mail: sales@omega.fr

Germany/Austria: Daimlerstrasse 26

D-75392 Deckenpfronn, Germany

Toll-Free: 0 800 6397678 TEL: +49 (0) 7059 9398-0 FAX: +49 (0) 7056 9398-29 e-mail: info@omega.de

United Kingdom: OMEGA Engineering Ltd.

ISO 9001 Certified One Omega Drive, River Bend Technology Centre, Northbank

Irlam, Manchester M44 5BD England

Toll-Free: 0800-488-488 TEL: +44 (0)161 777-6611 FAX: +44 (0)161 777-6622 e-mail: sales@omega.co.uk

It is the policy of OMEGA Engineering, Inc.to comply with all worldwide safety and EMC/EMI regulations that apply. OMEGA is constantly pursuing certification of its products to the European New Approach Directives. OMEGA will add the CE mark to every appropriate device upon certification.

The information contained in this document is believed to be correct, but OMEGA accepts no liability for any errors it contains, and reserves the right to alter specifications without notice.

WARNING: These products are not designed for use in, and should not be used for, human applications.

TABLE OF CONTENTS

1.	SAFETY INFORMATION	1
2.	GENERAL SPECIFICATION	1
3.	ELECTRICAL SPECIFICATION	2
	3-1 DIRECT VOLTAGE	2
	3-2 ALTERNATING VOLTAGE	2
	3-3 ALTERNATING CURRENT	2
	3-4 Resistance(Ω)	3
	3-5 CONTINUITY(***))	3
	3-6 Frequency Hz	3
4.	DESCRIPTION OF THE INSTRUMENT	4
	4-1 DESCRIPTION OF THE DISPLAY	4
	4-2 DESCRIPTION OF FRONT AND REAR	5
5.	BUTTON INSTRUCTION	6
	5-1 HOLD FUNCTION	6
	5-2 INRUSH Function	6
	5-3 BACKLIGHT FUNCTION	6
6.	MEASURING INSTRUCTION	6
	6-1 AC VOLTAGE MEASUREMENT	6
	6-2 DC VOLTAGE MEASUREMENT	7
	6-3 AC CURRENT MEASUREMENT	7
	6-4 RESISTANCE MEASUREMENT	8
	6-5 CONTINUITY MEASUREMENT	8
	6-6 MEASUREMENT OF THE VOLTAGE FREQUENCY	9
	6-7 MEASUREMENT OF THE CURRENT FREQUENCY	9
7.	BATTERY CHANGING	9
8.	MAINTENANCE 1	0

1. A SAFETY INFORMATION

Do not operate the tester if the body of meter or the test lead look broken

Check the main function dial and make sure it is at the correct position before each measurement.

Do not perform resistance and continuity test on a live power system. Do not apply voltage between the test terminals and test terminal to

ground that exceed the maximum limit record in this manual. Keep the fingers after the protection ring when measuring through the test lead.

Chang the battery when the symbol appears to avoid incorrect data

Environmental Conditions

Operation Temperature: 0°C to 40°C(32°F to 104°F): < 70 % RH Storage Temperature: -10°C to 60°C(14°F to 140°F): < 80 % RH

Explanation Symbols

	۸	
_	Λ	١
L	:	_

Attention refer to operation Instructions.



Dangerous voltage may be present at terminals.

_	
_	

This instrument has double insulation.

Approvals: **€** EN61010 600V CAT III

2. GENERAL SPECIFICATION

Digital Display:

4 digital liquid crystal(LCD), Maximum reading 6600.

Polarity:

When a negative signal is applied, the signal appears.

Low Battery Indication:

When the battery is under the proper operation range. • will appear on the LCD display.

Sample Rate:

3 times/sec for digital data.

Power Source:

1.5V size AAA battery X 2

Typical battery Life: 50 hours (without buzzer, backlight function)

Auto Power Off:

If there is no key or dial operation for 15 minutes, the meter will power itself off to save battery consumption. This function can be disabled by press and hold the "*\frac{1}{2}" button then power the unit on.

Over Load:

When the signal larger than the maximum will be show $2 \ L$.

Maximum jaw opening:

Ø 25 mm

Dimensions:

210 x 62 x 36 mm

Weight:

273g (with battery)

Accessories:

Carrying case, Batteries, Test Lead & Instruction Manual.

3. ELECTRICAL SPECIFICATION

Accuracy is to within \pm [% of the reading + number of counts (cts)] in the reference conditions indicated in the appendix.

3-1 Direct Voltage

Range	Resolution	Accuracy
600 V	0.1 V	1% ± 2dgts
•		

Input impedance: 1 M Ω

3-2 Alternating Voltage

Range	Resolution	Accuracy
600 V	0.1 V	1.2% ± 5dgts

Input impedance: 1 $M\Omega$

3-3 Alternating Current

Range	Resolution	Accuracy
66 A	0.01 A	1.9% ± 5dgts
660 A	0.1 A	1.5% ± Jugis

3-4 Resistance (Ω)

Range	Resolution	Accuracy
660 Ω	0,1 Ω	1% ± 2dgts

3-5 Continuity (1)

Range	Resolution	Accuracy
-3))	Ohm function	Buzzer<30Ω

3-6 Frequency Hz

Input impedance: 100 k Ω

For current:

Range	Resolution	Accuracy	Sensitivity
660Hz	0.1 Hz		
6.6KHz	0.001KHz	0.2% ±1 dgt	3 Arms
30KHz	0.01KHz		

For voltage:

Range	Resolution	Accuracy	Sensitivity
660Hz	0.1 Hz		
6.6KHz	0.001KHz	0.2% ±1 dqt	5 Vrms
66KHz	0.01KHz	0.2 /6 ± 1 ugt	5 VIIIIS
100KHz	0.1KHz		


4. DESCRIPTION OF THE INSTRUMENT

4-1 Description Of The Display



0	Auto power off indication	
	Polarity indication	
-	Low battery indication	
~	Alternative source indication	
	Direct source indication	
Α	Current measurement indication	
V Voltage measurement indication		
HOLD Data hold indication		
INRUSH	INRUSH Current Indication	
->>)]	Continuity test indication	
K	Measurement unit	
Ω	Resistance measurement indication	
Hz	Frequency measurement indication	

4-2 Description Of Front And Rear



- 1 Current Sensing Clamp
- ② Clamp opening handle
- ③ Function select dial
- (4) Inrush button
- ⑤ Backlight button
- 6 Data hold button
- 7 LCD display
- ® COM input terminal
- 9 Positive input termina
- 10 Battery cabinet

5. BUTTON INSTRUCTION

5-1 HOLD Function

It is possible to freeze the value displayed by pressing on the "HOLD" button. To deactivate this function, press the "HOLD" button a second time

5-2 INRUSH Function

In ACA range, press INRUSH button will force meter to enter INRUSH mode. Then LCD display "----" until the motor starts up and is detected (10A above). The detection will be done only one time and the output reading will be held. When done, press INRUSH button could enter INRUSH mode again. To exit INRUSH mode, press INRUSH button more than one second. Enter INRUSH mode in automatic ACA range will force the range be locked in higher one.

5-3 BACKLIGHT Function

If you press on the " *\vec{\pi}" button, it will turn on the backlight function. (The backlight is blue light. When you turn on this function, it will light for 1 minutes)

If you press on the " * " button again, the function will be turned off.

6. MEASURING INSTRUCTION

6-1 AC Voltage Measurement:

Switch the main function selector to \vec{v} range.

Connect red test lead to " + " terminal and black one to the " COM " terminal.

Measure the voltage by touching the test lead tips to the test circuit where the value of voltage is needed.

Read the result from the LCD panel.




6-2 DC Voltage Measurement:

Switch the main function selector to $\overline{\mathbf{v}}$ range.

Connect red test lead to " + " terminal and black one to the " COM " terminal.

Measure the voltage by touching the test lead tips to the test circuit where the value of voltage is needed.

Read the result from the LCD panel.



6-3 AC Current Measurement:

Switch the main function selector to A range.


Open the clamp by pressing the jaw-opening handle and insert the cable to be measured into the jaw.

Close the clamp and get the reading from the LCD panel.

Note:

Before this measurement, disconnect the test lead with the meter for safety.

In some occasion that the reading is hard to read, push the HOLD button and read the result later.



6-4 Resistance Measurement

Switch the main function to Ω (region connect red test lead to " + " terminal and black one to the "COM" terminal.

Connect tip of the test leads to the points where the value of the resistance is needed.

Read the result from the LCD panel.

Note:

When taking resistance readings from a circuit system, make sure the power is cut off and all capacitors need to be discharged.




6-5 Continuity Test With Buzzer:

Switch the main function to $\mathfrak{M}\Omega$ range.

Connect red test lead to "+" terminal and black one to the "COM" terminal.

Connect tip of the test leads to the points where the conduction condition needed. If the resistance is under 30Ω , the beeper will sound continuously.



8

6-6 Measurement Of The Voltage Frequency

Switch the main function to **Hz** range. Connect red test lead to "+" terminal and black one to the "COM" terminal. Place the probes in contact with the points where frequency is to be measured.

Read the result on the LCD panel.



6-7 Measurement Of The Current Frequency

Switch the main function to **Hz** range. Open the clamp by pressing the trigger. Encircle the conductor and close the jaws correctly by releasing the trigger. Read the result on the LCD panel.



7. BATTERY CHANGING


When the battery voltage drops below proper operation range the symbol will appear on the LCD display and the battery needs to be changed.

Before changing the battery, switch the main dial to " OFF " and disconnect test leads.

Open the back cover by a screwdriver.

Replace the old batteries with two new 1.5V (AAA Size) battery.

Close the back cover and fasten the screw.



8. MAINTENANCE

★ WARNING!

Before opening the meter, disconnect both test lead and never use the meter before the cover is closed.

CAUTION!

To avoid contamination or static damage, do not touch the circuit board without proper static protection.

8-1 REMARK:

- If the meter is not going to be used for a long time, take out the battery and do not store the meter in high temperature or high humidity environment.
- When taking current measurement, keep the cable at the center of the clamp to get more a ccurate test result.
- Repairs or servicing not covered in this manual should be performed only by qualified personal.

8-2 CLEANING:

Periodically wipe the case with a dry cloth. Do not use abrasives or solvents on these instruments.

NOTES:

WARRANTY/DISCLAIMER

OMEGA ENGINEERING, INC. warrants this unit to be free of defects in materials and workmanship for a period of **13 months** from date of purchase. OMEGA's WARRANTY adds an additional one (1) month grace period to the normal **one** (1) year product warranty to cover handling and shipping time. This ensures that OMEGA's customers receive maximum coverage on each product.

If the unit malfunctions, it must be returned to the factory for evaluation. OMEGA's Customer Service Department will issue an Authorized Return (AR) number immediately upon phone or written request. Upon examination by OMEGA, if the unit is found to be defective, it will be repaired or replaced at no charge. OMEGA's WARRANTY does not apply to defects resulting from any action of the purchaser, including but not limited to mishandling, improper interfacing, operation outside of design limits, improper repair, or unauthorized modification. This WARRANTY is VOID if the unit shows evidence of having been tampered with or shows evidence of having been damaged as a result of excessive corrosion; or current, heat, moisture or vibration; improper specification; misapplication; misuse or other operating conditions outside of OMEGA's control. Components in which wear is not warranted, include but are not limited to contact points, fuses, and triacs.

OMEGA is pleased to offer suggestions on the use of its various products. However, OMEGA neither assumes responsibility for any omissions or errors nor assumes liability for any damages that result from the use of its products in accordance with information provided by OMEGA, either verbal or written. OMEGA warrants only that the parts manufactured by the company will be as specified and free of defects. OMEGA MAKES NO OTHER WARRANTIES OR REPRESENTATIONS OF ANY KIND WHATSOEVER, EXPRESSED OR IMPLIED, EXCEPT THAT OF TITLE, AND ALL IMPLIED WARRANTIES INCLUDING ANY WARRANTY OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE ARE HEREBY DISCLAIMED. LIMITATION OF LIABILITY: The remedies of purchaser set forth herein are exclusive, and the total liability of OMEGA with respect to this order, whether based on contract, warranty, negligence, indemnification, strict liability or otherwise, shall not exceed the purchase price of the component upon which liability is based. In no event shall OMEGA be liable for consequential, incidental or special damages.

CONDITIONS: Equipment sold by OMEGA is not intended to be used, nor shall it be used: (1) as a "Basic Component" under 10 CFR 21 (NRC), used in or with any nuclear installation or activity, or (2) in medical applications or used on humans. Should any Product(s) be used in or with any nuclear installation or activity, medical application, used on humans, or misused in any way, OMEGA assumes no responsibility as set forth in our basic WARRANTY/DISCLAIMER language, and, additionally, purchaser will indemnify OMEGA and hold OMEGA harmless from any liability or damage whatsoever arising out of the use of the Product(s) in such a manner.

RETURN REQUESTS/INQUIRIES

Direct all warranty and repair requests/inquiries to the OMEGA Customer Service Department. BEFORE RETURNING ANY PRODUCT(S) TO OMEGA, PURCHASER MUST OBTAIN AN AUTHORIZED RETURN (AR) NUMBER FROM OMEGA'S CUSTOMER SERVICE DEPARTMENT (IN ORDER TO AVOID PROCESSING DELAYS). The assigned AR number should then be marked on the outside of the return package and on any correspondence.

The purchaser is responsible for shipping charges, freight, insurance and proper packaging to prevent breakage in transit.

FOR **WARRANTY** RETURNS, please have the following information available BEFORE contacting OMEGA:

- Purchase Order number under which the product was PURCHASED,
- 2. Model and serial number of the product under warranty, and
- Repair instructions and/or specific problems relative to the product.

FOR **NON-WARRANTY** REPAIRS, consult OMEGA for current repair charges. Have the following information available BEFORE contacting OMEGA:

- Purchase Order number to cover the COST of the repair,
- 2. Model and serial number of the product, and
- Repair instructions and/or specific problems relative to the product.

OMEGA's policy is to make running changes, not model changes, whenever an improvement is possible. This affords our customers the latest in technology and engineering.

OMEGA is a registered trademark of OMEGA ENGINEERING, INC.

© Copyright 2008 OMEGA ENGINEERING, INC. All rights reserved. This document may not be copied, photocopied, reproduced, translated, or reduced to any electronic medium or machine-readable form, in whole or in part, without the prior written consent of OMEGA ENGINEERING, INC.

Where Do I Find Everything I Need for Process Measurement and Control? OMEGA...Of Course!

Shop online at omega.comsm

TEMPERATURE

- Thermocouple, RTD & Thermistor Probes, Connectors, Panels & Assemblies
- Wire: Thermocouple, RTD & Thermistor
- ☑ Calibrators & Ice Point References
- Recorders, Controllers & Process Monitors
- ☑ Infrared Pyrometers

PRESSURE, STRAIN AND FORCE

- Transducers & Strain Gages
- Load Cells & Pressure Gages
- Displacement Transducers
- ☑ Instrumentation & Accessories

FLOW/LEVEL

- ☑ Rotameters, Gas Mass Flowmeters & Flow Computers
- Air Velocity Indicators
- ☑ Turbine/Paddlewheel Systems
- ☑ Totalizers & Batch Controllers

pH/CONDUCTIVITY

- ☑ Benchtop/Laboratory Meters
- Controllers, Calibrators, Simulators & Pumps
- Industrial pH & Conductivity Equipment

DATA ACQUISITION

- Data Acquisition & Engineering Software
- Communications-Based Acquisition Systems
- Plug-in Cards for Apple, IBM & Compatibles
- Datalogging Systems
- Recorders, Printers & Plotters

HEATERS

- Heating Cable
- Cartridge & Strip Heaters
- ☑ Immersion & Band Heaters
- Flexible Heaters
- Laboratory Heaters

ENVIRONMENTAL MONITORING AND CONTROL

- ✓ Metering & Control Instrumentation
- ☑ Refractometers
- Pumps & Tubing
- Air. Soil & Water Monitors
- ☑ Industrial Water & Wastewater Treatment
- pH, Conductivity & Dissolved Oxygen Instruments