

# User's Guide



*Shop online at*

**omega.com<sup>®</sup>**  
Ω OMEGA<sup>®</sup>

*omega.com*

*e-mail: info@omega.com*


*For latest product manuals:*

*omegamanual.info*



# PSW1000

## Operating Instructions Dual Pressure Switch





**OMEGAnet® Online Service**  
**omega.com**

**Internet e-mail**  
**info@omega.com**

### **Servicing North America:**

**U.S.A.:**  
ISO 9001 Certified  
 One Omega Drive, P.O. Box 4047  
 Stamford, CT 06907-0047  
 TEL: (203) 359-1660  
 FAX: (203) 359-7700  
 e-mail: info@omega.com

**Canada:**  
 976 Bergar  
 Laval (Quebec) H7L 5A1, Canada  
 TEL: (514) 856-6928  
 FAX: (514) 856-6886  
 e-mail: info@omega.ca

### **For immediate technical or application assistance:**

**U.S.A. and Canada:** Sales Service: 1-800-826-6342/1-800-TC-OMEGA®  
 Customer Service: 1-800-622-2378/1-800-622-BEST®  
 Engineering Service: 1-800-872-9436/1-800-USA-WHEN®

**Mexico:**  
 En Español: (001) 203-359-7803  
 e-mail: espanol@omega.com  
 FAX: (001) 203-359-7807  
 info@omega.com.mx

### **Servicing Europe:**

**Czech Republic:** Frystatska 184, 733 01 Karviná, Czech Republic  
 TEL: +420 (0)59 6311899  
 FAX: +420 (0)59 6311114  
 Toll Free: 0800-1-66342  
 e-mail: info@omegashop.cz


**Germany/Austria:** Daimlerstrasse 26, D-75392 Deckenpfronn, Germany  
 TEL: +49 (0)7056 9398-0  
 FAX: +49 (0)7056 9398-29  
 Toll Free in Germany: 0800 639 7678  
 e-mail: info@omega.de

**United Kingdom:**  
ISO 9002 Certified  
 One Omega Drive, River Bend Technology Centre  
 Northbank, Irlam, Manchester  
 M44 5BD United Kingdom  
 TEL: +44 (0)161 777 6611  
 FAX: +44 (0)161 777 6622  
 Toll Free in United Kingdom: 0800-488-488  
 e-mail: sales@omega.co.uk

It is the policy of OMEGA Engineering, Inc. to comply with all worldwide safety and EMC/EMI regulations that apply. OMEGA is constantly pursuing certification of its products to the European New Approach Directives. OMEGA will add the CE mark to every appropriate device upon certification.

The information contained in this document is believed to be correct, but OMEGA accepts no liability for any errors it contains, and reserves the right to alter specifications without notice.

**WARNING:** These products are not designed for use in, and should not be used for, human applications.




# 1. Product Description

## Intended Applications

- The dual pressure switch is a device to monitor system pressure and has up to two switching outputs and one analog output.
- The instruments must only be installed in systems where the maximum pressure Pmax or the maximum temperature Tmax is not exceeded (according to the values on the type label).
- Attention: This device is not designed to be used as the only safety relevant element in pressurized systems according PED 97/23/EC.

## Dimensions (in mm)



PSW1000

# 2. Starting operations


**Only assemble or disassemble the device when depressurized!**


## Connecting the switch

- Mount the pressure switch from bottom to the fitting with a wrench hex 19 (1/4") resp. hex 22 with 45 Nm torque.
- Electrical connection depends on the type of pressure switch (see type label) according to the chart below (connection chart plug 2 for interface see page 4).
- When display is adjusted (rotatable version only) the unit has to be fixed at the front side with an allen screw and and allen key 1,5 mm (torque = 3 Nm).

### Electrical connections plug 1 (standard) and power supply

Plug	PG9 with cable	Model with 1 switching output	Model with 2 switching outputs	Model with 1 switching output and 1 analog output	Model with 2 switching outputs and 1 analog output
M 12 x 1 4-pin / 5-pin	LifYY11Y 4 / 5x0,25mm <sup>2</sup>				
Pin 1	Brown	18...32 V DC	18...32 V DC	18...32 V DC	18...32 V DC
Pin 2	White	-	SP2 0,5 A max.	analog 4...20 mA/ 0...10 V DC	analog 4...20 mA/ 0...10 V DC
Pin 3	Blue	0 V	0 V	0 V	0 V
Pin 4	Black	SP1 0,5 A max.	SP1 0,5 A max.	SP1 0,5 A max.	SP1 0,5 A max.
Pin 5	Grey	-	-	-	SP2 0,5 A max.







List of functions:

(xxxx = 125% f. s.)

Dialog item	Value	Description
MENU	-1...9999	Primary display, e.g. the value selected in the DISP menu appears
DISP	.....	Display value which should be permanently in the display: act actually measured value sp1 switching point SP1 sp2 switching point SP2 max maximum peak value min minimum peak value
ACT.	-1...9999	Display of actually measured value in bar
UNIT	bar psi psi HPa mbar	Fixing the unit bar = bar                      The unit is shown in the display appr. psi x = psi x 10              every 30 sec. for appr. 5 sec. psi = psi HPa = Hekto-Pascal mbar = millibar
SP.1	.....	none switching output deactivated wind window technology stnd standard evaluation SP2 erro error output
ON-1	-1 ... xxxx	Switch-on point for SP1; if the ON value is smaller than the OFF value the switching point evaluation is falling
OFF-1	-1 ... xxxx	Switch-off point for SP1
DLY1	0,0s...9,9s	Switch-on / switch-off delay for SP1 in seconds
INV-1	.....	Inversion of switching output SP1 hlfs high-level-fail-save (normally open function) llfs low-level-fail-save (normally closed function)
SP.2	.....	none switching output deactivated wind window technology stnd standard evaluation SP2 erro error output
ON-2	-1 ... xxxx	Switch-on point for SP2; if the ON value is smaller than the OFF value the switching point evaluation is falling
OFF-2	-1 ... xxxx	Switch-off point for SP2
DLY2	0,0s...9,9s	Switch-on / switch-off delay for SP2 in seconds
INV-2	-----	Inversion of switching output SP2 hlfs high-level-fail-save (normally open function) llfs low-level-fail-save (normally closed function)
MAX	-1 ... xxxx	Display of peak value „Max“ (xxxx: = max. 125% f. s.)
CLRH	-----	Delete the maximum value memory ----- no deletion clr delete value



CDLY	0,0s...9,9s	Time setting to delete the maximum value memory after switching point SP1 is reached (manual deletion is still possible)
MIN	-1 ... xxxx	Display of peak value "Min"
CLRL	-----	Delete the minimum value memory ----- no deletion clr delete value
OFFS	-9,9 ...+xx	Measured value offset in bar
CUT	0,0 ... +xx	Cut-off. e.g. signal suppression at measuring range start in bar
DLDS	0,0 ... 9,9s	Time delay for currently displayed value in seconds
ERRC	-----	Error messages: 0: -ok- no error 1: max exceeding pos. measuring range 2: min exceeding neg. measuring range 3: dig1 switching output 1 error 4: dig2 switching output 2 error 5: anao analog output error 6: sens sensor error 7: data data error (EEProm) 8: prog program error 9: cal calibration error
V7.X	Lev0...Lev2	Programming lock: Version display with actual input level: 0: only display of operating parameters, no changes possible 1: only switching points can be set ("max" and "min" memories) 2: release user level (all operating parameters for customer)
LITH	20 ... 100	Change display brightness 20...100% (only for units with Dot-Matrix display)
AOZS (only V7.X)	0 ... 9999	Scale the analog output - start value (e. g. 0 bar = 4 mA)
AOFS	0 ... 9999	Scale the analog output - end value (e. g. 400 bar = 20 mA) (output signal start value always corresponds to the display initial value, e. g. 0 bar = 4mA) Maximum turn-down 4 : 1, i.e. at values below 25 % of the measuring range the analog output is switched off
STNO	-----	Enter the station number at Profibus DP
RECL	-----	SHRT short profile 8 byte LONG long profile 32 byte selection of the Profibus-protocol
CODE	000...999	Enter the code level: Changes: Lev1: 471 (up + down five seconds) Lev1-Lev0 Lev2: 740 (up + down + M five seconds) Lev2-Lev0 Lev0: 999
OPT (only V7.X)	-----	Display of the unit options



## Operation:

The pressure switch should be installed and operated only by authorized persons. After being switched on the PSW1000 runs through a self-test. The device is menu operated and configured with three keys on the front.

With the "M" key (= mode) you change between the dialog values and the adjusted / actual values. With the keys "▲" = up and "▼" = down you change between the dialog values in the menu or change the values / functions in the menus (see below: "List of functions").


If the dialog is not continued within two minutes the device automatically returns to the measuring mode. When the programming lock is entered, "LOCK" appears in the display when an attempt is made to change values.

## Programming:

The setting menu is activated with the mode key. The dialog items are selected with the "▲" and "▼" keys. If the mode key is pressed again the corresponding value for the dialog item is shown and can be altered with the "▲" and "▼" keys. If the dialog with the unit is not continued within two minutes the device auto-matically returns to the measuring mode without accepting the new values.

To terminate programming more quickly, you can switch back to the measuring mode (primary menu) from any item in the menu by holding the M-key pressed for five seconds.

If the programming lock has been activated, the values can be shown, but no changes made, i.e. when Level 0 is active ("LOCK" appears in the display when an attempt is made to change values).





## WARRANTY/DISCLAIMER

OMEGA ENGINEERING, INC. warrants this unit to be free of defects in materials and workmanship for a period of **13 months** from date of purchase. OMEGA's WARRANTY adds an additional one (1) month grace period to the normal **one (1) year product warranty** to cover handling and shipping time. This ensures that OMEGA's customers receive maximum coverage on each product.

If the unit malfunctions, it must be returned to the factory for evaluation. OMEGA's Customer Service Department will issue an Authorized Return (AR) number immediately upon phone or written request. Upon examination by OMEGA, if the unit is found to be defective, it will be repaired or replaced at no charge. OMEGA's WARRANTY does not apply to defects resulting from any action of the purchaser, including but not limited to mishandling, improper interfacing, operation outside of design limits, improper repair, or unauthorized modification. This WARRANTY is VOID if the unit shows evidence of having been tampered with or shows evidence of having been damaged as a result of excessive corrosion; or current, heat, moisture or vibration; improper specification; misapplication; misuse or other operating conditions outside of OMEGA's control. Components in which wear is not warranted, include but are not limited to contact points, fuses, and triacs.

**OMEGA is pleased to offer suggestions on the use of its various products. However, OMEGA neither assumes responsibility for any omissions or errors nor assumes liability for any damages that result from the use of its products in accordance with information provided by OMEGA, either verbal or written. OMEGA warrants only that the parts manufactured by the company will be as specified and free of defects. OMEGA MAKES NO OTHER WARRANTIES OR REPRESENTATIONS OF ANY KIND WHATSOEVER, EXPRESSED OR IMPLIED, EXCEPT THAT OF TITLE, AND ALL IMPLIED WARRANTIES INCLUDING ANY WARRANTY OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE ARE HEREBY DISCLAIMED. LIMITATION OF LIABILITY: The remedies of purchaser set forth herein are exclusive, and the total liability of OMEGA with respect to this order, whether based on contract, warranty, negligence, indemnification, strict liability or otherwise, shall not exceed the purchase price of the component upon which liability is based. In no event shall OMEGA be liable for consequential, incidental or special damages.**

CONDITIONS: Equipment sold by OMEGA is not intended to be used, nor shall it be used: (1) as a "Basic Component" under 10 CFR 21 (NRC), used in or with any nuclear installation or activity; or (2) in medical applications or used on humans. Should any Product(s) be used in or with any nuclear installation or activity, medical application, used on humans, or misused in any way, OMEGA assumes no responsibility as set forth in our basic WARRANTY/DISCLAIMER language, and, additionally, purchaser will indemnify OMEGA and hold OMEGA harmless from any liability or damage whatsoever arising out of the use of the Product(s) in such a manner.

## RETURN REQUESTS/INQUIRIES

Direct all warranty and repair requests/inquiries to the OMEGA Customer Service Department. BEFORE RETURNING ANY PRODUCT(S) TO OMEGA, PURCHASER MUST OBTAIN AN AUTHORIZED RETURN (AR) NUMBER FROM OMEGA'S CUSTOMER SERVICE DEPARTMENT (IN ORDER TO AVOID PROCESSING DELAYS). The assigned AR number should then be marked on the outside of the return package and on any correspondence.

The purchaser is responsible for shipping charges, freight, insurance and proper packaging to prevent breakage in transit.

FOR **WARRANTY** RETURNS, please have the following information available BEFORE contacting OMEGA:

1. Purchase Order number under which the product was PURCHASED,
2. Model and serial number of the product under warranty, and
3. Repair instructions and/or specific problems relative to the product.


FOR **NON-WARRANTY** REPAIRS, consult OMEGA for current repair charges. Have the following information available BEFORE contacting OMEGA:

1. Purchase Order number to cover the COST of the repair,
2. Model and serial number of the product, and
3. Repair instructions and/or specific problems relative to the product.

OMEGA's policy is to make running changes, not model changes, whenever an improvement is possible. This affords our customers the latest in technology and engineering.

OMEGA is a registered trademark of OMEGA ENGINEERING, INC.

© Copyright 2007 OMEGA ENGINEERING, INC. All rights reserved. This document may not be copied, photocopied, reproduced, translated, or reduced to any electronic medium or machine-readable form, in whole or in part, without the prior written consent of OMEGA ENGINEERING, INC.



# Where Do I Find Everything I Need for Process Measurement and Control? **OMEGA...Of Course!** *Shop online at [omega.com](http://omega.com)*

## **TEMPERATURE**

- Thermocouple, RTD & Thermistor Probes, Connectors, Panels & Assemblies
- Wire: Thermocouple, RTD & Thermistor
- Calibrators & Ice Point References
- Recorders, Controllers & Process Monitors
- Infrared Pyrometers

## **PRESSURE, STRAIN AND FORCE**

- Transducers & Strain Gages
- Load Cells & Pressure Gages
- Displacement Transducers
- Instrumentation & Accessories

## **FLOW/LEVEL**

- Rotameters, Gas Mass Flowmeters & Flow Computers
- Air Velocity Indicators
- Turbine/Paddlewheel Systems
- Totalizers & Batch Controllers

## **pH/CONDUCTIVITY**

- pH Electrodes, Testers & Accessories
- Benchtop/Laboratory Meters
- Controllers, Calibrators, Simulators & Pumps
- Industrial pH & Conductivity Equipment

## **DATA ACQUISITION**

- Data Acquisition & Engineering Software
- Communications-Based Acquisition Systems
- Plug-in Cards for Apple, IBM & Compatibles
- Datalogging Systems
- Recorders, Printers & Plotters

## **HEATERS**

- Heating Cable
- Cartridge & Strip Heaters
- Immersion & Band Heaters
- Flexible Heaters
- Laboratory Heaters

## **ENVIRONMENTAL MONITORING AND CONTROL**

- Metering & Control Instrumentation
- Refractometers
- Pumps & Tubing
- Air, Soil & Water Monitors
- Industrial Water & Wastewater Treatment
- pH, Conductivity & Dissolved Oxygen Instruments

