

Where Do I Find Everything I Need for Process Measurement and Control?

OMEGA...Of Course!

Shop online at omega.comSM

TEMPERATURE

- ☑ Thermocouple, RTD & Thermistor Probes, Connectors, Panels & Assemblies
- ☑ Wire: Thermocouple, RTD & Thermistor
- ☑ Calibrators & Ice Point References
- ☑ Recorders, Controllers & Process Monitors
- ☑ Infrared Pyrometers

PRESSURE, STRAIN AND FORCE

- ☑ Transducers & Strain Gages
- ☑ Load Cells & Pressure Gages
- ☑ Displacement Transducers
- ☑ Instrumentation & Accessories

FLOW/LEVEL

- ☑ Rotameters, Gas Mass Flowmeters & Flow Computers
- ☑ Air Velocity Indicators
- ☑ Turbine/Paddlewheel Systems
- ☑ Totalizers & Batch Controllers

pH/CONDUCTIVITY

- ☑ pH Electrodes, Testers & Accessories
- ☑ Benchtop/Laboratory Meters
- ☑ Controllers, Calibrators, Simulators & Pumps
- ☑ Industrial pH & Conductivity Equipment

DATA ACQUISITION

- ☑ Data Acquisition & Engineering Software
- ☑ Communications-Based Acquisition Systems
- ☑ Plug-in Cards for Apple, IBM & Compatibles
- ☑ Data Logging Systems
- ☑ Recorders, Printers & Plotters

HEATERS

- ☑ Heating Cable
- ☑ Cartridge & Strip Heaters
- ☑ Immersion & Band Heaters
- ☑ Flexible Heaters
- ☑ Laboratory Heaters

ENVIRONMENTAL MONITORING AND CONTROL

- ☑ Metering & Control Instrumentation
- ☑ Refractometers
- ☑ Pumps & Tubing
- ☑ Air, Soil & Water Monitors
- ☑ Industrial Water & Wastewater Treatment
- ☑ pH, Conductivity & Dissolved Oxygen Instruments

1 YEAR
WARRANTY



User's Guide

Shop online at

omega.com[®]

Ω OMEGA[®]

omega.com

e-mail: info@omega.com

For latest product manuals:
omegamanager.info



RH87 Multifunctional Environmental Meter

M4884/0310

| | |
|---------------------------------------|-----------------------------------|
| OMEGAnet® Online Service omega.com | Internet e-mail info@omega.com |
|---------------------------------------|-----------------------------------|

Servicing North America:

U.S.A.: Omega Engineering, Inc., One Omega Drive, P.O. Box 4047
Stamford, CT 06907-0047 USA
Toll Free: 1-800-826-6342 TEL: (203) 359-1660
FAX: (203) 359-7700 e-mail: info@omega.com

Canada: 976 Bergar
Laval (Quebec), H7L 5A1 Canada
Toll-Free: 1-800-826-6342 TEL: (514) 856-6928
FAX: (514) 856-6886 e-mail: info@omega.ca

For immediate technical or application assistance:

U.S.A. and Canada: Sales Service: 1-800-826-6342/1-800-TC-OMEGA®
Customer Service: 1-800-622-2378/1-800-622-BEST®
Engineering Service: 1-800-872-9436/1-800-USA-WHEN®

Mexico/Latin America: En Español: 001 (203) 359-7803 FAX: 001 (203) 359-7807
info@omega.com.mx e-mail: espanol@omega.com

Servicing Europe:

Benelux: Managed by the United Kingdom Office
Toll-Free: 0800 099 3344 TEL: +31 20 347 21 21
FAX: +31 20 643 46 43 e-mail: sales@omegaeng.nl

Czech Republic: Frystatska 184
733 01 Karviná, Czech Republic
Toll-Free: 0800-1-66342 TEL: +420-59-6311899
FAX: +420-59-6311114 e-mail: info@omegashop.cz

France: Managed by the United Kingdom Office
Toll-Free: 0800 466 342 TEL: +33 (0) 161 37 29 00
FAX: +33 (0) 130 57 54 27 e-mail: sales@omega.fr

Germany/Austria: Daimlerstrasse 26
D-75392 Deckenpfromm, Germany
Toll-Free: 0800 6397678 TEL: +49 (0) 7056 9398-0
FAX: +49 (0) 7056 9398-29 e-mail: info@omega.de

United Kingdom: OMEGA Engineering Ltd.
One Omega Drive, River Bend Technology Centre, Northbank
Irlam, Manchester M44 5BD United Kingdom
Toll-Free: 0800-488-488 TEL: +44 (0) 161 777-6611
FAX: +44 (0) 161 777-6622 e-mail: sales@omega.co.uk

It is the policy of OMEGA Engineering, Inc. to comply with all worldwide safety and EMC/EMI regulations that apply. OMEGA is constantly pursuing certification of its products to the European New Approach Directives. OMEGA will add the CE mark to every appropriate device upon certification. The information contained in this document is believed to be correct, but OMEGA accepts no liability for any errors it contains, and reserves the right to alter specifications without notice.
WARNING: These products are not designed for use in, and should not be used for, human applications.

WARRANTY/DISCLAIMER

OMEGA ENGINEERING, INC. warrants this unit to be free of defects in materials and workmanship for a period of **13 months** from date of purchase. OMEGA's WARRANTY adds an additional one (1) month grace period to the normal **one (1) year product warranty** to cover handling and shipping time. This ensures that OMEGA's customers receive maximum coverage on each product. If the unit malfunctions, it must be returned to the factory for evaluation. OMEGA's Customer Service Department will issue an Authorized Return (AR) number immediately upon phone or written request. Upon examination by OMEGA, if the unit is found to be defective, it will be repaired or replaced at no charge. OMEGA's WARRANTY does not apply to defects resulting from any action of the purchaser, including but not limited to mishandling, improper interfacing, operation outside of design limits, improper repair, or unauthorized modification. This WARRANTY is VOID if the unit shows evidence of having been tampered with or shows evidence of having been damaged as a result of excessive corrosion; or current, heat, moisture or vibration; improper specification; misapplication; misuse or other operating conditions outside of OMEGA's control. Components in which wear is not warranted, include but are not limited to contact points, fuses, and triacs.

OMEGA is pleased to offer suggestions on the use of its various products. However, OMEGA neither assumes responsibility for any omissions or errors nor assumes liability for any damages that result from the use of its products in accordance with information provided by OMEGA, either verbal or written. OMEGA warrants only that the parts manufactured by the company will be as specified and free of defects. OMEGA MAKES NO OTHER WARRANTIES OR REPRESENTATIONS OF ANY KIND WHATSOEVER, EXPRESSED OR IMPLIED, EXCEPT THAT OF TITLE, AND ALL IMPLIED WARRANTIES INCLUDING ANY WARRANTY OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE ARE HEREBY DISCLAIMED. LIMITATION OF LIABILITY: The remedies of purchaser set forth herein are exclusive, and the total liability of OMEGA with respect to this order, whether based on contract, warranty, negligence, indemnification, strict liability or otherwise, shall not exceed the purchase price of the component upon which liability is based. In no event shall OMEGA be liable for consequential, incidental or special damages.

CONDITIONS: Equipment sold by OMEGA is not intended to be used, nor shall it be used: (1) as a "Basic Component" under 10 CFR 21 (NRC), used in or with any nuclear installation or activity; or (2) in medical applications or used on humans. Should any Product(s) be used in or with any nuclear installation or activity, medical application, used on humans, or misused in any way, OMEGA assumes no responsibility as set forth in our basic WARRANTY/DISCLAIMER language, and, additionally, purchaser will indemnify OMEGA and hold OMEGA harmless from any liability or damage whatsoever arising out of the use of the Product(s) in such a manner.

RETURN REQUESTS/INQUIRIES

Direct all warranty and repair requests/inquiries to the OMEGA Customer Service Department. BEFORE RETURNING ANY PRODUCT(S) TO OMEGA, PURCHASER MUST OBTAIN AN AUTHORIZED RETURN (AR) NUMBER FROM OMEGA'S CUSTOMER SERVICE DEPARTMENT (IN ORDER TO AVOID PROCESSING DELAYS). The assigned AR number should then be marked on the outside of the return package and on any correspondence. The purchaser is responsible for shipping charges, freight, insurance and proper packaging to prevent breakage in transit.

FOR **WARRANTY** RETURNS, please have the following information available BEFORE contacting OMEGA:
1. Purchase Order number under which the product was PURCHASED,
2. Model and serial number of the product under warranty, and
3. Repair instructions and/or specific problems relative to the product.

FOR **NON-WARRANTY** REPAIRS, consult OMEGA for current repair charges. Have the following information available BEFORE contacting OMEGA:
1. Purchase Order number to cover the COST of the repair,
2. Model and serial number of the product, and
3. Repair instructions and/or specific problems relative to the product.

OMEGA's policy is to make running changes, not model changes, whenever an improvement is possible. This affords our customers the latest in technology and engineering. OMEGA is a registered trademark of OMEGA ENGINEERING, INC. © Copyright 2010 OMEGA ENGINEERING, INC. All rights reserved. This document may not be copied, photocopied, reproduced, translated, or reduced to any electronic medium or machine-readable form, in whole or in part, without the prior written consent of OMEGA ENGINEERING, INC.

Contents

| Description | Pages |
|--------------------------|-------|
| 1. Safety information | 1 |
| 2. Description | 2 |
| 3. Specifications | 6 |
| 4. Operating instruction | 8 |
| 5. Accessories | 12 |

4.12 Battery replacement

If the sign “ ” appears on the LCD display, it indicates that the battery should be replaced. Turn the unit off. Remove the battery cover. Replace the exhausted battery with a new one and replace the battery cover.

4.13 Use the tripod connector

If needed, the meter can be fixed on the tripod.

5. Accessories Included

- Battery: 9V 6F22
- Windbreak
- Operating Manual
- Tripod
- Durable Storage Case

| Circular | |
|----------|---------|
| Diameter | sq. ft. |
| 6.0 | 0.1 |
| 8.0 | 0.2 |
| 10.0 | 0.4 |
| 12.0 | 0.5 |
| 14.0 | 0.7 |
| 16.0 | 0.9 |
| 18.0 | 1.1 |

Free Area Calculation in sq. ft.
Dimensions (H/W) in inches

Note: Free area in this chart is based on 0.65 of face area

Rectangular

| H (in)/W (in) | 2.0 | 4.0 | 6.0 | 8.0 | 10.0 | 12.0 | 14.0 | 16.0 | 18.0 | 20.0 | 22.0 | 24.0 |
|---------------|-----|-----|-----|-----|------|------|------|------|------|------|------|------|
| 2.0 | 0.0 | 0.0 | 0.1 | 0.1 | 0.1 | 0.1 | 0.1 | 0.1 | 0.2 | 0.2 | 0.2 | 0.2 |
| 4.0 | 0.0 | 0.1 | 0.1 | 0.1 | 0.2 | 0.2 | 0.3 | 0.3 | 0.3 | 0.4 | 0.4 | 0.4 |
| 6.0 | 0.1 | 0.1 | 0.2 | 0.2 | 0.3 | 0.3 | 0.4 | 0.4 | 0.5 | 0.5 | 0.6 | 0.7 |
| 8.0 | 0.1 | 0.1 | 0.2 | 0.3 | 0.4 | 0.4 | 0.5 | 0.6 | 0.7 | 0.7 | 0.8 | 0.9 |
| 10.0 | 0.1 | 0.2 | 0.3 | 0.4 | 0.5 | 0.5 | 0.6 | 0.7 | 0.8 | 0.9 | 1.0 | 1.0 |
| 12.0 | 0.1 | 0.2 | 0.3 | 0.4 | 0.5 | 0.7 | 0.8 | 0.9 | 1.0 | 1.1 | 1.9 | 1.3 |
| 14.0 | 0.1 | 0.3 | 0.4 | 0.5 | 0.6 | 0.8 | 0.9 | 1.0 | 1.1 | 1.3 | 1.4 | 1.5 |
| 16.0 | 0.1 | 0.3 | 0.4 | 0.6 | 0.7 | 0.9 | 1.0 | 1.2 | 1.3 | 1.4 | 1.6 | 1.7 |
| 18.0 | 0.2 | 0.3 | 0.5 | 0.7 | 0.8 | 1.0 | 1.2 | 1.3 | 1.5 | 1.6 | 1.8 | 2.0 |
| 20.0 | 0.2 | 0.3 | 0.5 | 0.7 | 0.9 | 1.1 | 1.3 | 1.4 | 1.6 | 1.8 | 2.0 | 2.2 |
| 22.0 | 0.2 | 0.4 | 0.6 | 0.8 | 1.0 | 1.2 | 1.4 | 1.6 | 1.8 | 2.0 | 2.2 | 2.4 |
| 24.0 | 0.2 | 0.4 | 0.7 | 0.9 | 1.1 | 1.3 | 1.5 | 1.7 | 2.0 | 2.2 | 2.4 | 2.6 |

1. Safety information

Read the following safety information carefully before attempting to operate or service the meter. Use the meter only as specified in this manual, otherwise, the protection provided by the meter may be impaired. With proper use and care, your digital meter will provide service for years.

1.2 During use

- Operate the meter under the stated temperature and humidity conditions.
- Please do not store or use meter in areas exposed to direct sunlight, high temperature, humidity or condensation.
- Do not touch or manipulate the sensor.
- Do not expose the sensor to direct light, this may cause a false reading.
- Do not expose the sensor to static electricity.
- Never place the sensor directly into water.

1.3 Symbols

- CE Complies with EMC (Electromagnetic Compatibility Directive)
- △ Important safety information.

1.4 Maintenance

- Repairs or servicing not covered in this manual should only be performed by qualified personnel.
- If dust is present on the sensor, use clean air to blow it away or use alcohol to lightly scrub it away.
Do not use other chemicals for cleaning the sensor.
- Do not use abrasives or solvents on the meter, use a damp cloth and mild detergent only.
- Always set the power switch to the OFF position when the meter is not in use.
- If the meter is to be stored for a long period of time, the batteries should be removed to prevent damage to the unit.

2. Description

The EM5 is a digital Multifunctional Environmental Meter which combines the function of Sound Level, Luminometer, Relative Humidity Meter, Temperature Meter and Anemometer.

- Large LCD and back light for easy reading.
- Data hold function.
- Auto ranging feature.
- MAX,MIN, AVG and DIF (MIN-MAX) value.
- Auto/manual power off.
- Low battery indication.

2

4.9 Luminance(Lux) measurement

Move the sensor on top of the meter to light source in a horizontal position. Press the "Lux" button to measure. The LCD display will show the luminance at the meter.

4.10 Wind speed measurement

For measurement, place the sensor of anemometer in the environment to be tested, be sure the fan is in a upright position to the air current, and press the "ANEMO" button to measure. When the meter is first powered on, the default scale setting is set at m/s scale. The user may change it to km/h, ft/m and knots by pressing "UNIT" button.

4.11 Air flow measurement

Before measurement press "SET" button to enter the area of the air current. Press "UNIT" button to select which digit of the area to change. Press "HOLD" button and "B.L." button to change the selection to the value needed. Press "SET" button to save the setting.

Place the sensor for anemometer in the environment to be tested, be sure fan is in upright position, face to the air current, and press "ANEMO" button to measure.

When the meter is powered on the default scale is CMM, area set default is 1.0m². To change to CFM press "UNIT" button, then set area.

NOTE:

While measuring the wind speed and the air flow, avoid direct sunlight.

11

4.6 Temperature measurement

For measurement, place the sensor probe in the environment to be tested. Press the "TEMP/%RH" button to measure. When the meter is first powered on, the default scale setting is set at Celsius °C scale. The user may change it to Fahrenheit °F by pressing "UNIT" button and vice versa to Celsius by pressing "UNIT" button again.

4.7 Humidity measurement

For measurement, place the sensor probe in the tested environment. Press the "TEMP/%RH" two times. The meter will enter Humidity measurement mode. The response time of the sensor is 5 seconds.

4.8 Sound level (dB) measurement


Aim the sensor on top of the meter to the sound source. Press the "dB" button to measure. The LCD display will show the sound level at the meter. When the meter is first powered on, the default scale setting is set at A-Weighting scale. The user may change it to C-Weighting by pressing "UNIT" button and A-Weighting by pressing "UNIT" button again.

NOTE:

Strong wind striking the microphone may cause inaccurate measurement in windy locations. A windscreen should be used in front of microphone.

2.1 Button and components identification

- (1) Microphone
- (2) LCD display
- (3) "SET" - Sets the parameters for air volume measurement
- (4) "MODE" - Selects MAX,MIN,AVG and DIF (MAX-MIN)
- (5) "LUX" - Selects Light Meter function.
- (6) "dB" - Selects sound level value measurement.
- (7) "B.L" - Activates Back Light feature.
- (8) Airflow Sensor
- (9) "UNIT" - Selects the units of measurement.
- (10) "HOLD" - Data hold function.
- (11) "ANEMO" - Air Flow and Volume features.
- (12) "POWER" - Power "On" manual "Off"
- (13) "TEMP/%RH" - Activates Temperature and Relative Humidity measurement.
- (14) Light Sensor
- (15) Windscreen
- (16) Temperature/ Humidity Sensor
- (17) Tripod connector




- **Read hold**
Hold the present reading and keep it on the display by pressing the “HOLD” button. When the held data is no longer needed, release the data-hold operation by pressing “HOLD” button again.
- **Back light**
Press “B.L” button to open the back light which will last for 10 sec. To close it up at any time press the “B.L” button again.

NOTE:

- LED is the main source of back light. Its working current is large. Frequent use of back light will shorten the battery life.
- When the battery voltage is less than 7V, it will show . If back light is used at the same time, may come up. When shows, the accuracy of the measurement can not be assured. Replace the battery when appears and back light is not in use.
- **AVG/MAX/MIN/DIF measurement**
Press the “MODE” button, to select AVG/MAX/MIN/DIF(MAX-MIN) value to measure.

2.2 LCD illustration



3.5 Wind Speed

| Range | Resolution | Accuracy |
|------------------|------------|---------------------------------------------|
| 0.5 to 20m/s | 0.1m/s | $\pm(3\% \text{ of rdg} + 10\text{digits})$ |
| 1.8 to 72km/h | 0.1km/h | $\pm(3\% \text{ of rdg} + 10\text{digits})$ |
| 1.6 to 65.7ft/s | 0.1ft/s | $\pm(3\% \text{ of rdg} + 10\text{digits})$ |
| 0.9 to 38.9knots | 0.1knots | $\pm(3\% \text{ of rdg} + 10\text{digits})$ |

3.6 Airflow

| Range | Resolution | Accuracy |
|----------------|-----------------|---------------------------------------------|
| 0 to 999900CFM | 0.1 to 100 CFM | $\pm(3\% \text{ of rdg} + 10\text{digits})$ |
| 0 to 999900CMM | 0.1 to 1000 CMM | $\pm(3\% \text{ of rdg} + 10\text{digits})$ |




4. Operating instruction

• Power-up


Press the "POWER" button to turn the meter ON or OFF.

• Auto power off

By default, when the meter is powered on, it is under auto power off mode. The meter will power itself off after 20 minutes if no key operation. Press and hold "POWER" button then press "SET" button to disable the auto power off.

| | |
|-----------------------------------------------------------------------------------|-------------------------------------------------------|
| °F, °C | Fahrenheit / Centigrade indication. |
| %RH | Relative Humidity indication. |
| m/s, km/h, ft/s, Knots | The unit of wind speed indication. |
| CMM,CFM | The unit of airflow indication. |
| ft2, m2 | The unit of area indication. |
| X10, X100 | The multiplier indication of airflow and illuminance. |
| Lux | The unit of illuminance. |
| dB | The unit of sound level indication. |
| A,C | A-Weighting, C-weighting indication. |
| MAX | The maximum value is displayed. |
| MIN | The minimum value is displayed. |
| AVG | The average value is displayed. |
| DIF | The MAX-MIN value is displayed. |
|  | This indicates auto power off is enabled. |
|  | This indicates that the display data is being held. |
|  | The battery is not sufficient for proper operation. |

3. Specifications

- Numerical Display: 4 digit Liquid Crystal Display.
- Response Time: 2 times/second.
- Operating Environment: 14°F to 140°F (-10°C to 60°C)
- Storage Environment: 14°F to 122°F (-10°C to 50°C)
- Power Requirements: 9V battery
- Low Battery Indication:  displayed
- Dimension: Meter: 11”(L) x 3.5”(W) x 2”(H)
280(L) x 89(W) x 50(H)mm;
- Weight: Approx.: 15.3 oz (430g)

3.1 Temperature

| Range | Resolution | Accuracy |
|---------------|------------|----------|
| 14°F to 140°F | 0.1°F | ±2.7°F |
| -10°C to 60°C | 0.1°C | ±1.5°C |

3.2 Relative Humidity

| Range | Resolution | Accuracy |
|--------------|------------|------------|
| 20 to 80%RH | 0.1%RH | ±3%RH@77°F |
| (<20 >80)%RH | 0.1%RH | ±5%RH@77°F |

3.3 Sound level (dB)

| Range | Resolution | Accuracy |
|----------------|------------|----------|
| 30 to 130dB(A) | 0.1dB | ±1.5dB |
| 35 to 130dB(C) | 0.1dB | ±1.5dB |

Test condition: 94dB 1kHz sine wave

Response frequency: 100 to 8000Hz

3.4 Illuminance (Lux)

| Range | Resolution | Accuracy |
|--------------|------------|---------------------------------------------------------------------------------------------------------------------|
| 0 to 2000Lux | 1Lux | ±(5.0% of rdg + 10digits) at color temp. 2850K calibrated to standard incandescent lamp at color temperature 2856 k |
| X10(20000) | 10 Lux | |
| X100(50000) | 100 Lux | |