

Below is a flowchart showing how to navigate through all top level menus by pressing the 2 and 2 buttons.



READING CONFIGURATION SETUP (operation example)

Below is a flowchart showing how to navigate through the submenus of the Reading Configuration menu item by pressing the front buttons.



DISPLAY COLOR SETUP (examples)

Example 1:

Alarm setup: Absolute, Above, Alarm 2 HI Value "ALR.H" = 200, Alarm 1 HI Value "ALR.H" = 400 Color Display setup: Normal Color "N.CLR"=Green, Alarm 1 Color "1.CLR"=Amber, Alarm 2 Color "2.CLR"=Red

Display colors change sequences:

	GREEN	RED	AMBER	
0	AL2.H=200		.H=400	

Example 2:

Set Point 1 = 200, Set Point 2 = 200

Alarm 1 setup: Deviation, Band, "ALR.H" = 20 Alarm 2 setup: Deviation, Hi/Low, "ALR.H = 10", "ALR.L = 5" Color Display setup: "N.CLR"=Green, "1.CLR"=Amber, "2.CLR"=Red

Display colors change sequences:

	•	•	•		D AMBER •
0	180	195	200	210	220

SPECIFICATION

Accuracy:

+0.5°C temp; 0.03% rdg. process typical

Resolution:

1°/0.1°; 10 µV process Temperature Stability:

0.04°C/°C RTD; 0.05°C/°C TC @ 25°C (77°F); 50 ppm/°C process

Display:

4-digits, 9-segments LED, 21 mm (0.83") with red, green and

amber programmable colors Input Types:

Thermocouple, RTD, Analog Voltage

and Current

TC (ITS 90): J. K. T. E. R. S. B. C. N. L

RTD (ITS 68): 100/500/1000 ohm Pt sensor

2-, 3-, or 4-wire; 0.00385 or 0.00392 curve

Voltage:

0 to 100 mV. 0 to 1 V. 0 to 10 Vdc Current:

0 to 20 mA (4 to 20 mA)

Output 1[†]:

Relay 250 Vac @ 3 A Resistive Load, SSR. Pulse

Output 2[†]:

Relay 250 Vac @ 3 A Resistive Load, SSR, Pulse
† Only with -AL Limit Alarm option

Options: Communication

RS-232 / RS-485 or Excitation: 24 Vdc @ 25 mA

Exc. not available for Low Pow Line Voltage/Power:

90 - 240 Vac ±10%, 50 - 400 Hz*,

or 110 - 375 Vdc, 4 W
* No CE compliance above 60 Hz

Low Voltage Power Option:

12 - 36 Vdc, 3 W** * Units can be powered safely with 24 Vac but No Certification for CE/UL are claimed

Dimensions:

48 H x 96 W x 74 D mm (1.89 x 3.78 x 2.91") Weight:

295 g (0.65 lb)

Approvals: ÜL, C-UL, CE per EN61010-1:2001

WARNING: These products are not designed for use in, and should not be used for, patient-

This device is marked with the international caution symbol. It is important to read the Setup Guide before installing or commissioning this device, as the guide contains important information relating to safety and EMC. It is the policy of OMEGA to comply with all worldwide safety and EMC/EMI regulations that apply. OEMGA is constantly pursuing certification of its products to the European New Approach Directives. OMEGA will add the CE mark to every appropriate device upon certification.

The information contained in this document is believed to be correct, but OMEGA Engineering, Inc accepts no liability for any errors it contains, and reserves the right to alter specifications without notice.

Omega.com[®], Omega.com[®], and are Trademarks of OMEGA ENGINEERING, INC.

WARRANTY/DISCLAIMER

OMEGA ENGINEERING, INC. warrants this unit to be free of defects in materials and workmanship for a period of one (1) year from the date of purchase. In addition to OMEGA's standard warranty period, OMEGA Engineering will extend the warranty period for four (4) additional years if the warranty card enclosed with each instrument is returned to OMEGA.

If the unit malfunctions, it must be returned to the factory for evaluation. OMEGA's Customer Service Department will issue an Authorized Return (AR) number immediately upon phone or written request. Upon examination by OMEGA, if the unit is found to be defective, it will be repaired or replaced at no charge. OMEGA's WARRANTY does not apply to defects resulting from any action of the purchaser, including but not limited to mishandling, improper interfacing, operation outside of design limits, improper repair, or unauthorized modification. This WARRANTY is VOID if the suits shows evidence of having been tampered with or shows evidence of having been damaged as a result of excessive evolutions of the day of the day

OMEGA is pleased to offer suggestions on the use of its various products. However, OMEGA neither assumes responsibility for any omissions or errors nor assumes liability for any damages that result from the use of its products in accordance with information provided by OMEGA, either verbal or written. OMEGA warrants only that the parts manufactured by it will be as specified and free of defects. OMEGA MAKES NO OTHER WARRANTIES ON REPRESSOR IMPLIED, EXCEPT THAT OF TITLE, AND ALL IMPLIED WARRANTIES INCLUDING ANY WARRANTY OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE ARE HEREBY DISCLAIMED, LIMITATION OF LIABILITY: The remedies of purchaser set forth herein are exclusive, and the total liability of OMEGA with respect to this order, whether based on contract, warranty, negligence, indemnification, strict liability or otherwise, shall not exceed the purchase price of the component upon which liability is based. In no event shall OMEGA be liable for consequential, incidental or special damages.

CONDITIONS: Equipment sold by OMEGA is not intended to be used, nor shall it be used: (1) as a "Basic Component" under 10 CFR 21 (NRC), used in or with any nuclear installation or activity; or (2) in medical applications or used on humans. Should any Product(s) be used in or with any nuclear installation or activity, medical application, used on humans, or misused in any way, OMEGA assumes no responsibility as set forth in our basic WARRANT/DISCLAIMER language, and, additionally, purchaser will indemnify OMEGA and hold OMEGA harmless from any liability or damage whatsoever arising out of the use of the Product(s) in such a manner.

RETURN REQUESTS/INQUIRIES

Direct all warranty and repair requests/inquiries to the OMEGA Customer Service Department. BEFORE RETURNING ANY PRODUCT(S) TO OMEGA, PURCHASER MUST OBTAIN AN AUTHORIZED RETURN (AR) NUMBER FROM OMEGA'S CUSTOMER SERVICE DEPARTMENT (IN ORDER TO AVOID PROCESSING DELAYS). The assigned AR number should then be marked on the outside of the return package and on any

The purchaser is responsible for shipping charges, freight, insurance and proper packaging to prevent breakage in

FOR WARRANTY RETURNS, please have the following information available BEFORE contacting OMEGA:

- FOR NON-WARRANTY REPAIRS, consult OMEGA for current repair charges. Have the following information available BEFORE contacting OMEGA:
- 2. Model and serial number of the product under warranty, and
- Repair instructions and/or specific problems relative to the product.

OMEGA's policy is to make running changes, not model changes, whenever an improvement is possible. This affords our customers the latest in technology and engineering.

OMEGA is a registered trademark of OMEGA ENGINEERING, INC.

© Copyright 2006 OMEGA ENGINEERING, INC. All rights reserved. This document may not be copied, photocopied reproduced, translated, or reduced to any electronic medium or machine-readable form, in whole or in part, without the prior written consent of OMEGA ENGINEERING, INC. PATENT AND TRADEMARK NOTICE: This product is covered by one or more of the following patents: U.S. Pat. No. Des. 336,895; 5,274,577; 6,243,021 / CANADA 2052599; 2052600 / ITALY 1249456; 1250938 / GERMANY DE 41 34398 (C.) FSAIN 2039156; 2043066 / UR Patent No. GB2 249 837; GB2 248 994 / FRANCE BREVET NO. 91 12756. The "Meter Bezel Design" is a trademark of Newport Electronics, Inc. USED UNDER LICENSE. Other U.S. and International Patents pending or applied for.

QUICK START

MADE IN ϵ USA



Series

DPi8C Compact Temperature & Process Monitor CNi8C-AL Compact Temperature & Process Limit Alarm



OMEGAnet® On-Line Service www.omega.com

Internet e-mail info@omega.com

Servicing North America:

USA: One Omega Drive, P.O. Box 4047 Stamford CT 06907-0047 ISO 9001 Certified

TEL: (203) 359-1660 FAX: (203) 359-7700 e-mail: info@omega.com

Canada 976 Bergar

Laval (Quebec) H7L 5A1 TEL: (514) 856-6928 e-mail: info@omega.ca

FAX: (514) 856-6886

For immediate technical or application assistance:

USA and Canada:

Germany/Austria:

Sales Service: 1-800-826-6342 / 1-800-TC-OMEGA® Customer Service: 1-800-622-2378 / 1-800-622-BEST® Engineering Service: 1-800-872-9436 / 1-800-USA-WHEN®

Mexico and TEL: (001)800-TC-OMEGA® En Español: (001) 203-359-7803 Latin American e-mail: espanol@omega.com

FAX: (001) 203-359-7807

Servicing Europe:

Czech Republic: Frystatska 184 733 01 Karviná

TFL: +420 59 6311899 FAX: +420 59 6311114 e-mail: info@omegashop.cz

Daimlerstrasse 26, D-75392 Deckenpfronn, Germany

TEL: +49 7056 9398-0 FAX: +49 7056 9398-29

Toll Free in Germany: 0800 639 7678

e-mail: info@omega.de

United Kingdom: One Omega Drive ISO 9002 Certified

River Bend Technology Centre

Northbank, Irlam Manchester M44 5BD United Kingdom TEL: +44 161 777 6611 FAX: +44 161 777 6622

Toll Free in England: 0800 488 488 e-mail: sales@omega.co.uk

MQS3625/0206

Purchase Order number to cover the COST of the

Model and serial number of product, and

Repair instructions and/or specific problems relative to the product.



This Quick Start Reference provides information on setting up your instrument for basic operation. The latest complete Communication and Operational Manual as well as free Software and ActiveX Controls are available at www.omega.com/specs/iseries or on the CD-ROM enclosed with your shipment.

SAFETY CONSIDERATION



This device is marked with the international Caution symbol.

The instrument is a panel mount device protected in accordance with EN 61010-1:2001, electrical safety requirements for electrical equipment for measurement, control and laboratory. Remember that the unit has no power-on switch. Building installation should include a switch or circuit-breaker that must be compliant to IEC 947-1 and 947-3.


SAFETY:

- Do not exceed voltage rating on the label located on the top of the instrument housing.
- Always disconnect power before changing signal and power connections.
- Do not use this instrument on a work bench without its case for safety reasons.
- Do not operate this instrument in flammable or explosive atmospheres.
- Do not expose this instrument to rain or moisture.

EMC:

- Whenever EMC is an issue, always use shielded cables.
- Never run signal and power wires in the same conduit.
- Use signal wire connections with twisted-pair cables.
- Install Ferrite Bead(s) on signal wire close to the instrument if EMC problems persist.

MOUNTING



Panel Mounting Instruction:

- **1.** Using the dimensions from the panel cutout diagram shown, cut an opening in the panel.
- Remove sleeve from the rear of the case by removing thumbnuts.
- **3.** Insert the unit into the opening from the front of the panel, so the gasket seals between the bezel and the front of the panel.
- **4.** Slip the sleeve over the rear of the case.
- 5. Tighten the thumbnuts to hold the unit firmly in the panel.

Disassembly Instruction:

If necessary, the unit may be removed from the panel and opened.



Warning: Disconnect all ac power from the unit before proceeding.

- 1. Remove all wiring connections from the rear of the instrument, by unplugging the power and input connectors.
- 2. Remove both thumbnuts and set aside.

Output 1 and 2 are for

1V/10V-

8888

PRONT VIEW

100mV


- 3. Remove the sleeve and set aside.
- 4. Remove the meter from the panel and bend the side panel detents on the case outward to release the board. Pull the board assembly out of the case.

WIRING


Wire the instrument according to the figure shown below.



Warning: Do not connect ac power to your device until you have completed all input and output connections. This device must only be installed by a specially trained electrician with corresponding qualifications. Failure to follow all instructions and warnings may result in injury!



Connect the main power connections as shown in the figure below.




* See Specification Section

FUSE	Connector	Output Type	For 115Vac	For 230Vac	DC
FUSE 1	Output 1	Relay	3 A(T)	3 A(T)	-
FUSE 2	Output 2	Relay	3 A(T)	3 A(T)	-
FUSE 3	Power	N/A	100 mA(T)	100 mA(T)	100 mA(T)
FUSE 4	Power	N/A	N/A	N/A	400 mA(T)



Output 1 and 2 are for -AL Limit Alarm Option only.

CONFIGURATION Table 3.1 Button Function in Configuration Mode





Reset: Except for Alarms, modifying any settings of the menu configuration will reset the instrument prior to resuming Run Mode.

In the Run Mode, press twice to enable

Standby Mode with flashing 5 + 6 9.

DISPLAY ABBREVIATIONS

SP1	Set Point 1 Value	SP2	Set Point 2 Value
CNFG	Configuration Menu		
INPt	Input Type Menu	t.c	Thermocouple Input
kJ	Thermocouple Type	Rtd	RTD Input
385.2	RTD Curve and	100	100 /500 /1000
	Connection Type		RTD Sensor
392.4	(2, 3, 4-Wire)	1000	
PROC	Process Input		
0 - 0.1	100 mV Input Voltage	0 - 1.0	1 V Input Voltage
0 - 20	20 mA Input Current	0 - 10	10 V Input Voltage
RdG	Reading Configuration	dEC	Decimal Point
F.FFF.	Decimal Point	FLtR	Filter Constant
	Position		
0001	Filter Constant Value	IN.Rd	Input/Reading Scale
0128			and Offset Menu
IN 1	Input 1	IN 2	Input 2
Rd 1	Reading 1	Rd 2	Reading 2
ALR1	Alarm 1 Menu	AbSo	Absolute Mode
dEV	Deviation Mode	LtcH	Latched Mode
UNLt	Unlatched Mode	Ct.CL	Contact Closure
N.o.	Normally Open	N.c.	Normally Closed
ActV	Active Type	AboV	Active Above
bELo	Active Below	Hi.Lo	Above High/Below
			Low
bANd	Above or Below Band	A.P.oN	Alarm Enable/Disable
L			at Power On
ALR.L	Alarm Low Value	ALR.H	Alarm High Value
	Alarm 2 Menu		
	Reading Adjust	SP.dN	Set Point Deviation
ld	ID Code Menu	CH.ld	Change ID Code
FULL	Full ID	SP.Id	Set Point ID
	Communication Option*		Communication is
			Not Installed
C.PAR	Communication	bAUd	Baud Rate
	Parameters		
	Parity	odd_	Odd
EVEN	Even	_No_	No
dAtA	Data Bit	7.bit	7 Data Bit
8.bit	8 Data Bit	StOP	Stop Bit
1.bit	1 Data Bit	2.bit	2 Stop Bit
bus.F LF	Bus Format Line Feed	ECHO	Modbus Protocol Echo
StNd	Communication	232C	RS-232
5.1144	Standard	2020	202
485	RS-485	ModE	Data Flow Mode
CMd	Command Mode	CoNt	Continuous Mode
SEPR	Data Separation	SPCE	Space
	Character		•
cR	Carriage Return	dAt.F	Data Format
stAt	Alarm Status	RdNG	Transmit Reading
DE	T ''D '.'.'	0000	Value
PEAk	Transmit Peak Value	GROS	Transmit Gross
1181:4	Unite of Magazzanasa	V 44D	Value
UNit tR.tM	Units of Measurement Transmit Color Selection	AddR	Multipoint Address
COLR	Display Color Selection	N.CLR	Normal Color
JOLIN	Pispidy Color Selection	II.OLIX	Display
1.CLR	Alarm 1 Color Display	2.CLR	Alarm 2 Color
			Display
REd	Display Color is Red	AMbR	Display Color is
	25.27 20.0. 10 1100		Amber
GRN	Display Color is Green		
ENbL	Enable	dSbL	Disable
ERRo	Error	+ OL	Input (+) Overload
+OPN	Input (+) Open		, , , ,
	r abbreviations of Communicatio		
* F^	r abbreviations of Communicatio	n ()ntion e	ee Communication Manual

^{*} For abbreviations of Communication Option see Communication Manual.