



# User's Guide

*Shop online at*

**omega.com<sup>®</sup>**

**Ω OMEGA<sup>®</sup>**

*www.omega.com*

*e-mail: info@omega.com*

**ISO 9001**

CERTIFIED  
CORPORATE QUALITY

STAMFORD, CT

**ISO 9002**

CERTIFIED  
CORPORATE QUALITY

MANCHESTER, UK



**OS950 SERIES**  
**Handheld Infrared**  
**Thermometers**



Ω OMEGA®

OMEGAnet® On-Line Service  
www.omega.com

Internet e-mail  
info@omega.com

### Servicing North America:

**USA:** One Omega Drive, Box 4047  
**ISO 9001** Stamford CT 06907-0047  
**Certified** Tel: (203) 359-1660 FAX: (203) 359-7700  
e-mail: info@omega.com

**Canada:** 976 Bergar  
Laval (Quebec) H7L 5A1  
Tel: (514) 856-6928 FAX: (514) 856-6886  
e-mail: info@omega.ca

### For immediate technical or application assistance:

**USA and** Sales Service: 1-800-826-6342 / 1-800-TC-OMEGA®  
**Canada:** Customer Service: 1-800-622-2378 / 1-800-622-BEST®  
Engineering Service: 1-800-872-9436 / 1-800-USA-WHEN®  
TELEX: 996404 EASYLINK: 62968934 CABLE: OMEGA

**Mexico:** En Español: (001) 203-359-7803 e-mail: espanol@omega.com  
FAX: (001) 203-359-7807 info@omega.com.mx

### Servicing Europe:

**Benelux:** Postbus 8034, 1180 LA Amstelveen, The Netherlands  
Tel: +31 (0)20 3472121 FAX: +31 (0)20 6434643  
Toll Free in Benelux: 0800 0993344  
e-mail: sales@omegaeng.nl

**Czech** Rudé armády 1868, 733 01 Karviná 8  
**Republic** Tel: +420 (0)69 6311899 FAX: +420 (0)69 6311114  
Toll Free: 0800-1-66342 e-mail: czech@omega.com

**France:** 9, rue Denis Papin, 78190 Trappes  
Tel: +33 (0)130 621 400 FAX: +33 (0)130 699 120  
Toll Free in France: 0800-4-06342  
e-mail: sales@omega.fr

**Germany/** Daimlerstrasse 26, D-75392 Deckenpfronn, Germany  
**Austria:** Tel: + 49 (0)7056 9398-0 FAX: +49 (0)7056 9398-29  
Toll Free in Germany: 0800 639 7678  
e-mail: info@omega.dl

**United :** One Omega Drive, River Bend Technology Centre  
**Kingdom** Northbank, Irlam, Manchester  
**ISO 9002** M44 5BD United Kingdom  
**Certified** Tel: +44 (0)161 777 6611 FAX: +44 (0)161 777 6622  
Toll Free in United Kingdom: 0800-488-488  
e-mail: sales@omega.co.uk

---

It is the policy of OMEGA to comply with all worldwide safety and EMC/EMI regulations that apply. OMEGA is constantly pursuing certification of its products to the European New Approach Directives. OMEGA will add the CE mark to every appropriate device upon certification.

The information contained in this document is believed to be correct, but OMEGA Engineering, Inc. accepts no liability for any errors it contains, and reserves the right to alter specifications without notice. **WARNING:** These products are not designed for use in, and should not be used for, patient-connected applications.





# Table of Contents

Chapter One - Welcome to Infrared Thermometry . . . .	1
1.1 Introduction . . . . .	1
1.2 Product Features . . . . .	1
1.3 Models and Ordering Information . . . . .	1
Chapter Two - Operation . . . . .	2
2.1 OS950 Controls . . . . .	2
2.2 To Change Display Measurement Units . . . . .	2
2.3 To Change Mode of Operation . . . . .	3
2.4 Temperature Measurements . . . . .	3
2.4.1 General Operation . . . . .	3
2.4.2 Temperature Measurement of Moving Targets . . . . .	4
2.4.3 High Temperature Targets . . . . .	4
2.5 MAX Mode Temperature Measurements . . . . .	4
2.5.1 General Operation . . . . .	4
2.6 SCAN Mode Temperature Measurements . . . . .	5
2.6.1 General Operation . . . . .	5
Chapter Three - Measurement Tips . . . . .	5
3.1 Optimizing Target Area Measurements . . . . .	5
3.2 Measuring Metallic Targets . . . . .	6
3.3 Optimizing AESC Measurements for NIST Traceability . . . . .	6
3.4 Measuring Transparent Materials . . . . .	6
3.5 Measuring Wet or Icy Surfaces . . . . .	6
Chapter Four - Maintenance . . . . .	7
4.1 Battery Replacement . . . . .	7
4.2 Cleaning . . . . .	7
4.3 Storage . . . . .	7
4.4 Calibration . . . . .	7
Chapter Five - Troubleshooting . . . . .	7
5.1 Diagnostic Codes . . . . .	7
5.2 Troubleshooting Measurement Difficulties . . . . .	9
Chapter Six - OS950™ Specifications . . . . .	9

# Chapter One - Welcome to Infrared Thermometry

## 1.1 Introduction

Omega Engineering, the world's leading manufacturer of infrared temperature systems, presents the low cost OS950™ Series of hand held infrared thermometers. These dual-purpose systems function as both NIST traceable temperature calibrators and thermal scanning devices. Make fast, accurate, and reliable temperature measurements using advanced non-contact IR technology.

Meet your company's product quality conformance needs with the OS950's patented Automatic Emissivity Compensation System (AECS). In this mode, the unit will provide precision temperature measurements of spot targets, without knowing the target's emissivity value, and without errors caused by other sources of incident radiation. Since the OS950 is NIST traceable, it can function as a primary temperature calibrator for other temperature measuring devices, serving your corporate quality instrument calibration programs. Operate the OS950 in SCAN mode, for thermal scanning measurements over a range of target temperatures. Thermal Scanning is very useful in many applications such as evaluating insulation, monitoring machinery, and inspecting electrical equipment. Or the OS950 may be operated in the MAX mode where the highest temperature measured while monitoring is presented.

This manual provides complete instructions on how to operate and use your OS950-- to provide fast, accurate, reliable temperature measurements for your application needs.

## 1.2 Product Features

Designed for ease of use and measurement flexibility, the OS950 features:

- Dual purpose, AECS as well as MAX and SCAN measurement modes
- Measurement resolution to 0.1 °F or 0.1°C
- Factory calibration for precise results
- A 10 second display reading hold
- Internal self test and error diagnostic codes to insure proper function

## 1.3 Models and Ordering Information

OS950    -50 to 550°F (-45 to 287°C) Unit includes a 9 V DC Alkaline Battery and OS950 Instruction Manual. Also available with a Remote Sensor, RS232 Digital Output and an Analog Output.


OS953    0 to 1000°F (-18 to 538°C) Unit includes a 9 V DC Alkaline Battery and OS950 Instruction Manual. Also available with a Remote Sensor, RS232 Digital Output and an Analog Output.

OS955    0 to 1207°F (86 to 653°C) Unit includes a Remote Sensor, 9 V DC Alkaline Battery and OS950 Instruction Manual. Also available with an RS232 Digital Output and an Analog Output.

OS956 0 to 1600°F (86 to 871°C) Unit includes a Remote Sensor, 9 V DC Alkaline Battery and OS950 Instruction Manual. Also available with an RS232 Digital Output and an Analog Output.

## Chapter Two - Operation

### 2.1 OS950 Controls




LED Display	Displays target temperature and diagnostic codes
Measurement button	To turn on and start temperature measurement
Nosepiece w/AECS cup	Automatic emissivity compensation system nosepiece to contact target
Sensor window	Sensor viewing area for IR detector

### 2.2 To Change Display Measurement Units

The OS950 Models come from the factory displaying temperature in units of Fahrenheit. To display readings in units of Celsius, perform the following steps:

1. Remove the screw from the underside of the case.
2. Remove the cover, exposing the battery area.
3. Locate the push button switch as shown in the picture.
4. With the unit off (display is blank), push the push button in.
5. Holding the push button in, turn the unit on with the MEASUREMENT button.

The instrument now reads in °C instead of °F. To return to the original setting, simply repeat the process.



## 2.3 To Change Mode of Operation

The OS950 Models come from the factory operating in the MAX mode. To change to the SCAN mode perform the following steps:

1. Remove the screw from the underside of the case.
2. Remove the cover, exposing the battery area.
3. Locate the slide switch as shown in the picture.
4. Change the position of the slide switch from 1 to ON.

The unit will now operate in the SCAN mode. ON → SCAN, 1 → MAX.

## 2.4 Temperature Measurements

### 2.4.1 General Operation

**CAUTION... SHOCK HAZARD**

**DO NOT TOUCH THE INSTRUMENT TO ELECTRICAL CONDUCTORS\***

The OS950™ measures temperature very quickly. To obtain an accurate measurement, it is only necessary to touch the surface for a fraction of a second.

For exact surface temperature measurements that are NIST traceable, use the following procedure:

1. Press and hold the MEASURE button.
2. The display will briefly show [8888].
3. Touch the nosepiece to the target surface.
4. The display may or may not change, but the "beeping" sound will indicate that measurements are being made.
5. Record the temperature from the display.
6. Release the MEASURE button. The last reading will remain locked on the display for 10 seconds after releasing the button.



## 2.4.2 Temperature Measurement of Moving Targets

To measure moving targets that are not possible to touch, use the following procedure:

1. Press and hold the MEASURE button.
2. The display will briefly show [8888].
3. Bring the nosepiece as close as possible to the target, preferably within 1/32 inch (1 mm). \*\*
4. The display may or may not change, but the "beeping" sound will indicate that measurements are being made.
5. Record the temperature from the display.
6. Release the MEASURE button. The last reading will remain locked on the display for 10 seconds after releasing the button.

\*\* If the surface is metallic, be sure to mark it as described in the Measurement Tips section in Chapter Three.

## 2.4.3 High Temperature Targets

When using the OS950™ to measure high temperature targets, above 100 °F, quickly touch the target's surface -- one second is long enough to get an accurate reading.

Follow the procedures described above under 2.4.1 General Operation (see pg. 5). If the OS950 makes contact with a hot surface for an extended time (10 seconds or more) the target will conduct heat. Although this will not harm the unit, the indicated temperature may be a few degrees too high. Allow a few minutes between readings for the nosepiece to cool down and stabilize.

If the OS950 makes contact with a hot surface and an error message [HI] shows on the display remove the instrument from the object immediately.

## 2.5 MAX Mode Temperature Measurements

Use this measurement mode when making contact with the target or when the target is large. The OS950 is a wide-angle thermal scanner with a fixed emissivity of 0.9. The target's temperature is continuously displayed and updated 10 times per second for as long as you hold the MEASURE button down.

The OS950 displays the average temperature of everything within the sensor's field of view measurement area. The size of the measuring area depends on the distance of the device from the target. The OS950 has a 1:1 field of view, which means that this unit will measure a 1" diameter target area when the device is 1" from the target.

### 2.5.1 General Operation

For continuous temperature measurement of a target or for temperature measurement at a distance, use the following procedure.

1. Determine the appropriate measurement distance from your desired target. Best measurements are made when the OS950 is in contact with the target.
2. Make sure the MODE switch is on MAX.
3. Point the nosepiece at the target.
4. Press and hold the MEASURE button.

5. Record the temperature from the display.
6. Release the MEASURE button. The last reading will remain locked on the display for 10 seconds after releasing the button.

## 2.6 SCAN Mode Temperature Measurements

Use this measurement mode for thermal scanning of a target or when measuring targets located at a distance. The OS950 is a wide-angle thermal scanner with a fixed emissivity of 0.9. The target's temperature is continuously displayed and updated 10 times per second for as long as you hold the MEASURE button down.

The OS950 displays the average temperature of everything within the sensor's field of view measurement area. The size of the measuring area depends on the distance of the device from the target. The OS950 has a 1:1 field of view, which

means that this unit will measure a 1" diameter target area when the device is 1" from the target.

### 2.6.1 General Operation

For continuous temperature measurement of a target or for temperature measurement at a distance, use the following procedure.

1. Determine the appropriate measurement distance from your desired target.
2. Make sure the MODE switch is on SCAN.
3. Point the nosepiece at the target.
4. Press and hold the MEASURE button.
5. Record the temperature from the display.
6. Release the MEASURE button. The last reading will remain locked on the display for 10 seconds after releasing the button.

## Chapter Three - Measurement Tips

### 3.1 Optimizing Target Area Measurements

When performing a continuous thermal scan of a target, or measuring a target located at a distance, proper target alignment will help assure accurate results. Since the OS950's sensor measurement area is fixed at a field of view of 1 to 1, it is important to properly determine the best measuring distance from the target, to optimize the reading. A field of view of 1 to 1 means that the OS950 viewing area is 1" diameter for 1" distance from target. Optimize optical alignment, so that the OS950 views only the target and does not overlap the measurement area. See Figure below for examples of proper optical alignment.



POOR



POOR



GOOD

## **3.2 Measuring Metallic Targets**

In general, infrared thermometers can easily measure non-metallic surfaces because they emit most of their potential heat. Metallic surfaces, on the other hand, are poor emitters and require special treatment before infrared thermometers can accurately measure their temperature. Fortunately, that special treatment is simple and can be easily accomplished by marking the metallic surface you wish to measure with a non-metallic substance such as a solid paint marker. Other substances such as grease, oil, or tape may also be used. It is only necessary to mark an area slightly larger than the OS950 nosepiece, when operating in AECS mode. When operating in MAX or SCAN modes, mark the appropriate target area for the measuring distance from the target, based on a 1 to 1 Field of View.

## **3.3 Optimizing AESC Measurements for NIST Traceability**

If you look at the OS950's nosepiece, you will see that it is really a small reflective cup with the sensor's window at its base. When the OS950's nosepiece touches the surface of an object, that reflective cup automatically controls what the sensor sees by eliminating variables such as target emissivity and extraneous radiation. Patented by Exergen as the Automatic Emissivity Compensation System (AECS), this unique design ensures accurate readings every time. To optimize results, make sure that the nosepiece is flush with the target when possible, so that the reflective cone can completely trap out any light or incident radiation from the environment.

## **3.4 Measuring Transparent Materials**

Although transparent materials pass visible light, many visibly transparent materials are opaque in the infrared and can be directly measured by the OS950.

To test for infrared transparency, touch the OS950 to the target's surface and pass a heat source such as your hand or a penlight through the sensor's field of view on the other side of the material. If the OS950 responds to the heat source, the material is transparent in the infrared, and requires marking the surface for proper measurement. Mark the surface with an opaque non-metallic coating, such as paint or grease.

Alternatively, place a shiny metallic object, such as aluminum foil, behind the transparent material. The shiny metal will reflect the target's heat back to the OS950.

## **3.5 Measuring Wet or Icy Surfaces**

Wet or icy surfaces may interfere with the OS950's readings. Water and other liquids are good targets, but evaporation lowers their surface temperatures.

Frost forms on a surface at the freezing point of water. Frozen foods or similar targets will form frost unless the environment is controlled. If frost forms, the OS950 will measure the temperature of the frost instead of the object's temperature.

Melting ice will read slightly higher than 32 °F (0°C) because the instrument actually measures the air condensing on the ice, a reaction that generates a small amount of

heat. As long as the ice is not melting, the OS950 will accurately read its temperature.

To make an accurate target measurement, remove any ice or moisture before measuring.

## Chapter Four - Maintenance

The high-performance OS950 is a rugged and durable instrument, designed for long term performance reliability.

### 4.1 Battery Replacement

Open the instrument's cover to access the battery by loosening the screw on the back of the instrument. Remove the old battery and replace it with one fresh, 9 V alkaline battery. Align the battery contacts as indicated on the case.

### 4.2 Cleaning

The only maintenance required involves keeping the sensor window clean. This window, located at the base of the nosepiece's reflective cup, is made of a special crystal that passes infrared heat. Dirt, greasy films, or moisture on the window will interfere with the passage of infrared heat and affect the accuracy of the instrument.

If necessary, clean the sensor window and reflective cup with a cotton swab dipped in alcohol. Periodic cleaning is a good practice.

### 4.3 Storage

When not in use, store the OS950 in a container, to protect the unit from dirt and dust. Do not store the unit in areas of extreme heat, cold, or humidity. If not using the OS950 for a long period, remove the battery from the unit.

### 4.4 Calibration

The OS950 is factory calibrated under high quality standards. Because there are no mechanical adjustments, the instrument is able to maintain its calibration through vibration and normal use. No field calibration is necessary.

## Chapter Five - Troubleshooting

### 5.1 Diagnostic Codes

The high-performance OS950™ continuously monitors its ability to produce accurate temperature readings. If either the target's temperature or the unit's ambient temperature exceeds the operational limits, the display will default to an error message.

The battery voltage is also monitored. A low battery is indicated by a separate error code. The unit will continue to operate as long as accuracy can be assured. If the battery drops below 5.7 volts, the battery is considered "dead" and the display defaults to [----].

If the [E-##] or [Err] error messages are displayed, the unit will not function and must be returned to the factory for repair. (See section on Warranty for return instruction).

The following charts summarize the fault condition, and the associated indication.

### High Target Temperature

Condition	Error Code	Measurement Fault	Remedy
Model OS951	[HI]	Target >550°F (287 °C)	Use higher OS950
Model OS953	[HI]	Target >1000 °F (538 °C)	Use higher OS950
Model OS955	[HI]	Target >1207 °F (653 °C)	Use higher OS950
Model OS956	[HI]	Target >1600 °F (871 °C)	Contact Omega

### Low Target Temperature

Condition	Error Code	Measurement Fault	Remedy
Model OS951	[LO]	Target < -50 °F (-45 °C)	Contact Omega
Model OS953	[LO]	Target <0 °F (-18 °C)	Use lower OS950
Model OS955	[LO]	Target <186 °F (86 °C)	Use lower OS950
Model OS956	[LO]	Target <186 °F (86 °C)	Use OS951 or OS953

### Other Errors

Condition	Error Code	Measurement Fault	Remedy
High Ambient Temperature	[HI A]	Ambient > 122 °F (50 °C)	Move to alternate location
Low Ambient Temperature	[LO A]	Ambient < 32 °F (0 °C)	Move to alternate location
Low Battery	[N/A]	Battery power low	Replace battery
Dead Battery	[---]	Dead battery	Replace battery
Processing Error	[E-##] or [Err]	Internal fault	Repeat measurement, if error remains, contact Omega

## 5.2 Troubleshooting Measurement Difficulties

If you experience measurement problems, review the following troubleshooting steps:

*Is the sensor window clean?*

Clean the sensor window and reflective cup and repeat the measurement.

*Is the target's surface non-metallic?*

Coat metallic surfaces with a non-metallic finish and repeat the measurement.

*Is the target's surface transparent?*

Coat transparent surfaces with an opaque non-metallic finish and repeat the measurement.

Alternatively, put a shiny metallic surface such as aluminum foil behind the transparent target and repeat the measurement.

*Was the instrument's nosepiece in contact with the surface?*

Touch the nosepiece flush to the target's surface and repeat the measurement.

If after applying all of the above solutions, the instrument's accuracy is still in question, contact Omega for further help.

## Chapter Six - OS950™ Specifications

### Target Temperature Range

OS951	-50 to 550°F (-45 to 287°C)
OS953	0 to 1000°C (-18 to 538°C)
OS955	186 to 1207°F (86 to 653°C)
OS956	186 to 1600°F (86 to 871°C)

### Linearity Error

OS951	± 1% of reading
OS953	±3% of reading
OS955	±3% of reading
OS956	±3% of reading

### Emissivity Error

±1% of max. difference between target temperature and instrument temperature when touching, for emissivity of 0.8 to 1.0

### Minimum spot size diameter

Approx. 1/4" (6.4 mm)

Repeatability

± 0.1 °F/°C

### NIST Traceability

In AECS Mode

### Display Resolution

0.1 °F or 0.1 °C

## **Display Update**

10 times/second

## **Measurement Response Time**

Approximately 0.1 seconds

## **Field of View**

1:1 0.63" (15.9 mm) Diameter Spot Area in AECS Mode

## **Spectral Sensitivity**

2 to 20 microns

## **Battery**

One 9 volt

## **Battery Life**

5000 readings (10 seconds each)

## **Instrument Ambient Temperature**

Operating Range: 32 to 122°F (0 to 50°C)

Storage Range: -22 to 140°F (-30 to 60°C)\*

*\*Extended storage at temperature extremes will reduce battery life.*







## WARRANTY/DISCLAIMER

OMEGA ENGINEERING, INC. warrants this unit to be free of defects in materials and workmanship for a period of 13 months from date of purchase. OMEGA's WARRANTY adds an additional one (1) month grace period to the normal one (1) year product warranty to cover handling and shipping time. This ensures that OMEGA's customers receive maximum coverage on each product.

If the unit malfunctions, it must be returned to the factory for evaluation. OMEGA's Customer Service Department will issue an Authorized Return (AR) number immediately upon phone or written request. Upon examination by OMEGA, if the unit is found to be defective, it will be repaired or replaced at no charge. OMEGA's WARRANTY does not apply to defects resulting from any action of the purchaser, including but not limited to mishandling, improper interfacing, operation outside of design limits, improper repair, or unauthorized modification. This WARRANTY is VOID if the unit shows evidence of having been tampered with or shows evidence of having been damaged as a result of excessive corrosion; or current, heat, moisture or vibration; improper specification; misapplication; misuse or other operating conditions outside of OMEGA's control. Components which wear are not warranted, including but not limited to contact points, fuses, and triacs.

**OMEGA is pleased to offer suggestions on the use of its various products. However, OMEGA neither assumes responsibility for any omissions or errors nor assumes liability for any damages that result from the use of its products in accordance with information provided by OMEGA, either verbal or written. OMEGA warrants only that the parts manufactured by it will be as specified and free of defects. OMEGA MAKES NO OTHER WARRANTIES OR REPRESENTATIONS OF ANY KIND WHATSOEVER, EXPRESS OR IMPLIED, EXCEPT THAT OF TITLE, AND ALL IMPLIED WARRANTIES INCLUDING ANY WARRANTY OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE ARE HEREBY DISCLAIMED. LIMITATION OF LIABILITY: The remedies of purchaser set forth herein are exclusive, and the total liability of OMEGA with respect to this order, whether based on contract, warranty, negligence, indemnification, strict liability or otherwise, shall not exceed the purchase price of the component upon which liability is based. In no event shall OMEGA be liable for consequential, incidental or special damages.**

CONDITIONS: Equipment sold by OMEGA is not intended to be used, nor shall it be used: (1) as a "Basic Component" under 10 CFR 21 (NRC), used in or with any nuclear installation or activity; or (2) in medical applications or used on humans. Should any Product(s) be used in or with any nuclear installation or activity, medical application, used on humans, or misused in any way, OMEGA assumes no responsibility as set forth in our basic WARRANTY/DISCLAIMER language, and, additionally, purchaser will indemnify OMEGA and hold OMEGA harmless from any liability or damage whatsoever arising out of the use of the Product(s) in such a manner.

## RETURN REQUESTS / INQUIRIES

Direct all warranty and repair requests/inquiries to the OMEGA Customer Service Department. BEFORE RETURNING ANY PRODUCT(S) TO OMEGA, PURCHASER MUST OBTAIN AN AUTHORIZED RETURN (AR) NUMBER FROM OMEGA'S CUSTOMER SERVICE DEPARTMENT (IN ORDER TO AVOID PROCESSING DELAYS). The assigned AR number should then be marked on the outside of the return package and on any correspondence.

The purchaser is responsible for shipping charges, freight, insurance and proper packaging to prevent breakage in transit.

FOR WARRANTY RETURNS, please have the following information available BEFORE contacting OMEGA:

1. Purchase Order number under which the product was PURCHASED,
2. Model and serial number of the product under warranty, and
3. Repair instructions and/or specific problems relative to the product.

FOR NON-WARRANTY REPAIRS, consult OMEGA for current repair charges. Have the following information available BEFORE contacting OMEGA:

1. Purchase Order number to cover the COST of the repair,
2. Model and serial number of the product, and
3. Repair instructions and/or specific problems relative to the product.

OMEGA's policy is to make running changes, not model changes, whenever an improvement is possible. This affords our customers the latest in technology and engineering.

OMEGA is a registered trademark of OMEGA ENGINEERING, INC.

© Copyright 2001 OMEGA ENGINEERING, INC. All rights reserved. This document may not be copied, photocopied, reproduced, translated, or reduced to any electronic medium or machine-readable form, in whole or in part, without the prior written consent of OMEGA ENGINEERING, INC.

# Where Do I Find Everything I Need for Process Measurement and Control? **OMEGA...Of Course!** *Shop online at [www.omega.com](http://www.omega.com)*

## **TEMPERATURE**

- ✓ Thermocouple, RTD & Thermistor Probes, Connectors, Panels & Assemblies
- ✓ Wire: Thermocouple, RTD & Thermistor
- ✓ Calibrators & Ice Point References
- ✓ Recorders, Controllers & Process Monitors
- ✓ Infrared Pyrometers

## **PRESSURE, STRAIN AND FORCE**

- ✓ Transducers & Strain Gages
- ✓ Load Cells & Pressure Gages
- ✓ Displacement Transducers
- ✓ Instrumentation & Accessories

## **FLOW/LEVEL**

- ✓ Rotameters, Gas Mass Flowmeters & Flow Computers
- ✓ Air Velocity Indicators
- ✓ Turbine/Paddlewheel Systems
- ✓ Totalizers & Batch Controllers

## **pH/CONDUCTIVITY**

- ✓ pH Electrodes, Testers & Accessories
- ✓ Benchtop/Laboratory Meters
- ✓ Controllers, Calibrators, Simulators & Pumps
- ✓ Industrial pH & Conductivity Equipment

## **DATA ACQUISITION**

- ✓ Data Acquisition & Engineering Software
- ✓ Communications-Based Acquisition Systems
- ✓ Plug-in Cards for Apple, IBM & Compatibles
- ✓ Datalogging Systems
- ✓ Recorders, Printers & Plotters

## **HEATERS**

- ✓ Heating Cable
- ✓ Cartridge & Strip Heaters
- ✓ Immersion & Band Heaters
- ✓ Flexible Heaters
- ✓ Laboratory Heaters

## **ENVIRONMENTAL MONITORING AND CONTROL**

- ✓ Metering & Control Instrumentation
- ✓ Refractometers
- ✓ Pumps & Tubing
- ✓ Air, Soil & Water Monitors
- ✓ Industrial Water & Wastewater Treatment
- ✓ pH, CoOnductivity & Dissolved Oxygen Instruments