

1 YEAR
WARRANTY




MADE IN TAIWAN

DATALOGGER OS1327D

Infrared / Type K Thermometer
Remote Temperature Measurement
(Non-Contact)

INSTRUCTION MANUAL

※ Enclosed CD : Software & Protocol Inside.



User's Guide

Shop online at

omega.com®

Ω OMEGA®

omega.com

e-mail: info@omega.com

For latest product manuals:
omegamanual.info

ISO 9001
CERTIFIED
CORPORATE QUALITY
STAMFORD, CT

ISO 9001
CERTIFIED
CORPORATE QUALITY
MANCHESTER, UK



OMEGAnet® Online Service
omega.com

Internet e-mail
info@omega.com

Servicing North America:

U.S.A.:
ISO 9001 Certified

Omega Engineering, Inc., One Omega Drive, P.O. Box 4047
Stamford, CT 06907-0047 USA
Toll Free: 1-800-826-6342 TEL: (203) 359-1660
FAX: (203) 359-7700 e-mail: info@omega.com

Canada:

976 Bergar
Laval (Quebec), Canada H7L 5A1
Toll-Free: 1-800-826-6342 TEL: (514) 856-6928
FAX: (514) 856-6886 e-mail: info@omega.ca

For immediate technical or application assistance:

U.S.A. and Canada: Sales Service: 1-800-826-6342/1-800-TC-OMEGA®
Customer Service: 1-800-622-2378/1-800-622-BEST®
Engineering Service: 1-800-872-9436/1-800-USA-WHEN®

Mexico:

En Español: 001 (203) 359-7803 FAX: (001) 203-359-7807
info@omega.com.mx e-mail: espanol@omega.com

Servicing Europe:

Benelux:

Managed by the United Kingdom Office
Toll-Free: 0800 099 3344 TEL: +31 20 347 21 21
FAX: +31 20 643 46 43 e-mail: sales@omega.nl

Czech Republic:

Frystatska 184
733 01 Karviná, Czech Republic
Toll-Free: 0800-1-66342 TEL: +420-59-6311899
FAX: +420-59-6311114 e-mail: info@omegashop.cz

France:

Managed by the United Kingdom Office
Toll-Free: 0800 466 342 TEL: +33 (0) 161 37 29 00
FAX: +33 (0) 130 57 54 27 e-mail: sales@omega.fr

Germany/Austria:

Daimlerstrasse 26
D-75392 Deckenpfronn, Germany
Toll-Free: 0 800 6397678 TEL: +49 (0) 7059 9398-0
FAX: +49 (0) 7056 9398-29 e-mail: info@omega.de

United Kingdom:

ISO 9001 Certified

OMEGA Engineering Ltd.
One Omega Drive, River Bend Technology Centre, Northbank
Irlam, Manchester M44 5BD England
Toll-Free: 0800-488-488 TEL: +44 (0)161 777-6611
FAX: +44 (0)161 777-6622 e-mail: sales@omega.co.uk

It is the policy of OMEGA Engineering, Inc. to comply with all worldwide safety and EMC/EMI regulations that apply. OMEGA is constantly pursuing certification of its products to the European New Approach Directives. OMEGA will add the CE mark to every appropriate device upon certification.

The information contained in this document is believed to be correct, but OMEGA accepts no liability for any errors it contains, and reserves the right to alter specifications without notice.

WARNING: These products are not designed for use in, and should not be used for, human applications.

CONTENTS

Title	Page
1. INTRODUCTION.....	1
2. SAFETY INFORMATION	2
3. FEATURES	4
4. SPECIFICATIONS.....	4
5. FRONT PANEL DESCRIPTION.....	7
7. EMISSIVITY ADJUSTMENT	9
8. TEMPERATURE MEASUREMENT	12
9. SETTING MODE	14
10. BATTERY REPLACEMENT.....	16
11. SOFTWARE INSTALLATION AND OPERATION	17

1. INTRODUCTION

The Datalogger Infrared Thermometer is digital and is used with a type-K thermocouple input, being a dual measurement product.

Although its precise design, the hand-held Infrared Thermometer is easy to operate. Furthermore, the backlight illumination function is helpful to user who is accustomed to measure in dark places. The Infrared Thermometer will also indicate a Laser symbol on LCD as a reminder and its additional **auto hold reading & auto power off** functions are practical to users.

The Infrared Thermometer is a **non-contact** thermometer with laser pointer. It can be used to measure the temperature of objects' surface that is improper to be measured by traditional (contact) thermometer (such as moving object, surface with electricity current or objects that are difficult to reach).

2. SAFETY INFORMATION

1. Read the following safety information carefully before attempting to operate or service the meter.
2. Use the meter only as specified in this manual; otherwise, the protection provided by the meter may be impaired.



Warning

If user pulls the trigger while the  symbol is showing on LCD, then the meter will radiate the laser. At this moment, user has to avoid the laser radiating to your eyes to prevent any hurts.

- If the measured object with smooth surface and will reflect the laser, pls. prevent the reflected laser to radiate your eyes.
- Pls. don't radiate the laser to inflammable gas to avoid dangers.

3. Precautions:

- a). Do not operate the thermometer near large electrical or magnetic fields.
- b). Keep the thermometer away from direct sunlight or strong source of light, hot objects (70°C/158°F), high temperature, high humidity, or dust during use and storage.
- c). If the thermometer is in an environment where the temperature changes drastically, please wait until the thermometer returns to a stable status before starting the measuring.

- d). Condensation may form on the focal lens if the thermometer is moved quickly from a cold to a hot environment. Before taking measurements, please wait for the condensation to dissipate.
- e). Do not touch the focal lens.

4. Environmental conditions:

- a). Altitude up to 2000 meters.
- b). Relative humidity 80% max.
- c). Operating Ambient 0 ~ 50°C

5. Maintenance & Clearing:

- a). Repairs or servicing that are not covered in this manual and should be performed by qualified personnel only.
- b). Periodically wipe the case with a dry cloth. Do not use abrasives or solvents on the instrument.
- c). When servicing, use only specified replacement parts.

6. Safety symbols:

 Comply with EMC

3. FEATURES

- °C / °F Selectable.
- Backlight LCD display.
- Laser targeting.
- Adjustable Emissivity .
- Audible and visible alarm.
- Manual Data memory and read function.
- Type K thermometer.
- Auto Datalogger & USB PC interface.

4. SPECIFICATIONS

4-1 General Information :

Display : Backlight LCD Display.

Auto power off : Approx. 15 sec.

Manual Data memory capacity : 99 sets. (Direct reading from LCD display)

Auto Datalogger capacity: 10000 sets. (Only download to PC)

Over range indication : “OL” or “-OL”.

Low battery indication : The  symbol is displayed on LCD when the battery voltage drops below the operating voltage.

Power supply : Single 9V battery 006P 9V or IEC6F22, or NEDA1604.

Battery life : Approx. 100 hours (laser pointer and backlight aren't on use) (Alkaline batteries)

Operating temperature and humidity : 0°C to 50°C (32°F to 122°F), below 80%RH.

Storage temperature and humidity: -10°C to 60°C (14°F to 140°F), below 70%RH.

Dimensions : 172(L)×118(W)×46(H) mm
6.8(L)×4.6(W)×1.8(H) inches.

Weight : Approx. 220g with battery.

Accessories : instruction manual, battery, CD software and USB cable.

Optional : AC adaptor (IN-OUT Isolated type), 9VDC
150mA.



4-2 Electrical Specifications :

Measuring range : -35°C to 500°C (-31°F to 932°F)

Resolution : 0.1°C , 0.2°F

Accuracy : ± 2% reading or ± 2°C or ±4°F, whichever is greater.

Temperature coefficient : 0.1 times the applicable accuracy specification per °C from 0°C to 18°C and 28°C to 50°C (32°F to 64°F and 82°F to 122°F).

Responding time : 2.0 times per second.

Spectral Response : 6 ~ 14um.

Field of view : 12:1 ; optics ratio with a 1" min target.

Emissivity : 0.17 ~ 1.00

Sighting : Laser marker 1mw (class 2).

Sensor : Thermopile.

□ Type K

Measuring range : -150°C to 1350°C (-238°F to 1999°F).

Resolution : 0.1°C, 1°C, 0.1°F, 1°F.

Responding time : Once per second.

Basic accuracy : (@ 23±5°C calibration) accuracy are ±
(...% of reading + degree) at 18°C to
28°C with relative humidity up 80%.


Function	Resolution	Range	Accuracy
°C	0.1°C	-150°C ~ 0°C	±(0.2%rdg + 1.0°C)
		0°C ~ 200°C	±(0.1%rdg + 1.0°C)
	1°C	200°C ~ 1350°C	±(0.2%rdg + 2°C)
°F	0.1°F	-238°F ~ 32°F	±(0.2%rdg + 2°F)
		32°F ~ 200°F	±(0.1%rdg + 2°F)
	1°F	200°F ~ 1999°F	±(0.2%rdg + 4°F)

Temperature Coefficient :

0.1 times the applicable accuracy specification per °C from 0°C to 18°C and 28°C to 50°C (32°F to 64°F and 82°F to 122°F).

Note : The basic accuracy specification does not include the error of the probe. Please refer to the probe accuracy specification for additional details.

5. FRONT PANEL DESCRIPTION




1. Display.

Key	Press one time	Press and hold 3 seconds
2. MODE	Enter to MAX/MIN recorder mode. MAX→MIN→Current reading (MAX/MIN) ↑	① In MAX/MIN mode will exit this mode. ② In normal mode will enter to setting mode.
3. ☀ M ▼	① In normal mode will turn on or off the backlight. ② In Read mode can decrease gradually to select the desired memory reading. ③ In SET mode can decrease gradually to set the desired values.	Memory the LCD reading.
4. ⚡ R ▲	① In normal mode will turn on or off the laser mark. ② In Read mode can increase gradually to select the desired memory reading. ③ In SET mode can increase gradually to set the desired values.	Read the memory data.

5. Measuring trigger :
 - ① Trigger for powering on.
Pull the trigger to turn on the thermometer.
 - ② In SET mode, pull the trigger will stored the setting value and exit this mode.
6. Battery cover.
7. Laser aperture.
8. Focal lens.
9. Type K thermocouple input socket.
10. USB interface socket.
11. AC adaptor, input socket.

6. LCD DISPLAY DESCRIPTION



1. Hold function	11. Lo alarm
2. Maximum reading	12. Alarm function
3. Minimum reading	13. Hi alarm
4. Low battery mark	14. Memory and Read address number
5. Emissivity / Type K value	15. Read memory data
6. Emissivity value setting	16. Memory full indicator
7. Infrared measuring value	17. Store data to memory
8. Measure indicator	18. Unit " °C , °F "
9. Laser indicator	19. Type K measuring indicator
10. SET symbol	20. Auto datalogger indicator

7. Emissivity Adjustment

1. Emissivity : Emissivity is a value between 0.17 and 1 that indicates an object's ability to emit infrared energy. Emissivity is determined primarily by the object's composition and surface finish.

The thermometer's sensitivity to emissivity " \mathcal{E} " was set at 0.95 before shipment because in 90% of the time, objects' emissivity is set at 0.95.

2. Emissivity Adjustment

- ① Apply black tape, black mat paint or black magic marker to the object if it is safe.
- ② " \mathcal{E} " is set at 0.95 to measure the dark surface.
- ③ To aim the laser at dark surface, pull trigger to get measurement as T1.
- ④ Remove the black tape or black mat paint and aim laser at the same area again then pull trigger to get the measurement as (T).
- ⑤ Change & reset a value for emissivity " \mathcal{E} " to get measurement (T) until T equal to T1.
 - a). Enter to setting mode (refer to **MODE** key).
 - b). Press **MODE** key to select the \mathcal{E} value setting.
 - c). Press ▲ or ▼ keys to set desired values.
 - d). Pull the trigger to store the setting value and exit this mode.

Emissivity VALUES

Typical Emissivity Values-Metals (cont.)	
SURFACE	EMISSIVITY
Zinc (oxidized)	0.1*
Galvanized iron	0.3
Tin-plated steel	0.1*
Gold (polished)	0.1*
Silver (polished)	0.1*
Chromium (polished)	0.1*

Emissivity Values-Non-Metals Refractory & Building Materials	
Red brick (rough)	0.75 to 0.9
Fire clay	0.75
Asbestos	0.95
Concrete	0.7
Marble	0.9
Carborundum	0.85
Plaster	0.9
Alumina (fine grain)	0.25
Alumina (coarse grain)	0.45
Silica (fine grain)	0.4
Silica (coarse grain)	0.55
Zirconium silicate up to 500°C	0.85
Zirconium silicate at 850°C	0.6
Quartz (rough)	0.9
Carbon (graphite)	0.75
Carbon (soot)	0.95
Timber (various)	0.8 to 0.9
Miscellaneous	
Enamel (any color)	0.9
Oil paint (any color)	0.95
Lacquer	0.9
Matte black paint	0.95 to 0.98
Aluminum lacquer	0.5
Water	0.98
Rubber (smooth)	0.9
Rubber (rough)	0.98
Plastics (various, solid)	0.8 to 0.95
Plastic films (05 mm thick)	0.5 to 0.95
Polythene film (03 mm thick)	0.2 to 0.3
Paper and cardboard	0.9
Silicone polish (03 mm thick)	0.7
* Emissivity values with purity	

EMISSION VALUES	
Typical Emissivity Values-Metals	
SURFACE	EMISSION

Iron and Steel	
Cast iron (polished)	0.2
Cast iron (turned at 100°C)	0.45
Cast iron (turned at 1000°C)	0.6 to 0.7
Steel (ground sheet)	0.6
Mild steel	0.3 to 0.5
Steel plate (oxidized)	0.9
Iron plate (rusted)	0.7 to 0.85
Cast iron (rough) rusted	0.95
Rough ingot iron	0.9
Molten cast iron	0.3
Molten mild steel	0.3 to 0.4
Stainless steel (polished)	0.1
Stainless steel (various)	0.2 to 0.6
Aluminum	
Polished aluminum	0.1*
Aluminum (heavily oxidized)	0.25
Aluminum oxide at 260°C	0.6
Aluminum oxide at 800°C	0.3
Aluminum Alloys various	0.1 to 0.25
Brass	
Brass (polished)	0.1*
Brass (roughened surface)	0.2
Brass (oxidized)	0.6
Copper	
Copper (polished)	0.05*
Copper plate (oxidized)	0.8
Molten copper	0.15
Lead	
Lead (pure)	0.1*
Lead (oxidized at 25°C)	0.3
Lead (oxidized , reated to 200°C)	0.6
Nickel and its alloys	
Nickel (pure)	0.1*
Nickel plate (oxidized)	0.4 to 0.5
Nichrome	0.7
Nichrome (oxidized)	0.95

8. TEMPERATURE MEASUREMENT


1. Measurement :

- ① Pull the trigger to power on the meter and start measuring. Release the trigger to stop measuring and auto hold the reading. The meter will turn off automatically after 15 seconds.
- ② Auto detection type K thermocouple plug-in or pull-out. If plug-in type K thermocouple, the infrared \mathcal{E} value will auto change to type K measuring temperature value.

2. MAX/MIN hold function :

Pull & hold the trigger then press **MODE** for "1 time" to cycle select maximum (MAX), minimum (MIN) and current reading (MAX/MIN).

Press **MODE** for "3 seconds" to exit this mode.



Note:

- Laser offset: The laser beam is offset 18mm(0.71in) from the focal lens. Choose a sampling spot that is large enough to include the laser offset.
- Surface Temperatures: The thermometer will measure the first surface it detects, even a glass cover, dust or fog. Make sure the object is not obstructed.

3. Selecting °C/°F unit :

While powering on the meter, the temperature unit that appears in LCD would be the last unit you measured. If user wants to change the temperature unit, pull trigger to turn on the meter, then press **MODE** for "3 seconds" until "SET" mark appears on the LCD to enter SET mode, press ▲ or ▼ to select desired °C / °F unit, pull trigger to store the unit.

4. Manual Memorize / Read function (99 readings)

① To memorize the reading :

Press and hold down " **M** " key until the " **M** " mark is displayed (about 3 seconds), then release " **M** " key, stores one set logged reading in memory, LCD will show " **M** " and memory location numbers (1 to 99).

② To recall and read the reading :

- Press " **R** " key for 3 seconds to recall the reading memory data mode. LCD will show " **R** " and memory location numbers.
- Press " ▲ " or " ▼ " key to scroll through the logged readings.
- Press **MODE** key to exit READ mode.

③ To clean the memory :

- Under power off status, press and hold **M** key then pull trigger until " CLR no " shows on LCD.
- Press ▲ or ▼ to select "YES" or "no", then press **MODE** key two times to exit this mode. If you select "YES" the all memory will be cleared.

5. Auto Datalogger Function

① To setting interval time :

- Pull trigger to power on the meter. Press & hold **MODE** for "3 seconds" until "SET" appears on the LCD to enter the setting mode.
- Press **MODE** key 5 times, the "TIME" mark is displayed to enter the interval time setting mode.
- Press ▲ or ▼ key to select desired interval time from 1 second to 10 minutes.
- Pull trigger to exit this mode.

② To enter auto datalogger mode

- Press **M** key for 6 seconds until the "TIME" and "**M**" marks are displayed to enter the auto datalogger mode. When the "**M**" mark is disappear one time, one set of reading is stored to the memory.
- The maximum memory capacity is 10000 sets.
- Pull trigger to exit this mode.

③ To clear auto datalogged memorized data

- Under power off status, press and hold down **M** key then pull trigger until "CLR no" show on LCD.
- Press **MODE** key one time, the "TIME" mark is displayed.
- Press **▲** or **▼** key to select "YES" or "no", then press **MODE** key one time to exit this mode. If you select "YES" the all memory will be cleared.

9. SETTING MODE

Pull trigger to power on the meter. Press & hold **MODE** for "3 seconds" until "SET" appears on the LCD to enter the setting mode.

1. Parameter settings for measuring :

Under the infrared parameter setting mode, LCD will show **SET**. Press **MODE** to select setting of "°C/ °F", "ALM ON/OFF", "↓ALM" "ALM↑", emissivity "ε" and auto datalogger interval time "TIME". Pull trigger to exit the setting mode and return to the general measurement.

2. Parameter settings :

- "°C/ °F" : Temperature unit °C/ °F, press **▲** or **▼** to select units °C or °F.
- ALM (Alarm function ON/OFF) : Press **▲** or **▼** to select alarm function on or off.
- ↓ALM (Lo Alarm Function) : Press **▲** or **▼** to set up a value as an alarm value. When this Lo alarm value is exceeded, the beeper will beep and "↓ALM" symbol will appear on LCD.

- ④ ALM↑ (Hi Alarm Function) : Press ▲ or ▼ to set up a value as an alarm value. When this Hi alarm value is exceeded, the beeper will beep and “ALM↑” symbol will appear on LCD.

Example :

If you want alarm warning to exceed 100°C and below 0°C, can setting Hi Alarm point is 100°C,

Lo Alarm point is 0°C.

Setting procedure :

- a). Press **MODE** key for 3 seconds until LCD display “SET” mark.
 - b). Press “▲” key select °C unit.
 - c). Press **MODE** key one time, enter to ALARM ON/OFF choice, press ▲ or ▼ keys select “ON” mode.
 - d). Press **MODE** key one time enter to ↓ALARM (Lo Alarm point) setting.
Press ▲ or ▼ keys setting display to 0.0°C.
 - e). Press **MODE** key one time enter to ↑ALARM (Hi Alarm point) setting.
Press ▲ or ▼ keys setting display to 100.0°C.
 - f). Pull trigger to store the setting and exit this setting mode.
- ⑤ \mathcal{E} (Emissivity) : User can press ▲ or ▼ to adjust parameter.
- ⑥ TIME : Press ▲ or ▼ to setting the desired auto datalogger interval time from 1 seconds to 10 minutes.
- ⑦ ▲ : Key for increasing the value of Parameters. Hold down will increase the parameter rapidly.
- ⑧ ▼ : Key for decreasing the value of Parameters. Hold down will decrease the parameter rapidly.


Note: After setting procedure is terminated, the parameter will be memorized until next setting.

Under setting mode, Backlight, Laser light, Memory and Read functions will be disabled.

Pull trigger to exit setting mode.

10. BATTERY REPLACEMENT

1. As battery power is not sufficient, LCD will display the symbol . Replace old battery with a new one.
2. Open battery cover then take out the battery from instrument and replace with a new 9-Volt battery. Put back the battery cover.



11. SOFTWARE INSTALLATION and OPERATION

1. For the detailed instruction, please refer to the content of attached CD-ROM, which has the complete instruction of software operation and relevant information.
2. Protocol : are enclosed within the content of CD-ROM, please open the CD-ROM for details.

WARRANTY/DISCLAIMER

OMEGA ENGINEERING, INC. warrants this unit to be free of defects in materials and workmanship for a period of **13 months** from date of purchase. OMEGA's WARRANTY adds an additional one (1) month grace period to the normal **one (1) year product warranty** to cover handling and shipping time. This ensures that OMEGA's customers receive maximum coverage on each product.

If the unit malfunctions, it must be returned to the factory for evaluation. OMEGA's Customer Service Department will issue an Authorized Return (AR) number immediately upon phone or written request. Upon examination by OMEGA, if the unit is found to be defective, it will be repaired or replaced at no charge. OMEGA's WARRANTY does not apply to defects resulting from any action of the purchaser, including but not limited to mishandling, improper interfacing, operation outside of design limits, improper repair, or unauthorized modification. This WARRANTY is VOID if the unit shows evidence of having been tampered with or shows evidence of having been damaged as a result of excessive corrosion; or current, heat, moisture or vibration; improper specification; misapplication; misuse or other operating conditions outside of OMEGA's control. Components in which wear is not warranted, include but are not limited to contact points, fuses, and triacs.

OMEGA is pleased to offer suggestions on the use of its various products. However, OMEGA neither assumes responsibility for any omissions or errors nor assumes liability for any damages that result from the use of its products in accordance with information provided by OMEGA, either verbal or written. OMEGA warrants only that the parts manufactured by the company will be as specified and free of defects. OMEGA MAKES NO OTHER WARRANTIES OR REPRESENTATIONS OF ANY KIND WHATSOEVER, EXPRESSED OR IMPLIED, EXCEPT THAT OF TITLE, AND ALL IMPLIED WARRANTIES INCLUDING ANY WARRANTY OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE ARE HEREBY DISCLAIMED. LIMITATION OF LIABILITY: The remedies of purchaser set forth herein are exclusive, and the total liability of OMEGA with respect to this order, whether based on contract, warranty, negligence, indemnification, strict liability or otherwise, shall not exceed the purchase price of the component upon which liability is based. In no event shall OMEGA be liable for consequential, incidental or special damages.

CONDITIONS: Equipment sold by OMEGA is not intended to be used, nor shall it be used: (1) as a "Basic Component" under 10 CFR 21 (NRC), used in or with any nuclear installation or activity; or (2) in medical applications or used on humans. Should any Product(s) be used in or with any nuclear installation or activity, medical application, used on humans, or misused in any way, OMEGA assumes no responsibility as set forth in our basic WARRANTY/DISCLAIMER language, and, additionally, purchaser will indemnify OMEGA and hold OMEGA harmless from any liability or damage whatsoever arising out of the use of the Product(s) in such a manner.

RETURN REQUESTS/INQUIRIES

Direct all warranty and repair requests/inquiries to the OMEGA Customer Service Department. **BEFORE RETURNING ANY PRODUCT(S) TO OMEGA, PURCHASER MUST OBTAIN AN AUTHORIZED RETURN (AR) NUMBER FROM OMEGA'S CUSTOMER SERVICE DEPARTMENT (IN ORDER TO AVOID PROCESSING DELAYS).** The assigned AR number should then be marked on the outside of the return package and on any correspondence.

The purchaser is responsible for shipping charges, freight, insurance and proper packaging to prevent breakage in transit.

FOR **WARRANTY** RETURNS, please have the following information available BEFORE contacting OMEGA:

1. Purchase Order number under which the product was PURCHASED,
2. Model and serial number of the product under warranty, and
3. Repair instructions and/or specific problems relative to the product.

FOR **NON-WARRANTY** REPAIRS, consult OMEGA for current repair charges. Have the following information available BEFORE contacting OMEGA:

1. Purchase Order number to cover the COST of the repair,
2. Model and serial number of the product, and
3. Repair instructions and/or specific problems relative to the product.

OMEGA's policy is to make running changes, not model changes, whenever an improvement is possible. This affords our customers the latest in technology and engineering.

OMEGA is a registered trademark of OMEGA ENGINEERING, INC.

© Copyright 2009 OMEGA ENGINEERING, INC. All rights reserved. This document may not be copied, photocopied, reproduced, translated, or reduced to any electronic medium or machine-readable form, in whole or in part, without the prior written consent of OMEGA ENGINEERING, INC.

Where Do I Find Everything I Need for Process Measurement and Control? OMEGA...Of Course!

Shop online at omega.com SM

TEMPERATURE

- Thermocouple, RTD & Thermistor
Probes, Connectors, Panels &
Assemblies
- Wire: Thermocouple, RTD & Thermistor
- Calibrators & Ice Point References
- Recorders, Controllers & Process
Monitors
- Infrared Pyrometers

PRESSURE, STRAIN AND FORCE

- Transducers & Strain Gages
- Load Cells & Pressure Gages
- Displacement Transducers
- Instrumentation & Accessories

FLOW/LEVEL

- Rotameters, Gas Mass Flowmeters &
Flow Computers
- Air Velocity Indicators
- Turbine/Paddlewheel Systems
- Totalizers & Batch Controllers

pH/CONDUCTIVITY

- pH Electrodes, Testers & Accessories
- Benchtop/Laboratory Meters
- Controllers, Calibrators, Simulators &
Pumps
- Industrial pH & Conductivity
Equipment

DATA ACQUISITION

- Data Acquisition & Engineering
Software
- Communications-Based Acquisition
Systems
- Plug-in Cards for Apple, IBM &
Compatibles
- Data Logging Systems
- Recorders, Printers & Plotters

HEATERS

- Heating Cable
- Cartridge & Strip Heaters
- Immersion & Band Heaters
- Flexible Heaters
- Laboratory Heaters

ENVIRONMENTAL MONITORING AND CONTROL

- Metering & Control Instrumentation
- Refractometers
- Pumps & Tubing
- Air, Soil & Water Monitors
- Industrial Water & Wastewater
Treatment
- pH, Conductivity & Dissolved Oxygen
Instruments

M5009/0311