



-   Download HOBOMobile® to your phone or tablet.
- Open HOBOMobile. Enable Bluetooth® in your device settings if prompted.
- Press the button on the logger to wake it up.
- Tap the HOBOS icon (on Android™ devices) or tap the Devices icon and then tap Loggers at the top of the screen (on Apple® devices). Tap the logger in the list to connect to it. Press the button on the logger again to bring it to the top of the list if you are working with multiple loggers. If the logger does not appear in the list, make sure the logger is within range of your mobile device.
- Once connected, tap Configure to set up the logger. Choose your logger settings and then tap Start in the upper right corner of the Configure screen. The logger will begin logging data based on the settings you selected.
- Deploy the logger to the location where you will be monitoring the conditions. Follow the deployment guidelines in the full product manual at www.onsetcomp.com/manuals/mx2300.

- To offload data from the logger to your device, connect to it (described in steps 3 and 4) and tap Readout. The data from the logger is saved to your device. Tap the Data Files icon and then tap the mini-graph to view a larger version of the graph or to share the file.



For detailed specifications and information about the logger, scan the code at left or go to www.onsetcomp.com/manuals/mx2300.

⚠ WARNING: Do not cut open, incinerate, heat above 85°C (185°F), or recharge the lithium battery. The battery may explode if the logger is exposed to extreme heat or conditions that could damage or destroy the battery case. Do not dispose of the logger or battery in fire. Do not expose the contents of the battery to water. Dispose of the battery according to local regulations for lithium batteries.